

DEENDAYAL PORT AUTHORITY
(Erstwhile: DEENDAYAL PORT TRUST)



Administrative Office Building
Post Box NO. 50
GANDHIDHAM (Kutch).
Gujarat: 370 201.
Fax: (02836) 220050
Ph.: (02836) 220038

www.deendayalport.gov.in

EG/WK/4660(EC)/Part V/ 232

Date: /01/2023

02/02/2023

To,
Smt. Urvashi Upadhyay,
Environment Engineer,
Unit Head, Kachchh (Bhuj),
Gujarat Pollution Control Board,
Paryavaran Bhavan, Sector 10A,
Gandhinagar- 382 010.

Sub: "Construction of 13th to 16th Cargo Berth at Kandla Port by M/s Deendayal Port Authority"- **Point-wise compliance of conditions stipulated in NOC(CTE) granted by GPCB reg.**

- Ref.:1) No Objection Certificate granted by GPCB vide order no. PCC/CCA-BHUJ-179(3)/575 dated 9/1/2009.
- 2) Kandla Port letter no. EG/WK/4660 (EC)/Part III/1089 dated 9/12/2013.
 - 3) Kandla Port letter no. EG/WK/4660 (EC)/Part III/251 dated 19/5/2014.
 - 4) Kandla Port letter no. EG/WK/4660 (EC)/Part III/200 dated 14/11/2014.
 - 5) Kandla Port letter no. EG/WK/4660 (EC)/Part III/254 dated 11/05/2015.
 - 6) Kandla Port letter no. EG/WK/4660 (EC)/Part III/164 dated 15/10/2015.
 - 7) Kandla Port letter no. EG/WK/4660 (EC)/Part III/131 dated 09/05/2016.
 - 8) Kandla Port letter no. EG/WK/4660 (EC)/Part IV/ 169 dated 26/12/2016.
 - 9) Deendayal Port letter no. EG/WK/4660 (EC)/Part IV/ 326 dated 26/06/2018.
 - 10) Deendayal Port letter no. EG/WK/4660 (EC)/Part V/55 dated 14(16)/02/2019.
 - 11) Deendayal Port letter no. EG/WK/4660 (EC)/Part V/207 dated 30(6)/11(12)/2019.
 - 12) Deendayal Port letter no. EG/WK/4660 (EC)/Part IV/ dated 12/01/2020.
 - 13) Deendayal Port letter no. EG/WK/4660 (EC)/Part IV/ dated 15/01/2021.
 - 14) Deendayal Port letter no. EG/WK/4660 (EC)/Part V/90 dated 07/10/2021.
 - 15) DPA letter no. EG/WK/4660 (EC)/Part V dated 28/03/2022.
 - 16) DPA letter no. EG/WK/4660 (EC)/Part V/151 dated 19/07/2022

Sir,

It is requested to kindly refer above cited references for the said subject.

In this connection, it is to state that, GPCB vide above referred letter dated 9/1/2009 had granted Consent to Establish to Kandla Port Trust for the subject project & further extended the validity period up to 13/7/2020 (For construction of 14th & 16th CB) vide letter dated 2/9/2015. Accordingly, Deendayal Port Authority (Erstwhile Deendayal Port Trust) has regularly submitted point wise compliance to the condition stipulated in the NOC/CTE to the GPCB.

.....Cont.....

Annexure -1

Annexure 1

Compliance Report for the Period Upto November, 2022

Subject: Compliance of conditions stipulated in Consent to Establish (NOC) issued by Gujarat Pollution Control Board, GoG for the proposal of "Construction of 13th to 16th Cargo Berths" at Kandla Port Trust.

Ref: - No Objection Certificate granted by GPCB vide order no. PCC/CCA-BHUJ-179(3)/575 dated 9/1/2009. GPCB extended the validity of NOC for 14th and 16th Cargo berth vide their letter no. PC/CCA-KUTCH-812(2)/GPCBID-284941 dated 02/09/2015 and upto 13/07/2020.

Status of Berths:

13th Cargo Berth: Under operation since 18/2/2013.

15th Cargo Berth: Under Operation since 16/11/2013.

14th Cargo Berth: Under Operation since 8/4/2019.

16th Cargo Berth: Under Operation since 10/3/2019.

CONSENT TO OPERATE:

Consolidated Consent & Authorization (CC&A) issued by the GPCB (Consent Order no-AWH-110594 dated of issue-8/12/2020, with a validity period upto 21/7/2025)- Detailed Order issued by the GPCB vide outward no. 581914 dated 22/1/2021 & subsequently, issued Correction in CC&A order vide letter no. PC/CCA-KUTCH-812(5)/GPCB ID 28494/588116 dated 9/4/2021.

Sr. No.	Condition	Compliance
1	The validity of NOC is for five years from the date of issue.	DPA has obtained Consolidated Consent & Authorization (CC&A) from the GPCB vide Consent Order no-AWH-110594 dated 8/12/2020, with a validity period upto 21/7/2025)- Detailed Order issued by the GPCB vide outward no. 581914 dated 22/1/2021 & subsequently, issued Correction in CC&A order vide letter no. PC/CCA-KUTCH-812(5)/GPCB ID 28494/588116 dated 9/4/2021 (Annexure A) .
2	The quantity of the industrial effluent from the manufacturing process and other ancillary industrial operation shall be nil.	N/A, as proposed project is only for handling of dry cargo materials.
3	The quantity of the domestic wastewater (sewage) shall not exceed 6,00,000 litres /day of sewage waste water shall be treated in the treatment plant having capacity of 3300 KL and 60% of treated waste water shall be reused and 240kl/day shall be discharged in to sea.	As already informed in earlier compliance reports, Septic tanks were provided for sewage treatment by the BOT operators of 13th & 15 th CB. DPA is also having STP (1.5 MLD capacity) for treatment of sewage generated. The treated sewage is being used for gardening and plantation purpose.
4	The quality of the industrial effluent arise during any accidental incident or disaster shall conform to the following standards:	
	Parameter	Permissible Limit
	PH	6.5to8.5
	Color (Pt.co.units)	100units
	Temperature	40°C
	Total Suspended Solids	100mg/l
	Oil and Grease	10mg/l
	BOD (5 days 20°C)	30mg/l
	COD	250mg/l
	Total Dissolved Solids	2100mg/l
	Percent Sodium	60%
	Phenolic Compound	1mg/l
	BOD (5 days 20°C)	30mg/l

	COD	250mg/l	
	Bio-assay test:	90% Survival of fish after 96hrs. In 100% effluent.	
5	The treated sewage effluent conforming to the above standards shall discharge into the sea.		DPA is having STP (1.5 MLD capacity) for treatment of sewage generated. In addition to that, it also has septic tanks at places where STP is inaccessible The treated sewage is being used for gardening and plantation purpose.
6	Sewage shall be disposed of through septic tank and it shall be treated in STP having capacity of 3300KL to conform to the following standards.		Septic tanks were provided for sewage treatment by the BOT operators of 13th & 15th CB. DPA is also having STP (1.5 MLD capacity) for treatment of sewage generated.
	BOD	Lessthan20mg/l	A copy of monitoring report (prepared by M/s DETOX Corporation, Surat) enclosed here with as Annexure B .
	Suspended Solids	Lessthan30mg/l	
	Residual chlorine	Minimum0.5ppm	
7	There shall be no flue gas emission.		N/A, No manufacturing activity involved as only non-hazardous dry bulk cargo is to be handled.
8	There shall be no process gases emission.		N/A, No manufacturing activity involved as only non-hazardous dry bulk cargo is to be handled.
9	Ambient air quality within the premises of the industry shall conform to the following standards:		A copy of monitoring report (prepared by M/s DETOX Corporation, Surat) enclosed herewith as Annexure B .
	Parameters	Permissible limit	
	Suspended Particulate Matter	200 Microgram/M3	
	RSPM	100 Microgram/M3	
	SO2	80 Microgram/M3	
	NOx	80 Microgram/M3	
10	All measures for the control of environmental pollution shall be		All the measures for the control of environmental pollution were already taken.

	provided before commencing production.	All the 4 berths are in operation.
11	Solid waste shall be disposed of by incineration or it shall be disposed of by sanitary land filling method at a site approved by the Board.	Companies authorized by Central Pollution Control Board (CPCB) and State Pollution Control Board (SPCB) have been awarded the work of collection, transporting and disposal of solid waste by the Deendayal Port Authority.
12	Adequate plantation shall be carried out all along the periphery of the industrial premises in such a way that the density of plantation is at least 1000 trees per acre of land and a greenbelt of 5.0 meter width is developed.	<p>DPA have planted about one lakhs trees in road side dividers, colony areas at Kandla and Gopalpuri, in green belt area of Gandhidham & Adipur Township, Sewage Treatment Plants at Gopalpuri & Kandla and some green belt development plans initiated at different locations in Town ship areas.</p> <p>DPA entrusted work of green belt development in and around Port area to the Forest Department, Gujarat at a cost of Rs. 352 lakhs (Area 32 hectares) and the work is completed.</p> <p>Further, DPA has appointed Gujarat Institute of Desert Ecology (GUIDE) for "Green belt development in Deendayal Port Authority and its Surrounding Areas, Charcoal site' (Phase-I)" vide Work Order No.EG/WK/4757/Part [Greenbelt GUIDE], dated 31st May, 2022 (Annexure C).</p>
13	The applicant shall have to submit the returns in prescribed form regarding water consumption and shall have to make payment of water Cess to the Board under the water Cess Act-1974.	Earlier, DPA regularly submitted the returns regarding water consumption and paid the water cess applicable. However, now after GST implementation, water cess is not applicable.
14	In case of change of ownership/ management the name and address of the new owners/ partners/ directors/ proprietor should immediately be intimated to the board.	Point Noted.
15	The applicant shall however, not without the prior consent of the board bring into use any new or altered outlet for the discharge of effluent or gaseous emission or sewage waste from the proposed industrial plant. The applicant is required to make applications to	Point Noted.

	this board for this purpose in the prescribed forms under the provisions of the water act 1974, the air act-1981 and the environment (protection) Act-1986.	
16	Unit shall obtained CRZ clearance from the competent authority.	<p>CRZ Recommendation already obtained from Forest & Environment Department, GOG (letter no. ENV-10-2006-138-P dated on 14th February, 2008). Further, Ministry of Environment & Forest-New Delhi, Govt. of India accorded the Environmental/ CRZ clearance vide letter no. 11-70/2006-IA.III dated Sep 2008 & the validity of the same had been extended by MoEF, GoI vide letter No.F.NO.11-70/2006-IA.III dated 7th February, 2014 for a further period of 5 years.</p> <p>All the 4 berths are in operation.</p>
17	Unit shall comply the all conditions of environmental clearance from MoEF, New Delhi, ECTNo.11-70/2006-IA-III sep.08	<p>The construction of all 4 berths viz.13th to 16th CB have been carried out as per the EC & CRZ clearance accorded by the MoEF, GoI vide dated Sep, 2008. The compliance reports are being regularly submitted to the MoEF&CC, GoI and with a copy to the MoEF&CC, GoI, New Delhi, CPCB and to the GPCB.</p> <p>Now, all the 4 berths are in operation.</p>
18	Unit shall obtain CC&A of GPCB.	<p>Consolidated Consent & Authorization (CC&A) issued by the GPCB (Consent Order no-AWH-110594 dated of issue-8/12/2020, with a validity period upto 21/7/2025)- Detailed Order issued by the GPCB vide outward no. 581914 dated 22/1/2021 & subsequently, issued Correction in CC&A order vide letter no. PC/CCA-KUTCH-812(5)/GPCB ID 28494/588116 dated 9/4/2021. (Annexure A).</p>
19	Unit shall develop domestic solid waste disposal facility in accordance with the provision of MSW Rules-2000.	<p>Companies authorized by Central Pollution Control Board (CPCB) and State Pollution Control Board (SPCB) have been awarded the work of collection, transporting and disposal of solid waste by the Deendayal Port Authority.</p> <p>DPA is managing its plastic waste as per Plastic Waste Management Rules – 2016</p>

		<p>and amendments made therein. In order to strictly implement the said rules, DPA had issued a circular regarding plastic waste minimization, source segregation, recycling etc. vide its Circular no. EG/WK/4751/Part 243(A) dated 03/09/2021.</p> <p>In addition to the above, appointment of Advisor for "Preparation of Plan for Management of Plastic Wastes, Solid waste including C&D wastes, E-wastes, Hazardous wastes including Biomedical and Non-hazardous waste in the Deendayal Port Authority Area" is under progress.</p>
20	Unit shall regularly update the disaster management plan and intimate state government about update made therein.	DPA is already having Disaster Management Plan (Copy placed at Annexure D) .

ANNEXURE A



GUJARAT POLLUTION CONTROL BOARD

PARYAVARAN BHAVAN

Sector-10-A, Gandhinagar-382 010

Phone : (079) 23226295

Fax : (079) 23232156

Website : www.gpcb.gov.in

By R.P.A.D

In exercise of the power conferred under section-25 of the Water (Prevention and Control of Pollution) Act-1974, under section-21 of the Air (Prevention and Control of Pollution)-1981 and Authorization under rule 6(2) of the Hazardous and Other Waste (Management and Trans boundary) Rules, 2016 framed under the Environmental (Protection) Act-1986.

And whereas Board has received consolidated consent application inward No.176457 dated 22/09/2020 for the **Renewal of Consolidated Consent and Authorization (CC&A)** of this Board under the provisions / rules of the aforesaid Acts. Consents & Authorization are hereby granted as under:

CONSENTS AND AUTHORISATION:

(Under the provisions /rules of the aforesaid environmental acts)

To,
✓ M/s. Deendayal Port Trust, (New name) (ID-28494)
M/s. Kandla Port Trust, (Old name),
Kandla, A.O Building Gandhidham,
Tal: Gandhidham, Dist: Kutch - 370201

1. Consent Order No. AWH-110594 Date of issue: 08/12/2020.
2. The consents shall be valid upto 21/07/2025 for the use of outlet for the discharge of trade effluent and emission due to operation of industrial plant for manufacturing of the following items/ products:

Sr. No	Product/Services	Quantity
1	Dry Cargo Handling	26,54,00,000 MT/Month
2.	Liquid Cargo Handling	54,64,00,000 MT/Month
3.	Loading and unloading operation at 13 th Berth	2 MMTPA
4.	Loading and unloading operation at 15 th Berth	2 MMTPA

Subject to specific condition:

1. Unit shall strictly adhere to compliance ministry in its Clearance letter file no. 11-82/2011-IA-III, dated 19/12/2016.
2. Unit shall also strictly adhere to all conditions of Environment and CRZ Clearance issued by MoEF vide letter no. F. no. 11-70/2006-IA-III dated 01/10/2008.
3. Applicant shall comply with Manufacture, Storage and Import of Hazardous Chemicals Rules-1989 (MSIHC) as amended time to time.
4. Applicant shall ensure that all storage terminal located within DPT area shall strictly comply with MSIHC Rules including site notification & submit details periodically to board with relevant details.
5. Applicant shall renew Public Liability Insurance time to time & submit a copy to this Board.

Clean Gujarat Green Gujarat

ISO - 9001 - 2008 & ISO - 14001 - 2004 Certified Organisation

6. Unit shall notify site under MSIHC Rule-1989 from competent authority as mentioned in schedule-5 of MSIHC Notifications.
7. Industry shall not withdraw groundwater without prior NOC from CGWA as per Hon. National Green Tribunal order.
8. Industry shall manage Solid Wastes generated from industrial activities as per Solid Waste Management Rules-2016 (solid waste as defined in Rule-3(46)).
9. Industry shall comply with Plastic Waste Management Rules- 2016 and amendments made therein.
10. Industry shall strictly comply with coal handling guideline of this board.
11. Industry shall provide dedicated storage facility for dry cargos & ensure to take adequate measures to prevent dusting.
12. Applicant shall ensure that there shall be no damage to the existing mangrove patches near site and also ensure the free flow of water to avoid damage to the mangroves.
13. Applicant shall ensure as per EC condition that no creeks or rivers are blocked due to any activities at the site and free flow of water is maintained.
14. Applicant shall provide proper system for collection, storage & treatment & disposal of waste water generated by vessel as per MARPOL & maintain records.
15. Applicant shall install storm drainage catch basin to avoid directly discharge into surface water.
16. Waste effluent accumulated with port activities including storm water & sewage from port operation including sewage ballast water, bilge water & clean waste water from ships shall be as per MARPOL norms.
17. Applicant shall make separate records regarding generation, collection, transportation & disposal of waste generation from ship & maintain its records.
18. Applicant shall made necessary arrangement for the plastic Waste, Solid Waste or other waste generation due to port activities & for facilitation of reception facilities under MARPOL & Environment (Protection) Act-1986 rules etc.
19. Ports shall obtain approval of their oil spill contingency plan (OSCP) as required under national oil spill disaster contingency plan (NOS-DCP) of coast guard, ministry of defence, govt. of India.
20. Best environmental practices by ports maybe uploaded on "Indian ports Association" as well as the same maybe linked to websites of CPCB and respective SPCBs.
21. Manually handling of cargo should be converted into mechanized system, in time bound manner.

3. Conditions under the Water act-1974:

3.1 Source of Water: - GWIL.

3.2 There shall be no industrial water consumption and waste water generation from manufacturing process and other ancillary operations.

3.3 The quantity of the fresh water consumption for domestic purpose shall not exceed 1300 KLD.

3.4 The quantity of domestic waste water shall not exceed 800 KLD.





GPCB

GUJARAT POLLUTION CONTROL BOARD

PARYAVARAN BHAVAN

Sector-10-A, Gandhinagar-382 010

Phone : (079) 23226295

Fax : (079) 23232156

Website : www.gpcb.gov.in

- 3.5 Domestic effluent shall be treated in existing STP & treated effluent conforming to following norms shall be discharged on land within premises strictly for gardening and plantation purpose & no sewage shall be disposed outside premises in any manner.

PARAMETERS	PRESCRIBED LIMITS
pH	6.5 to 8.5
BOD (3 days at 27° C)	30 mg/L
Suspended Solid	100 mg/L
Fecal Coli form	< 1000 MPN/ 100 ml

- 3.6 Treated domestic effluent confirming to above norms shall be discharge on land only for gardening & plantation within premises.
- 3.7 Unit shall provide flow meter at inlet & outlet of STP & maintain its record.
- 3.8 Disposal system for storm water shall be provided separately. In no case storm water & sewage from port facility shall not be discharge into surface water.

4. Conditions under the Air Act-1981:

- 4.1. The following shall be used as a fuel in D.G. Sets:

Sr. No.	Utility	Fuel	Quantity
1	D.G. Sets	HSD	500 Ltr/Hr

- 4.2. The applicant shall install & operate air pollution control system efficiently in order to achieve prescribed norms.
- 4.3. The flue gas emission through stack attached to D.G. Sets shall conform to the following standards

Sr. No.	Stack attached to	Stack height in Meter	APCM	Parameter	Permissible Limit
1 & 2	DG sets (2 nos.) (1010 KVA)	15 each	--	PM SO ₂ NO _x	150 mg/NM ³ 100 ppm 50 ppm

- 4.4. There shall be no process gas emission from manufacturing process and other ancillary operations.
- 4.5. The concentration of the following parameters in the ambient air within the premises of the industry and a distance of 10meters from the source) other than the stack/vent) shall not exceed the following levels.

Sr. No.	Pollutant	Time Weighted Average	Concentration in Ambient air in µg/M ³
1.	Sulphur Dioxide (SO ₂)	Annual 24 Hours	50 80
2.	Nitrogen Dioxide (NO ₂)	Annual 24 Hours	40 80
3.	Particulate Matter (Size less than 10 µm) or PM ₁₀	Annual 24 Hours	60 100
4.	Particulate Matter (Size less than 2.5 µm) or PM _{2.5}	Annual 24 Hours	40 60

Clean Gujarat Green Gujarat

- 4.6. The applicant shall provide portholes, ladder, platform etc at chimney(s) for monitoring the air emissions and the same shall be open for inspection to/and for use of Board's staff. The chimney(s) vents attached to various sources of emission shall be designed by numbers such as S-1, S-2, etc. and these shall be painted/displayed to facilitate identification.
- 4.7. The industry shall take adequate measures for control of noise levels from its own sources within the premises so as to maintain ambient air quality standards in respect of noise to less than 75dB(A) during day time and 70 dB (A) during night time. Daytime is reckoned in between 6a.m. and 10 p.m. and nighttime is reckoned between 10 p.m. and 6 a.m.

5. AUTHORIZATION as per HAZARDOUS AND OTHER WASTE (MANAGEMENT AND TRANSBOUNDARY) RULES, 2016 Form-2 [See rule 6 (2)]

Form for grant of authorization for occupier or operator handling Hazardous waste

5.1 Authorization order no:-**AWH-110594** Date of issue: 08/12/2020.

5.2 **M/s. Kandla Port Trust** is hereby granted an authorization to operate facility for following hazardous wastes on the premises situated at Kandla, A.O Building Gandhidham, Tal: Gandhidham, Dist : Kutch.

Sr. No.	Waste	Quantity/ Year	Schedule & Category	Facility
1	Used Spent Oil	1125 MT	I- 5.1	Collection, Storage, Transportation and disposal by selling to authorized recycler.
2	Waste Residue Containing Oil	3344.43 MT	I-5.2	Collection, Storage, Transportation and disposal by selling to authorized recycler.

5.3 The authorization shall be valid up to **21/07/2025**.

5.4 The authorization is subject to the conditions stated below and such other conditions as may be specified in the rules from time to time under the Environment (Protection) Act-1986.

5.5 The authorization is granted to operate a facility for collection, storage within factory premises transportation and ultimate disposal of Hazardous wastes as per condition no 5.2 to the industry having valid CCA of this Board.

5.6 TERMS AND CONDITIONS OF AUTHORISATION

1. The applicant shall comply with the provisions of the Environment (Protection) Act-1986 and the rules made there under.
2. The authorization or its renewal shall be produced for inspection at the request of an officer authorized by the Gujarat Pollution Control Board.
3. The persons authorized shall not rent, lend, sell, and transfer or otherwise transport the hazardous wastes without obtaining prior permission of the Gujarat Pollution Control Board.





GUJARAT POLLUTION CONTROL BOARD

PARYAVARAN BHAVAN

Sector-10-A, Gandhinagar-382 010

Phone : (079) 23226295

Fax : (079) 23232156

Website : www.gpcb.gov.in

4. Any unauthorized change in personnel, equipment or working conditions as mentioned in the authorization order by the persons authorized shall constitute a breach of this authorization.
5. The person authorized shall implement Emergency Response Procedure (ERP) for which this authorization is being granted considering all site specific possible scenarios such as spillages, leakages, fire etc. and their possible impacts and also carry out mock drill in this regard at regular interval of time;
6. The person authorized shall comply with the provisions outlined in the Central Pollution Control Board guidelines on "Implementing Liabilities for Environmental Damages due to Handling and Disposal of Hazardous Wastes and Penalty"
7. It is the duty of the authorized person to take prior permission of the Gujarat Pollution Control Board to close down the facility.
8. An application for the renewal of an authorization shall be made as laid down in rules 6(2) under Hazardous and Other Waste Rules, 2016.
9. The imported hazardous and other wastes shall be fully insured for transit as well as for any accidental occurrence and its clean-up operation.
10. The record of consumption and fate of the imported hazardous and other wastes shall be maintained.
11. The hazardous and other wastes which gets generated during recycling or reuse or recovery or pre-processing or utilization of imported hazardous or other wastes shall be treated and disposed of as per specific conditions of authorization.
12. The importer or exporter shall bear the cost of import or export and mitigation of damages if any.
13. Any other conditions for compliance as per the Guidelines issued by the Ministry of Environment, Forest and Climate Change or Central Pollution Control Board from time to time.
14. The waste generator shall be totally responsible for (i.e. collection, storage, transportation and ultimate disposal) the wastes generated.
15. Records of waste generation, its management and annual return shall be submitted to Gujarat Pollution Control Board in Form-4 by 30th day of June of every year for the preceding period April to March.
16. In case of any accident, details of the same shall be submitted on Form-11 to Gujarat Pollution Control Board.
17. As per "Public Liability Insurance Act-91" company shall get Insurance Policy, if applicable.
18. Empty drums and containers of toxic and hazard material shall be treated as per guideline published for "Management & Handling of discarded containers". Records of the same shall be maintained and forwarded to Gujarat Pollution Control Board regularly.
19. In case of transport of hazardous wastes to a facility for (i.e. treatment, storage and disposal) existing in a State other than the State where hazardous wastes are generated, the occupier shall obtain 'No Objection Certificate' from the State Pollution Control Board or Committee of the concerned State of Union Territory Administration where the facility exists.
20. Unit shall take all concrete measures to show tangible results in waste generation, reduction, avoidance, reuse and recycle. Actions taken in this regard shall be submitted within three months and also along with Form-4.

Clean Gujarat Green Gujarat

21. Industry shall have to display the relevant information with regards to hazardous waste as indicated in the Hon. Supreme Court's Order in W.P. No.657 of 1995 dated 14th October, 2003.
22. Industry shall have to display on-line data outside the main factory gate with regard to quantity and nature of hazardous chemicals being handled in the plant, including wastewater and air emissions and solid hazardous wastes generated within the factory premises.

6. **SPECIFIC CONDITIONS:-**

- 6.1 The authorized actual user of hazardous and other wastes shall maintain records of hazardous and other wastes purchased in a passbook issued by the State Pollution Control Board along with the authorization.
- 6.2 Handling over of the hazardous and other wastes to the authorized actual user shall be only after making the entry in the passbook of the actual user.
- 6.3 In case of renewal of authorization, a self-certified compliance report in respect of effluent, emission standards and the conditions specified in the authorization for hazardous and other wastes shall be submitted to SPCB.
- 6.4 The occupier of the facility shall comply Standard operating procedure/guidelines published by MOEF&CC or CPCB or GPCB from time to time.
- 6.5 Unit shall comply provisions of E-Waste Management Rules-2016.
- 6.6 The disposal of Hazardous Waste shall be carried out as per the waste Management hierarchy.
- 6.7 The occupiers of facilities shall not store the hazardous and other wastes for a period not exceeding **ninety days**. Prior permission of the Board shall be obtained for extension of the storage period.
- 6.8 The occupier shall maintain the records of generation, sale, storage, transport, recycling, co processing and disposal of hazardous waste and make available during the inspection.
- 6.9 The transportation of the hazardous waste shall be carried out in GPS mounted dedicated vehicles.

7. **GENERAL CONDITIONS: -**

- 7.1 Any change in personnel, equipment or working conditions as mentioned in the consents form/order should immediately be intimated to this Board.
- 7.2 Applicant shall also comply with the general conditions given in annexure I.
- 7.3 Whenever due to accident or other unforeseen act or ever, such emissions occur or is apprehended to occur in excess of standards laid down such information shall be forthwith reported to Board, concerned Police Station Office of Directorate of Health Service, Department of Explosives, Inspectorate of Factories and local body.
- 7.4 In case of failure of pollution control equipments, the production process connected to it shall be stopped. Remedial actions/measures shall be implemented immediately to bring entire situation normal.





GUJARAT POLLUTION CONTROL BOARD

PARYAVARAN BHAVAN

Sector-10-A, Gandhinagar-382 010

Phone : (079) 23226295

Fax : (079) 23232156

Website : www.gpcb.gov.in

- 7.5 The Environmental Management Unit/Cell shall be setup to ensure implementation on and monitoring of environmental safeguards and other conditions stipulated by statutory authorities. The Environmental Management Cell/Unit shall directly report to the Chief Executive of the organization and shall work as a focal point for internalizing environmental issues. These cells/units also coordinate the exercise of environmental audit and preparation of environmental statements.
- 7.6 The Environmental audit shall be carried out yearly and the environmental statements pertaining to the previous year shall be submitting to this State Board latest by 30th September every year.
- 7.7 The Board reserves the right to review and/or revoke the consent and/or make variations in the conditions, which the Board deems, fit in accordance with Section 27 of the Act.
- 7.8 In case of change of ownership/management the name and address of the new owners/ partners/directors/proprietor should immediately be intimated to the Board.
- 7.9 Industry shall have to display the relevant information with regard to hazardous waste as indicated in the Hon. Supreme order in w.p. no. 657 of 1995 dated 14th October 2003.

For and on behalf of
GUJARAT POLLUTION CONTROL BOARD


(Smt. U.K. Upadhyay)
Environment Engineer

NO: GPCB/CCA-Kutch-812(5)/ID-28494/
Issued to:
M/s. Deendayal Port Trust, (New name),
M/s. Kandla Port Trust, (Old name),
Kandla, A.O Building Gandhidham,
Tal: Gandhidham, Dist: Kutch - 370 201

Date:-

Outward No: 581914, 22/01/2021

Clean Gujarat Green Gujarat



GUJARAT POLLUTION CONTROL BOARD

PARYAVARAN BHAVAN

Sector-10-A, Gandhinagar-382 010

Phone : (079) 23226295

Fax : (079) 23232156

Website : www.gpcb.gov.in

By R.P.A.D.

NO: PC/ CCA- KUTCH-812(5)/ GPCB ID: 28494/

Date: -

Correction in Consolidated Consent & Authorization order no AWH-110594 date of issue 22/01/2021 (Under the provisions/rules of Environmental acts)

To,

M/s. Deendayal Port Trust, (New name)

M/s. Kandla Port Trust, (old name),

Kandla, A.O Building Gandhidham,

Tal:-Gandhidham,

Dist: Kutch – 370 201.

Subject : Correction of Consolidated Consent and Authorization (CC& A) of this Board

Reference : 1) CCA issued vide order no. PC/ CCA- KUTCH-812(5)/ GPCB ID: 28494/ 581914 dated 22/01/2021.
2) Your letter dated 25/01/2021.

In exercise of the power conferred under section-27 of the Water (Prevention and Control of Pollution) Act-1974, under section-21 of the Air (Prevention and Control of Pollution)-1981 and Authorization under rule 6(2) of the Hazardous & Other Waste (Management & Transboundary Movement) Rules-2016 & as amended framed under the Environmental (Protection) Act-1986 and without reducing your responsibility under the said Acts/Rules in anyway. The Board had granted CCA vide order no. AWH-110594 dated 22/01/2021.

ANDWHEREAS the Board is empowered to amend CCA conditions. Accordingly, considering your request for corrected & after care full consideration, the CCA order no. AWH-110594 is hereby corrected/ amended as below;

1. The condition no. 2 of the said CCA order shall be corrected as below;
2. The consent shall be valid upto 21/07/2025 for the use of outlet for the discharge of trade effluent and emission due to operation of industrial plant for manufacturing of the following items/ products:

Sr No.	Product	Quantity
1.	Dry Cargo Handling	26,54,00,000 MT/Month
2.	Liquid Cargo Handling	54,64,00,000 MT/Month
3.	Loading and unloading operation of 13 th and 15 th berth	2 MMTPA(Each)
4.	Loading and unloading operation of 14 th and 16 th berth	4.5 MMTPA (Each)

2. All other terms and condition mentioned in AWH – 110594 issued vide CCA letter PC/ CCA- KUTCH-812(5)/ GPCB ID: 28494/581914 dated 22/01/2021 shall remain unchanged.

For and on behalf of
Gujarat Pollution Control Board

(Smt. U. K. Upadhyay)
Environment Engineer

Clean Gujarat Green Gujarat

ANNEXURE B

ENVIRONMENTAL MONITORING REPORT FOR DEENDAYAL PORT AUTHORITY



REPORT : **DCPL/DPA/21-22/31**

Mont : **November 01**

Issue : **00**

Revision : **00**

Prepare : **DETOX CORPORATION PVT. LTD.,**

Index		
Sr. No.	Name of Chapters	Page No.
	Executive Summary	3
A	Ambient Air	3
B	Weather	4
C	Marine Ecology (Flora and Fauna)	4
D	Drinking Water Quality	4
E	Monitoring Performance of Sewage Treatment Plant	5
F	Noise	5
1	Introduction- Deendayal Port Authority	7
2	Ambient Air Quality Monitoring	9
2.1	Ambient Air Quality Monitoring	11
2.2	Results	12
2.3	Observations and Conclusion	31
3	Meteorological Observations	32
3.1	Meteorological Data	33
4	Drinking Water Quality Monitoring	36
4.1	Drinking Water Monitoring Methodology	37
4.2	Results	37
4.3	Results & Discussion	45
4.4	Conclusions	48
5	Noise Monitoring	50
5.1	Method of Monitoring	50
5.2	Results & Discussion	50
5.3	Conclusions	51
6	Soil Monitoring	53
6.1	Methodology	53
6.2	Results	54
6.3	Discussion	55
6.4	Conclusion	55
7	Sewage Treatment Plant Monitoring	57
7.1	Methodology for STP Monitoring	57
7.2	Results	58
7.3	Conclusions	65
8	Marine Water Monitoring	67
8.1	Marine Water Quality and Results	68
8.2	Results and Discussion of Marine water samples	77
8.3	Conclusions	79
9	Marine Sediment Monitoring	81
9.1	Results	82
9.2	Discussion of Marine Sediment samples	84
9.3	Conclusions	84
10	Marine Ecological Monitoring	85
10.1	Introduction	86
10.2	Results	95
11	Conclusive Summary & Remedial Measures	136
12	References	142

A decorative scroll frame with a light gray background and a black border. The frame has a vertical scroll on the left side and a horizontal scroll on the top right side. The text "EXECUTIVE SUMMARY" is centered within the frame.

EXECUTIVE SUMMARY

ENVIRONMENTAL MONITORING PLAN FOR DEENDAYAL PORT ENVIRONMENTAL MONITORING REPORT- NOVEMBER, 2022

1. EXECUTIVE SUMMARY

Monitoring of various environmental aspects of the Deendayal port by M/s Detox Corporation Pvt. Ltd. has been carried out through collection of samples, analysis of the same, comparing results with respect to the national standards and any other relevant standards by GBCB/CPCB/MoEF & CC to understand status of various parameters in the Environment of the Deendayal Port. The results shall address the identified impacts and suggest measures to minimize the environmental impact due to various operations at Deendayal Port.

A) Ambient Air

The monitoring of Ambient Air quality at 6-locations at Deendayal Port Authority Kandla and 2- location at Vadinar Port on 24 hourly basis for TSPM, PM₁₀, PM_{2.5}, SO₂, NO₂, NH₃, CO₂, CO, C₆H₆ and NMHC in twice a week 24 hourly at uniform intervals (as per NAAQS) at Gopalpuri, Tuna Port, Marine Bhavan Building, Coal storage area, Estate building, Oil jetty and at Vadinar port, Vadinar Jetty and Vadinar colony area using respirable dust sampler, Fine particulate sampler and gaseous sampler.

The Maximum TSPM values in month of November 2022 were found 846 µg/m³ at Coal Storage area on 25.11.2022 and minimum 107 µg/m³ at Gopalpuri Hospital on 01.11.2022. The Maximum PM₁₀ values were 654 µg/m³ at Coal Storage area on 25.11.2022 and minimum was 67 µg/m³ at Gopalpuri Hospital 01.11.2022. Maximum PM_{2.5} values were 187 µg/m³ at Coal Storage area on 25.11.2022 and minimum was 34 µg/m³ at Gopalpuri on 01.11. 2022. The PM₁₀ and PM_{2.5} values were found for all monitoring locations (Marine Bhavan Building, Oil Jetty, Estate Office, Gopalpuri, Coal Storage Area and Tuna Port) to exceed the Standard limit (NAAQS).

At Gopalpuri location the mean concentration of PM₁₀ was 127 µg/m³ & PM_{2.5} was 66 µg/m³ which are slightly exceed the Standard limit (NAAQS).

The AAQ monitoring for Vadinar at Admin building the mean TSPM, PM₁₀ and PM_{2.5} were 237 µg/m³, 138 µg/m³ and 97 µg/m³ respectively which was exceed the Standard limit (NAAQS) the while at Signal Building the mean TSPM, PM₁₀ and PM_{2.5} were 113 µg/m³, 74 µg/m³ and 38 µg/m³ respectively slightly exceed the Standard limit (NAAQS).

The overall values of November for Gaseous SO₂, NO₂, NH₃, CO₂, CO, C₆H₆ concentration were within the permissible limit at all location and NMHC were found BQL (Below Quantification Limit).

B) Weather

The mean day time temperature at Deendayal Port was 27.92 °C. The day-time maximum temperature was 32.9°C and minimum was 21.1 °C. The mean night time temperature recorded was 25.47 °C. The night-time maximum temperature was 29.7°C and minimum was 20.0 °C. The mean Solar Radiation in November month was 167.27 w/m². The maximum solar radiation was recorded 759 w/m² in 4th November, 2022 and the minimum solar radiation was recorded 1.80 w/m² in 30th November, 2022. The mean Relative humidity was 69.00 % for the month of November. Maximum Relative humidity was recorded 99.0 % and minimum Relative humidity was recorded 34.0 %. The average wind velocity for the entire month of November was 1.21 m/s. Maximum wind velocity was recorded 10.19 m/s. The wind direction was mostly West-South.

C) Marine Ecology (Flora and Fauna) / Marine Water / Sediments:

The results obtained from the study for the month of November 2022 for biological and ecological parameters in marine water for Arabian Sea at surrounding area of Deendayal Port Authority (DPA) Kandla and Vadinar were not affected by Port activities.

D) Drinking Water Quality

The drinking water being supplied to Deendayal Port Authority was safe for drinking purpose. At all drinking water monitoring stations around port area were in line with the standard limit as per the drinking water specifications given in IS 10500:2012 as per tested parameters only.

The average results for 20 locations were as: pH were found Min 7.24 and maximum 7.52, TDS were found min 300.0 mg/l and Max found 1060.0 mg/l, Chloride were found Min 140.31 mg/l and Max 576.28 mg/l, Total Hardness were found Min 270.0 mg/l and Max 380.0 mg/l and Calcium were found Min 34.47 mg/l and Max 43.29 mg/l, color were colorless and odor were odorless. In all water samples BOD, Heavy metal like manganese, Hexavalent chromium, Copper, Cadmium, Arsenic, Mercury, Lead, zinc all are found BQL (Below Quantification Limit). The bacterial count (E-coli & Coliform) is absent in all drinking water samples.

E) Monitoring Performance of Sewage Treatment Plant

It was seen that the performance of STP at Deendayal Township Gopalpuri, DPA STP Plant Kandla and Vadinar STP plant was satisfactory by overall. The treatment plant was well maintained during [November 2022] with considerable removal efficiency achieving the standards prescribed for final disposal. At Gopalpuri STP, the pollutant removal efficiency for TSS, BOD and COD was ranged from 49.66-81.04%, 58.97-68.42% and 45.45-73.33% respectively. At Kandla STP, removal efficiency for TSS, BOD and COD was ranged from 53.47-73.49%, 46.15-76.74% and 50.00-82.35% respectively & at Vadinar STP removal efficiency for TSS, BOD and COD was ranged from 42.09-56.69%, 50.00-78.12% and 60.00-84.61% respectively. At all STP location treated waste water the pH were ranged from 7.21-7.42, Total Suspended Solids were found 16.9-67.9 mg/l, Residual Chlorine were below Detection Limit (< 0.5), COD were found 20-60 mg/l and 3day BOD @ 27 °C were found 7.0-16.0 mg/l.

F) Noise

Noise sources in port operations include cargo handling, vehicular traffic, and loading / unloading containers and ships. The Day Time Noise Level (SPL) in all 10 locations at Deendayal Port Authority ranged from 53.2 dB(A) to 70.4 dB(A) while at Vadinar port 3 location ranged from 52.5 dB(A) to 60.6 dB(A) which was within the permissible limits of 75 dB(A) for the industrial area for the daytime. The Night Time Average Noise Level (SPL) in all locations of Deendayal Port Authority ranged from 45.4 dB to 61.7 dB(A) while at Vadinar port ranged from 52.5 dB (A) to 60.6 dB(A) which was within the permissible limits of 70 dB(A) for the industrial area for the night time.



CHAPTER-1

INTRODUCTION

DEENDAYAL PORT AUTHORITY

1.0 Introduction

About Deendayal Port

The Deendayal Port is situated in the Kandla Creek and is 90 Kms. From the mouth of Gulf of Kachchh. Latitude: 23° 01" N Longitude: 70° 13"E. Deendayal Port's journey began in 1931 with construction of RCC Jetty by Maharao Khengarji. After partition, Deendayal Port's success story has continued and it rise to the No. 1 Port in India in the year 2007-08 and since then retained the position for the 15 consecutive year. On 31.03.2016, Deendayal Port created history by handling 100 MMT cargoes in a year, the first Major Port to achieve the milestone. Kandla, also known as the Deendayal Port Authority is a seaport in Kutch District of Gujarat state in western India, near the city of Gandhidham. Located on the Gulf of Kutch, it is one of major ports on west coast. Kandla was constructed in the 1950s as the chief seaport serving western India, after the partition of India from Pakistan left the port of Karachi in Pakistan. The Port of Deendayal is located on the Gulf of Kutch on the northwestern coast of India some 256 nautical miles North West of the Port of Karachi in Pakistan and over 430 nautical miles north-northwest of the Port of Mumbai (Bombay). It is the largest port of India by volume of cargo handled. Kandla history Deendayal Port Authority, India's busiest major port in recent years, is gearing to add substantial cargo handling capacity with private sector participation. Deendayal port Authority creates a new record by handling 127.10 million metric tons of cargo during the FY 2021-22, as against 117.566 million metric tons in FY 2020-21. Showing a growth of 8.11 %. Incidentally, DPA is the only major Indian port of handle more than 127 MMT cargo throughout and it has also registered the highest cargo throughput in its history. While the port has flagged off several projects related to infrastructure creation, DPA has successfully awarded the work of augmentation of liquid cargo handling capacity by revamping the existing pipeline network at the oil jetty area in Sept. 2021. Even as much of this growth has come from handling of crude oil imports, mainly for Essar Oil's Vadinar refinery in Gujarat, the port is also taking measures to boost non-POL cargo. Last fiscal, POL traffic accounted for 63 per cent of the total cargo handled at Deendayal Port, as against 59% in 2007-08. The Deendayal Port Authority had commissioned the Off-shore Oil Terminal facilities at Vadinar in the year 1978, for which M/s. Indian Oil Corporation Limited (IOCL) provided Single Bouy Mooring (SBM) system, having a capacity of 54 MMTPA, which was first of its kind in India. Further, significant. Quantum of infrastructural up-gradation has been affected & excellent maritime infrastructure been created at Vadinar for the 32 MMTPA Essar Oil Refinery in Jamnagar District. Monitoring of various environmental aspects of the Deendayal port by M/s Detox Corporation Pvt. Ltd. has been carried out through collection of samples, analysis of the same, comparing results with respect to the prescribed standards by GPCB/CPCB/MoEF& CC. The results shall address the identified impacts and suggest measures to minimize the environmental impact due to various operations at Deendayal Port. The environmental monitoring is carried out as per the Environment Management and Monitoring Plan submitted by Detox Corporation Pvt. Ltd.

CHAPTER-2

AMBIENT AIR QUALITY MONITORING

2. Introduction

Air pollutants are added in the atmosphere from variety of sources that change the composition of atmosphere and affect the biotic environment. The concentration of air pollutants depend not only on the quantities that are emitted from air pollution sources but also on the ability of the atmosphere to either absorb or disperse these emissions. The air pollution concentration vary spatially and temporarily causing the air pollution pattern to change with different locations and time due to changes in meteorological and topographical condition. Air pollution occurs when harmful substances including particulates and biological molecules are introduced into earth's atmosphere. It may cause diseases, allergies or death of humans; it may also cause harm to other living organisms such as animals and food crops, and may damage the natural or built environment. Human activity and natural processes can both generate air pollution. A physical, biological or chemical alteration to the air in the atmosphere can be termed as pollution. It occurs when any harmful gases, dust, smoke enters into the atmosphere and makes it difficult for plants, animals and humans to survive as the air becomes dirty. The consequences of industrialization and the demand for improved quality of life has been increased exposure to air pollution (Vallero, 2014). An air pollutant is a substance in the air that can have adverse effects on humans and the ecosystem. The substance can be solid particles, liquid droplets, or gases. A pollutant can be of natural origin or man-made. Pollutants are classified as primary or secondary. Any gas could qualify as pollution if it reached a high enough concentration to do harm. Theoretically, that means there are dozens of different pollution gases. In practice, about ten different substances cause most concern. Heavy metals represent a class of omnipresent pollutants, with toxic potential, in some cases even at low exposure levels. They concentrate in each tropic level because of their weak mobility, so the concentration in plants is higher than in soil, in herbivore animals higher than in plants, in carnivores' tissues higher than in herbivore, the highest concentration being reached at the end of the tropic chain, at big predacious and human bodies. Globally, one of the main contributors to emissions of atmospheric pollutants and a significant user of energy is the industrial sector (Conti et al. 2015).

The concentration of air pollutants depends not only on the quantities that are emitted from the polluting sources, but also on the ability of the atmosphere to either absorb or disperse such emissions (USEPA, 2008).

Nowadays, the shipping sector provides low-cost and reliable delivery services in the economic field (Arunachalam et al. 2015). Nevertheless, shipping-related activities have a considerable impact on air pollution, especially in coastal areas but also globally (Buccolieri et al. 2016). The primary air pollutants are PM, VOCs, NO_x, O₃, SO₂, and CO (Bailey and Solomon 2004). As a consequence, a wide range of options toward “greener” seaports is needed (Bailey and Solomon 2004). Some of these measures are easy to adopt such as the regulation of fuel quality (by using low-sulfur alternative fuels), the speed reduction (Lack et al. 2011), and the use of alternative transportation equipment (Lai et al. 2011).

Clean air is the basic requirement of all living organisms. In recent times, due to population growth, urban sprawl, industrial development, and vehicular boom, the quality of air is deteriorating and being polluted. Pollutants of major public health concerns include particulate matter, carbon monoxide, ozone, nitrogen dioxide, and sulfur dioxide, which pose serious threats to human health and hygiene. In the present study, prime particulate pollutants (PM₁₀, PM_{2.5}), and gaseous pollutants (SO₂, and NO₂) were estimated at seven stations in and around Dahej Port, Gujarat, India (Soni and Jagruti Patel, 2017).

Among particulate pollutants, particulate matter (PM) is a ubiquitous entity, and is especially a grave problem due to its higher suspension rate into the atmosphere, and adverse health effects on plants, animals, humans, and materials in the form of visibility reduction, soiling of buildings, etc. (Horaginamani and Ravichandran, 2010; Chaurasia *et al.*, 2013).

The sources of air pollutants include vehicles, industries, domestic sources and natural sources. Because of the presence of high amount of air pollutants in the ambient air, the health of the population and property is getting adversely affected. In order to arrest the deterioration in air quality, Govt. of India has enacted Air (Prevention and Control of Pollution) Act in 1981. The responsibility has been further emphasized under Environment (Protection) Act, 1986. It is necessary to assess the present and anticipated air pollution through continuous air quality survey/monitoring programs. Therefore, Central Pollution Control Board had started National Ambient Air Quality Monitoring (NAAQM) Network during 1984 - 85 at national level. The programme was later renamed as National Air Quality Monitoring Programme (NAMP).

2.1 Ambient Air Quality Monitoring

As per the Environmental Monitoring Plan of Deendayal Port Authority, Air monitoring was carried out at six identified locations at Deendayal Port and two locations at Vadinar Port.

Table: 1. Ambient Air Sampling Location

Sr. No.	Name of Location	Location Code	Latitude	Longitude	Remarks
1.	Marine Bhavan	AL-1	23° 0' 26.524"N	70° 13' 22.414"E	DPA-Kandla
2.	Oil Jetty	AL-2	23° 1' 45.613"N	70° 13' 11.052"E	
3.	Estate Office	AL-3	23° 1' 11.273"N	70° 12' 48.657"E	
4.	Gopalpuri Hospital	AL-4	23° 4' 53.551"N	70° 8' 7.047"E	
5.	Coal Storage Area	AL-5	22° 59' 31.812"N	70° 13' 9.979"E	
6.	Tuna Port	AL-6	22° 59' 15.291"N	70° 58' 57.018"E	
7.	Signal Building	AL-7	22° 26' 26.750"N	69° 40' 22.127"E	DPA-Vadinar
8.	Admin Building	AL-8	22° 26' 25.223"N	69° 40' 19.358"E	

● Air Quality Monitoring Methodology

Air quality is measured in all the stations, for 24 hour for Total Suspended Particulate Matter (TSPM), PM₁₀, PM_{2.5}, SO₂, NO₂, NH₃ & Benzene and Grab-sampling for CO & CO₂ measurements. The Air samplers are operated for a period of 24 hours and after a continuous operation of 8 hours for gaseous parameters. The absorbing reagents for SO₂:- Absorbing Reagent TCM (Potassium Tetrachloromercurate 0.04M): Mercuric Chloride, Potassium Chloride and EDTA used. For NO₂:- Absorbing Reagent Sodium Hydroxide (NaOH): Sodium Hydroxide and Sodium Arsenite used. For NH₃ need Conc. Sulphuric Acid and Distilled water was used. By replacing 3 times the reagents per day for each parameter namely, SO₂, NO₂, NH₃. The GFA filter paper and PTFE Membrane bound filter paper are used for a period of 24 hours to obtain one sample each of TSPM, PM₁₀ & PM_{2.5}. The AAQ samples are collected two consecutive days a week as per CPCB guidelines, from all the eight locations as mentioned in the EMP.

2.2 Results

The ambient air quality monitoring data for six stations, viz. Marine Bhavan, Oil Jetty, Port Colony, Gopalpuri Hospital, Tuna Port and Nr. Coal Storage Area for the month of November 2022 are given in Tables 2 to 7. The ambient air quality monitoring data for two stations at Vadinar (Nr. Admin Building & Nr. Signal Building) are given in Tables 8 to 9.

The Movement of heavy transport with uncovered coal transportation, raw road around ambient location may be causes fugitive dust emission from dry conditions. Particulate Matter then enters the atmosphere through the action of wind, vehicular movement, or other activities. The dust produces tends to float in air and spread all around the vicinity. Direction and speed of wind affect the dispersion of the dust particulate matter. Humidity of air also has strong effect on the spreading of particulate matter. With increasing humidity, moisture particles eventually grow in size to a point where 'dry deposition' occurs, reducing PM₁₀ concentrations in the atmosphere.

Location 1: Marine Bhavan (AL1)

Table 2 : Results of Air Pollutant Concentration at Marine Bhavan

	Date	TSPM [µg/m3]	PM10 [µg/m3]	PM2.5 [µg/m3]	SO2 [µg/m3]		NOx [µg/m3]		NH3 [µg/m3]	
Sampling Period		24hr	24hr	24hr	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)
NAAQMS Limit			100 µg/m3	60 µg/m3		80 µg/m3		80 µg/m3		400 µg/m3
AL1 – 1	01.11.2022	435	302	121	3.93	3.93	5.19	14.43	2.07	4.11
					6.04		23.66		6.33	
					1.81		14.43		3.91	
AL1 – 2	04.11.2022	344	228	106	3.32	2.52	17.31	12.70	2.42	3.72
					2.72		8.66		5.18	
					1.51		12.12		3.57	
AL1 – 3	08.11.2022	398	281	116	2.31	3.84	25.39	17.31	4.72	3.57
					6.34		17.89		2.42	
					2.88		8.66		3.57	
AL1 – 4	11.11.2022	445	315	124	3.63	6.35	17.89	13.08	4.03	3.61
					9.07		12.70		4.72	
					6.35		8.66		2.07	
AL1 – 5	15.11.2022	364	253	110	4.53	4.53	11.54	13.85	4.60	3.07
					6.35		19.62		2.88	
					2.72		10.39		1.73	
AL1 - 6	18.11.2022	442	315	121	8.46	4.84	23.08	16.54	3.22	4.37
					3.32		8.66		5.87	
					2.72		17.89		4.03	
AL1 - 7	22.11.2022	375	266	106	3.32	4.43	17.89	18.47	4.83	4.45
					7.55		25.97		5.87	
					2.42		11.54		2.65	
AL1 – 8	25.11.2022	483	350	129	4.53	4.63	23.66	21.55	3.22	3.68
					6.95		28.86		5.29	
					2.42		12.12		2.53	
AL1 – 9	29.11.2022	534	383	142	6.35	5.84	17.89	19.04	3.57	3.57
					8.46		25.97		4.95	
					2.72		13.27		2.19	
Monthly Average		424	299	119		4.55		16.33		3.79
Standard Deviation		61	48	12		1.12		3.03		0.44

Table 2 : Results of Air Pollutant Concentration at Marine Bhavan

	Date	C6H6 [µg/m ³]	HC	CO [mg/m ³]	CO ₂ [ppm]
Sampling Period		8 hr		Grab Sampling	Grab Sampling
NAAQMS limit		5.0 µg/m ³	ppm	4.0 mg/m ³	-
AL1 – 1	01.11.2022	1.09	BQL	1.44	444
AL1 – 2	04.11.2022	1.2	BQL	1.54	374
AL1 – 3	08.11.2022	1.17	BQL	1.08	538
AL1 – 4	11.11.2022	1.1	BQL	1.14	470
AL1 – 5	15.11.2022	1.11	BQL	1.26	481
AL1 - 6	18.11.2022	1.1	BQL	1.64	500
AL1 - 7	22.11.2022	1.12	BQL	1.35	620
AL1 - 8	25.11.2022	1.16	BQL	1.69	511
AL1 - 9	29.11.2022	1.21	BQL	1.16	522
Monthly Average		1.14	-	1.37	495.56
Standard Deviation		0.05	-	0.22	67.59

* NMHC- Non- Methane Hydrocarbons

BQL- Below Quantification Limit (Quantification Limit – NMHC: 0.5 ppm)

At Marine Bhavan, the overall values of TSPM, PM₁₀, PM_{2.5}, SO₂, NO₂ and NH₃ is attributed mainly by motor vehicle emission produced from various types of automobiles (both diesel and petrol driven). Moreover, the loading and unloading of Food Grains and Timber at Jetty no. 1 and 2 also contributes to the high levels of TSPM and PM₁₀. The mean TSPM value at Marine Bhavan was 424 µg/m³, the mean PM₁₀ value was 299 µg/m³, and PM_{2.5} value was 119 µg/m³ which is above the permissible limit prescribed by NAAQS. The average values of SO₂, NO₂ and NH₃ were 4.55 µg/m³, 16.33 µg/m³ & 3.79 µg/m³ respectively; these values were within the standard limit prescribed by NAAQS.

The levels of Benzene, Hydrocarbons (HC) and CO were within the permissible limit at Marine Bhavan. The mean Benzene concentration was 1.14 µg/m³, well below the permissible limit of 5.0 µg/m³. NMHC's were below the detectable limit and Carbon Monoxide concentration was 1.37 mg/m³, well below the permissible limit of 4.0 mg/m³ prescribed by NAAQS.

Location 3: Oil Jetty (AL2)

Table 2 : Results of Air Pollutant Concentration at Oil Jetty

Table 2 : Results of Air Pollutant Concentration at Oil Jetty										
	Date	TSPM [µg/m3]	PM10 [µg/m3]	PM2.5 [µg/m3]	SO2 [µg/m3]		NOx [µg/m3]		NH3 [µg/m3]	
Sampling Period		24hr	24hr	24hr	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)
NAAQMS Limit			100 µg/m3	60 µg/m3		80 µg/m3		80 µg/m3		400 µg/m3
AL2 -1	01.11.2022	150	99	50	2.42	3.22	6.35	13.66	2.88	4.53
					4.53		13.27		6.79	
					2.72		21.35		3.91	
AL2 -2	04.11.2022	253	180	70	2.72	3.53	5.77	11.73	0.81	3.18
					3.32		17.89		4.03	
					4.53		11.54		4.72	
AL2 -3	08.11.2022	235	166	67	2.59	2.50	5.19	14.04	2.19	2.80
					3.46		13.27		2.65	
					1.44		23.66		3.57	
AL2 -4	11.11.2022	275	194	76	6.35	4.53	10.39	14.24	2.42	2.42
					4.53		20.20		3.80	
					2.72		12.12		1.04	
AL2 – 5	15.11.2022	245	169	71	3.02	4.53	8.66	14.04	3.57	2.38
					6.65		16.16		2.30	
					3.93		17.31		1.27	
AL2 – 6	18.11.2022	185	119	53	5.74	4.94	14.43	13.47	4.95	3.84
					2.72		17.31		3.57	
					6.35		8.66		2.99	
AL2 – 7	22.11.2022	373	252	109	3.02	4.03	20.20	14.24	3.80	3.80
					6.35		12.12		5.53	
					2.72		10.39		2.07	
AL2 -8	25.11.2022	292	199	86	1.81	3.83	14.43	14.43	3.57	4.76
					6.35		19.62		4.72	
					3.32		9.23		5.99	
AL1 – 9	29.11.2022	299	194	97	3.63	4.63	5.19	13.47	2.88	3.49
					7.55		23.66		4.95	
					2.72		11.54		2.65	
Monthly Average		256	175	75		3.97		13.70		3.47
Standard Deviation		65	45	19		0.79		0.81		0.85

Table 3 : Results of Air Pollutant Concentration at Oil Jetty					
	Date	C₆H₆ [µg/m³]	*NMHC	CO [mg/m³]	CO₂ [ppm]
Sampling Period		8 hr		Grab Sampling	Grab Sampling
NAAQMS limit		5.0 µg/m³		4.0 mg/m³	-
AL2-1	01.11.2022	1.17	BQL	1.22	467
AL2-2	04.11.2022	1.01	BQL	1.53	451
AL2-3	08.11.2022	1.1	BQL	1.65	502
AL2-4	11.11.2022	1.19	BQL	1.04	447
AL2 -5	15.11.2022	1.24	BQL	1.27	634
AL2 -6	18.11.2022	1.16	BQL	1.22	531
AL2-7	22.11.2022	1.2	BQL	1.28	800
AL2-8	25.11.2022	1.06	BQL	1.89	1023
AL2-9	29.11.2022	1.22	BQL	1.46	576
Monthly Average		1.15	-	1.40	603.44
Standard Deviation		0.08	-	0.26	193.07

* NMHC- Non- Methane Hydrocarbons

BQL- Below Quantification Limit (Quantification Limit – NMHC: 0.5 ppm)

Oil Jetty Area, the overall values of TSPM, PM₁₀, PM_{2.5}, SO₂, NO₂ and NH₃ was mainly by motor vehicle emission produced from various types of vehicles at Oil Jetty Area. The mean TSPM value at Oil Jetty was 256 µg/m³. The mean PM₁₀ value was 175 µg/m³ and mean PM_{2.5} value was 75 µg/m³ which was above the permissible limit. The average values of SO₂, NO₂ and NH₃ were within the permissible limit prescribed by NAAQS. The mean concentration of SO₂, NO₂ and NH₃ were 3.97 µg/m³, 13.70 µg/m³ and 3.47 µg/m³ respectively.

The levels of Benzene, Hydrocarbons (HC) and CO were within the permissible limit at Oil Jetty. The mean Benzene concentration was 1.15 µg/m³ which was well below the permissible limit of 5.0 µg/m³. NMHC's were below the detectable limit and Carbon Monoxide concentration was 1.40 mg/m³, well below the permissible limit of 4.0 mg/m³.

Location 3: Kandla Colony – Estate Office (AL-3)

Table 4 : Results of Air Pollutant Concentration at Estate Office

Table 4 : Results of Air Pollutant Concentration at Estate Office										
	Date	TSPM [µg/m3]	PM10 [µg/m3]	PM2.5 [µg/m3]	SO2 [µg/m3]		NOx [µg/m3]		NH3 [µg/m3]	
Sampling Period		24hr	24hr	24hr	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)
NAAQMS Limit			100 µg/m3	60 µg/m3		80 µg/m3		80 µg/m3		400 µg/m3
AL3 – 1	01.11.2022	245	172	69	1.51	2.32	10.39	9.62	3.68	5.10
					3.32		13.27		7.02	
					2.12		5.19		4.60	
AL3 – 2	04.11.2022	577	445	130	4.53	2.32	5.19	10.39	3.57	2.49
					1.51		17.31		2.88	
					0.91		8.66		1.04	
AL3 – 3	08.11.2022	440	321	109	6.05	3.94	19.04	12.31	4.72	3.64
					2.59		12.12		2.42	
					3.17		5.77		3.80	
AL3 – 4	11.11.2022	518	403	111	3.32	4.23	18.47	10.58	1.38	2.42
					2.72		8.66		3.57	
					6.65		4.62		2.30	
AL3 – 5	15.11.2022	451	340	107	1.81	3.73	23.08	15.97	3.22	2.42
					6.04		14.43		2.30	
					3.32		10.39		1.73	
AL3 – 6	18.11.2022	459	346	112	4.53	4.43	16.16	15.97	5.76	4.14
					2.72		8.66		4.72	
					6.04		23.08		1.96	
AL3 – 7	22.11.2022	453	325	116	2.42	4.33	19.62	17.31	3.91	3.84
					4.23		23.66		5.18	
					6.35		8.66		2.42	
AL3 – 8	25.11.2022	337	252	83	6.04	3.93	15.00	15.58	3.80	3.91
					3.32		23.08		5.76	
					2.42		8.66		2.19	
AL1 – 9	29.11.2022	491	359	129	4.84	4.63	17.89	16.16	3.57	3.57
					6.95		24.24		5.18	
					2.12		6.35		1.96	
Monthly Average		441	329	107		3.76		13.77		3.50
Standard Deviation		98	80	20		0.87		3.00		0.91

Table 4 : Results of Air Pollutant Concentration at Estate Office

Sampling Period	Date	C ₆ H ₆ [µg/m ³]	*NMHC	CO [mg/m ³]	CO ₂ [ppm]
		8 hr		Grab Sampling	Grab Sampling
		5.0 µg/m ³		4.0 mg/m ³	-
NAAQMS limit					
AL3 -1	01.11.2022	1.06	BQL	1.27	508
AL3 -2	04.11.2022	1.1	BQL	1.19	508
AL3 -3	08.11.2022	1.1	BQL	1.65	502
AL3 -4	11.11.2022	1.09	BQL	1.83	429
AL3 - 5	15.11.2022	1.09	BQL	1.76	813
AL3 - 6	18.11.2022	1.2	BQL	1.14	559
AL3 - 7	22.11.2022	1.19	BQL	2.18	1022
AL3 - 8	25.11.2022	1.11	BQL	2	1026
	29.11.2022	1.06	BQL	1.22	537
Monthly Average		1.11	-	1.58	656.00
Standard Deviation		0.05	-	0.39	234.02

* NMHC- Non- Methane Hydrocarbons

BQL- Below Quantification Limit (Quantification Limit – NMHC: 0.5 ppm)

The overall values of TSPM, PM₁₀, PM_{2.5}, SO₂, NO₂ and NH₃ at Kandla Port Colony (Estate Office) was attributed by vehicle emission produced from trucks and heavy duty vehicles that pass through the road outside Kandla Port Colony. The mean TSPM values at Estate Office were 441 µg/m³, the mean PM₁₀ value was 329 µg/m³, and PM_{2.5} value was 107 µg/m³ which was above the permissible limit prescribed by NAAQS. The average values of SO₂, NO₂ and NH₃ were 3.76 µg/m³, 13.77 µg/m³ and 3.50 µg/m³ respectively and were all within the permissible limit.

The levels of Benzene, Hydrocarbons (HC) and CO were within the permissible limit at Kandla Port Colony. The mean Benzene concentration was 1.11 µg/m³, well below the permissible limit of 5.0 µg/m³. NMHC's were below the detectable limit and Carbon Monoxide was 1.58 mg/m³, well below the permissible limit of 4.0 mg/m³.

Location 4: Gopalpuri Hospital (AL-4)

Table 5 : Results of Air Pollutant Concentration at Gopalpuri Hospital

Table 5 : Results of Air Pollutant Concentration at Gopalpuri Hospital										
	Date	TSPM [µg/m3]	PM10 [µg/m3]	PM2.5 [µg/m3]	SO2 [µg/m3]		NOx [µg/m3]		NH3 [µg/m3]	
Sampling Period		24hr	24hr	24hr	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)
NAAQMS Limit			100 µg/m3	60 µg/m3		80 µg/m3		80 µg/m3		400 µg/m3
AL4 -1	01.11.2022	107	67	34	1.21	2.22	5.77	6.93	2.42	2.53
					3.02		10.39		4.14	
					2.42		4.62		1.04	
AL4 -2	04.11.2022	177	117	54	0.91	2.22	5.19	10.00	1.61	2.49
					4.53		8.66		2.42	
					1.21		16.16		3.45	
AL4 -3	08.11.2022	148	101	44	1.15	2.21	6.93	9.81	1.73	1.69
					2.88		17.31		2.42	
					2.59		5.19		0.92	
AL4 -4	11.11.2022	184	111	68	1.51	2.62	6.93	12.89	1.04	2.30
					3.63		14.43		2.42	
					2.72		17.31		3.45	
AL4 – 5	15.11.2022	202	125	72	2.12	2.42	12.12	12.70	2.42	2.49
					3.63		8.66		3.45	
					1.51		17.31		1.61	
AL4 – 6	18.11.2022	233	153	78	1.21	2.92	8.66	12.89	2.42	2.49
					4.84		17.89		1.61	
					2.72		12.12		3.45	
AL4 – 7	22.11.2022	268	168	94	0.60	2.22	5.77	12.70	1.73	2.88
					3.32		14.43		3.68	
					2.72		17.89		3.22	
AL4 – 8	25.11.2022	202	142	56	2.12	3.42	14.43	12.50	2.07	2.99
					5.14		17.89		4.03	
					3.02		5.19		2.88	
AL1 – 9	29.11.2022	249	157	91	3.02	4.03	8.66	11.54	1.38	2.49
					6.35		20.20		3.80	
					2.72		5.77		2.30	
Monthly Average		197	127	66		2.70		11.33		2.49
Standard Deviation		50	32	20		0.65		2.05		0.37

Table 5 : Results of Air Pollutant Concentration at Gopalpuri Hospital					
Sampling Period	Date	C₆H₆ [µg/m³]	*NMHC	CO [mg/m³]	CO₂ [ppm]
		8 hr		Grab Sampling	Grab Sampling
NAAQMS limit		5.0 µg/m³		4.0 mg/m³	-
AL4 -1	01.11.2022	1.14	BQL	1.26	503
AL4 -2	04.11.2022	1.15	BQL	1.26	450
AL4 -3	08.11.2022	1.03	BQL	1.73	506
AL4 -4	11.11.2022	1.02	BQL	1.82	462
AL4 – 5	15.11.2022	1.09	BQL	1.04	1048
AL4 – 6	18.11.2022	1.14	BQL	1.32	543
AL4 – 7	22.11.2022	1.16	BQL	1.83	758
AL4 – 8	25.11.2022	1.22	BQL	1.8	816
AL4 – 9	29.11.2022	1.16	BQL	1.36	665
Monthly Average		1.12	-	1.49	639.00
Standard Deviation		0.07	-	0.30	201.83

* NMHC- Non- Methane Hydrocarbons

BQL- Below Quantification Limit (Quantification Limit – NMHC: 0.5 ppm)

The overall values of TSPM, PM₁₀, PM_{2.5}, SO₂, NO₂ and NH₃ at Gopalpuri Hospital was attributed by vehicle emission produced from light motor vehicles of the colony residents. The mean TSPM values at Gopalpuri Hospital were 197 µg/m³, the mean PM₁₀ value was 127 µg/m³ and PM_{2.5} was 66 µg/m³ which was exceed the standard limit. The average values of SO₂, NO₂ and NH₃ were 2.70 µg/m³, 11.33 µg/m³ and 2.49 µg/m³ respectively and were all within the permissible limit.

The levels of Benzene, Hydrocarbons (HC) and CO were within the permissible limit at Gopalpuri Hospital. The mean Benzene concentration was 1.12 µg/m³, well below the permissible limit of 5.0 µg/m³. NMHC's were below the detectable limit and Carbon monoxide concentration was 1.49 mg/m³ which is well below the permissible limit of 4.0 mg/m³.

Location 5: Coal Storage Area (AL-5)

Table 6 : Results of Air Pollutant Concentration at Coal Storage Area

	Date	TSPM [µg/m3]	PM10 [µg/m3]	PM2.5 [µg/m3]	SO2 [µg/m3]		NOx [µg/m3]		NH3 [µg/m3]	
Sampling Period		24hr	24hr	24hr	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)
NAAQMS Limit			100 µg/m3	60 µg/m3		80 µg/m3		80 µg/m3		400 µg/m3
AL6 – 1	01.11.2022	779	598	175	2.72	4.33	6.35	16.54	3.68	5.06
					6.65		25.97		8.17	
					3.63		17.31		3.34	
AL6 – 2	04.11.2022	635	492	137	2.12	3.53	23.08	17.70	6.79	6.60
					5.44		12.12		8.17	
					3.02		17.89		4.83	
AL6 – 3	08.11.2022	538	412	125	8.94	5.00	23.66	21.74	2.53	3.88
					3.46		12.12		2.07	
					2.59		29.43		7.02	
AL6 – 4	11.11.2022	815	635	178	4.53	4.73	18.47	17.70	5.87	4.41
					2.72		8.66		2.65	
					6.95		25.97		4.72	
AL6 – 5	15.11.2022	792	614	176	6.35	6.65	18.47	13.66	4.72	3.88
					9.07		10.39		3.68	
					4.53		12.12		3.22	
AL6 – 6	18.11.2022	771	595	171	9.37	7.15	20.20	17.12	4.83	4.37
					5.74		8.08		2.53	
					6.35		23.08		5.76	
AL6 – 7	22.11.2022	706	543	156	4.84	4.53	10.39	18.47	4.83	5.03
					6.04		23.66		5.99	
					2.72		21.35		4.26	
AL6 – 8	25.11.2022	846	654	187	3.32	5.24	17.31	19.81	3.91	4.95
					7.86		25.97		6.91	
					4.53		16.16		4.03	
AL1 – 9	29.11.2022	801	621	172	5.14	5.64	16.16	18.28	3.57	4.30
					9.07		28.86		6.22	
					2.72		9.81		3.11	
Monthly Average		743	574	164		5.20		17.89		4.72
Standard Deviation		99	78	21		1.14		2.22		0.84

Table 6 : Results of Air Pollutant Concentration at Coal Storage Area

Sampling Period	Date	C ₆ H ₆ [µg/m ³]	*NMHC	CO [mg/m ³]	CO ₂ [ppm]
		8 hr		Grab Sampling	Grab Sampling
NAAQMS limit		5.0 µg/m ³		4.0 mg/m ³	-
AL5 – 1	01.11.2022	1.1	BQL	1.12	483
AL5 – 2	04.11.2022	1.06	BQL	1.48	475
AL5 – 3	08.11.2022	1.08	BQL	1.66	421
AL5 – 4	11.11.2022	1.06	BQL	1.69	492
AL5 – 5	15.11.2022	1.06	BQL	1.06	702
AL5 – 6	18.11.2022	1.22	BQL	1.18	483
AL5 – 7	22.11.2022	1.11	BQL	1.86	564
AL5 – 8	25.11.2022	1.2	BQL	1.54	777
AL5 – 9	29.11.2022	1.22	BQL	1.89	895
Monthly Average		1.12	-	1.50	588.00
Standard Deviation		0.07	-	0.31	164.11

* NMHC- Non- Methane Hydrocarbons

BQL- Below Quantification Limit (Quantification Limit – NMHC: 0.5 ppm)

The overall values of TSPM, PM₁₀, PM_{2.5}, SO₂, NO₂ and NH₃ at Coal Storage Area was comparatively highest among all the locations of Air Quality monitoring in Kandla Port. High values of TSPM, PM₁₀, PM_{2.5}, SO₂, NO₂ at this location was due to lifting of coal with grab and other coal handling processes near Berth no. 6 & 7. Moreover, the traffic was also heavy around this place for transport of coal thus emissions produced from heavy vehicles. The mean TSPM values at Coal storage were 743 µg/m³, the mean PM₁₀ value was 574 µg/m³, and the PM_{2.5} value was 164 µg/m³ which was above the permissible limit prescribed by NAAQS. The average values of SO₂, NO₂ and NH₃ were 5.20 µg/m³, 17.89 µg/m³ and 4.72 µg/m³ respectively and were all within the permissible limit.

The levels of Benzene, Hydrocarbons (HC) and CO were within the permissible limit at Coal Storage Area. The mean Benzene concentration was 1.12 µg/m³, well below the permissible limit of 5.0 µg/m³. NMHC's were below the detectable limit and Carbon Monoxide concentration was 1.50 mg/m³, well below the permissible limit of 4.0 mg/m³.

Location 6: Tuna Port (AL-6)

Table 7 : Results of Air Pollutant Concentration at Tuna Port

Table 7 : Results of Air Pollutant Concentration at Tuna Port										
	Date	TSPM [µg/m3]	PM10 [µg/m3]	PM2.5 [µg/m3]	SO2 [µg/m3]		NOx [µg/m3]		NH3 [µg/m3]	
Sampling Period		24hr	24hr	24hr	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)
NAAQMS Limit			100 µg/m3	60 µg/m3		80 µg/m3		80 µg/m3		400 µg/m3
AL5 -1	01.11.2022	141	88	47	0.91	1.61	2.89	6.16	2.07	2.84
					2.72		12.12		4.03	
					1.21		3.46		2.42	
AL5 – 2	04.11.2022	232	166	64	1.51	2.22	6.35	7.89	1.38	2.76
					3.02		5.19		4.49	
					2.12		12.12		2.42	
AL5 – 3	08.11.2022	184	120	55	1.44	2.40	10.39	13.08	1.73	2.61
					3.46		11.54		2.65	
					2.31		17.31		3.45	
AL5 – 4	11.11.2022	233	153	78	2.12	2.32	11.54	11.54	1.27	1.57
					3.93		17.89		1.04	
					0.91		5.19		2.42	
AL5 – 5	15.11.2022	221	145	74	1.21	2.32	6.35	12.12	3.57	2.49
					3.32		12.12		2.30	
					2.42		17.89		1.61	
AL5 – 6	18.11.2022	248	162	83	1.81	2.01	17.31	17.12	2.30	10.21
					1.21		23.66		15.57	
					3.02		10.39		12.76	
AL5 – 7	22.11.2022	214	139	74	1.51	2.52	8.66	8.46	3.57	2.84
					2.72		12.70		2.88	
					3.32		4.04		2.07	
AL5 – 8	25.11.2022	255	175	77	2.72	3.02	8.66	8.08	3.45	3.30
					4.84		11.54		4.72	
					1.51		4.04		1.73	
AL1 – 9	29.11.2022	245	155	87	1.51	3.63	12.70	11.73	1.04	2.88
					6.04		17.31		5.18	
					3.32		5.19		2.42	
Monthly Average		219	145	71		2.45		10.69		3.50
Standard Deviation		36	27	13		0.58		3.37		2.56

Table 7 : Results of Air Pollutant Concentration at Tuna Port

		C₆H₆ [µg/m³]		CO [mg/m³]	CO₂ [ppm]
Sampling Period	Date	8 hr	*NMHC	Grab Sampling	Grab Sampling
NAAQMS limit		5.0 µg/m³		4.0 mg/m³	-
AL6 -1	01.11.2022	1.12	BQL	1.43	543
AL6 – 2	04.11.2022	1.17	BQL	1.41	463
AL6 – 3	08.11.2022	1.13	BQL	1.39	410
AL6 – 4	11.11.2022	1.13	BQL	1.74	509
AL6 – 5	15.11.2022	1.17	BQL	1.08	911
AL6 – 6	18.11.2022	1.17	BQL	1.1	528
AL6 – 7	22.11.2022	1.06	BQL	1.88	565
AL6 – 8	25.11.2022	1.1	BQL	1.89	999
	29.11.2022	1.22	BQL	1.89	895
Monthly Average		1.14	-	1.53	647.00
Standard Deviation		0.05	-	0.33	222.45

* NMHC- Non- Methane Hydrocarbons

BQL- Below Quantification Limit (Quantification Limit – NMHC: 0.5 ppm)

The mean TSPM values at Tuna Port was 219 µg/m³, the mean PM₁₀ value was 145 µg/m³ and the mean PM_{2.5} value was 71 µg/m³ which was exceed the standard limit prescribed by NAAQS. The average values of SO₂, NO₂ and NH₃ were 2.45 µg/m³, 10.69 µg/m³ and 3.50 µg/m³ respectively and were all within the standard limit prescribed by NAAQS.

The levels of Benzene, Hydrocarbons (HC) and CO were within the permissible limit at Tuna Port. The mean Benzene concentration was 1.14 µg/m³, well below the permissible limit of 5.0 µg/m³. NMHC's were below the detectable limit and Carbon Monoxide concentration was 1.53 mg/m³, well below the permissible limit of 4.0 mg/m³.

Location 7: Admin Building (Vadinar) (AL-7)

Table 8 : Results of Air Pollutant Concentration at Admin Building										
	Date	TSPM [µg/m3]	PM10 [µg/m3]	PM2.5 [µg/m3]	SO2 [µg/m3]		NOx [µg/m3]		NH3 [µg/m3]	
Sampling Period		24hr	24hr	24hr	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)
NAAQMS Limit			100 µg/m3	60 µg/m3		80 µg/m3		80 µg/m3		400 µg/m3
AL7 -1	01.11.2022	150	98	51	2.20	3.52	9.53	10.59	5.36	5.28
					4.84		16.51		2.81	
					3.52		5.72		7.66	
AL7 -2	04.11.2022	177	115	61	3.08	4.69	17.78	21.81	2.81	6.13
					7.03		21.60		8.93	
					3.96		26.04		6.64	
AL7 -3	08.11.2022	193	113	73	6.15	6.30	6.99	11.43	3.83	7.49
					8.79		20.96		10.47	
					3.96		6.35		8.17	
AL7 -4	11.11.2022	200	121	78	3.96	6.01	17.78	15.24	10.47	6.81
					5.28		22.23		5.87	
					8.79		5.72		4.08	
AL7 -5	15.11.2022	179	108	69	1.76	5.28	7.62	18.00	3.06	5.62
					5.71		26.04		5.87	
					8.35		20.33		7.91	
AL7 -6	18.11.2022	223	121	96	2.64	4.54	8.89	15.03	5.62	5.70
					4.40		16.51		8.17	
					6.59		19.69		3.32	
AL1 -7	22.11.2022	162	104	57	4.84	5.28	14.61	14.61	13.02	9.10
					7.03		5.72		8.68	
					3.96		23.50		5.62	
AL1-8	25.11.2022	237	138	97	6.59	4.40	9.53	15.24	7.91	8.00
					3.96		14.61		5.62	
					2.64		21.60		10.47	
AL1-9	28.11.2022	203	112	87	3.96	3.66	6.99	13.76	5.62	6.04
					2.20		14.61		7.91	
					4.84		19.69		4.60	
Monthly Average		191	114	74		4.85		15.08		6.68
Standard Deviation		28	12	17		0.96		3.34		1.28

Table 8 : Results of Air Pollutant Concentration at Admin Building Vadinar

Sampling Period	Date	C ₆ H ₆ [µg/m ³]	*NMHC	CO [mg/m ³]	CO ₂ [ppm]
		8 hr		Grab Sampling	Grab Sampling
		5.0 µg/m ³		4.0 mg/m ³	-
AL7 -1	01.11.2022	1.08	BQL	1.43	225
AL7 -2	04.11.2022	1.13	BQL	1.54	236
AL7 -3	08.11.2022	1.17	1.81	1.53	455
AL7 -4	11.10.2022	1.14	BQL	1.61	443
AL7 -5	15.10.2022	1.03	BQL	1.1	347
AL7 -6	18.10.2022	1.06	BQL	1.57	416
AL7 -7	22.10.2022	1.10	BQL	1.05	372
AL7 -8	25.10.2022	1.20	BQL	1.79	464
AL7 -9	28.10.2022	1.13	BQL	1.42	487
Monthly Average		1.12	-	1.46	388
Standard Deviation		0.06	-	0.25	75

*NMHC- Non- Methane Hydrocarbons

BQL- Below Quantification Limit (Quantification Limit – NMHC: 0.5 ppm)

At Admin Building, Vadinar the mean TSPM value was 191 µg/m³, the mean PM₁₀ value was 114 µg/m³ and the mean PM_{2.5} value was 74 µg/m³ which was slightly exceed the standard limit. The average values of SO₂, NO₂ and NH₃ concentrations were 4.85 µg/m³, 15.08 µg/m³ and 6.68 µg/m³ respectively and were all within the permissible limit.

The levels of Benzene, Hydrocarbons (HC) and CO were within the permissible limit at Vadinar Port. The mean Benzene concentration was 1.12 µg/m³, well below the permissible limit of 5.0 µg/m³. NMHC's were below the detectable limit and Carbon Monoxide concentration was 1.46 mg/m³, well below the permissible limit of 4.0 mg/m³.

Location 8: Signal Building (Vadinar) (AL-8)

Table 9 : Results of Air Pollutant Concentration at Signal Building, Vadinar

Table 9 : Results of Air Pollutant Concentration at Signal Building, Vadinar										
	Date	TSPM [µg/m3]	PM10 [µg/m3]	PM2.5 [µg/m3]	SO2 [µg/m3]		NOx [µg/m3]		NH3 [µg/m3]	
Sampling Period		24hr	24hr	24hr	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)	8 hr	24hr (Avg.)
NAAQMS Limit			100 µg/m3	60 µg/m3		80 µg/m3		80 µg/m3		400 µg/m3
AL8 -1	01.11.2022	113	74	38	3.96	4.40	6.99	13.34	2.30	7.15
					6.59		19.05		8.68	
					2.64		13.97		10.47	
AL8 -2	04.11.2022	146	93	49	2.64	4.40	14.61	15.88	5.36	6.13
					4.84		22.23		8.42	
					5.71		10.80		4.60	
AL8 -3	08.11.2022	124	82	42	3.08	3.52	14.61	16.73	5.62	5.62
					5.28		26.04		7.91	
					2.20		9.53		3.32	
AL8 -4	11.11.2022	175	105	67	2.20	4.40	8.26	13.76	8.93	9.02
					7.03		19.05		12.76	
					3.96		13.97		5.36	
AL8 -5	15.11.2022	152	97	52	3.52	4.98	5.72	13.13	6.89	7.57
					4.84		13.34		10.98	
					6.59		20.33		4.85	
AL8 -6	18.11.2022	176	111	61	3.08	3.81	15.24	17.57	7.15	8.42
					3.96		26.04		7.91	
					4.40		11.43		10.21	
AL8 -7	22.11.2022	214	118	93	3.52	5.71	5.72	12.91	7.91	8.25
					5.28		13.34		6.38	
					8.35		19.69		10.47	
AL8-8	25.11.2022	219	125	92	3.08	4.54	9.53	11.01	5.36	6.04
					4.84		17.78		8.17	
					5.71		5.72		4.60	
AL8-9	28.11.2022	154	97	57	5.71	3.81	10.80	16.94	7.15	8.76
					3.96		22.23		8.93	
					1.76		17.78		10.21	
Monthly Average		164	100	61		4.40		14.59		7.44
Standard Deviation		36	16	20		0.67		2.25		1.27

Table 9 : Results of Air Pollutant Concentration at Signal Building Vadinar

		C₆H₆ [µg/m³]		CO [mg/m³]	CO₂ [ppm]
Sampling Period	Date	8 hr	*NMHC	Grab Sampling	Grab Sampling
NAAQMS limit		5.0 µg/m³		4.0 mg/m³	-
AL8 -1	01.11.2022	1.06	BQL	1.5	467
AL8 -2	04.11.2022	1.05	BQL	1.46	501
AL8 -3	08.11.2022	1.14	1.81	1.31	489
AL8 -4	11.11.2022	1.16	BQL	1.38	439
AL8 -5	15.11.2022	1.17	BQL	1.29	231
AL8 -6	18.11.2022	1.10	BQL	1.31	244
AL8 -7	22.11.2022	1.00	BQL	1.34	227
AL8 -8	25.11.2022	1.05	BQL	1.37	261
AL8 -9	28.11.2022	1.02	BQL	1.29	234
Monthly Average		1.16	-	1.46	442
Standard Deviation		0.05	-	0.27	63

* NMHC- Non- Methane Hydrocarbon

BQL- Below Quantification Limit (Quantification Limit – NMHC: 0.5 ppm)

At Signal Building, Vadinar the mean TSPM value was 164 µg/m³, the mean PM₁₀ value was 100 µg/m³ which was boundary line of the permissible limit, the mean PM_{2.5} value was 61 µg/m³ which was within the permissible limit. The average values of SO₂, NO₂ and NH₃ concentrations were 4.40 µg/m³, 14.59 µg/m³ and 7.44 µg/m³ respectively and were all within the standard limit.

The levels of Benzene, Hydrocarbons (HC) and CO were within the permissible limit at Vadinar Port. The mean Benzene concentration was 1.16 µg/m³, well below the standard limit of 5.0 µg/m³. NMHC's were below the detectable limit and Carbon Monoxide concentration was 1.46 mg/m³, well below the standard limit of 4.0 mg/m³.

Fig. No:-1 Average ambient air quality (PM) month of November-2022 at DPA and Vadinar Sampling Station




Fig. No:-2. Average ambient air quality (Gaseous) month of November-2022 at DPA and Vadinar sampling location




Fig. No:-3. Average ambient air quality (Gaseous) month of November-2022 at DPA and Vadinar sampling location





Fig. No:-4. Average ambient air quality (Gaseous) month of November-2022 at DPA and Vadinar sampling location



2.3 Observations and Conclusion

During the monitoring period, the overall Ambient Air Quality of the port area was found within permissible levels for various gaseous pollutants. However, Total Suspended Particulate matter as TSPM, Particulate matter as PM₁₀ and PM_{2.5} was found to exceed the limits at locations at all ambient air sampling location.

The concentration of PM₁₀ and PM_{2.5} were slightly exceeded at Gopalpuri and Tuna Port.

The mean concentration of PM₁₀ and PM_{2.5} were slightly exceeded at Admin building Vadinar & at Signal building Vadinar was very close to the standard limit.

CHAPTER-3

METEOROLOGICAL OBSERVATIONS

4.1 Meteorological Data

Automatic Weather station (ID KAZPHOEN424) have been installed in Seva Sadan-3 at the Deendayal Port which records the data on Temperature (°C), Relative Humidity (%), Wind speed (m/s), Wind Direction (°), Solar radiation (w/m²) and Rainfall mm.

Meteorological factors play an important role in environmental pollution studies particularly in pollutant transport irrespective of their entry into the environment. The wind speed and direction play a major role in dispersion of environment pollutants. Effects of pollution on receptors animate and inanimate depends on atmospheric condition.

Temperature

At Deendayal Port, the day time temperature was found range 21.1-32.9⁰C. The average day time temperature was 27.92°C. The night time temperature was range from 20.0-29.7⁰C. The mean night time temperature recorded was 25.47 °C.

Solar Radiation

The mean Solar Radiation in November month was 167.27 w/m². The maximum solar radiation was recorded 759.0 w/m² in 4th November, 2022 and the minimum solar radiation was recorded 1.80 w/m² in 30th November, 2022.

Rainfall


Rain fall of November month was recorded 0.00 mm.

Relative Humidity

The mean Relative humidity was 69.00 % for the month of November. Maximum Relative humidity was recorded 99.0 % and minimum Relative humidity was recorded 34.0 %.

Wind Velocity and Wind Direction

Velocity and direction of wind have a significant role in the dispersion of air borne materials and therefore determines the air quality of the area. The average wind velocity for the entire month of November was 1.21 m/s. Maximum wind velocity was recorded 10.19 m/s. The wind direction was mostly North-East.



CHAPTER-4

DRINKING WATER QUALITY MONITORING

4.0 Drinking Water Quality Monitoring

Drinking Water Quality Monitoring was carried out at twenty stations at Kandla, Vadinar & Township Area of Deendayal Port.

Table No:-10. Drinking Water Sampling Location

Sr. No.	Name of Location	Location Code	Latitude	Longitude
1.	Nirman Building	DL-1	23° 0' 27"N	70° 13' 21"E
2.	P & C Building	DL-2	23° 0' 33"N	70° 13' 20"E
3.	North Gate	DL-3	23° 0' 26.97"N	70° 13' 21.87"E
4.	KPT-Canteen	DL-4	23° 2' 17.2674"N	70° 13' 18.2814"E
5.	West Gate	DL-5	23° 59' 40.48"N	70° 12' 50.96"E
6.	Wharf Area	DL-6	22° 59' 52.2"N	70° 13' 22.95"E
7.	Sevasadan-3	DL-7	23° 0' 22.55"N	70° 13' 15.34"E
8.	Workshop	DL-8	23° 0' 33.74"N	70° 13' 20.05"E
9.	Custom Building	DL-9	23° 1' 8.70"N	70° 12' 52.0"E
10.	Kandla Colony	DL-10	23° 11' 14.9"N	70° 12' 48.4"E
11.	KPT Hospital	DL-11	23° 1' 5.02"N	70° 12' 44.38"E
12.	A.O. Building	DL-12	23° 3' 42.89"N	70° 8' 41.5"E
13.	Gopalpuri School	DL-13	23° 5' 1.03"N	70° 7' 55.42"E
14.	Gopalpuri Guest House	DL-14	23° 4' 43.14"N	70° 7' 51.92"E
15.	E-Type Quarters	DL-15	23° 4' 59.90"N	70° 7' 56.72"E
16.	F-Type Quarters	DL-16	23° 4' 38.45"N	70° 8' 8.63"E
17.	Gopalpuri Hospital	DL-17	23° 4' 54.09"N	70° 8' 7.5"E
18.	Tuna Port	DL-18	23° 58' 23.06"N	70° 5' 35.6"E
19.	Vadinar Jetty	DL-19	22° 25' 51.73"N	69° 41' 36.62"E
20.	Vadinar Colony	DL-20	22° 30' 26.25"N	69° 39' 45.03"E

4.1 Drinking Water Monitoring Methodology

Samples for physico-chemical analysis were collected in 2 Carboys and samples for microbiological parameters were collected in sterilized bottles. These samples were then analyzed in laboratory for various drinking water parameters at Kandla Lab/Surat.

The Sampling was done as per IS: 3025 Part-1, analysis was done as per IS: 3025/APHA standard methods and, the analysis results compare with IS 10500:2012. The water samples were analyzed for various parameters, viz. Color , Odor, Turbidity , Conductivity , pH , Chlorides , TDS, Total Hardness, Iron , Sulphate, Salinity , DO, BOD, Na, K, Ca, Mg, F, NO₃, NO₂, Mn, Cr-6, Cu, Cd, As, Hg, Pb, Zn, Bacterial Count (CFU) .

4.2 Results

The Drinking Water Quality monitoring data for 20 stations are given in below from table No. 11 to Table No. 17

Table 11: Drinking Water Quality Monitoring Parameters for Nirman Building, P & C Building and Main Gate (North) at Kandla.

Sr. No.	Parameter	Unit	Nirman Building 1	P & C Building	Main Gate North	Acceptable Limits as per IS 10500 :2012 2012	Permissible Limits in the absence of Alternate Source as per IS 10500 : 2012
1	pH	-	7.35	7.33	7.41	7.35	6.5 to 8.5
2	Total Dissolved Solids	mg/l	690	670	670	690	2000
3	Turbidity	NTU	0	1	1	0	5
4	Odor	-	Odorless	Odorless	Odorless	Agreeable	Agreeable
5	Color	-	Colorless	Colorless	Colorless	5	15
6	Conductivity	µs/cm	1229	1194	1211	NS*	NS*
7	Biochemical Oxygen	mg/l	BQL	BQL	BQL	NS*	NS*
8	Chloride as Cl	mg/l	576.28	355.79	340.76	250	1000
9	Ca as Ca	mg/l	43.29	41.68	39.28	75	200
10	Mg as Mg	mg/l	58.8060	57.3480	56.3760	30	100
11	Total Hardness	mg/l	350	340	330	200	600
12	Iron as Fe	mg/l	BQL	BQL	BQL	0.3	No Relaxation
13	Fluorides as F	mg/l	0.35	0.37	0.31	1	1.5
14	Sulphate as SO ₄	mg/l	35.80	30.20	28.30	200	400
15	Nitrite as NO ₂	mg/l	BQL	BQL	BQL	NS*	NS*
16	Nitrate as NO ₃	mg/l	12.70	16.70	15.50	45	No Relaxation
17	Salinity	‰	1.04	0.64	0.62	NS*	NS*
18	Sodium as Na	mg/l	204.00	180.00	192.00	NS*	NS*
19	Potassium as K	mg/l	3.22	3.15	3.18	NS*	NS*
20	Manganese	mg/l	BQL	BQL	BQL	0.1	0.3
21	Hexavalent Chromium	mg/l	BQL	BQL	BQL	NS*	NS*
22	Copper	mg/l	BQL	BQL	BQL	0.05	1.5
23	Cadmium	mg/l	BQL	BQL	BQL	0.003	NS*
24	Arsenic	mg/l	BQL	BQL	BQL	0.01	0.05
25	Mercury	mg/l	BQL	BQL	BQL	0.001	NS*
26	Lead	mg/l	BQL	BQL	BQL	0.01	NS*
27	Zinc	mg/l	BQL	BQL	BQL	5	15
28	Bacterial Count	CFU/10 0ml	Absent	Absent	Absent	Absent	Absent

*NS: Not Specified

BQL- Below Quantification Limit, (BOD-2.0 mg/l, Fe- 0.009 mg/l, Mn- 0.01 mg/l, Cr⁺⁶- 0.03 mg/l, Cu- 0.004 mg/l, Cd- 0.003 mg/l, As- 0.003mg/l, Hg- 0.001 mg/l, Pb- 0.006mg/l, Zinc- 0.021 mg/l).

Table 12: Drinking Water Quality Monitoring Parameters for Canteen, West Gate – I & Wharf Area at Kandla

Sr. No.	Parameter	Unit	Canteen	West Gate – I	Wharf Area	Acceptable Limits as per IS 10500 :	Permissible Limits in the absence of Alternate Source as per IS 10500 : 2012
1	pH	-	7.48	7.52	7.36	7.48	6.5 to 8.5
2	Total Dissolved Solids	mg/l	640	650	680	640	2000
3	Turbidity	NTU	0	1	0	0	5
4	Odor	-	Odorless	Odorless	Odorless	Agreeable	Agreeable
5	Color	-	Colorless	Colorless	Colorless	5	15
6	Conductivity	µs/cm	1166	1152	1196	NS*	NS*
7	Biochemical Oxygen Demand	mg/l	BQL	BQL	BQL	NS*	NS*
8	Chloride as Cl	mg/l	335.75	360.80	350.78	250	1000
9	Ca as Ca	mg/l	40.88	38.48	40.08	75	200
10	Mg as Mg	mg/l	62.6940	66.5820	53.4600	30	100
11	Total Hardness	mg/l	360	370	320	200	600
12	Iron as Fe	mg/l	BQL	BQL	BQL	0.3	No Relaxation
13	Fluorides as F	mg/l	0.32	0.30	0.35	1	1.5
14	Sulphate as SO ₄	mg/l	31.20	28.30	26.00	200	400
15	Nitrite as NO ₂	mg/l	BQL	BQL	BQL	NS*	NS*
16	Nitrate as NO ₃	mg/l	6.60	11.40	5.80	45	No Relaxation
17	Salinity	‰	0.61	0.65	0.63	NS*	NS*
18	Sodium as Na	mg/l	202.00	200.00	-	NS*	NS*
19	Potassium as K	mg/l	3.38	3.48	3.16	NS*	NS*
20	Manganese	mg/l	BQL	BQL	BQL	0.1	0.3
21	Hexavalent Chromium	mg/l	BQL	BQL	BQL	NS*	NS*
22	Copper	mg/l	BQL	BQL	BQL	0.05	1.5
23	Cadmium	mg/l	BQL	BQL	BQL	0.003	NS*
24	Arsenic	mg/l	BQL	BQL	BQL	0.01	0.05
25	Mercury	mg/l	BQL	BQL	BQL	0.001	NS*
26	Lead	mg/l	BQL	BQL	BQL	0.01	NS*
27	Zinc	mg/l	BQL	BQL	BQL	5	15
28	Bacterial Count	CFU/100ml	Absent	Absent	Absent	Absent	Absent

*NS: Not Specified,

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Fe-0.009 mg/l, Mn- 0.01 mg/l, Cr+6- 0.03 mg/l, Cu-0.004 mg/l, Cd-0.003 mg/l, As-0.003mg/l, Hg-0.001 mg/l, Pb-0.006mg/l, Zinc-0.021 mg/l).

DCPL/DPA/21-22/31– November-2022

Table 13: Drinking Water Quality Monitoring Parameters for Sewa sadan-3, Workshop I and Custom Building at Kandla

Sr. No.	Parameter	Unit	Sewa Sadan – 3	Workshop	Custom Building	Acceptable Limits as per IS 10500 : 2012	Permissible Limits in the absence of Alternate Source as per IS 10500 : 2012
1	pH	-	7.45	7.38	7.29	6.5 to 8.5	6.5 to 8.5
2	Total Dissolved Solids	mg/l	700	670	910	500	2000
3	Turbidity	NTU	0	1	1	1	5
4	Odor	-	Odorless	Odorless	Odorless	Agreeable	Agreeable
5	Color	-	Colorless	Colorless	Colorless	5	15
6	Conductivity	µs/cm	1213	1164	1564	NS*	NS*
7	Biochemical	mg/l	BQL	BQL	BQL	NS*	NS*
8	Chloride as Cl	mg/l	365.81	370.82	340.76	250	1000
9	Ca as Ca	mg/l	42.48	37.68	39.28	75	200
10	Mg as Mg	mg/l	59.2920	59.7780	53.9460	30	100
11	Total Hardness	mg/l	350	340	320	200	600
12	Iron as Fe	mg/l	BQL	BQL	BQL	0.3	No Relaxation
13	Fluorides as F	mg/l	0.41	0.30	0.35	1	1.5
14	Sulphate as SO ₄	mg/l	24.90	34.20	27.2	200	400
15	Nitrite as NO ₂	mg/l	BQL	BQL	BQL	NS*	NS*
16	Nitrate as NO ₃	mg/l	6.90	3.90	11.00	45	No Relaxation
17	Salinity	‰	0.66	0.67	0.62	NS*	NS*
18	Sodium as Na	mg/l	-	-	-	NS*	NS*
19	Potassium as K	mg/l	3.26	4.03	3.29	NS*	NS*
20	Manganese	mg/l	BQL	BQL	BQL	0.1	0.3
21	Hexavalent Chromium	mg/l	BQL	BQL	BQL	NS*	NS*
22	Copper	mg/l	BQL	BQL	BQL	0.05	1.5
23	Cadmium	mg/l	BQL	BQL	BQL	0.003	NS*
24	Arsenic	mg/l	BQL	BQL	BQL	0.01	0.05
25	Mercury	mg/l	BQL	BQL	BQL	0.001	NS*
26	Lead	mg/l	BQL	BQL	BQL	0.01	NS*
27	Zinc	mg/l	BQL	BQL	BQL	5	15
28	Bacterial Count	CFU/100ml	Absent	Absent	Absent	Absent	Absent

*NS: Not Specified,

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Fe-0.009 mg/l, Mn- 0.01 mg/l, Cr+6- 0.03 mg/l, Cu-0.004 mg/l, Cd-0.003 mg/l, As-0.003mg/l, Hg-0.001 mg/l, Pb-0.006mg/l, Zinc-0.021 mg/l).

DCPL/DPA/21-22/31– November-2022

Table 14: Drinking Water Quality Monitoring Parameters for Port Colony Kandla, Hospital Kandla and A.O. Building at Gandhidham.

Sr. No.	Parameter	Unit	Port Colony Kandla	Hospital Kandla	A.O. Building	Acceptable Limits as per IS 10500 : 2012	Permissible Limits in the absence of Alternate Source as per IS 10500 :
1	pH	-	7.39	7.31	7.24	6.5 to 8.5	6.5 to 8.5
2	Total Dissolved Solids	mg/l	760	710	1060	500	2000
3	Turbidity	NTU	1	0	0	1	5
4	Odor	-	Odorless	Odorless	Odorless	Agreeable	Agreeable
5	Color	-	Colorless	Colorless	Colorless	5	15
6	Conductivity	µs/cm	1328	1251	1821	NS*	NS*
7	Biochemical	mg/l	BQL	BQL	BQL	NS*	NS*
8	Chloride as Cl	mg/l	335.75	345.77	365.81	250	1000
9	Ca as Ca	mg/l	41.68	42.48	40.88	75	200
10	Mg as Mg	mg/l	50.0580	54.4320	62.6940	30	100
11	Total Hardness	mg/l	310	330	360	200	600
12	Iron as Fe	mg/l	BQL	BQL	BQL	0.3	No Relaxation
13	Fluorides as F	mg/l	0.35	0.32	0.46	1	1.5
14	Sulphate as SO ₄	mg/l	28.10	24.50	24.50	200	400
15	Nitrite as NO ₂	mg/l	BQL	BQL	BQL	NS*	NS*
16	Nitrate as NO ₃	mg/l	20.20	7.40	15.60	45	No Relaxation
17	Salinity	‰	0.61	0.62	0.66	NS*	NS*
18	Sodium as Na	mg/l	192.80	193.60	194.50	NS*	NS*
19	Potassium as K	mg/l	4.13	4.18	3.26	NS*	NS*
20	Manganese	mg/l	BQL	BQL	BQL	0.1	0.3
21	Hexavalent Chromium	mg/l	BQL	BQL	BQL	NS*	NS*
22	Copper	mg/l	BQL	BQL	BQL	0.05	1.5
23	Cadmium	mg/l	BQL	BQL	BQL	0.003	NS*
24	Arsenic	mg/l	BQL	BQL	BQL	0.01	0.05
25	Mercury	mg/l	BQL	BQL	BQL	0.001	NS*
26	Lead	mg/l	BQL	BQL	BQL	0.01	NS*
27	Zinc	mg/l	BQL	BQL	BQL	5	15
28	Bacterial Count	CFU/100ml	Absent	Absent	Absent	Absent	Absent

*NS: Not Specified,

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Fe-0.009 mg/l, Mn- 0.01 mg/l, Cr+6- 0.03 mg/l, Cu-0.004 mg/l, Cd-0.003 mg/l, As-0.003mg/l, Hg-0.001 mg/l, Pb-0.006mg/l, Zinc-0.021 mg/l).

Table 15: Drinking Water Quality Monitoring Parameters for School Gopalpuri, Guest House) and E - Type Quarter at Gopalpuri, Gandhidham

Sr. No.	Parameter	Unit	Gopalpuri School	Guest House	E - Type Quarter	Acceptable Limits as per IS 10500 : 2012	Permissible Limits in the absence of Alternate Source as per IS 10500 : 2012
1	pH	-	7.3	7.24	7.26	6.5 to 8.5	6.5 to 8.5
2	Total Dissolved Solids	mg/l	830	950	1030	500	2000
3	Turbidity	NTU	1	1	0	1	5
4	Odor	-	Odorless	Odorless	Odorless	Agreeable	Agreeable
5	Color	-	Colorless	Colorless	Colorless	5	15
6	Conductivity	µs/cm	1435	1638	1769	NS*	NS*
7	Biochemical Oxygen Demand	mg/l	BQL	BQL	BQL	NS*	NS*
8	Chloride as Cl	mg/l	355.79	350.78	340.76	250	1000
9	Ca as Ca	mg/l	39.28	43.29	39.28	75	200
10	Mg as Mg	mg/l	61.2360	61.2360	51.5160	30	100
11	Total Hardness	mg/l	350	360	310	200	600
12	Iron as Fe	mg/l	BQL	BQL	BQL	0.3	No Relaxation
13	Fluorides as F	mg/l	0.45	0.42	0.47	1	1.5
14	Sulphate as SO ₄	mg/l	24.90	26.00	30.20	200	400
15	Nitrite as NO ₂	mg/l	BQL	BQL	BQL	NS*	NS*
16	Nitrate as NO ₃	mg/l	7.10	8.30	12.60	45	No Relaxation
17	Salinity	‰	0.64	0.63	0.62	NS*	NS*
18	Sodium as Na	mg/l	199.00	193.80	193.00	NS*	NS*
19	Potassium as K	mg/l	3.90	3.26	3.18	NS*	NS*
20	Manganese	mg/l	BQL	BQL	BQL	0.1	0.3
21	Hexavalent Chromium	mg/l	BQL	BQL	BQL	NS*	NS*
22	Copper	mg/l	BQL	BQL	BQL	0.05	1.5
23	Cadmium	mg/l	BQL	BQL	BQL	0.003	NS*
24	Arsenic	mg/l	BQL	BQL	BQL	0.01	0.05
25	Mercury	mg/l	BQL	BQL	BQL	0.001	NS*
26	Lead	mg/l	BQL	BQL	BQL	0.01	NS*
27	Zinc	mg/l	BQL	BQL	BQL	5	15
28	Bacterial Count	CFU/100 ml	Absent	Absent	Absent	Absent	Absent

*NS: Not Specified,

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Fe-0.009 mg/l, Mn- 0.01 mg/l, Cr+6- 0.03 mg/l, Cu-0.004 mg/l, Cd-0.003 mg/l, As-0.003mg/l, Hg-0.001 mg/l, Pb-0.006mg/l, Zinc-0.021 mg/l).

Table 16: Drinking Water Quality Monitoring Parameters for F-Type Quarter, Hospital Gopalpuri and Tuna Port.

Sr. No.	Parameter	Unit	F - Type Quarter	Hospital Gopalpuri	Tuna Port	Acceptable Limits as per IS 10500 : 2012	Permissible Limits in the absence of Alternate Source as per IS 10500 : 2012
1	pH	-	7.28	7.42	7.51	6.5 to 8.5	6.5 to 8.5
2	Total Dissolved Solids	mg/l	1050	990	600	500	2000
3	Turbidity	NTU	1	1	-	1	5
4	Odor	-	Odorless	Odorless	Odorless	Agreeable	Agreeable
5	Color	-	Colorless	Colorless	Colorless	5	15
6	Conductivity	µs/cm	1796	1700	1044	NS*	NS*
7	Biochemical Oxygen Demand	mg/l	BQL	BQL	BQL	NS*	NS*
8	Chloride as Cl	mg/l	345.77	360.80	380.85	250	1000
9	Ca as Ca	mg/l	38.48	40.88	32.87	75	200
10	Mg as Mg	mg/l	61.7220	62.6940	72.41	30	100
11	Total Hardness	mg/l	350	360	380	200	600
12	Iron as Fe	mg/l	BQL	BQL	BQL	0.3	No Relaxation
13	Fluorides as F	mg/l	0.42	0.45	0.43	1	1.5
14	Sulphate as SO ₄	mg/l	26.00	26.10	24.50	200	400
15	Nitrite as NO ₂	mg/l	BQL	BQL	BQL	NS*	NS*
16	Nitrate as NO ₃	mg/l	10.30	6.80	3.00	45	No Relaxation
17	Salinity	‰	0.62	0.65	0.69	NS*	NS*
18	Sodium as Na	mg/l	201.00	201.00	193.60	NS*	NS*
19	Potassium as K	mg/l	3.15	3.16	3.21	NS*	NS*
20	Manganese	mg/l	BQL	BQL	BQL	0.1	0.3
21	Hexavalent Chromium	mg/l	BQL	BQL	BQL	NS*	NS*
22	Copper	mg/l	BQL	BQL	BQL	0.05	1.5
23	Cadmium	mg/l	BQL	BQL	BQL	0.003	NS*
24	Arsenic	mg/l	BQL	BQL	BQL	0.01	0.05
25	Mercury	mg/l	BQL	BQL	BQL	0.001	NS*
26	Lead	mg/l	BQL	BQL	BQL	0.01	NS*
27	Zinc	mg/l	BQL	BQL	BQL	5	15
28	Bacterial Count	CFU/100ml	Absent	Absent	Absent	Absent	Absent

*NS: Not Specified, BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Fe-0.009 mg/l, Mn- 0.01 mg/l, Cr+6- 0.03 mg/l, Cu-0.004 mg/l, Cd-0.003 mg/l, As-0.003mg/l, Hg-0.001 mg/l, Pb-0.006mg/l, Zinc-0.021 mg/l).

Table 17: Drinking Water Quality Monitoring Parameters for Vadinar Jetty and Port Colony at Vadinar.

Sr. No.	Parameter	Unit	Vadinar Jetty	Port Colony Vadinar	Acceptable Limits as per IS 10500 : 2012	Permissible Limits in the absence of Alternate Source as per IS 10500 : 2012
1	pH	-	7.4	7.43	6.5 to 8.5	6.5 to 8.5
2	Total Dissolved Solids	mg/l	320	300	500	2000
3	Turbidity	NTU	0.00	1.00	1	5
4	Odor	-	Odorless	Odorless	Agreeable	Agreeable
5	Color	-	Colorless	Colorless	5	15
6	Conductivity	µs/cm	570	300	NS*	NS*
7	Biochemical Oxygen Demand	mg/l	BQL	BQL	NS*	NS*
8	Chloride as Cl	mg/l	160.36	140.31	250	1000
9	Ca as Ca	mg/l	36.87	34.47	75	200
10	Mg as Mg	mg/l	43.25	52.00	30	100
11	Total Hardness	mg/l	270	300	200	600
12	Iron as Fe	mg/l	BQL	BQL	0.3	No Relaxation
13	Fluorides as F	mg/l	0.25	0.22	1	1.5
14	Sulphate as SO ₄	mg/l	0.75	0.24	200	400
15	Nitrite as NO ₂	mg/l	BQL	BQL	NS*	NS*
16	Nitrate as NO ₃	mg/l	15.60	12.70	45	No Relaxation
17	Salinity	‰	0.29	0.25	NS*	NS*
18	Sodium as Na	mg/l	191.6	192.0	NS*	NS*
19	Potassium as K	mg/l	BQL	BQL	NS*	NS*
20	Manganese	mg/l	BQL	BQL	0.1	0.3
21	Hexavalent Chromium	mg/l	BQL	BQL	NS*	NS*
22	Copper	mg/l	BQL	BQL	0.05	1.5
23	Cadmium	mg/l	BQL	BQL	0.003	NS*
24	Arsenic	mg/l	BQL	BQL	0.01	0.05
25	Mercury	mg/l	BQL	BQL	0.001	NS*
26	Lead	mg/l	BQL	BQL	0.01	NS*
27	Zinc	mg/l	BQL	BQL	5	15
28	Bacterial Count	CFU/100ml	Absent	Absent	Absent	Absent

*NS: Not Specified,

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Fe-0.009 mg/l, Mn- 0.01 mg/l, Cr+6- 0.03 mg/l, Cu-0.004 mg/l, Cd-0.003 mg/l, As-0.003mg/l, Hg-0.001 mg/l, Pb-0.006mg/l, Zinc-0.021 mg/l).

4.3 Results & Discussion

The colour of all drinking water samples was found Colourless and odour of the samples also agreeable. All parameters were found within the specified limit as per the Drinking water Standard.

pH

The pH is measure of the intensity of acidity or alkalinity and the concentration of hydrogen ion in water. At DPA Site the pH values for drinking water samples ranged from 7.24-7.52 and mean value was 7.36 while at Vadinar pH ranged from 7.40-7.43 and mean value was 7.42. All the sampling points showed pH values within the prescribed limit by Indian Standards.

Turbidity

The selected drinking water sample location turbidity range from 0-1NTU at all location of DPA and Vadinar in month of November. The Turbidity values were within the permissible limit at all sampling location prescribed limit by Indian standards.

Total Dissolved Solids (TDS)

Water has the ability to dissolve a wide range of inorganic and some organic minerals or salts such as potassium, calcium, sodium, bicarbonates, chlorides, magnesium, sulfates etc.

TDS values at DPA varied between 600-1060 mg/l. The average TDS value was found 792 mg/l. The minimum value for TDS was 600 mg/l at Hospital Gopalpuri and maximum was 980 mg/l at Tuna Port while at Vadinar TDS ranged from 280-300 mg/l and mean was 290.0 mg/l. The TDS values were within the permissible limit at all sampling location prescribed limit by Indian standards.

Conductivity

Electrical Conductivity is the ability of a solution to transfer (conduct) electric current. Conductivity is used to measure the concentration of dissolved solids which have been ionized in a polar solution such as water. The conductivity in the samples collected during the month of November DPA ranged from 1044.0 $\mu\text{S}/\text{cm}$ at Tuna Port to 1821.0 $\mu\text{S}/\text{cm}$ at A.O. Building and mean value was 1381.72 $\mu\text{S}/\text{cm}$ while at Vadinar ranged from 300-570 $\mu\text{S}/\text{cm}$ and mean was 435 $\mu\text{S}/\text{cm}$.

BOD

BOD value in the studied area of DPA and Vadinar was found Below Quantification Limit (<2.0 mg/l). IS 10500:2012 does not show any standard values for BOD in drinking water.

Chlorides

Excessive chloride concentration increase rates of corrosion of metals in the distribution system. This can lead to increased concentration of metals in the supply. The Chloride value in the studied area of DPA ranged from 335.75-576.28 mg/l. The mean value was 365.53 mg/l. The minimum chloride was 335.75 mg/l at Port colony and maximum was 576.28 mg/l at Nirmal Building while at Vadinar location chloride ranged from 140.31-160.36 mg/l and mean was 150.33 mg/l. The Chloride was found within the Permissible limit of the Drinking Water Standard.

Calcium

Calcium is most abundant element on the earth crust and is very important for human cell physiology and bones. About 95% calcium in human body stored in bones and teeth. The high deficiency of calcium in humans may caused rickets, poor blood clotting, bones fracture etc. and the exceeding limit of calcium produced cardiovascular diseases.

The Calcium value in the studied area of DPA ranged from 32.87-43.29 mg/l. The mean value was 40.12 mg/l. The minimum calcium was 32.87 mg/l at Tuna Port and maximum was 43.29 mg/l at Gopalpuri Hospital while at Vadinar location Calcium ranged from 34.47-36.87 and mean was 35.67 mg/l. All the locations had calcium within the prescribed limits of 75-200 mg/L.

Magnesium

The magnesium value in the studied area of DPA ranged from 50.06-72.41 mg/l. The mean value was 59.24 mg/l. The minimum magnesium was 50.06 mg/l at Port Colony and maximum was 74.41 mg/l at Tuna Port while at Vadinar location magnesium ranged from 43.25-52.00 and mean was 47.61 mg/l. All the locations had magnesium within the prescribed limits of 30-100 mg/L.

Total Hardness

Total Hardness value in the studied area of DPA ranged from 310.0 mg/l at Port Colony to 380.0 mg/l at Tuna Port and mean value was 343.89 mg/l while at Vadinar location total hardness ranged from 270.0-300.00 mg/l and mean was 285.0 mg/l. The values of total

hardness were found within the Permissible limit of the Drinking Water Standard (200-600 mg/L). These results clear, that hardness of water is according to the IS standards and it is not harmful for local inhabitants.

Iron

Iron values in the studied area of DPA & Vadinar were Below Quantification Limit (0.009 mg/l) and hence well below the permissible limit as per Indian Standards are 0.3 mg/L.

Fluoride

Fluoride value in the studied area of DPA varied between 0.3-0.47 mg/l and mean was 0.38 mg/l. The minimum value was 0.3 mg/ at West gate workshop and maximum was 0.47 mg/l at E-Type and mean was 0.38 mg/l while at Vadinar location fluoride ranged from 0.22-0.25 mg/l and mean was 0.24 mg/l. The Fluoride values were well below the permissible limit as per Indian Standards is 1.0-1.5 mg/L. Moderate amounts lead to dental effects, but long-term ingestion of large amounts can lead to potentially severe skeletal problems.

Sulphate

Sulphate value in the studied area of DPA varied between 24.5–35.8 mg/l and mean was 27.83 mg/l. The minimum value was 24.5 mg/ at A.O. Building, Hospital Kandla and Tuna Port and maximum was 35.8 mg/l at Nirmal Building while at Vadinar location Sulphate ranged from 0.24-0.75 mg/l and mean was 0.50 mg/l. All the sampling points showed Sulphate values within the prescribed limits by Indian Standards (200-400 mg/L). Sulphate content in drinking water exceeding the 400 mg/L imparts bitter taste.

Nitrites (NO₂) and Nitrates (NO₃)

The all values of Nitrite were found BQL (<0.05 mg/l) and Nitrate were well within the permissible limit of the Drinking water Standard.

Salinity

Salinity in drinking water in the present samples collected at DPA ranged from 0.61 ‰ at Canteen to 1.04 ‰ at Nirmal Building and average salinity was 0.66 ‰ while at Vadinar sampling location salinity ranged from 0.25-0.29 ‰. There are no prescribed Indian standards for salinity in Drinking water.

Sodium and Potassium Salts

Sodium values in the samples collected at DPA ranged from 180 - 204 mg/l and average was 195.74 mg/l while at Vadinar sodium ranged from 191.6- 192.0 mg/l and average was 191.8 mg/l . Potassium salts ranged at DPA ranged from 3.15 to 4.18 mg/l while average was 3.42 mg/l while at Vadinar sampling locations potassium were BQL (<2.0 mg/l). There are no prescribed limits of Sodium and Potassium in Indian standards for Drinking water.

Heavy Metals in Drinking Water

In the present study period drinking water samples were analyzed for Mn, Cr, Cu, Cd, As, Hg, Pb and Zn. All these heavy metals were well Below the Quantification limits prescribed by the Indian Standards.

Bacteriological Study

Analysis of the bacteriological parameter (E-coli and total coliform) at all location shows that Bacteria were not detectable. This shows that drinking water samples were safe for human consumption as per tested parameters.

4.4 Conclusions

These results were compared with permissible limits as prescribed in IS 10500:2012 – Drinking Water Specification. It was seen from the analysis data that during the study period at selected sampling location the water was safe for human consumption as per analyzed parameters at all drinking water monitoring stations.

CHAPTER-5

NOISE MONITORING

5.0 Noise Level Monitoring

Noise sources in port operations include cargo handling, vehicular traffic, and loading / unloading containers and ships. Noise Monitoring was done at 13 stations at Kandla, Vadinar and Township area.

5.1 Method of Monitoring

Sampling was done at all stations for 24 hour period. Data was recorded using automated sound level meter. The intensity of sound was measured in sound pressure level (SPL) and common unit of measurement is decibel (dB).

5.2 Results

Table 18: Noise Monitoring data for ten locations of Deendayal Port and three locations of Vadinar Port

Sr. No.	Location	Day Time Average Noise Level (SPL) in dB(A)	Night Time Average Noise Level (SPL) in dB(A)
	Sampling Time	6:00 am to 10:00 PM	10:00PM to 6:00 AM
1	Marine Bhavan	60.8	51.9
2	Nirman Building 1	69.9	52.0
3	Tuna Port	53.2	45.4
4	Main Gate North	63.3	51.9
5	West Gate I	67.7	58.1
6	Canteen Area	68.2	51.2
7	Main Road	66.3	52.2
8	ATM Building	69.1	51.1
9	Wharf Area /Jetty Area	70.4	61.7
10	Port & Custom Office	54.7	50.2
Vadinar Port			
11	Entrance Gate of Vadinar Port	55.0	53.5
12	Nr. Port Colony, Vadinar	60.6	57.6
13	Nr. Vadinar Jetty	52.5	51.0

5.3 Conclusions

Transportation systems are the main source of noise pollution in urban areas. Construction of buildings, highways, and roads cause a lot of noise, due to the usage of air compressors, bulldozers, loaders, dump trucks, and pavement breakers. Noise sources in port operations include cargo handling, vehicular traffic, and loading / unloading containers and ships.

Noise sources in port operations include cargo handling, vehicular traffic, and loading / unloading containers and ships. The Day Time Noise Level (SPL) in all 10 locations at Deendayal Port Authority ranged from 53.2 dB(A) to 70.4 dB(A) while at Vadinar port 3 location ranged from 52.5 dB(A) to 60.6 dB(A) which was within the permissible limits of 75 dB(A) for the industrial area for the daytime. The Night Time Average Noise Level (SPL) in all locations of Deendayal Port Authority ranged from 45.4 dB to 61.7 dB(A) while at Vadinar port ranged from 52.5 dB (A) to 60.6 dB(A) which was within the permissible limits of 70 dB(A) for the industrial area for the night time.

CHAPTER-6

SOIL MONITORING

6.0 Soil Monitoring

Sampling and analysis of soil samples were undertaken at six locations within the study area (Deendayal Port and Vadinar Port) as a part of EMP. The soil sampling locations are initially decided based on the locations as provided in the tender document of the Deendayal Port.

Table No.:-19. Soil Sampling Location

Sr. No.	Name of Location	Location Code	Latitude	Longitude	Remarks
1.	Tuna Port	SL-1	22° 58' 10.18"N	70° 6' 3.7"E	Near main gate of Port
2.	IFFCO Plant	SL-2	23° 26' 8.37"N	70° 13' 4.4"E	10 m away from main gate
3.	Khori creek	SL-3	22° 58' 10.18"N	70° 6' 3.7"E	Sand from creek after tide
4.	Nakti Creek	SL-4	23° 2' 1.10"N	70° 9' 33.6"E	
5.	DPA admin site	SL-5	22° 26' 30.9"N	69° 40' 37.03"E	Vadinar
6.	DPA colony	SL-6	22° 23' 57.09"N	69° 42' 49.42"E	

6.1 Methodology

The soil samples were collected in the month of November 2022. The samples collected from the all locations are homogeneous representative of each location. At random locations were identified at each location and soil was dug from 30 cm below the surface. It was uniformly mixed before homogenizing the soil samples. The samples were filled in polythene bags, labeled in the field with number and site name and sent to laboratory for analysis.

6.2 Results

Table-20: Chemical Characteristics of Soil in the Study Area for Tuna port, IFFCO, Khori Creek, Nakti Creek, DPA admin site, DPA colony.

Sr. No.	Parameter	Unit	Station Name					
			SL1	SL2	SL3	SL4	SL5	SL6
			Tuna Port	IFFCO Plant	Khori Creek	Nakti Creek	DPA Admin Site	DPA Colony
			Near main gate of Port	10 m away from main	Sand from creek after tide		Vadinar	
1	Texture		Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam
2	pH	-	7.79	7.80	7.54	7.58	8.14	7.54
3	Electrical Conductivity	µs/cm	35000.0	36100.0	26,820.00	12,700.0	155.0	594.0
4	Phosphorus	mg/kg	10.3	10.5	9.19	8.49	6.00	4.80
5	Moisture	%	15.9	20.3	20.90	3.50	7.20	10.10
6	Total Organic	%	4.04	1.7	3.64	7.80	2.30	2.00
7	Alkalinity	mg/kg	900.0	1000.0	800.0	500.0	800.0	600.0
8	Total Nitrogen	%	BQL	BQL	BQL	BQL	BQL	BQL
9	Sulphate	mg/kg	820.00	982.00	1,080.00	810.00	30.0	70.0
10	Chloride	mg/kg	15598.0	14275.0	12,600.00	2,950.00	140.00	525.00
11	Calcium	mg/kg	2,605.00	2,505.00	31,600.00	3,086.00	1,729.00	1,849.00
12	Sodium	mg/kg	5657	7136.0	7,649.00	4,675.00	33.02	116.90
13	Potassium	mg/kg	552	694	708.00	437.00	44.60	44.52
14	Copper as Cu	mg/kg	27.4	15.5	30.50	14.50	54.10	31.60
15	Lead as Pb	mg/kg	7.4	7.4	9.50	6.30	74.10	75.30
16	Nickel as Ni	mg/kg	39.40	32.70	44.40	27.20	30.30	32.00
17	Zinc as Zn	mg/kg	62.4	77.40	79.20	56.50	50.60	86.00
18	Cadmium as Cd	mg/kg	BQL	BQL	BQL	BQL	BQL	BQL

BQL- Below Quantification Limit, (TN: 0.001%, Cd: 1.0mg/kg)

6.3 Discussion

- DPA Kandla soil sampling data shows that value of pH ranges from 7.54 at Khori Creek to 7.80 at IFFCO Plant while the average value was 7.68. At Vadinar sampling location pH were 7.54 at DPA colony and 8.14 at DPA Admin Site.
- The Electrical Conductivity of DPA Kandla soil sample ranged from 12700.0 $\mu\text{S}/\text{cm}$ at Nakti Creek (Sand from creek after tide) to 36100 $\mu\text{S}/\text{cm}$ at IFFCO Plant and mean was 27655 $\mu\text{S}/\text{cm}$ while Vadinar soil sampling location conductivity were 155 $\mu\text{S}/\text{cm}$ at DPA Admin Site and 594 $\mu\text{S}/\text{cm}$ at DPA Colony site.
- Total organic Carbon of DPA Kandla soil sample ranged from 1.7 % at IFFCO Plant to 7.80 % at Nakti Creek (Sand from creek after tide) and mean was 4.30 % while Vadinar soil sample were 2.0 % at DPA Colony and 2.30 % at DPA admin Site.
- The concentration of Phosphorus in the soil samples of DPA Kandla varies from 8.49 mg/kg at Nakti Creek (Sand from creek after tide) and 10.5 mg/kg at IFFCO Plant and mean was 9.62 mg/kg while the Vadinar soil sample for Phosphorus were 4.80 mg/kg at DPA Colony and 6.00 mg/kg at DPA Admin Site.
- Chloride in soil sample of DPA ranged from 2950.00 mg/kg at Nakti Creek (Sand from creek after tide) to 15598 mg/kg at Tuna Port and mean was 11356 mg/kg while Vadinar soil sample were 140 mg/kg at DPA admin and 525 mg/kg at DPA Colony.
- The Concentration of Potassium in the soil samples of DPA Kandla ranged from 437 mg/kg at Nakti creek and 708 mg/kg at Khori Creek and mean was 597.75 mg/kg while the Vadinar soil sample for Potassium were 44.52 mg/kg at DPA Colony Site and 44.60 mg/kg at DPA Admin Site.
- The concentration of Sodium in the soil samples of DPA Kandla ranged from 4675.0 mg/kg at Nakti creek and 7649.0 mg/kg at Khori Creek and mean was 6279 mg/kg while the Vadinar soil sample for Sodium were 33.00 mg/kg at DPA Admin Site and 117 mg/kg at DPA Colony.

These differences in NPK in soil at different locations are due to the dissimilar nature of soil at each of the locations. Samples SL3 & SL4 (Khori Creek & Nakti Creek) were coastal soil; where as other locations are inland locations and have different chemical properties.

Heavy Metals in the Soil

Traces of Copper, Lead, Nickel and Zinc were observed in the soil samples collected from all the four locations of Deendayal Port Authority Kandla and two locations of Vadinar Port. Cadmium metal was below detection limit in the Soil.

6.4 Conclusion

The soils of Deendayal Port Authority Kandla and Vadinar Port appears to be neutral to basic with varying levels of Chloride, Sulphate, NPK and Calcium. As the nature of soil at different locations are different with respect to its proximity to the sea, the samples showed high degree of variations in their chemical properties.

CHAPTER-7

SEWAGE TREATMENT PLANT MONITORING

7.0 Sewage Treatment Plant Monitoring

This involves safe collection of waste water (spent/used water) from wash areas, bathroom, industrial units, etc., waste from toilets of various buildings and its conveyance to the treatment plant and final disposal in conformity with the requirement and guidelines of State Pollution Control Board and other statutory bodies.

7.1 Methodology for STP Monitoring

To monitor the working efficiency of Sewage Treatment Plant (STP), STP Inlet and Outlet Samples were collected once a week. Locations selected are namely Gopalpuri Township, Deendayal Port and Vadinar. Samples were collected in 1 lit. Carboys and were analyzed in laboratory for various parameters.

A new STP with an improved capacity of 1 MLD is being constructed at Gopalpuri Colony.

Table No. 21. Sewage Treatment Plant

Sr. No.	Location of STP	Types of Treatment	STP Capacity	Treated water Utilization
1.	Gopalpuri Township	MBBR	450 KLD	Plantation and Gardening
2.	Deendayal Port, Kandla	MBBR	600 KLD	Discharge to marine through pipeline, Plantation, Gardening
3.	Vadinar Port Colony	MBBR	1.5 MLD	Plantation and Gardening

7.2 Results

Table 22: Sewage Water Monitoring at Kandla STP (1st Week)

Date of Sampling	03.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			DPA STP I/L	DPA STP O/L	
1	pH	-	7.55	7.42	6.5 - 8.5
2	Total Suspended Solids	mg/l	100.6	46.8	100
3	Residual Chlorine	mg/l	-	<0.5	-
4	COD	mg/l	80.8	30.3	100
5	BOD @ 27 °C	mg/l	22	11	30
Aeration Tank					
6	MLSS	mg/l	14.0		
7	MLVSS	%	99.73		

Table 23: Sewage Water Monitoring at Kandla STP (2nd Week)

Date of Sampling	10.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			DPA STP I/L	DPA STP O/L	
1	pH	-	7.41	7.36	6.5 - 8.5
2	Total Suspended Solids	mg/l	127	52.6	100
3	Residual Chlorine	mg/l	-	<0.5	-
4	COD	mg/l	90.9	40.4	100
5	BOD @ 27 °C	mg/l	23	11	30
Aeration Tank					
6	MLSS	mg/l	18.0		
7	MLVSS	%	85.00		

Table 24: Sewage Water Monitoring at Kandla STP (3rd Week)

Date of Sampling	17.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		CPCB Prescribed Limit
			DPA STP I/L	DPA STP O/L	
1	pH	-	7.48	7.29	6.5 - 8.5
2	Total Suspended Solids	mg/l	86.4	22.9	100
3	Residual Chlorine	mg/l	-	<0.5	-
4	COD	mg/l	101	50.5	100
5	BOD @ 27 °C	mg/l	26	14	30
Aeration Tank					
6	MLSS	mg/l	20.0		
7	MLVSS	%	98.0		

Table 25: Sewage Water Monitoring at Kandla STP (4th Week)

Date of Sampling	24.10.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			DPA STP I/L	DPA STP O/L	
1	pH	-	7.41	7.29	6.5 - 8.5
2	Total Suspended Solids	mg/l	164.2	58.7	100
3	Residual Chlorine	mg/l	-	<0.5	-
4	COD	mg/l	171.7	30.3	100
5	BOD @ 27 °C	mg/l	43	10	30
Aeration Tank					
6	MLSS	mg/l	20.0		
7	MLVSS	%	89.0		

Table 26: Sewage Water Monitoring at Gopalpuri STP (1st Week)

Date of Sampling	03.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			DPA STP I/L	DPA STP O/L	
1	pH	-	7.47	7.31	6.5 - 8.5
2	Total Suspended Solids	mg/l	121.2	61	100
3	Residual Chlorine	mg/l	-	<0.5	-
4	COD	mg/l	111.1	60.6	100
5	BOD @ 27 °C	mg/l	32	13	30
Aeration Tank					
6	MLSS	mg/l	22.0		
7	MLVSS	%	97.16		

Table 27: Sewage Water Monitoring at Gopalpuri STP (2nd Week)

Date of Sampling	10.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			DPA STP I/L	DPA STP O/L	
1	pH	-	7.35	7.27	6.5 - 8.5
2	Total Suspended Solids	mg/l	189	67.9	100
3	Residual Chlorine	mg/l			-
4	COD	mg/l	141.4	60.6	100
5	BOD @ 27 °C	mg/l	37	15	30
Aeration Tank					
6	MLSS	mg/l	16.0		
7	MLVSS	%	89.6		

Table 28: Sewage Water Monitoring at Gopalpuri STP (3rd Week)

Date of Sampling	17.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			Gopalpuri STP I/L	Gopalpuri STP O/L	
1	pH	-	7.41	7.36	6.5 - 8.5
2	Total Suspended Solids	mg/l	127	52.6	100
3	Residual Chlorine	mg/l			-
4	COD	mg/l	90.9	40.4	100
5	BOD @ 27 °C	mg/l	23	11	30
Aeration Tank					
6	MLSS	mg/l	08.0		
7	MLVSS	%	98.0		

Table 29: Sewage Water Monitoring at Gopalpuri STP (4th Week)

Date of Sampling	24.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			Gopalpuri STP I/L	Gopalpuri STP O/L	
1	pH	-	7.48	7.28	6.5 - 8.5
2	Total Suspended Solids	mg/l	110.2	42.1	100
3	Residual Chlorine	mg/l	-	<0.5	-
4	COD	mg/l	78	40	100
5	BOD @ 27 °C	mg/l	24.0	12.0	30
Aeration Tank					
6	MLSS	mg/l	18.0		
7	MLVSS	%	90.0		

Table 30: Sewage Water Monitoring at Vadinar STP (1st Week)

Date of Sampling	03.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			Vadinar STP I/L	Vadinar STP O/L	
1	pH	-	7.35	7.25	6.5 - 8.5
2	Total Suspended Solids	mg/l	74.9	39.5	100
3	Residual Chlorine	mg/	-	<0.5	-
4	COD	mg/l	101	40.4	100
5	BOD @ 27 °C	mg/l	26.0	10.0	30

Table 31: Sewage Water Monitoring at Vadinar STP (2nd Week)

Date of Sampling	10.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			Vadinar STP I/L	Vadinar STP O/L	
1	pH	-	7.38	7.21	6.5 - 8.5
2	Total Suspended Solids	mg/l	69.6	40.3	100
3	Residual Chlorine	mg/l	-	<0.5	-
4	COD	mg/l	131.3	50.5	100
5	BOD @ 27 °C	mg/l	32.0	7.0	30

Table 32: Sewage Water Monitoring at Vadinar STP (3rd Week)

Date of Sampling	17.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			Vadinar STP I/L	Vadinar O/L	
1	pH	-	7.51	7.42	6.5 - 8.5
2	Total Suspended Solids	mg/l	38.6	16.9	100
3	Residual Chlorine	mg/l	-	<0.5	-
4	COD	mg/l	80.8	20.2	100
5	BOD @ 27 °C	mg/l	24.0	12.0	30

Table 33: Sewage Water Monitoring at Vadinar STP (4th Week)

Date of Sampling	24.11.2022
-------------------------	------------

Sr. No.	Parameters	Unit	Results		GPCB Prescribed Limit
			Vadinar STP I/L	Vadinar STP O/L	
1	pH	-	7.61	7.42	6.5 - 8.5
2	Total Suspended Solids	mg/l	76.9	33.3	100
3	Residual Chlorine	mg/l	-	<0.5	-
4	COD	mg/l	131.3	20.2	100
5	BOD @ 27 °C	mg/l	20.0	8.0	30

Table No. 34. General Standards for discharge of Environmental Pollutant Part-A

Sr. No.	Parameter	Inland Surface Water	Land Irrigation	Marine Coastal Areas
1.	pH	5.5-9.0	5.5-9.0	5.5-9.0
2.	Total Suspended Solids (mg/l)	100	200	100
3.	Residual Chlorine (mg/l)	1.0	-	1.0
4.	BOD (mg/l)	30	100	100
5.	COD (mg/l)	250	-	250

Sources:-CPCB**7.3 Results & Discussion**

The STP Sample carried out to evaluate the efficiency and performance of the wastewater treatment plant at Gopalpuri, Kandla and Vadinar STP. The performance of these plants is an essential parameter to monitor because the treated sewage water is discharged for irrigation purposes and discharge into marine. Wastewater samples were collected from different unit operations of the plant i.e, the inlet, aeration tank and the final treated outlet. These samples were analyzed for various physico-chemical characteristics such as pH, TSS, Residual Chlorine, COD, BOD, MLSS and MLVS.

The final treated outlet observed pH values were within the allowed range at STP Gopalpuri, STP Kandla & STP Vadinar ranged from 7.22 -7.35, 7.29-7.42 & 7.21-7.42 respectively. The wastewater treatment makes it suitable for irrigation. These values are below the allowed limit of the GPCB.

- The final treated outlet observed Total suspended solid values at Gopalpuri, DPA Kandla & Vadinar ranged from 27.10-67.90 mg/l, 22.90-58.70 mg/l & 16.60-40.30 mg/l respectively. These values are below the allowed limit of the GPCB.
- The final treated outlet observed Residual Chlorine values were <0.5 at Gopalpuri, DPA Kandla & Vadinar. These values are below the allowed limit of the CPCB.
- The final treated outlet observed COD values were at Gopalpuri, DPA Kandla & Vadinar ranged from 40.40-60.60 mg/l, 30.30-50.50 mg/l & 20.20-50.50 mg/l respectively. These values are below the allowed limit of the CPCB.

- The main focus of wastewater treatment plants is supposed to reduce the BOD in the effluent discharged to natural waters. Wastewater treatment plants are designed to function as bacteria farms, where bacteria are fed oxygen and organic waste. The final treated outlet observed BOD values were at Gopalpuri, DPA Kandla & Vadinar ranged from 12.0-16.0 mg/l, 10.0-14.0 mg/l & 7.0-12.0 mg/l respectively. These values are below the allowed limit of the GPCB.

7.4 Conclusions:

All parameters for STP outlet are within limit prescribed by CPCB. After the final treatment, it is found that the treated water is satisfactory.

CHAPTER-8

MARINE WATER MONITORING

8.0 Marine Water Monitoring

Marine Water Quality

The Forty Second Amendment to the Constitution in 1976 underscored the importance of ‘green thinking’. Article 48A enjoins the state to protect and improve the environment and safeguard the forests and wildlife in the country. Further, Article 51A (g) states that the “fundamental duty of every citizen is to protect and improve the natural environment including forests, lakes, rivers and wildlife and to have compassion for living creatures”.

Policy Statement for Abatement of Pollution (1992) has suggested developing relevant legislation and regulation, fiscal incentives, voluntary agreements and educational programs and information campaigns. It emphasizes the need for integration by incorporating environmental considerations into decision making at all levels by adopting frameworks namely, pollution prevention at source, application of best practicable solution, ensure polluter pays for control of pollution, focus on heavily polluted areas and river stretches and involve public in decision-making. The National Conservation Strategy and Policy Statement on Environment and Development, (1992) aimed at “integrating environmental concerns with developmental imperatives to meet the challenges by redirecting the thrust of our developmental process so that the basic needs of our people could be fulfilled by making judicious and sustainable use of natural resources.” The priorities mentioned in this policy document include the sustainable use of land and water resources, prevention and control of pollution and preservation of biodiversity.

The National Water Policy, (2002) contains provisions for developing, conserving, sustainable utilizing and managing this important water resources and need to be governed by national perspectives.

Sampling Stations

The monitoring of marine environment for the study of biological and ecological parameters was carried out on 01st & 02nd November-2022 in harbor regions of DPA & Vadinar during Neap tide period of New moon phase of Lunar Cycle. The monitoring of marine environment for the study of biological and ecological parameters was repeated again on 8th & 9th November-2022 in harbor regions of DPA & Vadinar during Spring tide period first quarter of Lunar Cycle.

Plankton samples from sub surface layer was collected both during high tide period and low tide period from 3 water quality monitoring stations of DPA harbor area and two stations in Nakti creek and one station in Khorī creek. The same sampling schedule was repeated during consecutive spring tide and neap tide in same month. Plankton samples from sub surface layer was collected both during high tide period and low tide period from 1 water quality monitoring stations near Vadinar jetty area during spring tide and neap tide in this month. Collected water samples were processed for estimation

of Chlorophyll- a, Pheophytin- a, qualitative & quantitative evaluation of phytoplankton, qualitative & quantitative evaluation zooplanktons (density and their population).

Sampling Locations

Offshore monitoring requirement	Number of locations
Offshore Installations	3 in Kandla creek 2 in Nakti creek 1 in Khori creek 1 near Vadinar Jetty 1 near 1 st SBM
Total Number of locations	8

8.1 Marine Water Quality and Results

Marine water quality of marine waters of Deendayal Port Harbor waters, Khori & Nakti Creeks and two locations of Vadinar are monitored for various physico-chemical parameters during spring and neap tide of each month. The results of marine water quality from table no 35 to 42. During low tide DPA-6 Nakti-II location monitoring was not possible due to non-availability of marine water.

Table 35: Marine Water Quality Monitoring Parameters for Location Near DPA Colony

Sr. No.	Parameters	Unit	Kandla Creek Near DPA Colony (1)			
			23°0'58"N 70°13'22."E			
			Spring Tide		Neap Tide	
	Tide		High Tide	Low Tide	High Tide	Low Tide
1	pH	-	7.61	7.58	7.55	7.46
2	Color	-	Agreeable	Agreeable	Agreeable	Agreeable
3	Odor	-	Agreeable	Agreeable	Agreeable	Agreeable
4	Salinity	‰	19.0	19.9	20.4	19.0
5	Turbidity	NTU	38	35	42	35
6	Total Dissolved Solids	mg/l	34152.0	30868.0	30941.0	31974.0
7	Total Suspended Solids	mg/l	639.6	600.6	646.4	595.6
8	Total Solids	mg/l	34791.6	31468.6	31587.4	32569.6
9	DO	mg/l	5.8	5.6	5.7	5.5
10	COD	mg/l	88.0	79.0	82.0	86.0
11	BOD	mg/l	BQL	BQL	BQL	BQL
12	Silica	mg/l	1.06	0.82	0.99	0.91
13	Phosphate	mg/l	0.48	0.31	0.09	0.04
14	Sulphate	mg/l	3580	3407	3708.0	3658
15	Nitrate	mg/l	4.70	0.50	0.75	0.42
16	Nitrite	mg/l	<0.05	<0.05	BQL	BQL
17	Calcium	mg/l	521.04	440.88	561.12	480.96
18	Magnesium	mg/l	1773.9	1749.6	1701	1773.9
19	Sodium	mg/l	8011.0	8399.0	8396.0	8699.0
20	Potassium	mg/l	299.0	385.0	391.0	395.0
21	Iron	mg/l	BQL	BQL	0.88	0.57
22	Chromium	mg/l	BQL	BQL	BQL	BQL
23	Copper	mg/l	BQL	BQL	BQL	BQL
24	Arsenic	mg/l	BQL	BQL	BQL	BQL
25	Cadmium	mg/l	BQL	BQL	BQL	BQL
26	Mercury	mg/l	BQL	BQL	BQL	BQL
27	Lead	mg/l	BQL	BQL	BQL	BQL
28	Zinc	mg/l	BQL	BQL	BQL	BQL

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Cu-0.1 mg/l, As-0.1mg/l, Hg-0.01 mg/l, Zinc-0.1 mg/l).

Table 36: Marine Water Quality Monitoring Parameters for Location Near Passenger Jetty One at Kandla

Sr. No.	Parameters	Unit	Near passenger Jetty One (2)			
			23° 0'18 "N 70°13'31"E			
			Spring Tide		Neap Tide	
			High Tide	Low Tide	High Tide	Low Tide
1	pH	-	7.43	7.28	7.33	7.41
2	Color	-	Agreeable	Agreeable	Agreeable	Agreeable
3	Odor	-	Agreeable	Agreeable	Agreeable	Agreeable
4	Salinity	‰	20.8	20.4	19.9	18.6
5	Turbidity	NTU	43	48	36	41
6	Total Dissolved Solids	mg/l	35468.0	37102.0	34662.0	33398.0
7	Total Suspended Solids	mg/l	679.7	665.5	703.7	663.8
8	Total Solids	mg/l	36147.7	37767.5	35365.7	34061.8
9	DO	mg/l	5.9	6.2	5.6	5.2
10	COD	mg/l	86.0	94.0	90.0	92.0
11	BOD	mg/l	BQL	BQL	BQL	BQL
12	Silica	mg/l	1.26	0.86	1.33	0.85
13	Phosphate	mg/l	0.29	0.13	0.33	0.19
14	Sulphate	mg/l	3571	3470	4072	3407
15	Nitrate	mg/l	3.40	2.70	1.17	4.36
16	Nitrite	mg/l	<0.05	<0.05	BQL	BQL
17	Calcium	mg/l	561.12	601.20	601.2	521.04
18	Magnesium	mg/l	1701	1603.8	1749.6	1701
19	Sodium	mg/l	9142.0	9345.0	9247.0	9219.0
20	Potassium	mg/l	370.0	385.0	370.0	380.0
21	Iron	mg/l	0.47	BQL	1.76	0.30
22	Chromium	mg/l	BQL	BQL	BQL	BQL
23	Copper	mg/l	BQL	BQL	BQL	BQL
24	Arsenic	mg/l	BQL	BQL	BQL	BQL
25	Cadmium	mg/l	BQL	BQL	BQL	BQL
26	Mercury	mg/l	BQL	BQL	BQL	BQL
27	Lead	mg/l	BQL	BQL	BQL	BQL
28	Zinc	mg/l	BQL	BQL	BQL	BQL

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Nitrite: 0.05mg/l Cu-0.1 mg/l, As-0.1mg/l, Hg-0.01 mg/l, Zinc-0.1 mg/l).

Table 37: Marine Water Quality Monitoring Parameters for location Near Coal Berth

Sr. No.	Parameters	Unit	Near Coal Berth			
			22°59'12"N 70°13'40"E			
			Spring Tide		Neap Tide	
			High Tide	Low Tide	High Tide	Low Tide
1	pH	-	7.37	7.51	7.53	7.25
2	Color	-	Agreeable	Agreeable	Agreeable	Agreeable
3	Odor	-	Agreeable	Agreeable	Agreeable	Agreeable
4	Salinity	‰	18.6	18.1	19.5	20.8
5	Turbidity	NTU	33	42	38	45
6	Total Dissolved Solids	mg/l	39222.0	37586.0	37123.0	36668.0
7	Total Suspended Solids	mg/l	540.2	638.4	620.6	580.2
8	Total Solids	mg/l	39762.2	38224.4	37743.6	37248.2
9	DO	mg/l	7.3	6.4	7.1	6.5
10	COD	mg/l	81.0	874.0	88.0	84.0
11	BOD	mg/l	BQL	BQL	BQL	BQL
12	Silica	mg/l	0.56	0.98	0.69	1.76
13	Phosphate	mg/l	0.06	0.56	0.12	0.61
14	Sulphate	mg/l	4222	3458	2981	3758
15	Nitrate	mg/l	2.20	4.60	2.68	4.70
16	Nitrite	mg/l	<0.05	<0.05	BQL	BQL
17	Calcium	mg/l	480.96	641.28	641.28	721.44
18	Magnesium	mg/l	1628.1	1628.1	1676.7	1603.8
19	Sodium	mg/l	8346.0	9380.0	9245.0	9814.0
20	Potassium	mg/l	391.0	300.0	392.0	384.0
21	Iron	mg/l	BQL	BQL	BQL	1.34
22	Chromium	mg/l	BQL	BQL	BQL	BQL
23	Copper	mg/l	BQL	BQL	BQL	BQL
24	Arsenic	mg/l	BQL	BQL	BQL	BQL
25	Cadmium	mg/l	BQL	BQL	BQL	BQL
26	Mercury	mg/l	BQL	BQL	BQL	BQL
27	Lead	mg/l	BQL	BQL	BQL	BQL
28	Zinc	mg/l	BQL	BQL	BQL	BQL

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Cu-0.1 mg/l, As-0.1mg/l, Hg-0.01 mg/l, Zinc-0.1 mg/l).

Table 38: Marine Water Quality Monitoring Parameters for location Khori creek at Kandla

Sr. No.	Parameters	Unit	Khori creek			
			Near 15/16 Berth			
			Spring Tide		Neap Tide	
			High Tide	Low Tide	High Tide	Low Tide
1	pH	-	7.48	7.27	7.34	7.21
2	Color	-	Agreeable	Agreeable	Agreeable	Agreeable
3	Odor	-	Agreeable	Agreeable	Agreeable	Agreeable
4	Salinity	‰	20.4	19.5	18.6	17.7
5	Turbidity	NTU	35	31	43	39
6	Total Dissolved Solids	mg/l	32557.0	34294.0	30473.0	33329.0
7	Total Suspended Solids	mg/l	641.2	616.3	594.7	731.2
8	Total Solids	mg/l	33198.2	34910.3	31067.7	34060.2
9	DO	mg/l	7.6	6.3	7.3	6.8
10	COD	mg/l	85.0	96.0	92.0	96.0
11	BOD	mg/l	BQL	BQL	BQL	BQL
12	Silica	mg/l	0.78	1.04	1.39	1.18
13	Phosphate	mg/l	0.44	0.67	0.35	0.42
14	Sulphate	mg/l	4047	3646	3157	3170
15	Nitrate	mg/l	3.70	1.10	1.34	5.20
16	Nitrite	mg/l	<0.05	<0.05	BQL	BQL
17	Calcium	mg/l	561.12	480.96	480.96	561.12
18	Magnesium	mg/l	1725.3	1676.7	1701	1628.1
19	Sodium	mg/l	9112.0	8436.0	7966.0	8696.0
20	Potassium	mg/l	299.0	385.0	382.0	377.0
21	Iron	mg/l	0.44	BQL	0.17	0.31
22	Chromium	mg/l	BQL	BQL	BQL	BQL
23	Copper	mg/l	BQL	BQL	BQL	0.02
24	Arsenic	mg/l	BQL	BQL	BQL	BQL
25	Cadmium	mg/l	BQL	BQL	BQL	BQL
26	Mercury	mg/l	BQL	BQL	BQL	BQL
27	Lead	mg/l	BQL	BQL	BQL	BQL
28	Zinc	mg/l	BQL	BQL	BQL	BQL

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Cu-0.1 mg/l, As-0.1mg/l, Hg-0.01 mg/l, Zinc-0.1 mg/l).

Table 39: Marine Water Quality Monitoring Parameters for location Nakti Creek near Tuna Port

Sr. No.	Parameters	Unit	Nakti Creek Near Tuna Port			
			22°57'49."N 70° 7'0.67"E			
			Spring Tide		Neap Tide	
	Tide		High Tide	Low Tide	High Tide	Low Tide
1	pH	-	7.41	7.36	7.48	7.23
2	Color	-	Agreeable	Agreeable	Agreeable	Agreeable
3	Odor	-	Agreeable	Agreeable	Agreeable	Agreeable
4	Salinity	‰	19.0	18.6	19.0	19.5
5	Turbidity	NTU	45	36	40	42
6	Total Dissolved Solids	mg/l	30214.0	28996.0	31047.0	31957.0
7	Total Suspended Solids	mg/l	642.7	526.2	682.5	606.8
8	Total Solids	mg/l	30856.7	29522.2	31729.5	32563.8
9	DO	mg/l	8.1	7.5	6.4	7.2
10	COD	mg/l	94.0	112.0	98.0	100.0
11	BOD	mg/l	BQL	BQL	BQL	BQL
12	Silica	mg/l	1.12	1.20	1.42	1.22
13	Phosphate	mg/l	0.71	0.37	0.46	0.12
14	Sulphate	mg/l	4172	3846	3445	3433
15	Nitrate	mg/l	1.50	1.70	5.12	1.69
16	Nitrite	mg/l	<0.05	<0.05	BQL	BQL
17	Calcium	mg/l	440.88	641.28	601.2	521.04
18	Magnesium	mg/l	1725.3	1555.2	1701	1773.9
19	Sodium	mg/l	8639.0	9143.0	8655.0	7939.0
20	Potassium	mg/l	395.0	386.0	384.0	386.0
21	Iron	mg/l	BQL	0.33	0.34	0.18
22	Chromium	mg/l	BQL	BQL	BQL	BQL
23	Copper	mg/l	BQL	BQL	BQL	BQL
24	Arsenic	mg/l	BQL	BQL	BQL	BQL
25	Cadmium	mg/l	BQL	BQL	BQL	BQL
26	Mercury	mg/l	BQL	BQL	BQL	BQL
27	Lead	mg/l	BQL	BQL	BQL	BQL
28	Zinc	mg/l	BQL	BQL	BQL	BQL

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l,BOD-2.0 mg/l,Cu-0.1 mg/l, As-0.1mg/l, Hg-0.01 mg/l,Zinc-0.1 mg/l).

Table 40: Marine Water Quality Monitoring Parameters for location Nakti Creek Near NH-8A at Kandla

Sr. No.	Parameters	Unit	Nakti Creek Near NH-8A			
			23° 02'01"N 70° 09'31"E			
			Spring Tide		Neap Tide	
			High Tide	Low Tide	High Tide	Low Tide
1	pH	-	7.45	Sampling not possible during Low Tide	7.45	Sampling not possible during Low Tide
2	Color	-	Agreeable		Agreeable	
3	Odor	-	Agreeable		Agreeable	
4	Salinity	‰	19.9		20.8	
5	Turbidity	NTU	45		44	
6	Total Dissolved Solids	mg/l	30288.0		32796.0	
7	Total Suspended Solids	mg/l	529.6		595.7	
8	Total Solids	mg/l	30817.6		33391.7	
9	DO	mg/l	7.4		6.9	
10	COD	mg/l	118.0		110.0	
11	BOD	mg/l	BQL		BQL	
12	Silica	mg/l	1.02		0.16	
13	Phosphate	mg/l	0.75		0.46	
14	Sulphate	mg/l	4109		4961	
15	Nitrate	mg/l	2.70		3.52	
16	Nitrite	mg/l	<0.05		BQL	
17	Calcium	mg/l	681.36		641.28	
18	Magnesium	mg/l	1506.6		1628.1	
19	Sodium	mg/l	9280.0		8528.0	
20	Potassium	mg/l	427.0		427.0	
21	Iron	mg/l	BQL		0.54	
22	Chromium	mg/l	BQL		BQL	
23	Copper	mg/l	BQL		BQL	
24	Arsenic	mg/l	BQL		BQL	
25	Cadmium	mg/l	BQL		0.01	
26	Mercury	mg/l	BQL		BQL	
27	Lead	mg/l	BQL		BQL	
28	Zinc	mg/l	BQL		BQL	

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Cu-0.1 mg/l, As-0.1 mg/l, Hg-0.01 mg/l, Zinc-0.1 mg/l).

Table 41: Marine Water Quality Monitoring Parameters for locations Nr. Vadinar Jetty

Sr. No.	Parameters	Unit	Nr.Vadinar Jetty			
			22°26'25.26"N 69°40'20.41"E			
			Spring Tide		Neap Tide	
			High Tide	Low Tide	High Tide	Low Tide
1	pH	-	7.43	7.26	7.36	7.29
2	Color	-	Agreeable	Agreeable	Agreeable	Agreeable
3	Odor	-	Agreeable	Agreeable	Agreeable	Agreeable
4	Salinity	‰	20.4	20.8	19.0	19.9
5	Turbidity	NTU	39	42	38	42
6	Total Dissolved Solids	mg/l	35265.0	37685.0	36325.0	36681.0
7	Total Suspended Solids	mg/l	585.3	590.8	681.4	657.6
8	Total Solids	mg/l	35850.3	38275.8	37006.4	37338.6
9	DO	mg/l	5.7	5.4	6.3	5.8
10	COD	mg/l	87.0	89.0	96.0	92.0
11	BOD	mg/l	BQL	BQL	BQL	BQL
12	Silica	mg/l	0.55	0.45	0.36	0.28
13	Phosphate	mg/l	0.18	0.42	0.33	0.19
14	Sulphate	mg/l	3608	3558	3683	3645
15	Nitrate	mg/l	2.35	1.09	1.00	2.43
16	Nitrite	mg/l	<0.05	<0.05	BQL	BQL
17	Calcium	mg/l	480.96	601.20	521.04	480.96
18	Magnesium	mg/l	1603.8	1652.4	1676.7	1749.6
19	Sodium	mg/l	9448.0	7368.0	7810.0	8912.0
20	Potassium	mg/l	371.0	354.0	452.0	456.0
21	Iron	mg/l	BQL	BQL	0.31	BQL
22	Chromium	mg/l	BQL	BQL	BQL	BQL
23	Copper	mg/l	BQL	BQL	BQL	BQL
24	Arsenic	mg/l	BQL	BQL	BQL	BQL
25	Cadmium	mg/l	BQL	BQL	BQL	BQL
26	Mercury	mg/l	BQL	BQL	BQL	BQL
27	Lead	mg/l	BQL	BQL	BQL	BQL
28	Zinc	mg/l	0.29	BQL	0.77	0.35

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Cu-0.1 mg/l, As-0.1mg/l, Hg-0.01 mg/l, Zinc-0.1 mg/l).

Table 42: Marine Water Quality Monitoring Parameters for locations Nr. Vadinar SPM

Sr. No.	Parameters	Unit	Nr. Vadinar SPM			
			22°30'56.15"N 69°42'12.07"E			
			Spring Tide		Neap Tide	
			High Tide	Low Tide	High Tide	Low Tide
1	pH	-	7.37	7.22	7.41	7.35
2	Color	-	Agreeable	Agreeable	Agreeable	Agreeable
3	Odor	-	Agreeable	Agreeable	Agreeable	Agreeable
4	Salinity	‰	19.0	17.7	19.5	18.6
5	Turbidity	NTU	37	40	37	39
6	Total Dissolved Solids	mg/l	39961.0	39198.0	42642.0	40730.0
7	Total Suspended Solids	mg/l	545.5	493.6	714.3	657.9
8	Total Solids	mg/l	40506.5	39691.6	43356.3	41387.9
9	DO	mg/l	6.1	5.5	5.6	6.1
10	COD	mg/l	95.0	98.0	96.0	94.0
11	BOD	mg/l	BQL	BQL	BQL	BQL
12	Silica	mg/l	0.47	0.37	0.34	0.30
13	Phosphate	mg/l	1.08	0.19	0.46	0.28
14	Sulphate	mg/l	3495	3796	3745	4008
15	Nitrate	mg/l	3.86	2.18	4.95	2.10
16	Nitrite	mg/l	<0.05	<0.05	BQL	BQL
17	Calcium	mg/l	561.12	400.80	681.36	641.28
18	Magnesium	mg/l	1628.1	1676.7	1555.2	1628.1
19	Sodium	mg/l	8473.0	10386.0	9131.0	8526.0
20	Potassium	mg/l	452.0	406.0	413.0	441.0
21	Iron	mg/l	BQL	BQL	0.24	BQL
22	Chromium	mg/l	BQL	BQL	BQL	BQL
23	Copper	mg/l	BQL	BQL	BQL	BQL
24	Arsenic	mg/l	BQL	BQL	BQL	BQL
25	Cadmium	mg/l	BQL	BQL	BQL	BQL
26	Mercury	mg/l	BQL	BQL	BQL	BQL
27	Lead	mg/l	BQL	BQL	BQL	BQL
28	Zinc	mg/l	0.28	BQL	0.40	BQL

BQL- Below Quantification Limit, (Nitrite - 0.05 mg/l, BOD-2.0 mg/l, Cu-0.1 mg/l, As-0.1mg/l, Hg-0.01 mg/l, Zinc-0.1 mg/l)

8.2 Results & Discussion for Marine water samples

Marine water quality of Deendayal Port Harbor waters, Khorī and Nakti Creeks and two locations of Vadinar are monitored for various physico-chemical parameters during spring and neap tide of each month. The Heavy metal analyzed and mostly found below quantification limit.

pH

During spring tide the pH values was ranged from 7.27-7.61 at DPA Kandla and 7.22-7.43 at Vadinar while during Neap Tide pH values was ranged from 7.21-7.55 at DPA Kandla and 7.29-7.41 at Vadinar.

Color and Odor

All marine samples for Odor and Color were found agreeable at all sampling locations.

Turbidity

During spring tide the Turbidity values was ranged from 31-48 NTU at DPA Kandla and 37-42 NTU at Vadinar while during Neap Tide Turbidity values was ranged from 35-45 NTU at DPA Kandla and 37-42 NTU at Vadinar. Turbidity is the amount of particulate matter that is suspended in water. Turbidity measures the scattering effect that suspended solids have on light: the higher the intensity of scattered light, the higher the turbidity (Yap et al, 2011). Materials that cause water to be turbid include clay, silt, finely divided organic and inorganic matter, soluble colored organic compounds, plankton and microscopic organisms (Lawler, 2004). The turbidity affects the amount of light penetrating to the plants for photosynthesis.

Total Dissolved Solids (TDS)

TDS values in the studied area during Spring Tide varied between 28966- 39222 mg/l at DPA Kandla and 35265-39961 mg/l at Vadinar while during Neap Tide TDS values was varied 30473-37123 mg/l at DPA Kandla and 36325-42642 mg/l at Near Vadinar.

Calcium

Calcium value in the studied area during Spring Tide varied between 440.9-681.4 mg/l at DPA Kandla and 400.8-601.2 mg/l at Vadinar while during Neap Tide calcium values between 481.0-721.4 mg/l at DPA Kandla and 481.0-681.4 mg/l at Vadinar.

Magnesium

Magnesium value in the studied area during Spring Tide varied between 1506.6-1773.9 mg/l at DPA Kandla and 1603.8-1676.7 mg/l at Vadinar while during Neap Tide magnesium values between 1603.80-173.9 mg/l at DPA Kandla and 1555.2 -1749.60 at Vadinar. Calcium and magnesium both play an important role in antagonizing the toxic effects of various ions and neutralizing the excess acid produced (Narayan R. et. al., 2007)

Nitrate

Nitrate value in the studied area during Spring Tide varied between 0.5-4.7 mg/l at DPA Kandla and 1.09-3.86 mg/l at Vadinar while during Neap Tide Nitrate values between 0.42-5.2 mg/l at DPA Kandla and 1.0-4.95 at Vadinar.

The variations were observed due to variation in phytoplankton excretion, oxidation of ammonia, reduction of nitrate and by recycling of nitrogen and bacterial decomposition of planktonic detritus (Asha and Diwakar, 2007).

Iron

Iron values in the studied area during Spring Tide ranged from 0.33-0.47 mg/l at DPA Kandla and at Vadinar were BQL (<0.10) while during Neap Tide Iron values ranged from 0.17-1.76 mg/l at DPA Kandla and 0.24-0.31 mg/l at Vadinar.

Sulphates

Sulphate values in the studied area during Spring Tide ranged from 3407-4222 mg/l at DPA Kandla and 3495-3796 mg/l at Vadinar while during Neap Tide the Sulphate values was varied 2981-4961 mg/l at DPA Kandla and 3645-4008mg/l at Vadinar.

Salinity

Salinity values in the studied area during Spring Tide varied ranged 18.11 to 20.82 ‰ at DPA Kandla and 17.65 to 20.82 ‰ at Vadinar while during Neap Tide the Salinity values was varied 17.65 to 20.82 ‰ at DPA Kandla and 18.55 to 19.92 ‰ at Vadinar.

Sodium and Potassium Salts

During Spring Tide the Sodium values ranged from 8011-9380 mg/l at DPA Kandla & 7368-10386 mg/l at Vadinar and Potassium salts ranged from 299-427 mg/l at DPA Kandla & 354-452 mg/l at Vadinar while during Neap Tide the Sodium values was ranges from 7939-

9814 mg/l at DPA Kandla & 7810-9131 mg/l at Vadinar and Potassium salts ranged from 370-427 mg/l at DPA Kandla & 413-456 mg/l at Vadinar.

DO

The DO refers to the amount of oxygen dissolved in the water and it is particularly important in limnology {(aquatic ecology) (Weiss 1970)}. The fate and behavior of DO is of critical importance to marine organisms in determining the severity of adverse impacts (Best et al. 2007). The major factor controlling dissolved oxygen concentration is biological activity: photosynthesis producing oxygen while respiration and nitrification consume oxygen (Best et al. 2007). From the studied samples, DO in marine water during Spring Tide was found in ranges from 5.6-8.1 mg/l at DPA Kandla and 5.4-6.1 mg/l at Vadinar while during Neap Tide 5.2-7.3 mg/l at DPA Kandla and 5.6-6.3 mg/l at Vadinar.

BOD

BOD in marine water at all sampling location in the studied samples were found BQL (<2.0 mg/l).

Heavy Metals in Marine Water

In the present study period marine water samples were analyzed for Cr, Cu, Cd, As, Hg, Pb and Zn. Maximum heavy metals parameters were well Below the Quantification limits.

9.3 Conclusion

In the present study period marine water samples were analyzed and found inline as per Primary Water Quality criteria for class-IV WATERS (For Harbour Waters).

CHAPTER-9

MARINE SEDIMENT MONITORING

9.0 Marine Sediments

The deep-sea ocean floor is made up of sediment. This sediment is composed of tiny particles such as fine sand, silt, clay, or animal skeletons that have settled on the ocean bottom. Over long periods of time, some of these particles become compressed and form stratified layers. Scientists that study these layers look at particle size, particle composition, and origin to help them create historical records of the deep ocean floor. This process is called weathering. Weathering can be either mechanical or chemical. Mechanical weathering can occur as ice, wind, or water wears away the rock's surface. Chemical weathering can occur as rocks are dissolved by a chemical such as acid rain. The particles created as a result of weathering are called terrigenous sediments. These particles are transported to the ocean by wind and by rivers and streams. Once the particles enter the ocean, they are dispersed by waves, currents, and tides. The heaviest and largest particles that reach the oceans, such as sand, settle very quickly to the bottom as a result of gravity. Sand is deposited near the coast whereas the smaller silt and clay particles are transported farther distances offshore before they settle to the bottom. Sediments are an important component of aquatic ecosystems because they provide nutrients and habitat for aquatic organisms (Benhamed et al. 2016). However, human activities result in accumulation of toxic substances such as heavy metals in marine sediments. Heavy metals are well-known environmental pollutants due to their toxicity, persistence in the environment, and bioaccumulation. Metals affect the ecosystem because they are not removed from water by self-purification, but accumulate in sediments and enter the food chain (Astakhov et al. 2015).

Sediment samples were collected with Van Veen Grab from the six locations in Kandla Port Waters and two locations in Vadinar Port. Benthic surface grab samplers look like giant metal jaws. They dig into the bottom and take a bite of the sediment. These samplers are good for collecting softer, sandy or silty sediments that do not contain rocks. A box corer is a cross between a surface sampler and a sediment corer. It is a special device that is used to collect an undisturbed sample of the very top surface layers and the sediment underneath. Samples were collected and preserved in silver foil in ice box to prevent the contamination/decaying of the samples.

10.1 Results

The Sediment Quality results are given in below from table no. 43 & 44.

Table 43: Results of Analysis of Sediment of Kandla & Vadinar Port (Neap Tide)

Sr. No.	Parameters	Unit	DPA – 1	DPA - 2	DPA - 3	DPA - 4	DPA - 5	Jetty	SPM
1	Texture	-	Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam
2	Organic Matter	mg/kg	1.32	0.6	0.1	0.1	0.16	1.14	1.59
3	Organic Carbon	mg/kg	0.76	0.35	0.07	0.06	0.09	0.66	0.91
4	Inorganic Phosphate	mg/kg	89.00	90.00	101.00	92.00	100.00	90.00	100.00
5	Moisture	%	3.90	2.37	4.12	3.00	4.10	3.40	4.00
6	Aluminum	mg/kg	ND	ND	ND	ND	ND	ND	ND
7	Silica	mg/kg	7.30	7.68	8.90	9.30	9.10	8.90	9.60
8	Phosphate	mg/kg	5.20	4.99	4.09	5.25	9.00	3.28	10.40
9	Sulphate	mg/kg	759.00	849.00	555.00	496.00	768.00	732.00	496.00
10	Nitrite	mg/kg	0.11	0.11	0.10	0.10	0.12	0.10	0.11
11	Nitrate	mg/kg	BQL	BQL	BQL	BQL	BQL	BQL	BQL
12	Calcium	mg/kg	2765.00	1523.00	861.00	961.00	981.00	1162.00	2485.00
13	Magnesium	mg/kg	1372.00	1300.00	1020.00	1263.00	1032.00	1089.00	2065.00
14	Sodium	mg/kg	2410.0	2760.0	2644.0	2940.0	2722.0	1394.00	1082.00
15	Potassium	mg/kg	404.00	459.00	390.00	510.00	447.00	811.0	560.0
16	Chromium	mg/kg	61.30	71.90	66.00	53.30	56.40	42.80	49.70
17	Nickel	mg/kg	26.80	31.70	29.00	23.00	24.10	13.80	29.20
18	Copper	mg/kg	17.40	19.40	17.80	15.50	15.80	13.80	47.10
19	Zinc	mg/kg	43.40	55.80	49.80	41.80	46.00	32.00	64.30
20	Cadmium	mg/kg	BQL	BQL	BQL	BQL	BQL	BQL	BQL
21	Lead	mg/kg	5.20	6.20	5.70	9.80	8.40	12.00	BQL
22	Mercury	mg/kg	BQL	BQL	BQL	BQL	BQL	BQL	BQL
23	Arsenic	mg/kg	BQL	BQL	BQL	BQL	BQL	BQL	BQL

*ND - Not Detected, BQL: Below Quantification Limit (NO3:10.0mg/kg, Cd: 1.0mg/kg, Hg: 1.0mg/kg, As: 1.0mg/kg).

Table 44 : Results of Analysis of Sediment of Kandla & Vadinar Port (Spring Tide)

Sr. No.	Parameters	Unit	DPA – 1	DPA - 2	DPA - 3	DPA - 4	DPA - 5	Jetty	SPM
1	Texture	-	Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam	Sandy Loam
2	Organic Matter	mg/kg	0.91	0.50	1.52	0.37	0.27	1.45	1.68
3	Organic Carbon	mg/kg	0.52	0.29	0.87	0.21	0.15	0.83	0.97
4	Inorganic Phosphate	mg/kg	98.00	90.00	80.00	78.00	100.00	88.00	90.00
5	Moisture	%	17.00	8.70	15.00	6.60	4.80	14.24	13.14
6	Aluminum	mg/kg	ND	ND	ND	ND	ND	ND	ND
7	Silica	mg/kg	7.20	8.26	9.02	5.50	7.80	9.20	10.02
8	Phosphate	mg/kg	7.87	9.29	6.16	5.75	9.49	11.61	10.80
9	Sulphate	mg/kg	745.00	862.00	585.00	490.00	510.00	590.00	396.00
10	Nitrite	mg/kg	0.11	0.12	0.12	0.11	0.10	0.10	0.11
11	Nitrate	mg/kg	BQL	BQL	12.00	16.6	26.2	BQL	BQL
12	Calcium	mg/kg	1723.00	1057.00	1320.00	1220.00	1390.00	1907.00	1643.00
13	Magnesium	mg/kg	1044.00	716.00	1090.00	690.00	896.00	1563.00	2320.00
14	Sodium	mg/kg	2733.00	2720.00	2578.00	2107.00	1558.00	1042.00	952.00
15	Potassium	mg/kg	302.00	332.00	378.0	357.0	87.8	384.00	325.00
16	Chromium	mg/kg	38.00	24.40	51.70	16.10	60.00	48.90	69.20
17	Nickel	mg/kg	15.60	9.50	21.70	6.00	24.70	19.70	28.30
18	Copper	mg/kg	7.80	BQL	11.30	31.40	16.40	12.10	19.90
19	Zinc	mg/kg	30.10	21.90	35.70	13.70	44.90	31.50	51.90
20	Cadmium	mg/kg	BQL	BQL	BQL	BQL	BQL	BQL	BQL
21	Lead	mg/kg	BQL	BQL	BQL	BQL	BQL	BQL	BQL
22	Mercury	mg/kg	BQL	BQL	BQL	BQL	BQL	BQL	BQL
23	Arsenic	mg/kg	BQL	BQL	BQL	BQL	BQL	BQL	BQL

*ND - Not Detected, BQL: Below Quantification Limit (NO₃:10.0 mg/kg, Cd: 1.0 mg/kg, Hg: 1.0mg/kg, As: 1.0mg/kg)

9.2 Discussion of Marine Sediment samples

Marine Sediments of Deendayal Port Harbor waters, Khorī and Nakti Creeks and two locations of Vadinar are monitored for various physico-chemical parameters during spring and neap tide of each month. The Heavy metal analyzed and found below quantification limit.

9.3 Conclusion

The sediment types are majority Sandy loamy. Also maximum heavy metals parameters found below Quantification limit wise, Pb, Cd, Hg , As, Al was not Detected and Nitrate for some locations.

CHAPTER-11

MARINE ECOLOGICAL MONITORING

10.0 INTRODUCTION:

10.1 Sampling Stations:

The monitoring of marine environment for the study of biological and ecological Parameters was carried out on 01st November 2022 in harbour region of DPA at Kandla Creek, and on 02nd November 2022 in creeks near by the port during Neap tide. The monitoring of marine environment for the study of biological and ecological parameters was repeated again on 08th November, 2022 in harbour region of DPA at Kandla Creek and on 09th November, 2022 in creeks near by the port during spring tidal condition.

Plankton samples from sub surface layer was collected both during high tide period and low tide period from 3 water quality monitoring stations of DPA harbour area and two stations in Nakti creek and one station in Khori creek. Sampling at second sampling station of Nakti creek was possible only during high tide period.

Plankton samples from sub surface layer were collected during high tide period and low tide period from monitoring station near Vadinar Jetty at Path Finder Creek during Neap tide on 01/11/2022 and Spring tide period on 08/11/2022. Collected water samples were processed for estimation of Chlorophyll- a, Pheophytin- a, qualitative and quantitative evaluation of phytoplankton, qualitative and quantitative evaluation of zoo plankton density and their population.

TABLE 43. SAMPLING LOCATIONS

monitoring requirement	Number of locations
Kandla creek	3 in Kandla creek
Nakti creek	2 in Nakti creek
Khori Creek	1 in Khori creek
Vadinar jetty	1 near Vadinar Jetty
SPM	1 near I st SPM
Total Number of locations	8

Sampling methodology adopted:

A marine sampling is an estimation of the body of information in the population. The theory of the sampling design is depending upon the underlying frequency distribution of the population of interest. The requirement for useful water sampling is to collect a representative sample of suitable volume from the specified depth and retain it free from contamination during retrieval.

50 litres of the water sample were collected from Sub surface by using bucket. From the collected water sample 1 litres of water sample was taken in an opaque plastic bottle for chlorophyll estimation, thereafter plankton samples were collected by using filtration assembly with Nylobolt cloth of 20µm mesh size. . During low tide DPA-6 Nakti-II location monitoring was not possible due to non-availability of marine water.

Samples Processing for chlorophyll estimation:

Samples for chlorophyll estimation were preserved in ice box on board in darkness to avoid degradation in opaque container covered with aluminium foil. Immediately after reaching the shore after sampling, 1 litre of collected water sample was filtered through GF/F filters (pore size 0.45 µm) by using vacuum filtration assembly. After vacuum filtration the glass micro fiber filter paper was grunted in tissue grinder, macerating of glass fiber filter paper along with the filtrate was done in 90% aqueous Acetone in the glass tissue grinder with glass grinding tube. Glass fiber filter paper will assist breaking the cell during grinding and chlorophyll content was extracted with 10 ml of 90% Acetone, under cold dark conditions along with saturated magnesium carbonate solution in glass screw cap tubes. After an extraction period of 24 hours, the samples were transferred to calibrated centrifuge tubes and adjusted the volume to original volume with 90% aqueous acetone solution to make up the evaporation loss. The extract was clarified by using centrifuge in closed tubes. The clarified extracts were then decanted in clean cuvette and optical density was observed at wavelength 664, 665 nm. By using corrected optical density, Chlorophyll-a value was calculated as given in (APHA, 2017).

PLANKTON:

The entire area open water in the sea is the pelagic realm. Pelagic organisms live in the open sea. In contrast to the pelagic realm, the benthic realm comprises organisms and zone of the bottom of the sea. Vertically the pelagic realm can be dividing into two zones based on light penetration; upper photic or euphotic zone and lower dark water mass, aphotic zone below the photic zone.

The term plankton is a general term for organisms which have such limited powers of locomotion that they are at the mercy of the prevailing water movement. Plankton is subdivided to phytoplankton and zooplankton. Phytoplanktons are free floating organisms that are capable of photosynthesis and zooplankton is the various free-floating animals.

Pelagic zone, represents the entire ocean water column from the surface to the deepest depths, is home to a diverse community of organisms. Differences in their locomotive ability categorize the organisms in the pelagic realm into two, *plankton* and *nekton* (Lalli and Parsons, 1997). *Plankton* consists of all organisms drifting in the water and is unable to swim against water currents, whereas *Nekton* includes organisms having strong locomotive power. Ecological studies on the plankton community, which form the base of the aquatic food chain, help in the better understanding of the dynamics and

functioning of the marine ecosystem. The term 'Plankton' first coined by Victor Hensen (1887), Plankton, (Greek word: *planktos* meaning "passively drifting or wandering") is defined as drifting or free-floating organisms that inhabit the pelagic zone of water. Based on their mode of nutrition planktonic organisms are categorised into phytoplankton (organisms having an autotrophic mode of nutrition) and zooplankton (organisms having a heterotrophic mode of nutrition).

Phytoplankton in the marine environment:

Phytoplanktons are free floating unicellular, filamentous and colonial eutrophic organisms that grow in aquatic environments whose movement is more or less dependent upon water currents. These micro flora acts as primary producers as well as the basis of food chain, source of protein, bio-purifier and bio-indicators of the aquatic ecosystems of which diverse array of the life depends .They are considered as an important component of aquatic flora, play a key role in maintaining equilibrium between abiotic and biotic components of aquatic ecosystem.

The phytoplankton includes a wide range of photosynthetic and phototrophic organisms. Marine phytoplankton is mostly microscopic and unicellular floating flora, which are the primary producers that support the pelagic food-chain. The two most prominent groups of phytoplankton are Diatoms (Bacillariophyceae) and Dinoflagellates (Dinophyceae). The phytoplankton those normally captured in the net from the Gulf of Kutch is normally dominated by these two major groups; Diatoms and Dinoflagellates. Phytoplankton also include numerous and diverse collection of extremely small, motile algae which are termed micro flagellates (naked flagellates) as well as and Cyanophytes (Blue-green algae).

Algae are an ecologically important group in most aquatic ecosystems and have been an important component of biological monitoring programs. Algae are ideally suited for water quality assessment because they have rapid reproduction rates and very short life cycles, making them valuable indicators of short-term impacts.

Aquatic populations are impacted by anthropogenic stress, resulting in a variety of alterations in the biological integrity of aquatic systems. Algae can serve as an indicator of the degree of deterioration of water quality, and many algal indicators have been used to assess environmental status.

Zooplankton in the marine environment:

Zooplankton includes a taxonomically and morphologically diverse community of heterotrophic organisms that drift in the waters of the world's oceans. Qualitative and quantitative studies on zooplankton community are a prerequisite to delineate the ecological processes active in the marine ecosystem. Zooplankton community plays a pivotal role in the pelagic food web as the primary consumers of phytoplankton and act as the food source for organisms in the higher trophic levels, particularly the economically essential groups such as fish larvae and fishes. They also function in the cycling of elements in the marine ecosystem. The dynamics of the zooplankton community, their reproduction, and growth and survival rate are all significant factors determining the recruitment and

abundance of fish stocks as they form an essential food for larval, juvenile and adult fishes (Beaugrand et al., 2004). Zooplankton grazing in the marine environment controls the primary Production and helps in determining the pelagic ecosystem (Banse, 1995). Through grazing in surface waters and following the production of sinking faecal matters and also by the active transportation of dissolved and particulate matter to deeper waters via vertical migration, they help in the transport of organic carbon to deep ocean layers and thus act as key drivers of 'biological pump' in the marine ecosystem. Zooplankton grazing and metabolism also, transform particulate organic matter into dissolved forms, promoting primary producer community, microbial demineralization, and particle export to the ocean's interior.

The categorisation of zooplankton into various ecological groups is based on several factors such as duration of planktonic life, size, food preferences and habitat. As they vary significantly in size from microscopic to metazoic forms, the classification of zooplankton based on size has paramount importance in the field of quantitative plankton research.

Based on the duration of planktonic life, zooplankton are categorised into Holoplankton (organisms which complete their entire lifecycle as plankton) and Meroplankton (organisms which are planktonic during the early part of their lives such as the larval stages of benthic and nektonic organisms). Tychoplankton are organisms which live a brief planktonic life, such as the benthic crustaceans (Cumaceans, mysids, isopods) which ascend to the water column at night for feeding and certain ectoparasitic copepods, they leave the host and spend their life as plankton during their breeding cycle.


Zooplankton can be subdivided into holoplankton, i.e., permanent members of the plankton (e.g., Calanoid copepods), and meroplankton, i.e., temporary members in the plankton e.g., larvae of fish, shrimp, and crab). The meroplankton group consists of larval and young stages of animals that will adopt a different lifestyle once they mature. In contrast to phytoplankton which consist of a relatively smaller variety of organisms, Zooplankton are extremely divers, consist of a host of larval and adult forms representing many animal phylum.

Among the zooplankton one group always dominate than others; members of sub class copepods (Phylum Athropoda) and Tintinids (Phylum Protozoa) among the net planktons. These small animals are of vital importance in marine ecosystem as one of the primary herbivores animals in the sea, and it is they provide vital link between primary producer (autotrophs) and numerous small and large marine consumers.

As their community structure and function are highly susceptible to changes in the environmental conditions regular monitoring of their distribution as well as their interactions with various physicochemical parameters is inevitable for the sustainable management of the ecosystem (Kusum et al., 2014). Of all the marine zooplankton groups, copepods mainly Calanoid copepods are the

dominant groups in marine subtropical and tropical waters and exhibit considerable diversity in morphology and habitats they occupy (Madhupratap, 1991 ;)

It has been well established that potential of pelagic fishes viz. finfishes, crustaceans, molluscs and marine mammals either directly or indirectly depend on zooplankton. The herbivorous zooplanktons are efficient grazers of the phytoplankton and are referred to as living machines transforming plant material into animal tissue. Hence they play an essential role as the intermediaries for nutrients/energy transfer between primary and tertiary trophic levels. Due to their large density, shorter lifespan, drifting nature, high group/species diversity and different tolerance to the stress, they used as the indicator organisms for the physical, chemical and biological processes in the aquatic ecosystem (Ghajibhiye, 2002).



Spatial distribution of Plankton:

A characteristic of plankton population is that they tend to occur in patches, which are varying spatially on a scale of few meters to far as few kilo metres in distance. They also vary in time scale, season as well as vertically in the water column. It is this patchiness and its constant changes in time and spot, that has made it so difficult for plankton biologist to learn about the ecology of plankton. The biological factors that causes this patchiness is due to the ability of zooplankton to migrate vertically and graze out the phytoplankton at a rapid rate that can create patchiness. Similarly the active swimming ability by certain zooplankton organisms can cause to aggregate in dense group.

DCPL/DPA/21-22/31– November-2022

At its most extreme, because the water in which plankton is suspended is constantly moving, each sample taken by the plankton biologists remain a different volume of water, so each sample is unique and replicate does not exist.

Plankton in the month of November also exhibit vertical patchiness. Physical factors contribute to this type of patchiness include light intensity, nutrients and density gradients in the water column.

Phytoplankton in particular tends to be unequally distributed vertically, which leads to the existence of different concentration of a chlorophyll value between photic zone and below the photic zone.

Methodology adopted for Plankton sampling:

Preservation and storage:

Both filtered plankton and those collected from the plankton net were preserved with 5% buffered formalin and stored in 1L plastic container for further processing in the laboratory.

Sample concentration:

The collected plankton samples were concentrated by using centrifuge and made up to 50 ml with 5% formalin -Glycerine mixture.

Taxonomic evaluation:

Before processing, the sample was mixed carefully and a subsample was taken with a calibrated Stempel-pipette. 1 ml of the concentrated plankton samples were transferred on a glass slide with automatic pipette. The plankton sample on the glass slides were stained by using Lugol's iodine and added glycerin to avoid drying while observation. The plankton samples were identified by using Labex triangular Research microscope with photographic attachment. Microphotographs of the plankton samples were taken for record as well as for confirming the identification. The bigger sized zooplankton was observed through dissecting stereomicroscope with magnification of 20-30 x. Plankton organisms in the whole slide were identified to the lowest taxon possible. A thorough literature search was conducted for the identification of the different groups of phytoplankton and zooplankton that were encountered

Cell counts by drop count method:

The common glass slide mounted with a 1ml of concentrated phytoplankton/zooplankton sample in glycerol and covered with cover slip 22 mm x 60 mm was placed under the compound microscope provided with a mechanical stage. The plankton was then counted from the microscopic field of the left top corner of the slide. Then slide is moved horizontally along the right side and plankton in each microscopic field was thus counted. When first microscopic field row was finished the next consecutive row was adjusted using the mechanical device of the stage. In this way all the plankton present in entire microscopic field are counted. From this total number in 1ml of the concentrated plankton, total amount of phytoplankton in the original volume of sample filtered was calculated as units/L and Zooplankton as N/m^3 .

BENTHIC ORGANISMS:

Benthos is those organisms that are associated with the sea bed or benthic habitats. Epi- benthic organisms live attached to a hard substratum or rooted to a shallow depth below the surface. In fauna organisms live below the sediment–water interface. Interstitial organisms live and move in pore water among sedimentary grains.

Because the benthic organisms are often collected and separated on sieves, a classification based on the overall size is used. Macro benthos include organisms whose shortest dimension is greater than or equal to 0.5 mm. Meio benthos are smaller than 0.5mm but larger than 42μ in size.

The terms such as macro fauna and Meio fauna generally have little relevance with taxonomic classification. The terms Meio fauna and macro fauna depend on the size. Meio fauna were considered as good bioassay of community health and rather sensitive indicators of environmental changes

SAMPLING METHODOLOGY ADOPTED FOR SUB TIDAL REGION:

Van veen sampler (0.09m²) was used for sampling bottom sediments. Two sets of sediments were sampled from each location, one for macro fauna and other for Meio fauna. The macro fauna in the sediments were sieved on board to separate out the organisms. The fixation of Meio fauna is normally done by bulk fixation of the sediment sample. The bulk fixation is done by using 10% formalin (Buffered with borate). The organisms were preserved with seawater as diluting agent.

Sample sieving:

Sediments samples were sieved to extract the organisms. Sieving was performed carefully as possible to avoid any damage to the animals. The large portion of the sediment was split in to smaller portions and mixed with sea water in a bucket. The cohesive lumps were broken down by continuous stirring. The disaggregated sediments were then passed through the sieves.

Sample staining:

Sorting of the Meio fauna from the sieve is difficult task especially in the preserved material, because organisms are not easily detectable. To facilitate the animal detection the entire sample retained on the sieve after sieving operation were stained by immersing the sieve in a flat bottom tub with 1% Rose Bengal stain; a protein stain. A staining period of 10-30 minutes is sufficient for sample detection.

DIVERSITY INDICES:

On the whole, diversity indices provide more information about community composition than simply species richness (number of species present); they also, take the relative abundances of different species into account. Based on this fact, diversity indices therefore depend not only on species richness but on the evenness, or equitability, with which individuals are distributed among the different species (Magurram, A. E. (1988)

A diversity index is a measure of species diversity within a community that consists of co-occurring populations of several (two or more) different species. It includes two components: richness and evenness. Richness is the measure of the number of different species within a sample showing that more the types of species in a community, the higher is the diversity or greater is the richness. Evenness is the measure of relative abundance of the different species within a community.

The basic idea of diversity index is to obtain a quantitative estimate of biological variability that can be used to compare biological entities composed of discrete components in space and time (Carol H. R. *et al.* 1998). Biodiversity is commonly expressed through indices based on species richness and species abundances (Whittaker 1972, Lande 1996, Purvis and Hector 2000). Biodiversity indices are a non-parametric tool used to describe the relationship between species number and abundance. The most widely used bio diversity indices are Shannon Weiner index and Simpson's index.

A diversity Index is a single statistic that incorporates information on richness and evenness. Any study intended to interpret causes and effect of adverse impact on Biodiversity of communities require suitable measures to evaluate specie richness and Diversity. The former is number of species in community, while latter is a function of relative frequency of different species. Species richness is the iconic measure of biological diversity (Magurran, 2004). Several indices have been created to measure the diversity of species; however, the most widely used in the last decades are the Shannon (1948) and Simpson (1949) (Buzas and Hayek 1996; Gorelick 2006), with the components of diversity: richness (S) and evenness (J)

Simpson's diversity index

Simpson's index (D) is a measure of diversity, which takes into account both species richness, and evenness of abundance among the species present. The Simpson index is one of the meaningful and robust biodiversity measures available. (Magurran, 2004).

The formula for calculating D is presented as:

$$D = \frac{\sum n_i(n_i - 1)}{N(N - 1)}$$

Where n_i = the total number of organisms of each individual species

N = the total number of organisms of all species

The value of D ranges from 0 to 1. With this index, 0 represents infinite diversity and, 1, no diversity. When D increases diversity decreases. Simpson's index is therefore usually expressed as $1-D$ or $1/D$. (Magurran, 2004)

Low species diversity suggests:

- relatively few successful species in the habitat
- the environment is quite stressful with relatively few ecological niches and only a few organisms are really well adapted to that environment

- food webs which are relatively simple
- change in the environment would probably have quite serious effects

High species diversity suggests:

- a greater number of successful species and a more stable ecosystem
- more ecological niches are available and the environment is less likely to be hostile complex food webs
- environmental change is less likely to be damaging to the ecosystem as a whole

Species richness indices

The species richness(S) is simply the number of species present in an ecosystem. Species richness Indices of species richness are widely used to quantify or monitor the effects of anthropogenic disturbance. A decline in species richness in may be concomitant with severe or chronic human-induced perturbation (Fair Fair weather 1990) Species richness measures have traditionally been the mainstay in assessing the effects of environmental degradation on the biodiversity of natural assemblages of organisms (Clarke & Warwick, 2001)

Species richness is the iconic measure of biological diversity (Magurran, 2004). The species richness(S) is simply the number of species present in an ecosystem. This index makes no use of relative abundances. The term species richness was coined by Mc Intosh (1967) and oldest and most intuitive measure of biological diversity (Magurran, 2004).

Margalef's diversity index is a species richness index. Margalef's Species richness index (d), or indices that describe the evenness of the distribution of the numbers of individuals among species, were derived.

The value of a diversity index increases both when the number of types increases and when evenness increases. For a given number of types, the value of diversity index is maximised when all types are equally abundant [Rosenzweig, M. L. (1995)]

Shannon-Wiener's index:

An index of diversity commonly used in plankton community analyses is the Shannon-Wiener's index (H), which emphasizes not only the number of species (richness or variety), but also the apportionment of the numbers of individuals among the species (Odum 1971 and Reish 1984). Shannon-Wiener's index (H) reproduces community parameters to a single number by using an equation.

Shannon and Weiner index represents entropy. It is a diversity index taking into account the number of individuals as well as the number of taxon. It varies from 0 for communities with only single taxa to high values for community with many taxon each with few individuals. This index can also determine the pollution status of a water body. Normal values range from 0 to 4. This index is a combination of species present and the evenness of the species. Examining the diversity in the range

of polluted and unpolluted ecosystems, Wilham and Dorris (1968) concluded that the values of the index greater than

3 indicate clean water, values in the range of 1 to 3 are characterized by moderate pollution and values less than 1 are characterized as heavily polluted

10.2:- RESULTS:

CHLOROPHYLL-a:

$$H' = - \sum_{j=1}^s \frac{n_j}{N} \ln \left(\frac{n_j}{N} \right)$$

In the sub surface water chlorophyll-a was varying from 0.472-0.969 mg/m³ with an average value 0.645 mg/m³ in harbour region of DPA in Kandla Creek during sampling done in spring tide period of November 2022. In the nearby creeks chlorophyll-a was varying from 0.359-0.717 mg/m³ with an average value 0.552 mg/m³ Pheophytin –a level was below detectable limit- the all the sampling stations during springtide. Even though the plankton diversity and abundance were more during the spring tide sampling, the chlorophyll-content was detected lesser than expected because, the phytoplankton communities were mainly represented by diatoms *Skeletonema* sp. *Coscinodiscus* sp. and *Chaetoceros* sp.

In the sub surface water chlorophyll-a was varying from 0.338-0.547 mg/m³ with an average value 0.437 mg/m³ in harbour region of DPA in Kandla Creek during sampling done in Neap tide period of November 2022. In the nearby creeks chlorophyll-a was varying from 0.205- 0.440mg/m³ with an average value 0.370 mg/m³. Pheophytin–a level was below detectable limit- the all the sampling stations. During neap tide sampling phytoplankton communities were mainly represented by *Coscinodiscus* sp. and *Ditylum* sp.

In the sub surface water chlorophyll-a was varying from 0.598-0.968 mg/m³ in harbour region of DPA OOT in path finder Creek during sampling done in spring tide period of November 2022. In the sub surface water chlorophyll-a was varying from 0.709 - 0.987mg/m³ in harbour region of DPA OOT in path finder Creek during sampling done in Neap Tide period of November 2022

TABLE:-45 VARIATIONS IN CHLOROPHYLL-a PHEOPHYTIN-a AND ALGAL BIOMASS FROM SAMPLING STATIONS IN DPA HARBOUR AREA IN KANDLA CREEK ,NEAR BY CREEKS AND DPA OOT JETTY IN PATH FINDER CREEK AND SPM NEAR VADINAR DURING SPRING TIDE IN NOVEMBER 2022

Sr. No.	Station	Tide	Chlorophyll-a (mg/m ³)	Pheophytin- a (mg/m ³)	Algal Biomass (Chlorophyll method) mg/m ³
DPA HARBOUR AREA KANDLA CREEK					
1	KPT1	High tide	0.969	BDL	64.92
		Low tide	0.647	BDL	43.35
2	KPT 2	High tide	0.511	BDL	34.24
		Low tide	0.521	BDL	34.91
3	KPT 3	High tide	0.749	BDL	50.18
		Low tide	0.472	BDL	31.62
CREEKS					
4	KPT-4 Khor-I	High tide	0.638	BDL	42.75
		Low tide	0.359	BDL	24.05
5	KPT-5 Nakti-I	High tide	0.717	BDL	48.04
		Low tide	0.493	BDL	33.03
6	KPT-6 Nakti-II	High tide	ND	ND	ND
PATHFINDER CREEK VADINAR					
7	VADINAR-I jetty	High tide	0.968	BDL	64.86
8		Low tide	0.732	BDL	49.04
9	SPM	High tide	0.953	BDL	63.85
10		Low tide	0.598	BDL	

BDL: Below Detectable Limit., ND: Not detected

TABLE:-46. VARIATIONS IN CHLOROPHYLL-a PHEOPHYTIN-a AND ALGAL BIOMASS FROM SAMPLING STATIONS IN DPA HARBOUR AREA, NEAR BY CREEKS AND DPA OOT JETTY IN PATH FINDER CREEK AND SPM NEAR VADINAR DURING NEAP TIDE IN NOVEMBER 2022

Sr.No.	Station	Tide	Chlorophyll-a (mg/m ³)	Pheophytin- a (mg/m ³)	Algal Biomass (Chlorophyll method) mg/m ³
DPA HARBOUR AREA KANDLA CREEK					
1	KPT1	High tide	0.547	BDL	
		Low tide	0.450	BDL	
2	KPT 2	High tide	0.338	BDL	
		Low tide	0.409	BDL	
3	KPT 3	High tide	0.354	BDL	
		Low tide	0.523	BDL	
CREEKS					
4	KPT-4 Khor-I	High tide	0.440	BDL	
		Low tide	0.408	BDL	
5	KPT-5 Nakti-I	High tide	0.205	BDL	
		Low tide	0.426	BDL	
6	KPT-6 Nakti-II	High tide	ND	ND	ND
PATHFINDER CREEK VADINAR					
7	VADINAR-I jetty	High tide	0.799	BDL	
8		Low tide	0.709	BDL	
9	SPM	High tide	0.857	BDL	
10		Low tide	0.987	BDL	

BDL: Below Detectable Limit.ND: Not detected

PHYTOPLANKTON POPULATION:

For the evaluation of the Phytoplankton population in DPA harbour area and within the immediate surroundings of the port, sampling was conducted from 5 sampling locations (3 in harbour area and two in Nakti creek) during high tide period and low tide period of spring tide and neap tide.

The phytoplankton community of the sub surface water in the harbour and nearby creeks was represented by, Diatoms, blue green algae and Dinoflagellates during spring tide period. Diatoms were represented by 26 genera, Blue green algae were represented by 2 genera and Dinoflagellates were represented by 6 genera during the sampling conducted in spring tide in November, 2022. Phytoplankton of the sampling stations at sub surface layer in the harbour area and nearby creeks was varying from 39-243units/ L during high tide period and 115-199 units/L during low tide of Spring Tide. During spring tide sampling phytoplankton communities were dominated by *Skeletonema* sp almost forming a bloom in the Kandla creek and other nearby creek area and abundant population of *Coscinodiscus* sp. and *Chaetoceros* sp.

The phytoplankton community of the sub surface water in the harbour and nearby creeks was represented by Diatoms, Blue green algae and Dinoflagellates during Neap tide period. Diatoms were represented by 24 genera, Blue green algae were represented 2 genera and Dinoflagellates with 5 genera during the sampling conducted in Neap tide in November, 2022. Phytoplankton of the sampling stations at sub surface layer in the harbour area and nearby creeks was varying from 43-299 units/ L during high tide period and 143-193 units/L during low tide of Neap Tide. During Neap tide sampling phytoplankton communities were dominated by, *Ditylum* sp and *Coscinodiscus* sp.

For the evaluation of the Phytoplankton population in DPA OOT jetty area in Path Finder creek sampling was conducted from two sampling locations; Jetty area and SPM area during high tide period and low tide of spring tide and Neap tide period.

The phytoplankton community of the sub surface water in the path finder creeks was represented by Diatoms, Blue green algae and Dinoflagellates during spring tide period. Diatoms were represented by 25 genera, Blue Green algae by 5 genera and Dinoflagellates by 6 genera during the sampling conducted in spring tide in November, 2022. Phytoplankton of the sampling stations at sub surface path finder creek near OOT Jetty area was 209 units/L during high tide period and 177 units/L during low tide of Spring Tide. Phytoplankton of the sampling stations at sub surface layer in the SPM area was varying from 206 units/ L during high tide period and 131 units/ L during low tide of Spring Tide.

The phytoplankton community of the sub surface water in the path finder creeks was represented by Diatoms, Blue green and Dinoflagellates during Neap tide period. Diatoms were represented by 32 genera and Blue green algae by 4 genera and Dinoflagellates by 6 genera during the sampling conducted in Neap tide in November, 2022. Phytoplankton of the sampling stations at sub surface path finder creek near OOT Jetty was varying from 244units/ L during high tide period and 200

units/L during low tide of Neap Tide. Phytoplankton of the sampling stations at sub surface path finder creek near SPM area was varying from 259 units/L during high tide period and 294 units/L during low tide of Neap Tide.

Species Richness Indices and Diversity Indices:

Margalef's diversity index (Species Richness)

Margalef's diversity index (Species Richness) of phytoplankton communities in the Kandla creek and nearby creeks sampling stations was varying from 2.184- 4.688 with an average of 3.346 during the sampling conducted in High tide period of spring tide. While Margalef's diversity index (Species Richness) S of phytoplankton communities in the Kandla creek region and nearby creeks was varying from 1.963- 3.589 with an average of 2.835 during the consecutive low tide period.

Margalef's diversity index (Species Richness) of phytoplankton communities in the stations in Kandla creek and nearby creeks was varying from 2.393-4.279 with an average of 3.586 during the sampling conducted in High tide period of Neap tide. While Margalef's diversity index (Species Richness) of phytoplankton communities in the Kandla creek region and nearby creeks was varying from 2.821- 3.86 with an average of 3.357 during consecutive low tide.

Margalef's diversity index (Species Richness) S of phytoplankton communities in the stations was 4.867 at OOT jetty area and 4.129 at SPM area during the sampling conducted in High tide period of spring tide. While Margalef's diversity index (Species Richness) S of phytoplankton communities in the path finder creek near OOT jetty was 4.443 and 3.692 at SPM during the consecutive low tide period.

Margalef's diversity index (Species Richness) of phytoplankton communities in the stations was 4.73 at OOT jetty area and 4.139 at SPM area during the sampling conducted in High tide period of Neap tide. While Margalef's diversity index (Species Richness) of phytoplankton communities in the path finder creek near OOT jetty was 4.152 and SPM area was 5.454 during the consecutive low tide period.

Shannon-Wiener's index:

Shannon-Wiener's Index (H) of phytoplankton communities in the sampling stations was in the range of 0.786- 1.034 between selected sampling stations with an average value of 0.925 during high tide period of spring tide at Kandla creek and nearby creeks. Shannon-Wiener's Index (H) of phytoplankton communities in the sampling stations was in the range of 0.790-0.915 between selected sampling stations with an average value of 0.855 during consecutive low tide at Kandla creek and nearby creeks.

Shannon-Wiener's Index (H) of phytoplankton communities in the sampling stations was in the range of 0.867–1.022 between selected sampling stations with an average value of 0.932 during high tide period of neap tide at Kandla creek and nearby creeks. Shannon-Wiener's Index (H) of phytoplankton

communities in the sampling stations was in the range of 0.926- 1.001 between selected sampling stations with an average value of 0.951 during consecutive low tide at Kandla creek and nearby creeks. Shannon-Wiener's Index (H) of phytoplankton communities in the stations was 1.037 at OOT jetty area and 0.946 at SPM area during the sampling conducted in High tide period of spring tide. While Shannon-Wiener's Index (H) of phytoplankton communities in the path finder creek near OOT jetty was 1.043 and 0.982 at SPM during the consecutive low tide period of spring tide.

Shannon-Wiener's Index (H) of phytoplankton communities in the stations was 0.998 at OOT jetty area and 1.035 at SPM area during the sampling conducted in High tide period of Neap tide. While Shannon-Wiener's Index (H) of phytoplankton communities in the path finder creek near OOT jetty was 0.942 and at SPM area was 1.036 during the consecutive low tide period.

Typical values are generally between 1.5 and 3.5 in most ecological studies, and the index is rarely greater than 4. The Shannon-Wiener's index increases as both the richness and the evenness of the community increase. This result indicates that diversity of phytoplankton of Kandla Harbour region and nearby creeks is less but with abundant population of few, with relatively few ecological niches and only very few opportunist organisms are really well adapted to this environment and thrive better than other species.

Simpson's diversity index:

Simpson diversity index (1-D) of phytoplankton communities was below 0.9 at all sampling stations in the Kandla Harbour region and nearby creeks, which was varying from 0.778-0.851 between selected sampling stations with an average of 0.823 during high tide period of spring tide. Simpson diversity index (1-D) of phytoplankton communities was below 0.9 at all sampling stations in the Kandla Harbour region and nearby creeks except few, which was varying from 0.787-0.842 between selected sampling stations with an average of 0.814 during consecutive low tide.

Simpson diversity index (1-D) of phytoplankton communities was below 0.9 at all sampling stations except few in Kandla Harbour region and nearby creeks, during high tide period and low tide period during Neap tide also, which was varying from 0.813-0.874 with an average value of 0.847 between selected sampling stations during high tide period and 0.840-0.871 varying from with an average value of 0.858 between selected sampling stations during consecutive low tide period. Low species diversity suggests a relatively few successful species in this habitat.

Simpson diversity index (1-D) of phytoplankton communities in the stations was 0.863 at OOT jetty area and 0.820 at SPM area during the sampling conducted in High tide period of spring tide at Path finder creek. While Simpson diversity index (1-D) of phytoplankton communities in the path finder creek near OOT jetty was 0.876 and 0.867 at SPM during the consecutive low tide period in the path finder creek.

Simpson diversity index (1-D) of phytoplankton communities in the stations was 0.838 at OOT jetty area and 0.881 at SPM area during the sampling conducted in High tide period of Neap tide at Path

finder Creek. While Simpson diversity index (1-D) of phytoplankton communities in the path finder creek near OOT jetty was 0.832 and at SPM area was 0.867 during the consecutive low tide period.

Table:-47 4PHYTOPLANKTON VARIATIONS IN ABUNDANCE AND DIVERSITY IN SUB SURFACE SAMPLING STATIONS IN DPA HARBOUR AREA AT KANDLA CREEK AND , NEAR BY CREEKS DURING SPRING TIDE IN NOVEMBER 2022

Tide	Sampling Station	Abundance In units/L	No of Species observed /total species	% Of diversity	Margalef's diversity index (Species Richness)	Shannon Weiner index H (log ₁₀)	Diversity Index (Simpson's Index) 1-D
HIGH TIDE	1	207	26/34	76.47	4.688	1.034	0.8511
	2	183	22/34	64.71	4.031	1.005	0.8437
	3	193	13/34	38.24	2.28	0.811	0.7778
	4	243	18/34	52.94	3.095	0.9391	0.8192
	5	193	21/34	61.76	3.8	0.9777	0.8281
	6	39	9/34	26.47	2.184	0.786	0.8178
LOW TIDE	1	178	14/34	41.18	2.509	0.8042	0.787
	2	199	20/34	58.82	3.589	0.8982	0.8075
	3	115	14/34	41.18	2.74	0.8696	0.8365
	4	154	18/34	52.94	3.375	0.915	0.8416
	5	163	11/34	32.35	1.963	0.7895	0.7957

Table:-48 PHYTOPLANKTON VARIATIONS IN ABUNDANCE AND DIVERSITY IN SUB SURFACE SAMPLING STATIONS IN DPA HARBOUR AREA AT KANDLA CREEK AND NEAR BY CREEKS DURING NEAP TIDE IN NOVEMBER 2022

Tide	Sampling Station	Abundance In units/L	No of Species observed /total species	% of diversity	Margalef's diversity index (Species Richness)	Shannon Weiner index H (log ₁₀)	Diversity Index (Simpson's Index) 1-D
HIGH TIDE	1	216	24/31	77.42	4.279	0.98	0.8568
	2	229	22/31	70.97	3.865	0.958	0.853
	3	228	22/31	70.97	3.868	1.022	0.8743
	4	299	23/31	74.19	3.859	0.8667	0.8127
	5	254	19/31	61.29	3.251	0.8929	0.8307
	6	43	10/31	32.26	2.393	0.8712	0.8571
LOW TIDE	1	183	18/31	58.06	3.263	0.9504	0.8636
	2	143	15/31	48.39	2.821	0.946	0.8666
	3	178	21/31	67.74	3.86	1.001	0.8708
	4	193	19/31	61.29	3.42	0.931	0.84
	5	193	19/31	61.29	3.42	0.9259	0.8469

Table:-49 ABUNDANCE OF PHYTOPLANKTON SUBSURFACE SAMPLING STATIONS IN DPA HARBOUR AREA AT KANDLA CREEK AND, NEAR BY CREEKS DURING SPRING TIDE IN NOVEMBER2022

Tide	Surface	No of Sampling location	Group of phytoplankton	Phytoplankton Group range Units/L	Genera or species /total Phyto plankton	Species Composition % (Group level)
HIGH TIDE	Sub surface	6	BLUE GREEN ALGAE	0-8	2/34	5.88
			DIATOMS	38-238	26/34	76.47
			DINOFLAGELLATES	0-11	6/34	17.65
			TOTAL PHYTO PLANKTON	39-243	34	
LOW TIDE	Sub surface	5	BLUE GREEN ALGAE	1-6	2/34	5.88
			DIATOMS	110-190	26/34	76.47
			DINOFLAGELLATES	1-7	6/34	17.65
			TOTAL PHYTO PLANKTON	115-199	34	

TABLE:-50 ABUNDANCE OF PHYTOPLANKTON SUBSURFACE SAMPLING STATIONS IN DPA HARBOUR AREA AT KANDLA CREEK AND, NEAR BY CREEKS DURING NEAP TIDE IN NOVEMBER 2022

Tide	Surface	No of Sampling location	Group of phytoplankton	Phytoplankton Group range Units/L	Genera or species /total Phyto plankton	Species Composition % (Group level)
HIGH TIDE	Sub surface	6	BLUE GREEN ALGAE	0-6	2/31	6.45
			DIATOMS	43-293	24/31	77.42
			DINOFLAGELLATES	0-9	5/31	16.13
			TOTAL PHYTO PLANKTON	43-299	31	
LOW TIDE	Sub surface	5	BLUE GREEN ALGAE	2-6	2/31	6.45
			DIATOMS	133-186	24/31	77.42
			DINOFLAGELLATES	3-8	5/31	16.13
			TOTAL PHYTO PLANKTON	143-193	31	

TABLE:-51 PHYTOPLANKTON VARIATIONS IN ABUNDANCE AND DIVERSITY IN SUB SURFACE SAMPLING STATIONS IN DPA OOT AT PATH FINDER CREEK , VADINAR & NEAR BY SPM, DURING SPRING TIDE IN NOVEMBER 2022

Tide	Sampling Station	Abundance In units/L	No of Species observed /total species	% of diversity	Margalef's diversity index (Species Richness S)	Shannon Weiner index H (log ₁₀)	Diversity Index (Simpson's Index) 1-D
HIGH TIDE	Jetty	209	27/36	75.00	4.867	1.037	0.863
	SPM	206	23/36	63.89	4.129	0.946	0.820
LOW TIDE	Jetty	177	24/36	66.67	4.443	1.043	0.876
	SPM	131	19/36	52.78	3.692	0.982	0.867

TABLE:-52 PHYTOPLANKTON VARIATIONS IN ABUNDANCE AND DIVERSITY IN SUB SURFACE SAMPLING STATIONS IN DPA OOT AT PATH FINDER CREEK , VADINAR & NEAR BY SPM, DURING NEAP TIDE IN NOVEMBER 2022

Tide	Sampling Station	Abundance In units/L	No of Species observed /total species	% of diversity	Margalef's diversity index (Species Richness)	Shannon Weiner index H (log ₁₀)	Diversity Index (Simpson's Index) 1-D
HIGH TIDE	Jetty	244	27/42	64.29	4.73	0.998	0.838
	SPM	259	24/42	57.14	4.139	1.035	0.881
LOW TIDE	Jetty	200	23/42	54.76	4.152	0.942	0.832
	SPM	294	32/42	76.19	5.454	1.036	0.867


TABLE:-53 ABUNDANCE OF PHYTOPLANKTON SUBSURFACE SAMPLING STATIONS IN DPAOOT AT PATH FINDER CREEK, VADINAR & NEAR BY SPM, DURING SPRING TIDE IN NOVEMBER 2022

Tide	Surface	No of Sampling location	Group of phytoplankton	Phytoplankton Group range Units/L	Genera or species /total Phyto plankton	Taxon Diversity % (Group level)
HIGH TIDE	Sub surface	2	BLUE GREEN ALGAE	14-20	5/36	13.89
			DIATOMS	180-192	25/36	69.44
			DINOFLAGELLATES	3-6	6/36	16.67
			TOTAL PHYTO PLANKTON	206-209	36	
LOW TIDE	Sub surface	2	BLUE GREEN ALGAE	12-19	5/36	13.89
			DIATOMS	118-156	25/36	69.44
			DINOFLAGELLATES	1-2	6/36	16.67
			TOTAL PHYTO PLANKTON	131-177	36	


Table:- 54 ABUNDANCE OF PHYTOPLANKTON SUBSURFACE SAMPLING STATIONS IN DPA OOT AT PATH FINDER CREEK , VADINAR & NEAR BY SPM, DURING NEAP TIDE IN NOVEMBER 2022

Tide	Surface	No of Sampling location	Group of phytoplankton	Phytoplankton Group range Units/L	Genera or species /total Phyto plankton	Species Composition % (Group level)
HIGH TIDE	Sub surface	2	BLUE GREEN ALGAE	5-7	4/42	9.52
			DIATOMS	238-248	32/42	76.19
			DINOFLAGELLATES	1-4	6/42	14.29
			TOTAL PHYTO PLANKTON	244-259		
LOW TIDE	Sub surface	2	BLUE GREEN ALGAE	4-8	4/42	9.52
			DIATOMS	194-282	32/42	76.19
			DINOFLAGELLATES	2-4	6/42	14.29
			TOTAL PHYTO PLANKTON	200-294		


Species Composition % of Phytoplankton during High tide and Low tide period during spring tide in Kandla creek and nearby creeks




Species Composition % of Phytoplankton during High tide and Low tide period during Neap tide in Kandla creek and nearby creeks



Species Composition % of Phytoplankton during High tide and Low tide period during spring tide in Path Finder Creek, Vadinar



Species Composition % of Phytoplankton during High tide and Low tide period during Neap tide in Path Finder Creek, Vadinar



ZOOPLANKTON POPULATION:

For the evaluation of the Zooplankton population in DPA harbour area and within the immediate surroundings of the port sampling was conducted from 6 sampling locations (3 in harbour area and two in Nakti creek and one in Khoricreek) during high tide period and low tide period of spring tide and Neap tide in November, 2022. The Zooplankton community of the sub surface water in the harbour and nearby creeks during spring tide was represented by mainly six groups; Tintinnids, Copepods, Arrow worms, Mysids, Urochordata, Ciliates and 8 larval forms. The Zooplankton community of the sub surface water in the harbour and nearby creeks during neap tide was represented by mainly six groups; Tintinnids, Copepods, Arrow worms, Mysids, Urochordata, Ciliates and 6 larval forms.

Zooplankton of the sampling stations at sub surface layer in the DPA harbour area and nearby creek was varying from $25-128 \times 10^3 \text{ N/m}^3$ during high tide and $103-144 \times 10^3 \text{ N/m}^3$ during low tide of Spring Tide period. Zooplankton of the sampling stations at sub surface layer in the DPA harbour area and nearby creek was varying from $19-114 \times 10^3 \text{ N/m}^3$ during high tide and $76-106 \times 10^3 \text{ N/m}^3$ during low tide of Neap Tide period.

For the evaluation of the Zooplankton population in DPA OOT jetty area in Path Finder creek and SPM in Vadinar selected 2 sampling locations (1 in jetty area and one near SPM).

During spring tide sampling plankton sample were collected at Jetty area and near SPM during consecutive high tide period and low tide period. During Neap tide sampling Plankton samples were collected from jetty area and SPM during consecutive high tide period and low tide period.

The Zooplankton community of the sub surface water in the path finder creek during spring tide was represented by mainly four groups Tintinnids, Copepods, Urochordata, Ciliates and 4 larval forms. While the Zooplankton community of the sub surface water in the path Finder creeks at Jetty region and SPM during neap tide was represented by four groups, Tintinnids, Copepods, Arrow worms, Urochordata and 5 larval forms.

Zooplankton of the sampling stations at sub surface layer in the DPA OOT Jetty area of path finder creek was $91 \times 10^3 \text{ N/m}^3$ during high tide and $86 \times 10^3 \text{ N/m}^3$ during low tide of Spring Tide period. Zooplankton of the sampling stations at sub surface layer in the DPA SPM area of path finder creek was $101 \times 10^3 \text{ N/m}^3$ during high tide and $70 \times 10^3 \text{ N/m}^3$ during low tide of spring Tide period.

Zooplankton of the sampling stations at sub surface layer in the DPA OOT jetty area in path finder creek was recorded $87 \times 10^3 \text{ N/m}^3$ during high tide and $65 \times 10^3 \text{ N/m}^3$ during consecutive low tide period of Neap tide. Zooplankton of the sampling stations at sub surface layer in the DPASPM area in path finder creek was recorded $64 \times 10^3 \text{ N/m}^3$ during high tide and $87 \times 10^3 \text{ N/m}^3$ during consecutive low tide period of Neap Tide.

Species Richness Indices and Diversity Indices:

Margalef's diversity index (Species Richness)

Margalef's diversity index (Species Richness) of Zooplankton communities in the stations Kandla creek region and nearby creeks was varying from 2.175- 5.186 with an average of 3.450 during the sampling conducted in High tide period. Margalef's diversity index (Species Richness) of Zooplankton communities varying from 2.373-3.823 with an average of 3.261 during the sampling conducted in low tide period during Spring tide.

Margalef's diversity index (Species Richness) of Zooplankton communities in the Kandla creek region and nearby creeks sampling stations were varying from 1.358-3.858 with an average of 2.930 during the sampling conducted in high tide and varying from 2.289- 4.618 with an average of 3.513 during the sampling conducted in low tide during Neap tide period.

Margalef's diversity index (Species Richness) of Zooplankton communities in the sampling station near jetty at Path Finder Creek, Vadinar during the sampling conducted in consecutive high tide period and low tide of spring tide was recorded as 1.995 and 1.796 respectively. Margalef's diversity index (Species Richness) of Zooplankton communities in the sampling station near SPM at Path Finder Creek, Vadinar during the sampling conducted in consecutive high tide period and low tide of spring tide was recorded as 2.600 and 2.118 respectively.

Margalef's diversity index (Species Richness) of Zooplankton communities near Jetty at Path finder creek were varying from 3.807 and 2.396 respectively during the sampling conducted in consecutive high tide period and Low tide period of Neap tide. While Margalef's diversity index (Species Richness) of Zooplankton communities near SPM at Path finder creek were varying from 2.645-3.135 respectively during the consecutive high tide and low tide period.

Shannon-Wiener's index:

Shannon-Wiener's Index (H) of Zooplankton communities in the sampling stations in Kandla Harbour region and nearby creeks was in the range of 0.778-1.164 between selected sampling stations with an average value of 0.939 during high tide period of spring tide. Shannon-Wiener's Index (H) of Zooplankton communities in the sampling stations in Kandla Harbour region and nearby creeks was in the range of 0.795-1.015 between selected sampling stations with an average value of 0.938 during consecutive low tide period.

Shannon-Wiener's Index (H) of Zooplankton communities in the sampling stations in Kandla Harbour region and nearby creeks was in the range of 0.490-0.914 between selected sampling stations with an average value of 0.805 during high tide period of Neap tide. Shannon-Wiener's Index (H) of Zooplankton communities in the sampling stations in Kandla Harbour region and nearby creeks was in the range 0.797-1.041 of between selected sampling stations with an average value of 0.928 during consecutive low tide period.

Shannon-Wiener's Index (H) of Zooplankton communities in the sampling station near jetty at Path Finder Creek, Vadinar during the sampling conducted in consecutive High tide period and low tide of spring tide was recorded as 0.816-0.793 respectively. Shannon-Wiener's Index (H) of Zooplankton communities in the sampling station near SPM at Path Finder Creek, Vadinar during the sampling conducted in consecutive High tide period and low tide of spring tide was recorded as 0.834-0.808 respectively.

Shannon-Wiener's Index (H) of Zooplankton communities near jetty at Path finder creek was varying from 0.956-0.755 respectively during the sampling conducted consecutive high tide period and low tide period of Neap tide. While Shannon-Wiener's Index (H) of Zooplankton communities near SPM at Path finder creek was varying from 0.775-0.751 during the consecutive high tide and low tide period.

Typical values are generally between 1.5 and 3.5 in most ecological studies, and the index is rarely greater than 4. The Shannon-Wiener's index increases as both the richness and the evenness of the community increase. This result indicates that diversity of Zooplankton of Kandla Harbour region and nearby creeks stations is slightly high with very minimum diverse population but very few opportunist organisms are really well adapted to this environment and thrive better than other species.

Simpson's diversity index:

Simpson diversity index (1-D) of Zooplankton communities was below 0.9 most of sampling stations in the Kandla Harbour region and nearby creeks during high tide and low tide of spring tide period except few stations, which was varying from 0.780-0.909 between selected sampling stations with an average of 0.837 during high tide period and was varying from 0.785- 0.864 with an average value of 0.837 between selected sampling stations during low tide.

Simpson diversity index (1-D) of Zooplankton communities was below 0.9 at all sampling stations in the Kandla Harbour region and nearby creeks during high tide and low tide period of Neap tide except few, which was varying from 0.591-0.827 between selected sampling stations with an average of 0.753 during high tide period and was varying from 0.793-0.852 with an average value of 0.820 between selected sampling stations during consecutive low tide. This species diversity suggests a relatively few successful species in this habitat during November, 2022 sampling.

Simpson diversity index (1-D) of Zooplankton communities in the sampling station near jetty at Path Finder Creek, Vadinar during the sampling conducted in consecutive High tide period and low tide of spring tide was recorded as 0.821 and 0.815 respectively. Simpson diversity index (1-D) of Zooplankton communities in the sampling station near SPM at Path Finder Creek, Vadinar during the sampling conducted in consecutive High tide period and low tide of spring tide was recorded as 0.812 and 0.828 respectively.

Simpson diversity index (1-D) of Zooplankton communities in the sampling station near jetty at Path Finder Creek, Vadinar during the sampling conducted in consecutive High tide period and low tide of Neap tide was recorded as 0.836- 0.766 respectively. Simpson diversity index (1-D) of Zooplankton communities in the sampling station near SPM at Path Finder Creek, Vadinar during the sampling conducted in consecutive High tide period and low tide of spring tide was recorded as 0.768 and 0.719 respectively.

TABLE:-55 ZOOPLANKTON VARIATION IN ABUNDANCE AND DIVERSITY IN SUB SURFACE SAMPLING STATIONS IN DPA HARBOUR AREA AT KANDLA CREEK AND NEAR BY CREEKS DURING SPRING TIDE IN NOVEMBER 2022

Tide	Sampling Station	Abundance In $N \times 10^3 / m^3$	No of Species/groups observed /total species/group	% of diversity	Margalef's diversity index (Species Richness S)	Shannon Weiner index H (\log_{10})	Diversity Index (Simpson's Index) 1-D
HIGH TIDE	1	124	26/33	78.79	5.186	1.164	0.9089
	2	114	18/33	54.55	3.589	0.8655	0.7802
	3	102	16/33	48.48	3.243	0.9207	0.8189
	4	128	17/33	51.52	3.298	0.9062	0.8124
	5	107	16/33	48.48	3.21	0.997	0.8686
	6	25	8/33	24.24	2.175	0.7777	0.83
LOW TIDE	1	117	16/33	48.48	3.15	0.9709	0.8609
	2	144	20/33	60.61	3.823	0.9468	0.8238
	3	121	19/33	57.58	3.753	1.015	0.8639
	4	108	16/33	48.48	3.204	0.9609	0.8505
	5	103	12/33	36.36	2.373	0.7949	0.7853

TABLE:-56 ZOOPLANKTON VARIATIONS IN ABUNDANCE AND DIVERSITY IN SUB SURFACE SAMPLING STATIONS IN DPA HARBOUR AREA AT KANDLA CREEK AND NEAR BY CREEKS DURING NEAP TIDE IN NOVEMBER 2022

Tide	Sampling Station	Abundance In $No \times 10^3 / m^3$	No of Species/groups observed /total species/group	% of diversity	Margalef's diversity index (Species Richness S)	Shannon Weiner index H (\log_{10})	Diversity Index (Simpson's Index) 1-D
HIGH TIDE	1	82	18/32	56.25	3.858	0.9017	0.7814
	2	99	16/32	50.00	3.264	0.9138	0.8273
	3	89	13/32	40.63	2.673	0.8264	0.7763
	4	114	18/32	56.25	3.589	0.8478	0.7645
	5	98	14/32	43.75	2.835	0.8503	0.7766
	6	19	5/32	15.63	1.358	0.4901	0.5906
LOW TIDE	1	79	11/32	34.38	2.289	0.797	0.7932
	2	76	21/32	65.63	4.618	1.041	0.8516
	3	106	21/32	65.63	4.289	1.026	0.8446
	4	90	15/32	46.88	3.111	0.9087	0.8177
	5	100	16/32	50.00	3.257	0.865	0.7939

**Table:-57 ABUNDANCE OF ZOOPLANKTON IN SUBSURFACE SAMPLING STATIONS
IN DPA HARBOUR AREAATKANDLA CREEK AND NEAR BY CREEKS DURING
SPRING TIDE IN NOVEMBER 2022**

Tide	Surface	No of Sampling locations	Group of Zooplankton	Abundance of Zooplankton $\times 10^3 / m^3$ Group Range	Genera or species /total Zooplankton	Taxon Diversity % (Group level)
HIGH TIDE	Sub surface	6	tintinnids	9-26	11/33	33.33
			Copepods	11-51	9/33	27.27
			Arrow worms	0-1	1/33	3.03
			Mysids	0-2	1/33	3.03
			Urochordata	1-6	2/33	6.06
			Ciliates	0-2	1/33	3.03
			Larval forms	4-50	8/33	24.25
			TOTAL ZOOPLANKTON N/ M ³	25-128	33	
LOW TIDE	Sub surface	5	Tintinnids	18-33	11/33	33.33
			Copepods	37-49	9/33	27.27
			Arrow worms	0-4	1/33	3.03
			Mysids	0-2	1/33	3.03
			Urochordata	0-2	2/33	6.06
			Ciliates	0-2	1/33	3.03
			Larval forms	41-65	8/33	24.25
			TOTAL ZOOPLANKTON N/M ³	103-144	33	

TABLE:-58 ABUNDANCE OF ZOOPLANKTON IN SUBSURFACE SAMPLING STATIONS IN DPA HARBOUR AREA IN KANDLA CREEK AND, NEAR BY CREEKS DURING NEAP TIDE IN NOVEMBER 2022

Tide	Surface	No of Sampling locations	Group of Zooplankton	Abundance of Zooplankton $\times 10^3 / m^3$ Group Range	Genera or species /total Zooplankton	Taxon Diversity % (Group level)
HIGH TIDE	Sub surface	6	Tintinnids	0-14	10/32	31.25
			Copepods	6-49	10/32	31.25
			Arrow worms	0	1/32	3.13
			Mysids	0-6	2/32	6.25
			Urochordata	0-4	2/32	6.25
			Ciliates	0-2	1/32	3.13
			Larval forms	13-50	6/32	18.74
			TOTAL ZOOPLANKTON N/M ³	19-114	32	
LOW TIDE	Sub surface	5	tintinnids	4-17	10/32	31.25
			Copepods	25-45	10/32	31.25
			Arrow worms	0-2	1/32	3.13
			Mysids	0-6	2/32	6.25
			Urochordata	0-5	2/32	6.25
			Ciliates	0-1	1/32	3.13
			Larval forms	27-47	6/32	18.74
			TOTAL ZOOPLANKTON N/M ³	76-106	32	

Table:-59 ZOOPLANKTON VARIATIONS IN ABUNDANCE AND DIVERSITY IN SUBSURFACE SAMPLING STATIONS IN DPA OOT AREA AT PATH FINDER CREEK AND NEAR BY SPM DURING SPRING TIDE IN NOVEMBER 2022

Tide	Sampling Station	Abundance In $\times 10^3 N / m^3$	No of Species/groups observed /total species/group	% of diversity	Margalef's diversity index (Species Richness S)	Shannon Weiner index H (log ₁₀)	Diversity Index (Simpson's Index) 1-D
HIGH TIDE	Jetty	91	10/20	50.00	1.995	0.816	0.821
	SPM	101	13/20	65.00	2.6	0.834	0.812
LOW TIDE	Jetty	86	9/20	45.00	1.796	0.793	0.815
	SPM	70	10/20	50.00	2.118	0.808	0.828

TABLE:-60 ZOOPLANKTON VARIATION IN ABUNDANCE AND DIVERSITY IN SUB SURFACE SAMPLING STATIONS IN DPA OOT AREA AT PATH FINDER CREEK AND NEAR BY SPM DURING NEAP TIDE IN NOVEMBER 2022

Tide	Sampling Station	Abundance In $N \times 10^3 / m^3$	No of Species/groups observed /total species/group	% of diversity	Margalef's diversity index (Species Richness S)	Shannon Weiner index $H (\log_{10})$	Diversity Index (Simpson's Index) 1-D
HIGH TIDE	Jetty	87	18/21	85.71	3.807	0.956	0.836
	SPM	64	12/21	57.14	2.645	0.775	0.768
LOW TIDE	Jetty	65	11/21	52.38	2.396	0.755	0.766
	SPM	87	15/21	71.43	3.135	0.751	0.719


Table:-61 ABUNDANCE OF ZOOPLANKTON IN SUBSURFACE SAMPLING STATIONS IN DPA OOT AREA AND PATH FINDER CREEK AND NEAR BY SPM DURING SPRING TIDE IN NOVEMBER 2022

Tide	Surface	No of Sampling locations	Group of Zooplankton	Abundance of Zooplankton $\times 10^3 / m^3$ Group Range	Genera or species /total Zooplankton	Taxon Diversity % (Group level)
HIGH TIDE	Sub surface	2	Tintinnids	24-32	5/20	25.00
			Copepods	28-38	8/20	40.00
			Urochordata	1-2	2/20	10.00
			Ciliates	0-1	1/20	5.00
			Larval forms	30-36	4/20	20.00
			TOTAL ZOOPLANKTON	91-101	20	
LOW TIDE	Sub surface	2	Tintinnids	17-21	5/20	25.00
			Copepods	30-37	8/20	40.00
			Urochordata	0	2/20	10.00
			Ciliates	0	1/20	5.00
			Larval forms	19-32	4/20	20.00
			TOTAL ZOOPLANKTON	70-86	20	


TABLE:-62 ABUNDANCE OF ZOOPLANKTON IN SUBSURFACE SAMPLING STATIONS IN DPA OOT AREA AT PATH FINDER CREEK AND NEAR BY SPM DURING NEAP TIDE IN NOVEMBER 2022

Tide	Surface	No of Sampling locations	Group of Zooplankton	Abundance of Zooplankton $\times 10^3 / m^3$ Group Range	Genera or species /total Zooplankton	Taxon Diversity % (Group level)
HIGH TIDE	Sub surface	2	tintinnids	9-16	7/21	33.33
			Copepods	23-34	6/21	28.57
			Arrow worms	0	1/21	4.76
			Urochordata	0-2	2/21	9.52
			Larval forms	32-35	5/21	23.82
			TOTAL ZOOPLANKTON	64-87	21	
LOW TIDE	Sub surface	2	tintinnids	6-9	7/21	33.33
			Copepods	29	6/21	28.57
			Arrow worms	0-1	1/21	4.76
			Urochordata	0-3	2/21	9.52
			Larval forms	27-48	5/21	23.82
			TOTAL ZOOPLANKTON	65-87	21	


**Species Composition % of Zooplankton during High tide and Low tide period of spring tide In
Kandla Creek and nearby Creeks**



**Species Composition % of Zooplankton during High tide and Low tide period of Neap tide In
Kandla Creek and nearby Creeks**



Species Composition % of Zooplankton during High tide and Low tide period of Spring tide In Path Finder Creek and near Jetty



Species Composition % of Zooplankton during High tide and Low tide period of Neap tide In Path Finder Creek near jetty and nearby SPM




TABLE:-63 SYSTEMATIC ACCOUNT OF PHYTOPLANKTON IN THE SAMPLING LOCATIONS OF DPA HARBOUR AREA AT KANDLA CREEK AND NEARBY CREEKS DURING NEAP TIDE OF NOVEMBER 2022

CLASS	ORDER	FAMILY	GENUS/SPECIES	#	Relative Abundance
Cyanophyceae	Nostocales	Oscillatoriaceae	<i>Oscillatoria sp.</i>	B1	Very sparse
	Oscillatoriales	Phormidiaceae	<i>Planktothrix sp.</i>	B2	Very sparse
Coscinodiscophyceae	Biddulphiales	Biddulphiaceae	<i>Biddulphiasp</i>	D1	Abundant
	Chaetocerotales	Chaetocerotaceae	<i>Bacteriastrum sp</i>	D2	Very sparse
			<i>Chaetoceros sp.</i>	D3	Scattered
	Corethrales	Corethraceae	<i>Corethron sp</i>	D4	Very sparse
	Coscinodiscales	Coscinodiscaceae	<i>Coscinodiscus sp.</i>	D5	Dominant
	Hemiaulales	Bellerocheaceae	<i>Bellerochea sp</i>	D6	Very sparse
		Streptothecaceae	<i>Helicotheca sp</i>	D7	Very sparse
	Rhizosoleniales	Rhizosoleniaceae	<i>Rhizosolenia sp.</i>	D8	Sparse
	Lithodesmiales	Lithodesmiaceae	<i>Ditylum sp</i>	D9	Dominant
	Thalassiosirales	Thalassiosiraceae	<i>Planktoniellasp</i>	D10	Very sparse
		Skeletonemataceae	<i>Skeletonemas sp</i>	D11	Abundant
	Triceratiales	Triceratiaceae	<i>Odontella sp.</i>	D12	Very sparse
			<i>Triceratium sp.</i>	D13	Very sparse
Bacillariophyceae	Bacillariales	Bacillariaceae	<i>Bacillaria sp.</i>	D14	Very sparse
			<i>Nitzschia sp</i>	D15	Sparse
			<i>Pseudo-nitzschia sp.</i>	D16	Very sparse
	Naviculales	<u>Pleurosigmataceae</u>	<i>Pleurosigma sp.</i>	D17	Very sparse
	Surirellales	Entomoneidaceae	<i>Entomoneis sp.</i>	D18	Very sparse
Fragilariophyceae	Fragilariales	Fragilariaceae	<i>Asterionellopsis sp</i>	D19	Scattered
			<i>Fragilariasp</i>	D20	Very sparse
			<i>Synedrassp</i>	D21	Very sparse

	Striatellales	Striatellaceae	<i>Grammatophora sp</i>	D22	Very sparse
	Thalassionematales	Thalassionemataceae	<i>Thalassionema sp.</i>	D23	Sparse
			<i>Thalassiothrix sp.</i>	D24	Very sparse
Noctiluca / Noctiluciphyceae (Dinokaryota)	Noctilucales	Noctilucaceae	<i>Noctiluca sp.</i>	DF1	Sparse
Dinophyceae	Peridinales	Protopteridiniaceae	<i>Protopteridinium sp.</i>	DF2	Very sparse
	Gonyaulacales	Pyrophacaceae	<i>Pyrophacus sp.</i>	DF3	Very sparse
		Ceratiaceae	<i>Ceratium furca</i>	DF4	Very sparse
			<i>Ceratium tripos</i>	DF5	Very sparse

TABLE:-64 SYSTEMATIC ACCOUNT OF PHYTOPLANKTON IN THE SAMPLING LOCATIONS IN OF DPA HARBOUR AREA AT KANDLA CREEK AND NEARBY CREEKS DURING SPRING TIDE OF NOVEMBER 2022:

CLASS	ORDER	FAMILY	GENUS/SPECIES	#	Relative Abundance
Cyanophyceae	Nostocales	Oscillatoriaceae	<i>Oscillatoria sp.</i>	B1	Very sparse
	Oscillatoriales	Phormidiaceae	<i>Planktothrix sp.</i>	B2	Very sparse
Coscinodiscophyceae	Biddulphiales	Biddulphiaceae	<i>Biddulphia</i> sp.	D1	Sparse
	Chaetocerotales	Chaetocerotaceae	<i>Chaetoceros sp.</i>	D2	Abundant
	Corethrales	Corethraceae	<i>Corethron sp.</i>	D3	Very sparse
	Coscinodiscales	Coscinodiscaceae	<i>Coscinodiscus sp.</i>	D4	Abundant
	Rhizosoleniales	Rhizosoleniaceae	<i>Rhizosolenia sp.</i>	D5	Sparse
	Leptocylindrales	Leptocylindraceae	<i>Leptocylindrus sp.</i>	D6	Very sparse
	Lithodesmiales	Lithodesmiaceae	<i>Ditylum sp.</i>	D7	Scattered
	Thalassiosirales	Thalassiosiraceae	<i>Planktoniella</i> sp.	D8	Very sparse
		Lauderiaceae	<i>Lauderia sp.</i>	D9	Very sparse
		Skeletonemataceae	<i>Skeletonemas</i> sp.	D10	Dominant
	Triceratiales	Triceratiaceae	<i>Odontella sp.</i>	D11	Very sparse
			<i>Triceratium sp.</i>	D12	Very sparse
Bacillariophyceae	Bacillariales	Bacillariaceae	<i>Bacillaria sp.</i>	D13	Very sparse
			<i>Nitzschia sp.</i>	D14	Very sparse
			<i>Pseudo-nitzschia sp.</i>	D15	Very sparse
	Naviculales	Naviculaceae	<i>Navicula sp.</i>	D16	Very sparse
		Plagiotropidaceae	<i>Plagiotropis sp.</i>	D17	Very sparse
		<u>Pleurosigmataceae</u>	<i>Pleurosigma sp.</i>	D18	Sparse
	Surirellales	Entomoneidaceae	<i>Entomoneis sp.</i>	D19	Very sparse
		Surirellaceae	<i>Surirella sp.</i>	D20	Very sparse
Fragilariophyceae	Fragilariales	Fragilariaceae	<i>Asterionellopsis sp.</i>	D21	Sparse

			<i>Fragilariasp</i>	D22	Very sparse
			<i>Synedrasp</i>	D23	Sparse
	Striatellales	Striatellaceae	<i>Grammatophora sp</i>	D24	Very sparse
	Thalassionematales	Thalassionemataceae	<i>Thalassionema sp.</i>	D25	Scattered
			<i>Thalassiothrix sp.</i>	D26	Sparse
Noctiluca / Noctiluciphyceae (Dinokaryota)	Noctilucales	Noctilucaceae	<i>Noctiluca sp.</i>	DF1	Sparse
Dinophyceae	Peridiniales	Protoperidiniaceae	<i>Protoperidinium sp.</i>	DF2	Very sparse
	Gonyaulacales	Ceratiaceae	<i>Ceratium breve</i>	DF3	Very sparse
			<i>Ceratium furca</i>	DF4	Very sparse
			<i>Ceratium fusus</i>	DF5	Very sparse
			<i>Ceratium tripos</i>	DF6	Very sparse

TABLE:-65 SYSTEMATIC ACCOUNT OF PHYTOPLANKTON IN THE SAMPLING LOCATIONS IN OF DPA OOT AREA AT PATH FINDER CREEK AND NEARBY SPM AT VADINARDURING NEAP TIDE OF NOVEMBER 2022:

CLASS	ORDER	FAMILY	GENUS/SPECIES	#	Relative Abundance
Cyanophyceae	Nostocales	Oscillatoriaceae	<i>Lyngbya sp.</i>	B1	Very sparse
			<i>Oscillatoria sp.</i>	B2	Very sparse
			<i>Spirulina sp.</i>	B3	Very sparse
	Oscillatoriales	Phormidiaceae	<i>Planktothrix sp.</i>	B4	Very sparse
Coscinodiscophyceae	Biddulphiales	Biddulphiaceae	<i>Biddulphia</i> sp	D1	Scattered
	Chaetocerotales	Chaetocerotaceae	<i>Chaetoceros</i> sp	D2	Scattered
	Corethrales	Corethraceae	<i>Corethron sp</i>	D3	Very sparse
	Coscinodiscales	Coscinodiscaceae	<i>Coscinodiscus sp.</i>	D4	Dominant
	Hemiaulales	Bellerocheaceae	<i>Belleroche</i> sp	D5	Very sparse
		Hemiaulaceae	<i>Cerataulina sp.</i>	D6	Very sparse
			<i>Eucampia sp</i>	D7	Very sparse
		Streptothecaceae	<i>Helicotheca sp</i>	D8	Very sparse
	Leptocylindrales	Leptocylindraceae	<i>Leptocylindrus sp</i>	D9	Very sparse
	Lithodesmiales	Lithodesmiaceae	<i>Ditylum</i> sp	D10	Abundant
	Rhizosoleniales	Rhizosoleniaceae	<i>Dactyliosolen sp.</i>	D11	Very sparse
			<i>Rhizosolenia sp.</i>	D12	Sparse
	Thalassiosirales	Skeletonemataceae	<i>Skeletonema sp.</i>	D13	Abundant
		Lauderiaceae	<i>Lauderia sp</i>	D14	Very sparse
		Thalassiosiraceae	<i>Planktoniella</i> sp	D15	Very sparse
	Triceratiales	Triceratiaceae	<i>Odontella</i> sp	D16	Very sparse
			<i>Triceratium</i> sp	D17	Very sparse
Bacillariophyceae	Bacillariales	Bacillariaceae	<i>Bacillaria</i> sp.	D18	Abundant
			<i>Nitzschia sp</i>	D19	Very sparse

			<i>Pseudo-nitzschia</i> sp	D20	Scattered
	Naviculales	Naviculaceae	<i>Meuniera</i> sp.	D21	Very sparse
			<i>Navicula</i> sp	D22	Very sparse
		Pinnulariaceae	<i>Pinnularia</i> sp	D23	Very sparse
		<u>Pleurosigmataceae</u>	<i>Pleurosigma</i> sp	D24	Very sparse
	Surirellales	Entomoneidaceae	<i>Entomoneis</i> sp.	D25	Very sparse
		Surirellaceae	<i>Surirella</i> sp	D26	Very sparse
Fragilariophyceae	Climacospheniales	Climacospheniaceae	<i>Climacosphenia</i> sp.	D27	Very sparse
	Fragilariales	Fragilariaceae	<i>Asterionellopsis</i> sp.	D28	Very sparse
			<i>Synedra</i> sp.	D29	Very sparse
	Striatellales	Striatellaceae	<i>Striatella</i> sp	D30	Very sparse
	Thalassionematales	Thalassionemataceae	<i>Thalassionema</i> sp.	D31	Sparse
			<i>Thalassiothrix</i> sp.	D32	Sparse
Dinophyceae	Peridiniales	Protoperidiniaceae	<i>Protoperidinium</i> sp.	DF1	Very sparse
	Dinophysales	Dinophysaceae	<i>Dinophysis</i> sp.	DF2	Very sparse
	Gonyaulacales	Pyrophacaceae	<i>Pyrophacus</i> sp.	DF3	Very sparse
		Ceratiaceae	<i>Ceratium furca</i>	DF4	Very sparse
			<i>Ceratium fusus</i>	DF5	Very sparse
			<i>Ceratium tripos</i>	DF6	Very sparse

TABLE:-66 SYSTEMATIC ACCOUNT OF PHYTOPLANKTON IN THE SAMPLING LOCATIONS IN OF DPAOOT AREA AT PATH FINDER CREEK AND NEARBY SPM AT VADINAR DURING AND SPRING TIDE OF NOVEMBER 2022:

CLASS	ORDER	FAMILY	GENUS/SPECIES	#	Relative Abundance
Cyanophyceae	Chroococcales	Chroococcaceae	<i>Merismopedia sp.</i>	B1	Very sparse
	Nostocales	Oscillatoriaceae	<i>Lyngbya sp.</i>	B2	Very sparse
			<i>Oscillatoria sp.</i>	B3	Sparse
	Oscillatoriales	Phormidiaceae	<i>Planktothrix sp.</i>	B4	Very sparse
	Stigonematales	Stigonemataceae	<i>Stigonema sp.</i>	B5	Very sparse
Coscinodiscophyceae	Biddulphiales	Biddulphiaceae	<i>Biddulphia</i> sp.	D1	Sparse
	Chaetocerotales	Chaetocerotaceae	<i>Chaetoceros sp.</i>	D2	Dominant
	Corethrales	Corethraceae	<i>Corethron sp.</i>	D3	Very sparse
	Coscinodiscales	Coscinodiscaceae	<i>Coscinodiscus sp.</i>	D4	Abundant
	Hemiaulales	Belleracheaceae	<i>Bellerachea sp.</i>	D5	Very sparse
		Hemiaulaceae	<i>Cerataulina sp.</i>	D6	Very sparse
		Streptothecaceae	<i>Helicotheca sp.</i>	D7	Very sparse
	Rhizosoleniales	Rhizosoleniaceae	<i>Rhizosolenia sp.</i>	D8	Scattered
	Leptocylindrales	Leptocylindraceae	<i>Leptocylindrus sp.</i>	D9	Very sparse
	Lithodesmiales	Lithodesmiaceae	<i>Ditylum sp.</i>	D10	Abundant
	Thalassiosirales	Thalassiosiraceae	<i>Planktoniella</i> sp.	D11	Very sparse
		Lauderiaceae	<i>Lauderia sp.</i>	D12	Very sparse
	Triceratiales	Triceratiaceae	<i>Odontella sp.</i>	D13	Sparse
			<i>Triceratium sp.</i>	D14	Very sparse
Bacillariophyceae	Bacillariales	Bacillariaceae	<i>Bacillaria sp.</i>	D15	Scattered
			<i>Nitzschia sp.</i>	D16	Very sparse
			<i>Pseudo-nitzschia</i> sp.	D17	Sparse
	Naviculales	Pinnulariaceae	<i>Pinnularia</i> sp.	D18	Very sparse

		<u>Pleurosigmataceae</u>	<i>Pleurosigma</i> sp.	D19	Very sparse
	Surirellales	Entomoneidaceae	<i>Entomoneis</i> sp.	D20	Very sparse
		Surirellaceae	<i>Surirella</i> sp.	D21	Very sparse
Fragilariophyceae	Fragilariales	Fragilariaceae	<i>Asterionellopsis</i> sp	D22	Sparse
			<i>Synedrasp</i>	D23	Very sparse
	Thalassionematales	Thalassionemataceae	<i>Thalassionema</i> sp.	D24	Sparse
			<i>Thalassiothrix</i> sp.	D25	Very sparse
Dinophyceae	Peridinales	Protoperidiniaceae	<i>Protoperidinium</i> sp.	DF1	Very sparse
	Dinophysales	Dinophysaceae	<i>Dinophysis</i> sp.	DF2	Very sparse
	Gonyaulacales	Pyrophacaceae	<i>Pyrophacus</i> sp.	DF3	Very sparse
		Ceratiaceae	<i>Ceratium furca</i>	DF4	Very sparse
			<i>Ceratium fusus</i>	DF5	Very sparse
			<i>Ceratium tripos</i>	DF6	Very sparse

TABLE:-67 SYSTEMATIC ACCOUNT OF ZOOPLANKTON FROM THE SAMPLING LOCATIONS OF DPA HARBOUR AREA AT KANDLA CREEK AND NEARBY CREEKS DURING NEAP TIDE OF NOVEMBER 2022:

CLASS	ORDER	FAMILY	GENUS/SPECIES	#	RELATIVE ABUNDANCE
Spirotrichea	Tintinnida	Tintinnidiidae	<i>Leprotintinnus</i> sp.	T1	Very sparse
		Codonellidae	<i>Tintinnopsis dadayi</i>	T2	Very sparse
			<i>Tintinnopsis failakkaensis</i>	T3	Very sparse
			<i>Tintinnopsis gracilis</i>	T4	Very sparse
			<i>Tintinnopsis mortensenii</i>	T5	Very sparse
			<i>Tintinnopsis radix</i>	T6	Very sparse
			<i>Tintinnopsis tocaninensis</i>	T7	Very sparse
		Tintinnidae	<i>Amphorellopsis</i> sp.	T8	Very sparse
			<i>Eutintinnus</i> sp.	T9	Very sparse
		Xystonellidae	<i>Favella</i> sp.	T10	Very sparse
Crustacea Subclass: Copepoda	Calanoida	Paracalanidae	<i>Acrocalanus</i> sp.	C1	Sparse
			<i>Parvocalanus</i> sp.	C2	Very sparse
		Acartiidae	<i>Acartia</i> sp.	C3	Very sparse
		Clausocalanidae	<i>Clausocalanus</i> sp.	C4	Very sparse
		Centropagidae	<i>Centropages</i> sp.	C5	Very sparse
		Temoridae	<i>Temora</i> sp.	C6	Very sparse
	Cyclopoida	Oithonidae	<i>Oithona</i> sp.	C7	Abundant
	Harpacticoida	Ectinosomatidae	<i>Microsetella</i> sp.	C8	Scattered
		Euterpinae	<i>Euterpina</i> sp.	C9	Sparse
	Poecilostomatoida	Oncaeidae	<i>Oncaea</i> sp.	C10	Very sparse
Sagittioidea	Aphragmophora	Sagittidae	<i>Sagitta</i> sp.	A1	Very sparse
Malacostraca	Mysida,	Penaeidae	<i>Metapenaeus</i> sp.	M1	Very sparse
	Decapoda	Solenoceridae	<i>Solenocera</i> sp.	M2	Very sparse

Environmental Monitoring Report of Deendayal Port Authority, November - 2022

Appendicularia		Fritillariidae	<i>Fritillaria sp.</i>	U1	Very sparse
		Oikopleuridae	<i>Oikopleura sp.</i>	U2	Very sparse
Oligohymenophorea	Sessilida	Zoothamniidae	<i>Zoothamnium sp.</i>	CI1	Very sparse
Copepoda			Nauplius larvae of copepods	L1	Dominant
Malacostraca Decapoda			Brachyuran zoea	L2	Very sparse
Maxillopoda Thecostraca			Cirripede larvae	L3	Very sparse
			Cyphonautes larvae	L4	Very sparse
			Ophiopluteus larvae	L5	Very sparse
Polychaeta			Trochophore larvae	L6	Very sparse

TABLE:-68 SYSTEMATIC ACCOUNT OF ZOOPLANKTON FROM THE SAMPLING OF DPA HARBOUR AREA AT KANDLA CREEK AND NEARBY CREEKS DURING SPRING TIDE OF NOVEMBER 2022:

CLASS	ORDER	FAMILY	GENUS/SPECIES	#	RELATIVE ABUNDANCE
Spirotrichea	Tintinnida	Tintinnidiidae	<i>Leptotintinnus</i> sp.	T1	Scattered
		Codonellidae	<i>Tintinnopsis dadayi</i>	T2	Very sparse
			<i>Tintinnopsis failakkaensis</i>	T3	Very sparse
			<i>Tintinnopsis gracilis</i>	T4	Very sparse
			<i>Tintinnopsis mortensenii</i>	T5	Very sparse
			<i>Tintinnopsis radix</i>	T6	Sparse
			<i>Tintinnopsis tocanensis</i>	T7	Very sparse
		Metacyclidae	<i>Metacyclis</i> sp.	T8	Very sparse
		Tintinnidae	<i>Amphorellopsis</i> sp.	T9	Very sparse
			<i>Eutintinnus</i> sp.	T10	Very sparse
		Xystonellidae	<i>Favella</i> sp.	T11	Sparse
Crustacea Subclass: Copepoda	Calanoida	Paracalanidae	<i>Acrocalanus</i> sp.	C1	Scattered
			<i>Parvocalanus</i> sp.	C2	Very sparse
		Acartiidae	<i>Acartia</i> sp.	C3	Very sparse
		Clausocalanidae	<i>Clausocalanus</i> sp.	C4	Very sparse
		Centropagidae	<i>Centropages</i> sp.	C5	Very sparse
		Eucalanidae	<i>Subeucalanus</i> sp.	C6	Very sparse
	Cyclopoida	Oithonidae	<i>Oithona</i> sp.	C7	Abundant
	Harpacticoida	Ectinosomatidae	<i>Microsetella</i> sp.	C8	Sparse
		Euterpinae	<i>Euterpina</i> sp.	C9	Sparse
Sagittioidea	Aphragmophora	Sagittidae	<i>Sagitta</i> sp.	A1	Very sparse
Malacostraca	Mysida, Decapoda	Solenoceridae	<i>Solenocera</i> sp.	M1	Very sparse

Appendicularia		Fritillariidae	<i>Fritillaria sp.</i>	U1	Very sparse
		Oikopleuridae	<i>Oikopleura sp.</i>	U2	Very sparse
Oligohymenophorea	Sessilida	Zoothamniidae	<i>Zoothamnium sp.</i>	CI1	Very sparse
Copepoda			Nauplius larvae of copepods	L1	Dominant
Malacostraca			Brachyuran zoea	L2	Sparse
Decapoda					
Maxillopoda			Cirripede larvae	L3	Very sparse
Thecostraca					
			Cyphonautes larvae	L4	Very sparse
			Ophiopluteus larvae	L5	Very sparse
Gastropoda			Opisthobranchia larvae	L6	Very sparse
Streptoneura					
Polychaeta			Trochophore larvae	L7	Sparse
Pelecypoda			Veliger larvae of bivalves	L8	Very sparse

TABLE:-69 SYSTEMATIC ACCOUNT OF ZOOPLANKTON FROM THE SAMPLING LOCATIONS OF DPA OOT AREA AT PATH FINDER CREEK AND NEARBY SPM AT VADINARDURING NEAP TIDE OF NOVEMBER 2022:

CLASS	ORDER	FAMILY	GENUS/SPECIES	#	RELATIVE ABUNDANCE
Spirotrichea	Tintinnida	Tintinnidiidae	<i>Leptotintinnussp.</i>	T1	Sparse
		Codonellidae	<i>Tintinnopsisfailakkaensis</i>	T2	Very sparse
			<i>Tintinnopsis gracilis</i>	T3	Very sparse
			<i>Tintinnopsis radix</i>	T4	Very sparse
			<i>Tintinnopsis tocaninensis</i>	T5	Very sparse
		Tintinnidae	<i>Amphorellopsis sp.</i>	T6	Very sparse
		Xystonellidae	<i>Favella sp.</i>	T7	Very sparse
Crustacea Subclass: Copepoda	Calanoida	Paracalanidae	<i>Acrocalanus sp.</i>	C1	Scattered
			<i>Parvocalanus sp.</i>	C2	Very sparse
	Cyclopoida	Oithonidae	<i>Oithona sp.</i>	C3	Abundant
	Harpacticoida	Euterpinae	<i>Euterpina sp.</i>	C4	Very sparse
		Ectinosomatidae	<i>Microsetellasp.</i>	C5	Very sparse
	Poecilostomatoida	Oncaeidae	<i>Oncaea sp.</i>	C6	Very sparse
Sagittioidea	Aphragmophora	Sagittidae	<i>Sagitta sp.</i>	A1	Very sparse
Appendicularia		Fritillariidae	<i>Fritillaria sp.</i>	U1	Very sparse
		Oikopleuridae	<i>Oikopleura sp.</i>	U2	Very sparse
Copepoda			Nauplius larvae of copepods	L1	Dominant
Maxillopoda Thecostraca			Cirripede larvae	L2	Very sparse
Gastropoda Streptoneura			Opisthobranchia larvae	L3	Very sparse
Polychaeta			Trochophore larvae	L4	Very sparse
Pelecypoda			Veliger larvae of bivalves	L5	Very sparse

TABLE:-70 SYSTEMATIC ACCOUNT OF ZOOPLANKTON FROM THE SAMPLING LOCATIONS OF DPA OOT AREA AT PATH FINDER CREEK AND NEARBY SPM AT VADINAR DURING SPRING TIDE OF NOVEMBER 2022:

CLASS	ORDER	FAMILY	GENUS/SPECIES	#	RELATIVE ABUNDANCE
Spirotrichea	Tintinnida	Tintinnidiidae	<i>Leprotintinnussp.</i>	T1	Abundant
		Codonellidae	<i>Tintinnopsisgracilis</i>	T2	Very sparse
			<i>Tintinnopsis mortensenii</i>	T3	Very sparse
			<i>Tintinnopsis radix</i>	T4	Very sparse
		Xystonellidae	<i>Favella sp.</i>	T5	Scattered
Crustacea Subclass: Copepoda	Calanoida	Paracalanidae	<i>Acrocalanus sp.</i>	C1	Sparse
			<i>Parvocalanus sp.</i>	C2	Very sparse
		Centropagidae	<i>Centropages sp.</i>	C3	Very sparse
		Tortanidae	<i>Tortanus sp.</i>	C4	Very sparse
	Cyclopoida	Oithonidae	<i>Oithona sp.</i>	C5	Abundant
		Euterpinae	<i>Euterpina sp.</i>	C6	Very sparse
	Harpacticoida	Ectinosomatidae	<i>Microsetellasp.</i>	C7	Scattered
	Poecilostomatatoida	Corycaidae	<i>Corycaeus sp.</i>	C8	Very sparse
Appendicularia		Fritillariidae	<i>Fritillaria sp.</i>	U1	Very sparse
		Oikopleuridae	<i>Oikopleura sp.</i>	U2	Very sparse
Oligohymenophorea	Sessilida	Zoothamniidae	<i>Zoothamnium sp.</i>	CI1	Very sparse
Copepoda			Nauplius larvae of copepods	L1	Dominant
Malacostraca Decapoda			Brachyuran zoea	L2	Very sparse
Gastropoda Streptoneura			Opisthobranchia larvae	L3	Very sparse
Pelecypoda			Veliger larvae of bivalves	L4	Very sparse

BENTHIC ORGANISMS:

Few Benthic organisms were observed in the collected sediments by using the Van-Veen grabs during the sampling conducted during spring tide period and Neap tide period from DPA harbour region and nearby creek. The Meio-benthic organisms during spring tide were represented by Polychaetes *Tharyx sp.* and *Nereis sp.*, during Neap tide by *Nereis sp.* and few Amphipods. Population of benthic fauna was varying from 10-60- N/m² during spring tide and 0-80 N/m² during Neap tide. The benthic communities at path finder Creek were represented by Polychaetes *Glycera sp.* *Cirratulus sp.* *Nereis sp.* and few Amphipods. Their population was varying as 60 N/m² at OOT jetty premises and 80 N/m² near the SPM area during spring tide and 50 N/m² at OOT jetty premises and 50 N/m² near the SPM area during Neap tide period.

Table:-71 BENTHIC FAUNA IN THE SAMPLING LOCATIONS IN DPA HARBOUR AREA CREEKS DURING SPRING TIDE IN NOVEMBER 2022

ABUNDANCE IN NO/M ² DIFFERENT SAMPLING STATIONS						
REPRESENTATION BY GROUP	DPA HARBOUR			CREEKS		
Benthic fauna						
POLYCHAETES	DPA-1	DPA-2	DPA-3	DPA-4	DPA-5	DPA-6
Family : CIRRATULIDAE <i>Tharyxsp.</i>	20	10	10	0	0	NS
Family :NEREIDAE <i>Nereis sp.</i>	0	0	0	20	40	NS
AMPHIPODA	0	0	0		20	NS
TOTAL Benthic Fauna NUMBER/ M ²	20	10	10	20	60	NS

NS: No sample

Table:-72 BENTHIC FAUNA IN THE SAMPLING LOCATIONS IN DPA HARBOUR AREA CREEKS DURING NEAP TIDE IN NOVEMBER 2022

ABUNDANCE IN NO/M ² DIFFERENT SAMPLING STATIONS						
REPRESENTATION BY GROUP	DPA HARBOUR			CREEKS		
Benthic fauna						
POLYCHAETES	DPA-1	DPA-2	DPA-3	DPA-4	DPA-5	DPA-6
Family :NEREIDAE <i>Nereis sp.</i>	0	0	0	40	60	NS
<i>Amphipoda</i>	0	20	10	10	20	NS
TOTAL Benthic Fauna NUMBER/M ²	0	20	10	50	80	NS

**Table:-73 BENTHIC FAUNA IN THE SAMPLING LOCATIONS IN DPA OOT JETTY AREA,
VADINAR DURING SPRING TIDE IN NOVEMBER 2022**

ABUNDANCE IN NO/M ² DIFFERENT SAMPLING STATIONS		
REPRESENTATION BY GROUP	OOT Jetty Area	SPM area
POLYCHAETES		
Family : Glyceride <i>Glycerasp.</i>	20	40
Family : CIRRATULIDAE <i>Cirratulussp.</i>	0	20
Family: NEREIDAE <i>Nereis sp.</i>	30	10
<i>Amphipoda</i>	10	20
TOTAL Benthic Fauna NUMBER/ M ²	60	80

**Table:-74 BENTHIC FAUNA IN THE SAMPLING LOCATIONS IN DPA OOT JETTY AREA,
VADINAR DURING NEAP TIDE IN NOVEMBER 2022**

ABUNDANCE IN NO/M ² DIFFERENT SAMPLING STATIONS		
REPRESENTATION BY GROUP	OOT Jetty Area	SPM area
POLYCHAETES		
Family : Glyceridase <i>Glycera sp.</i>	20	40
Family: NEREIDAE <i>Nereis sp.</i>	30	10
TOTAL Benthic Fauna NUMBER/ M ²	50	50

CHAPTER-11

CONCLUSIVE SUMMARY & REMEDIAL MEASURES

11.0 Conclusive Summary and Remedial measures Suggested

- The AAQ monitoring of six locations at Deendayal Port Authority indicates that the mean PM_{10} and $PM_{2.5}$ values for four locations viz. Marine Bhavan, Oil Jetty, Estate Office and Coal storage area were found higher than the permissible limit (standards $100 \mu g/m^3$, $60 \mu g/m^3$). The higher concentration of Particulate matter at Marine Bhavan may be due to vehicles emissions during loading-unloading of food grains and timbers; at Estate office due to construction work, vehicles emission produced from trucks, heavy duty vehicles that pass through the road outside Kandla port and Oil jetty area; while at Coal Storage area lifting of coal from grab yard and other coal handling processes. Moreover, the transportation of coal produces pollution from heavy vehicles. At Tuna Port location, concentration of PM_{10} varied from $88-175 \mu g/m^3$ and mean value was observed $145 \mu g/m^3$ which was exceed the prescribed standard limit ($100 \mu g/m^3$), concentration of $PM_{2.5}$ was ranged from $47-87 \mu g/m^3$ and mean was found $71 \mu g/m^3$ which was exceed the standard limit ($60 \mu g/m^3$). At Gopalpuri PM_{10} concentration ranged from $67-168 \mu g/m^3$ and mean was $127 \mu g/m^3$ while $PM_{2.5}$ concentration ranged from $34-94 \mu g/m^3$ and mean was $66 \mu g/m^3$ were found exceed standard limit prescribed by NAAQS.
- At Vadinar, the average concentration of PM_{10} was $114 \mu g/m^3$ and $PM_{2.5}$ was $74 \mu g/m^3$ at Admin Colony which was slightly exceed the standard limit while at Signal building the mean concentration PM_{10} was $100 \mu g/m^3$ and $PM_{2.5}$ was $61 \mu g/m^3$ which were very close to standard limit.
- During winter, the concentration of PM_{10} and $PM_{2.5}$ has been slowly augmented and reached a peak in the evening due to surface inversion of temperature after sunset. Thus, the pollutants are subsequently trapped in the lower layer of the atmosphere due to high atmospheric air pressure.
- Further, precautionary measures and management strategies to minimize the effect of particulate as well as gaseous pollutants have also been suggested for achieving its ambient levels in and around Kandla Port and Vadinar Port, Gujarat, India.
- Drinking water at all the twenty locations was found potable and it was found within in line of BIS standards (IS: 10500-2012).
- Transportation systems are the main source of noise pollution in project areas. Noise sources in port operations include cargo handling, vehicular traffic, and loading / unloading

containers and ships. All sampling location were within the permissible limit day time 75 dB (A) and night time 70 dB (A) for the industrial area.

- The treated sewage water of Kandla STP, Deendayal Port Colony (Gopalpuri) STP and Vadinar were in line with the standards set by the Central Pollution Control Board.
- It was suggested to monitor the STP performance on regular basis to avoid flow of contamination / Polluted water into the sea.
- Good species diversity suggests a relatively successful species in this habitat. A greater number of successful species and a more stable ecosystem. More ecological niches are available and the environment is less likely to be hostile complex food webs environmental change is less likely to be damaging to the ecosystem as a whole.
- The results obtained from the study for biological and ecological parameters in marine water for Arabian Sea at surrounding area of Deendayal Port Authority (DPA) Kandla and Vadinar were not affected by Port activities.
- The mean day time temperature at Deendayal Port was 27.92 °C. The day-time maximum temperature was 32.9°C and minimum was 21.1 °C. The mean night time temperature recorded was 25.47 °C. The night-time maximum temperature was 29.7°C and minimum was 20.0 °C. The mean Solar Radiation in November month was 167.27 w/m². The maximum solar radiation was recorded 759 w/m² in 4th November, 2022 and the minimum solar radiation was recorded 1.80 w/m² in 30th November, 2022. The mean Relative humidity was 69.00 % for the month of November. Maximum Relative humidity was recorded 99.0 % and minimum Relative humidity was recorded 34.0 %. The average wind velocity for the entire month of November was 1.21 m/s. Maximum wind velocity was recorded 10.19 m/s. The wind direction was mostly North-East.
- The results obtained from the study for the month of November 2022 for biological and ecological parameters in marine water for Arabian Sea at surrounding area of Deendayal Port Authority (DPA) Kandla and Vadinar were not affected by Port activities.

Reasons for higher Values of PM₁₀

- The unloading of coal directly in the truck, using grabs cause coal to spread in air as well as coal dust to fall on ground. This settled coal dust again mixes with the air while trucks travel through it.

- Also, the coal loaded trucks were not always covered with tarpaulin sheets and these results in spillage of coal from trucks/dumpers during its transit from vessel to yard or storage site. This also increased PM values around marine Bhavan & Coal storage area.

Remedial Measures

The values of PM₁₀ & PM_{2.5} during the month of November, 2022 were beyond the standard limit at all locations (Coal Storage, Marine Bhavan, Oil Jetty and Estate office, Tuna Port) except Gopalpuri the concentration of particulate matter was slightly exceed. Given below are the remedial measures suggest to minimize the Air pollution.

- During November, 2022 overall ambient air quality of the DPA was within CPCB permissible limits except TSPM, PM₁₀, PM_{2.5} at Coal storage area, Marine Bhavan, Oil Jetty and Estate Office. To improve air quality the port was using number of precautionary measures, such as maintained a wide expanse of Green zone, initiated Inter-Terminal Transfer (ITT) of tractor-trailers, Centralized Parking Plaza, providing shore power supply to tugs and port crafts, the use of LED lights at DPA area helps in lower energy consumption and decreases the carbon foot prints in the environment, time to time cleaning of paved and un paved roads, use of tarpaulin sheets to cover dumpers at project sites etc. are helping to achieve the cleaner and green future at port.

Solution towards the Green port:

Today, it is increasingly recognized that air pollution hurts human health. Consequently, efficient mitigation strategies need to be implementation for substantial environmental and health co-benefits.

The guidelines can be considered a basis for governments for the implementation of a strategic plan focused on the reduction of multi pollutant emission, as well as of the overall air pollution related risk.

- The plantation should be all along the periphery of the port and inside and outside the port along with the road. Trees having high dust trapping efficiency (*Azadirachta indica*, *Cassia fistula*, *Delonix regia*, *Ficus religiosa*, *Pterocarpus marsupium*) are to be grown alongside the roads.
- The water sprinkling should be use at each and every stage of transporting coal up the loading of truck to avoid generation of coal dust.

- The vehicles should be covered during transportation and the vehicle carrying the coal should not be overloaded by raising the height of carriage.
- The water sprinklers should be use during transportation of loaded heavy vehicles on raw road.
- It should be ensure that regular sweeping of coal internal, main road and space a free circulation.
- Practice should be initiated for using mask as preventative measure, to avoid Inhalation of dust particle- Mask advised in sensitive areas.
- Department for use maintenance should have a routine checkup noise level by replacing bearings, tights of all loose parts that can vibrate.
- Speed control is also an effective way to mitigate noise pollution, the lowest sound emission arise from vehicles moving smoothly.
- Use of renewable energy like solar energy should be optimal and ensure to work continuously.
- Keep neat and clean public transport and all basic items at public interaction places as much as possible.
- Technology like Electric cart, Inter-Terminal Transfer (ITT) are worthy selection to reduce Port operation efficiency and fuel cost.
- Conventional RTGCs should be altered as E-RTGCs counting inside the port completely.
- Initiate Natural Gas (CNG) as fuel by all buses and trucks.

Green Ports Initiative

- Deendayal Port is committed to sustainable development and adequate measures are being taken to maintain the Environmental well-being of the Port and its surrounding environs. Weighing in the environmental perspective for sustained growth, the Ministry of Shipping had started “Project Green Ports” which will help in making the Major Ports across India cleaner and greener. “Project Green Ports” will have two verticals - one is “Green Ports Initiatives” related to environmental issues and second is “Swachh Bharat Abhiyaan”.
- The Green Port Initiatives include twelve initiatives such as preparation and monitoring plan, acquiring equipments required for monitoring environmental pollution, acquiring dust suppression system, setting up of waste water treatment plants/ garbage disposal plant, setting up Green Cover area, projects for energy generation from renewable

energy sources, completion of shortfalls of Oil Spill Response (OSR) facilities (Tier-I), prohibition of disposal of almost all kind of garbage at sea, improving the quality of harbour wastes etc.

- Deendayal port has also appointed GEMI as an Advisor for “Making Deendayal Port a Green Port - Intended Sustainable Development under the Green Port Initiatives.
- Deendayal Port has also signed MOU with Gujarat Forest Department in August 2019 for Green Belt Development in an area of 31.942 Ha of land owned by Deendayal Port Trust. The plantation is being carried out by the Social Forestry division of Kachchh.

CHAPTER-12

REFERENCES

12.0 SOURCE OF LITERATURE AND ADDITIONAL REFERENCE

- 1) ALBERT WEST PHAL (1976) Protozoa Blackwell , London
- 2) Arunachalam S, Brantley H, Barzyk TM, Hagler G, Isakov V, Kimbrough E, Naess B, Rice N, Snyder MG, Talgo K, Venkatram A (2015) Assessment of port-related air quality impacts: geographic analysis of population. *Int J Environ Pollut* 58(4):231–250
- 3) Asha, P. S. and Diwakar (2007). Hydrobiology of the inshore waters off Tuticorin in the Gulf. *J. Mar. Biol. Ass. India*, 49: 7-11.
- 4) Astakhov AS, Kalugin IA, Aksentov KI, Daryin AV (2015) Geochemical indicators of paleo typhoons in shelf sediments. *Geochemistry* 4:387–392.
- 5) Bailey D, Solomon G (2004) Pollution prevention at ports: clearing the air. *Environ Impact Assess Rev* 24(7):749–774.
- 6) BANERJEE R.K. (1989) Heavy metals and Benthic foraminiferal distribution along Bombay coast India. *Studies in benthic foraminifera. Tokyo University Press Tokyo* pp 151-157
- 7) Banse K (1995) Zooplankton: Pivotal role in the control of ocean production: I. Biomass and production. *ICES J Mar Sci* 52: 265–277.
- 8) Beaugrand G, and Ibanez F (2004) Monitoring marine plankton ecosystems. II: long-term changes in North Sea calanoid copepods in relation to hydroclimatic variability. *Inter Res Mar Ecol Prog Ser* 284:35-47.
- 9) Benhamed S, Guardiola FA, Martinez S, Sanchez MJM, Sirvent CP, Mars M, Esteban MA (2016) Exposure of the gilthead seabream (*Sparus aurata*) to sediments contaminated with heavy metals down-regulates the gene expression of stress biomarkers. *Toxicol Rep* 3:364–372.
- 10) Best, M. A., Wither, A.W. and Coates, S. (2007). Dissolved oxygen as a physicochemical supporting element in the Water Framework Directive. *Marine Pollution Bulletin* 55(1-6): 53-64.
- 11) Buccolieri R, Cesari R, Dinoi A, Maurizi A, Tampieri F, Di Sabatino S (2016) Impact of ship emissions on local air quality in a Mediterranean City's harbour after the European sulphur directive. *Int J Environ Pollut* 59(1):30–42.
- 12) Chaurasia, S, Singh, S. and Gupta, A.D., 2013. Study on air quality of SKS Ispat and Power Ltd. Raipur (CG), India. *Asian Journal of Science and Technologies*, 4 (4), 48-50.

- 13) Conti ME, Ciasullo R, Tudino MB, Matta EJ (2015) “The industrial emissions trend and the problem of the implementation of the industrial emissions directive (IED)” Air Quality. *Atmosph Health* 8(2): 151–161.
- 14) CPCB (2013): Guidelines for Manual Sampling & Analyses. (Guidelines for the Measurement of Ambient Air Pollutants, Vol. I), Central Pollution Control Board, National Ambient Air Quality Series: NAAQMS/36/2012-13.
- 15) DAY F. (1889) The fauna of British India Ceylon and Burma- Fishes Vol-1- Vol-2 *Taylor and Francis* London
- 16) DESIKACHARYT.V. (1989) Atlas of diatoms, Madras Science Foundation
- 17) DESIKACHARYT.V.(1959) Cyanophyta I CAP Monographs on Algae *Indian Council of Agricultural research* New Delhi
- 18) FAIZAYOUSIF AL-YAMANI & MARIA A. SABUROVA (2010) illustrative guide on the flagellates of Intertidal soft sediment *Kuwait Institute for scientific Research* Kuwait
- 19) FAIZAYOUSIF AL-YAMANI, VALERIYSKRYABIN, ALEKSANDRA GUBANOVA, SERGEY KHVOROV AND IRINA PRUSOVA (2011), Marine zooplankton Practical guide from North western Arabian gulf Vol-1 and vol-2 *Kuwait Institute for scientific Research* Kuwait
- 20) FAUVEL P. (1953), The fauna of India Annelida - Polychaeta *Indian Press* Allahabad
- 21) Gajbhiye SN, Nair VR, and Desai BN (1984). Diurnal variation of zooplankton in Malad creek, Bombay. *Indian Journal of Marine Science*. 13:75-79.
- 22) Guidelines for the Measurement of Ambient Air Pollutants: National Ambient Air Quality Series/NAAQMS/36/2012-13, Volume-I.
- 23) Gujrat Pollution Control Board Inward No. 143215 dated 06.09.2018.
- 24) HAYWARD P.J AND RYLAND J.S. (1995) Handbook of Marine fauna of north –West Europe *oxford University Press* London
- 25) Hefmi R., Tanjung R., Hamuna B., and Alianto (2019). Assessment of Water Quality and Pollution Index in Coastal Waters of Mimika, Indonesia. *Journal of Ecological Engineering*, 20(2); 87-94
- 26) HIGGINS R.P. HAJAMARTHIEL Eds. (1998) Introduction to the study of Meio Fauna
- 27) HORACE G. BARBER AND ELIZABETH Y. HAWORTH (1981) A guide to the Morphology of DIATOMS FRUSTULES.

- 28) Horaginamani, S.M. and Ravichandran, M., 2010. Ambient air quality an urban area and its effects on plants and human beings: A case study of Tiruchirappalli, India. Kathmandu University Journal of Science, Engineering and Technology, 6 (2), 13-19.
- 29) INGRAM HENDEY (1964) An introductory account of smaller Algae of British coastal waters part-V. Bacillariophyceae
- 30) IS1050:2012 Drinking Water-Specification: (second Revision).
- 31) JOHN H. WICKSTEAD(1965) an Introduction to the study of Tropical Plankton .Hutchinson Tropical Monographs
- 32) JOYOTHIBABU,R. MADHU, N.V. MAHESHWARAN, P.A.,NAIRK.K.C., VENUGOPL,P. BALASUBRAMANIAN T.2005) Dominance of Dinoflagellates in micro zooplankton communities in the oceanic region Bay of Bengal and Andaman sea Current science vol.84. 10thNOVEMBER2003
- 33) KASTURIRANGANL.R. (1963) A key for the identification of the Common Planktonic Copepoda of Indian Coastal water
- 34) KusumKK, Vineetha G, Raveendran TV, Nair VR, Muraleedharan KR, Achuthankutty CT and Joseph T (2014) Chaetognath community and their responses to varying environmental factors in the northern Indian ocean. J Plankton Res 36(4): 1146- 1152.
- 35) Lack DA, Cappa CD, Langridge J, Bahreini R, Buffaloe G, Brock C, Cerully K, Coffman D, Hayden K, Holloway J, Lerner B, Massoli P, Li SM, McLaren R, Middlebrook AM, Moore R, Nenes A, Nuaaman I, Onasch TB, Peischl J, Perring A, Quinn PK, Ryerson T, Schwartz JP, Spackman R, Wofsy SC, Worsnop D, Xiang B, Williams E (2011) Impact of fuel quality regulation and speed reductions on shipping emissions: implications for climate and air quality. Environ Sci Technol 45(20):9052–9060.
- 36) Lai KH, Lun VYH, Wong CWY, Cheng TCE (2011) Green shipping practices in the shipping industry: conceptualization, adoption, and implications. Resour Conserv Recycl 55(6):631–638.
- 37) Lalli CM and Parsons TR (1997) Biological Oceanography: An Introduction. DOI<https://doi.org/10.1016/B978-0-7506-3384-0.X5056-7>.
- 38) Lawler, D.M. 2004. Turbidimetry and nephelometry. In:Townshend, A. (Ed.) Encyclopedia of Analytical Science, 2nd edition. London: Academic Press (pp. 343-351).

- 39) Madhu D. Nathani, Mrugesh H. Trivedi (2015). Pre Monsoon Study of Water Quality with reference to Rapid Industrial Development in and around Gandhidham, Kachchh, Gujarat, *International Journal of Scientific & Engineering Research*, 6(9):1851-1862.
- 40) Madhupratap M (1978) Studies on ecology of zooplankton of Cochin backwaters. *Mahasagar Bull Nat Inst Oceanogr* 11: 45-56.
- 41) Madhupratap M (1979) Distribution, community structure and species succession of copepods from Cochin Backwaters. *Indian J Ma Sci* 8: 1-8.
- 42) Madhupratap M (1987) Status and strategy of zooplankton of tropical Indian estuaries: A review. *Bull Plank Soc Jpn* 34: 65-81.
- 43) Madhupratap M (1999). Free living copepods of the Arabian Sea, Distribution and Research Perspectives. *I J Mar Sci* 146-149.
- 44) Madhupratap M and Haridas P (1986) Epipelagic calanoid copepods of the northern Indian Ocean. *Oceanologica Acta* 9(2):105-117.
- 45) MANAL AL-KANDARI, FAIZA Y. AL-YAMANI , KHOLOOD AL-RIFAIE (2009) Marine phytoplankton Atlas of Kuwait's water *Kuwait Institute for scientific Research*
- 46) Meiaraj C. & Jeyapriya S.P. (2019). Marine water quality studies at Tuticorin harbour coastal area. *Indian Journal of Geo Marine Sciences* 48 (06): 943-946.
- 47) MPEDA (1998) Commercial Fishes and shell fishes of India
- 48) Murtini J.T., Ariyani F., Wahyuni I.S., Hak N., Suherman M., Dolaria N., Nurwiyanto. 2001. Inventory research and identification of heavy metal pollution in waters and fish. Technical Report. Pusat Riset Pengolahan Produk dan Bioteknologi Kelautan dan Perikanan. Jakarta. (in Indonesian).
- 49) Narayan R, Saxena K.K. and Chauhan S. (2007). Limnological investigations of Texi Temple pond in district Etawah (U.P.), *Journal of Environmental Biology*, January 28(1):155-157.
- 50) NEWEL G.E. & NEWELL R.C. (1963) *Marine plankton a Practical Guide* Hutchinson Educational
- 51) NIGAM R.C. AND CHATURVEDIS.K. (2000) Foraminiferal Study from Kharo Creek , Kachchh (Gujarat) North west coast of India. *Indian Journal of marine science* Vol.29 133-189
- 52) OLAV GIERE (1993) *Meiobenthology , Microscopic Fauna in Aquatic Sediments* m Springer London

- 53) PERRAGALLO (1965) *Diatomees marines de France* A. Asher & Co. Amsterdam
- 54) Robert P. Higgins (Eds.), (1985) *An introduction to the study of Meiofauna* Smithsonian Institution press Washington DC
- 55) Salmin (2005). Dissolved oxygen (DO) and biological oxygen demand (BOD) as indicator to determine water quality. *Oseana*, 30(3):21–26.
- 56) Salvi H., Patel R., Thakur B., Shah K. and Parmar D. (2014). Assessment of Coastal Water Quality Parameters of Selected Areas of Marine National Park & Sanctuary (Okha, Sikka & Khijadiya), *SSRN Electronic Journal*, (pg 1-16)
- 57) STERRER W. STERRER C.S Eds. *Marine fauna and flora of Bermuda A systematic Guide to the identification of Marine Organisms. John Wiley and Sons* New York
- 58) Suresh Gandhi. M. (2009) Distribution of certain ecological parameters and Foraminiferal distribution in the depositional environment of Pak Strait east coast of India. *Indian J. of Marine Science* Vol.33 pp 287-295
- 59) USEPA, 2008. *Air Quality Index: A Guide to Air Quality and Your Health*. Environmental Protection Agency, Office of Air Quality Planning and Standards, Research Triangle Park, USA. 12 pp.
- 60) Vallero (2014): *Fundamentals of Air Pollution* 5th Edition 2014.
- 61) Venkataraman (1993) A systematic account of some south Indian diatoms. *Proceedings of Indian Academy of Science* Vol. X No.6 Sec.B.
- 62) Weiss, R.F., (1970): The solubility of nitrogen, oxygen and argon in water and seawater. *Deep Sea Research and Oceanographic Abstracts* 17(4): 721-735.
- 63) Yap C.K., Chee M.W., Shamarina S., Edward F.B., Chew W. and Tan S.G. (2011). Assessment of Surface Water Quality in the Malaysian Coastal Waters by Using Multivariate Analyses, *Sains Malaysiana* 40 (10)1053–1062

ANNEXURE C

DEENDAYAL PORT AUTHORITY



Administrative Office Building
Post Box NO. 50
GANDHIDHAM (Kutch).
Gujarat: 370 201.
Fax: (02836) 220050
Ph.: (02836) 220038

www.deendayalport.gov.in

NO.EG/WK/4751/Part (Greenbelt-GUIDE) 196

Dated : 31/5/2022

✓ M/S Gujarat Institute of Desert Ecology,
P.O.Box No. 83,
Opp. Changleshwar Temple, Mundra Road,
Bhuj (Kachchh)- 370 001, Gujarat (India).
Tel.: 02832-329408, 235025.
Tele/Fax: 02832-235027

Email: desert_ecology@yahoo.com

Kind Attn.: Dr.V.Vijay Kumar, Director, M/s GUIDE, Bhuj.

Sub: Greenbelt Development in Deendayal Port Authority and its Surrounding Areas Charcoal site (Phase-I).

Ref.: M/s GUIDE, Bhuj offer vide letter no. M/s GUIDE, Bhuj vide communication no. GUIDE/DPA/GRN/080/2022-23 dated 24/5/2022.

Sir,

Your offer for the subject work submitted vide above referred letter dated 24/5/2022 amounting to Rs. 38,22,900.00 + applicable GST (Rupees Thirty-Eight Lakhs Twenty-Two Thousand and Nine Hundred Only Plus Eighteen Percent GST), with all terms & conditions mentioned in the offer letter, has been accepted **(Copy of offer letter M/s GUIDE attached)**.

2. Scope of work:

Development of Greenbelt in Charcoal site – Kandla, DPA and its surrounding areas. The activities under the Greenbelt Development include; inventory of suitable sites for greenbelt development in DPA, soil & Moisture conservation and management at Plantation sites, selection of suitable species of Plants for plantation, Procurement and plantation of plant saplings and seeds (5000 plants), along with management and monitoring of plantation, including drip/tanker water supply for a period 1 year.

.....Cont.....

3. Obligation of Deendayal Port Authority :

- Assistance regarding the statutory clearance from authorities concerned to be rendered by DPA for field visits/plantation activities.

4. The Terms of Payment:

1. 50% of the project budget to be paid to GUIDE within 15 days from the date of acceptance of Work order by GUIDE.
2. 20% of the project budget to be paid to GUIDE within 15 days from the date of completion of plantation works.
3. 20% of the project budget to be paid to GUIDE within 15 days from the date of submission Progress Report (December 2022).
4. 10% of the project budget to be paid to GUIDE within 15 days from the date of submission of Final Completion Report (May 2023).

5. Time Period : One year (from 5/6/2022 to 4/6/2023).

6. Kindly send the acceptance of this work order & start the work w.e.f. 5/6/2022 .

Thanking you.

Yours faithfully,



Superintending Engineer (PL) & EMC (I/c)
Deendayal Port Authority

Copy To :1) A.O.(W/A) - The proposal has been approved by the Board in its meeting held on 27/5/2022.

The expenditure shall be charged to the scheme
Environmental Services & Clearance thereof
(Allocation: 841/587/9744 WC - 5-13001).

- 2) TPA to CE for kind information of the Chief Engineer, please.
- 3) DA (PL) for further necessary action.
- 4) M/s Precitech Laboratorie ,Vapi, Environmental Management Cell to coordinate with M/s GUIDE,Bhuj.
- 5) RAO, DPA

Annexure -D

Disaster Management Plan
(UPDATED MAY 2019)
for
DEENDAYAL PORT TRUST
ISO 9001:2008 & ISO 14001:2004 Certified Port
Post Box No: 50
Gandhidham (Kutch) – 370201



OF CONTENTS

Contents

1	12
2	13
2.1 Objectives of DMP.....	14
2.2 Responsibility Nodal officer	16
3	17
3.1 Introduction	17
3.1.1 Unique Location	17
3.1.2 The Evolution	17
3.1.3 The Strengths to Anchor On.....	17
3.1.4 Vision.....	18
3.1.5 Mission	18
HAZARD RISK VULERNABILITIES 3.2 Business Horizon	18
3.2.1 Advantage Deendayal Port	18
3.3 Port Logistics	19
3.3.1 Navigation Facilities	19
3.3.2 Flotilla.....	19
3.4 Strategic & Climatic Advantage.....	20
3.5 Port Location	20
3.5.1 Location - Latitude : 23° 1' N, Longitude : 70° 13' E.....	20
Figure 1 – Over view of DEENDAYAL PORT TRUST	21
3.6 Future Vision of KPT as per Business Plan.....	8
3.8 Infrastructure Advantages at Kandla Port.....	10
3.8.1 Chemical & Liquid handling Complex	10
3.9 Road Network	11
3.10 Storage Facilities.....	11
3.10.1 Private Sector Liquid Storage Facilities	11

3.10.2	Public Sector Liquid Storage Facilities.....	12
3.11	Container Handling Facilities Being upgraded.....	13
3.12	Port Equipments.....	13
3.12.1	Wharf Cranes	13
3.12.2	Weighbridges	14
3.12.3	Other Support Equipment.....	14
3.13	Berths at Kandla Port.....	14
3.13.1	Details of Draught.....	14
3.13.2	Details of Berths	15
3.13.3	Details of Existing Godown	17
3.14	Various Private Terminal Storages at Kandla & the chemicals POL products handled.	18
3.14.1	Bharat Petroleum Corporation Ltd	18
3.14.2	CRL.....	19
3.14.3	United Storage & Tank Terminals Ltd	19
3.14.12	IFFCO.....	25
3.15	Offshore Oil Terminal (OOT) Vadinar	26
4	27
4.1.1	Dispersion Modeling	27
4.1.1.1	What is Dispersion.....	27
4.1.1.2	Gaussian Model:	28
	Gaussian distribution (left) & Gaussian Spread (right)	29
4.1.1.3	Heavy gases:	29
4.1.1.4	Classification of Heavy Gases:	30
4.1.2	Fires & Explosions	30
	ALOHA Sources & Scenarios	31
4.1.2.1	Fire.....	31
4.1.2.2	Thermal Radiation Levels of Concern:	32
4.1.3	Overpressure.....	33
4.1.3.1	Overpressure Levels of Concern	34
	Explosion Overpressure Damage Estimates	35
4.2	Effect at different Heat Radiations & Overpressure	36
4.2.1	Emergency Response Planning Guidelines (ERPGs).....	36
4.2.2	Temporary Emergency Exposure Limit (TEEL)	37

4.3	Various emergencies that may be expected at the port area.....	38
4.4	Leak / Spill and Fire & Explosion of Hazardous Chemicals at the Jetties	39
4.5	Important assumptions considered for the Study	39
4.6	Maximum Credible Loss Scenarios.....	40
4.7	Impact Distances for MCLS under study	41
4.7.2	Jetty No – 1 Instantaneous Release / Ev TOLUENE	42
4.7.3	ACRYLONITRILE (ACN)	43
4.7.4	ANILINE.....	46
4.7.5	BENZENE.....	47
4.7.6	1:3, BUTADIENE.....	49
4.7.7	ACETONE	51
4.7.10	Jetty No – 4 Instantaneous Release / Ev VINYL CHLORIDE (VCM)	56
4.7.11	Jetty No – 5 Instantaneous Release / Ev AMMONIA	57
4.7.12	Jetty No – 5 Instantaneous Release / Evaporation Puddle / Burning Puddle for HSD.....	60
4.7.13	Jetty No – 6 Instantaneous Release / Evaporation Puddle / Burning Puddle for MOTOR SPIRIT	61
4.8	Coal Storage at Open Yard	65
4.8.1	General Characteristics of Coal.....	65
4.8.2	Effects of Coal Burning.....	65
4.8.3	Spontaneous Combustion in Coal.....	66
4.8.4	Causes of Spontaneous Coal Fires	66
4.8.4.1	Preventing Spontaneous Combustion in Stored Coal	67
4.8.5	Recommendations for Coal Storage	67
4.8.6	Roll Packing	68
4.8.7	Checking Temperature.....	68
4.9	Risk Analysis for Coal Fires in Storage Yard Berth 14.....	69
4.9.1	Formula used for Calculation of Impact Distance (D) =.....	69
4.9.2	Summary:.....	71
4.10	Fire & Explosion Response Plan.....	73
4.11	Fire & Toxic Leakage	74
4.12	Details of Fire Fighting Equipment available at Kandla Port	76
4.12.1	Fire Water Tender – 6 Nos	76
4.12.3	Multi Purpose Fire Tender – 1 No.....	77
4.12.4	SURVEYED OFF NEW PROCUREMENT IN PROCESS	78


4.12.5	Tank Lorry - 01 No.....	78
4.12.6	Fire Jeep – 01 No.....	78
4.12.7	Safety Jeep – 01 No.....	79
4.12.8	Ambulance – 01 No.....	79
4.13	Station wise Manpower Break Up (Manned Round The Clock)	79
4.13.1	Emergency Response Centre / Old Kandla Fire Station (Liquid Cargo Jetty)	80
4.13.2	Tilak Fire Station (Dry Cargo Jetty).....	81
4.13.3	Azad Fire Station (Dry Cargo Jetty).	81
4.14	Fire fighting facility at Chemical / Oil Handling Berths.....	82
4.14.1	Oil Jetty No: 1.....	82
4.14.2	Oil Jetty No: 2.....	83
4.14.3	Oil Jetty No: 3, 4 & 5	84
4.14.4	Oil Jetty No: 6.....	85
4.15	General Fire fighting guidelines at the Oil Jetty	86
4.16	General guidelines in case of Toxic Chemical spill / leak.....	87
	IDENTIFICATION OF EMERGENCIES AT THE OIL & CHEMICAL FACILITIES AROUND THE.....	89
	KANDLA PORT	89
5.1	Impact Distances	89
5.2	Maximum Credible Loss Scenarios (MCLS) considered for the study	89
5.2.1.1	Radiation Effects: Bleeve / Fire Ball.....	90
5.2.1.2	Explosion Effects	90
5.2.2.1	Dispersion Distance for PHenol.....	91
5.2.2.2	Radiation Effects – Pool Fire	91
5.2.3.1	Dispersion Distance for Toluene.....	92
5.2.3.2	Radiation Effects – Pool Fire.....	92
5.2.3.3	Flash Fire.....	92
5.2.4.1	Dispersion Distance for Acrylonitrile	93
5.2.4.2	Radiation Effects – Pool Fire.....	93
5.2.4.3	Flash Fire.....	94
5.2.5.1	Radiation Effects	95
5.2.6.1	Dispersion Distance for Benzene.....	95
5.2.6.2	Radiation Effects: Pool Fire	95

5.2.6.3 Flash Fire.....	96
5.2.7.1 Dispersion Distance for Methanol.....	96
5.2.7.2 Radiation Effects: Pool Fire	96
5.2.7.3 Flash Fire.....	97
5.2.7.4 Explosion Effects – Late Ignition	97
5.2.8.1 Radiation Effects: Pool Fire	98
5.2.8.2 Flash Fire.....	98
5.2.9.1 Dispersion Distance for Ammonia.....	98
5.2.10.1 Dispersion Distance for Phenol.....	99
5.2.10.2 Radiation Effects: Pool Fire	99
5.2.11.1 Dispersion Distance for Acrylonitrile	100
5.2.11.2 Radiation Effects: Pool Fire	100
5.2.11.3 Flash Fire	100
5.2.12.1 Dispersion Distance for Aniline.....	101
5.2.13.1 Radiation Effects – Bleeve / Fireball	102
5.2.13.2 Explosion Effects.....	102
5.2.15.1 Explosion Effects.....	103
5.2.16.1 Dispersion Distance for Ammonia	103
5.2.17.1 Dispersion Distance for Acrylonitrile	103
6 TOXIC HAZARD RANKING FOR HAZARDOUS CHEMICALS HANDLED AT PORT PREMISES	105
6.1 Hazard Ranking	105
7	129
7.1 Bomb Emergency Management.....	129
7.4 Responsibility of the CISF Commandant / Officer of Kandla port.....	132
7.5 Action Plan	132
7.5.2 Search procedures:	133
7.6 Important Telephone Nos of Police Authorities	133
7.6 Contact Telephone Nos of Bomb Detection & Disposal Squad	135
8.....	136
8.1 Commandant CISF Responsibilities	136
9	137
9.1.2 Earthquake.....	140

As per Munich Re World Map for Natural hazards, Gandhidham region is in Zone – I which means on an average there are 2 - 6 lightning strikes per km area per year which signifies moderate risk exposure.

2

Thus risk exposure can be considered as moderate.



9.1.4 Tsunami

.....	142
PREPAREDNESS & RESPONSE	144
9.2 Internal Action Plan in case of Cyclone / Flood & Any other Natural Calamity	144
9.2.1 Particulars of the Action Plan Committee Members	144
9.3 Control Room	147
List of Duty Roster of Marine Department (Ministerial Staff)	148
9.4 Kandla Control Room	152
9.5 A.O. Building, Control Room (Gandhidham)	152
9.6 Functions of the Control Room	153
9.8.2 The Telephone Numbers of Some of the VIP s	154
9.8.6 Gujarat State Disaster Management Authority Telephone Numbers of Senior Officials	156
24 hrs 079- 23251900 - 20	156
9.9 Continuous Monitoring Process	157
9.11 Inmarsat Mini – M – Terminal Kandla - 00873762092789	158
9.11.1 Control Room, Gandhidham	158

9.11.2 Control Room, Vadinar	158
9.12 Plotting of Information on Map	159
9.13.2 Immediate stopping of operations at the Port	160
9.14 Securing of Cranes	161
9.14.1 Securing of all Crafts	162
9.15 Private Barges / Crafts	163
9.16 Evacuation of People from Kandla Area during Emergency – Action Plan.....	163
9.17 Population of Kandla	165
9.17.3.1 List of Salt Lessees.....	166
9.17.3.2 List of Private / Public Tank Farm Owners	171
9.17.3.3 List of Stevedores in the Port.....	176
9.18 Core Team	188
9.19 Public Announcement	190
9.20 Temporary Shelters	190
9.22 Traffic Movement	191
Staff Attendance	192
9.24 Sanction of Advance	193
9.26 Private Vehicles Buses { To be arranged by Labour Section}	193
9.26.2 The list of Travel Agencies	198
9.27 Contact with Railway & GSRTC.....	199
9.28 Generator Sets.....	199
9.29 Fire Dewatering Pumps	200
9.30 Shipping Navigational Aid Section	201
9.31 Periodical Reporting by all HODS	201
9.31.5 Ensuring the Functioning of Telephones	203
9.32 Accidents in the Channel	204
9.32.2 Grounding of a Tanker	205
9.32.3 Breaking / Ground of a Ship outside Kandla Port Limit	206
STRENGTHNING DISASTER RISK GOVERNANCE	207
9.33 Contingency plans in grave situation.....	207
9.33.1 First Information	207
9.33.2 Authorities responsible for sending of First Information	208
9.33.3 List of Members NDMA	209

10 PRESS MANAGEMENT	213
10.1 Important Telephone Numbers of Indian Meteorological Department Ahmedabad.....	213
11 DEPARTMENT WISE ACTION PLAN	214
11.1 General Administration Department.....	214
11.1.1 List of Schools in Gandhidham – Kandla Complex	215
11.2 Contacts of Officials of GAD following nodal officer will form a team	217
11.5 Contact Nos of CISF Officials.....	220
11.7 Medical Department	221
11.9 Post Disaster Phase	221
11.10 Prevention of Epidemics.....	222
11.11 Marine Department.....	223
11.12 Ships	224
11.13 Securing of all Crafts.....	225
11.13.2 Flotilla Staff Will be decided by FS as per available team with mooring crew	226
11.14 Private Barges / Crafts.....	227
11.14.2 List of Telephone Nos & Addresses of DC, HM & Pilots	228
11.15 Traffic Department.....	229
11.15.1 List of Stevedores	230
11.16 Mechanical Engineering Department.....	235
11.16.1 List of Duty Roster of Mechanical Engineering Department As formed by CME on available officers	239
11.17 Civil Department.....	239
11.17.1 The following officers are to be contacted in the event of any such problems.....	240
11.17.2 List of Duty Roster of Civil Engineering Department CE will form a team as per	241
12 RESPONSE TO MARINE OIL SPILLS	242
12.2.1.1 Computer Models.....	244
12.3 Aerial Surveillance at Sea	244
12.3.1.1 Ladder Search.....	244
12.6 Spill Control Management.....	247
12.6.1.1 Tankers	247
12.7.2.1 Common features	249
12.7.3.1 Currents, Wind, Waves, Turbulence	249
12.7.3.2 Boom size	250
12.7.3.3 Strength, Ease of deployment	250

12.9.1.1 Recovery	253
12.10 Skimmers	253
13 ROLE OF INDUSTRIAL TERMINALS ON KPT LAND	257
13.1.1 Natural Disasters.....	261
14 LINKS BETWEEN THE ARMY, COAST GUARD & AIR FORCE.....	267
15 PROCEDURE FOR CO-ORDINATION	269
16 ASSEMBLY POINTS & ESCAPE ROUTES	274
RECOVERY AND BUILDING BACK	275
17 RECOVERY FACILITY RE-ENTRY.....	275
CAPACITY DEVELOPMENT.....	276
18 MAINTAINING.....	277
18.1 Training & Education	277
18.2 Drills & Exercises.....	278
18.3 Review of the plan	280
18.4 Emergency Control Center	280
19 DEENDAYAL PORT TRUST OFF SHORE OIL.....	283
TERMINAL – VADINAR PORT.....	283
19.1 Vadinar Port Information	283
19.1.1 Metrological Data	283
19.2 Control Room –Vadinar Port	285
Manning at Vadinar Control Room Jetty	285
19.3 Functions of Control Room –Vadinar Port	287
19.4 Stopping of Port Operations.....	289
19.5 Securing of Ships / Crafts / Tugs etc.....	290
19.6 Communication	290
Traffic Movement & Security.....	291
Medical Aid at Vadinar Port Health Center	291
Action to be taken by Pilots.....	292
Generator Set	292
Vehicle Pool	293
Temporary Evacuation Centre	294
19.13 Press & Media Management	295
19.14 Action to be taken by Accounts Officer (OOT)	296

19.15 Advance Planning	296
19.15.2 For securing of ships / crafts / tugs etc	296
19.15.3 Post Calamity Operations	296
19.15.3.1.1 Marine Operations	297
19.15.3.1.2 Other than Marine Operations.....	297
19.16 Action Plan – Land Fire Station.....	297
19.16.2 List of Press Reporters & News Services at Jamnagar	299
19.16.9 Chart of Weather Warnings	303
19.17 Vadinar Oil Terminal Limited (VOTL) of Essar.....	305
19.17.2 Oil Spill Risks	308
19.17.4 Containment & Control	310
19.17.6.1 Pilotage	311
19.17.6.2 Main Approach Channel	311
19.17.6.3 Approach to SPM Berth	311
19.17.7.2 Berthing incident (Jetty)	312
19.17.7.4 Cargo Transfer Operations (SPM Berth).....	312
19.17.7.5 Connection of Floating Hose String	312
19.17.7.9 Vessel Breakout	313
19.17.7.11 Fire and Explosion	314
19.18 Fire Fighting Facilities at Vadinar Oil Terminal Limited (VOTL) of Essar.....	316
19.18.6 Jumbo Curtain at Berth A	317
19.19 Off Shore DMP of Indian Oil Corporation (Vadinar)	325
TIER ONE	328
TIER TWO	328
TIER THREE	328
19.21 Chief Coordinator (Location Head, WRPL Vadinar)	331
19.22 Roles of IOC in Controlling Oil Spill Disaster	332
Regional Coast Guard Commanders (RCC)	333
19.22.4 Responsibility of Port Authority	334
Inflatable booms	334
Oil skimmer equipment	334
19.22.7 Handling SPM Emergency.....	335
19.22.13 Pollution Control near SPM	336

19.23 Oil Spill Equipment Available with IOCL Vadinar	339
19.26 Important Telephone Nos of VOTL Marine Operations	342
19.28 Mutual Aid Members	347
19.29 Details of Fire Fighting Equipment at Vadinar	349
19.30 Details of Fire Fighting Equipment at Jamnagar	351
20 ANNEXURES - GRAPHS.....	354
CBRN: Chemical Biological Radio Activity Nuclear related contingencies Dos & Dnts.....	432
20 ANNEXURE Very useful telephone numbers.....	432
NDMA CONTACT DETAILS	432
GSDMA	432
Emergencies	436
RADIO ACTIVE DISASTERS Dos AND DONTs.....	530

1 PREFACE

The Disaster Management Plan (DMP) for Kandla Port has been developed to provide procedures for the implementation and continual development of the Internal Action Plan.

The Internal Action Plan is an interactive document which will be continuously refined and updated every year.

This plan has been formulated to fulfil the requirements of the relevant standards and guidelines set forth by the National Disaster Plan 2016.

It should be noted that the findings and recommendations of the study are based on the data provided and discussions held during the site visit with the port personnel at the time of the site visit on 18th & 19th August 2010 and updated in the Month of July 2016. FOLLOWED BY MAY 2019

National Disaster Management Plan, 2016. A publication of the National Disaster Management Authority, Government of India. May 2016, New Delhi

Documents provided by DEENDAYAL PORT TRUST for reference are:-

1. DEENDAYAL PORT TRUST– Internal action plan up dated July 2018.
2. DMP – DEENDAYAL PORT TRUST– Originally Prepared by Tata AIG Risk Management in the year 1999. Updated by A R Jadeja, Signal Supdt. KPT 2016
3. Copies of DMP of chemical / POL Terminals on Kandla Port Property.
 - a) JRE tank terminal (P) Ltd.
 - b) CRL
 - c) BPCL

- d) United storage and tank terminals Ltd – Liquid Terminal
 - e) United storage and tank terminals Ltd – Liquefied Gas Storage and handling terminals.
 - f) Indo Nippon chemical Company Ltd.
 - g) Rishi Kiran Logistics (P) Ltd,
 - h) INEOS ABS (India) Ltd
 - i) Friends oil and chemical terminals (P) Ltd
 - j) Indian oil (LPG)
 - k) Indian Oil
 - l) IOC Marketing Division
 - m) HPCL
 - n) Friends salt works and allied industries
 - o) IFFCO
4. Layout Map of DEENDAYAL PORT TRUST– DRG. NO: KPH/09
 5. Layout of Fire fighting line at DEENDAYAL PORT TRUST
 6. Layout of proposed oil pipe line at oil jetty DEENDAYAL PORT TRUST

We have exercised all reasonable skill, care and diligence in carrying out the study. This report / document is

not deemed to be any undertaking, warranty or certificate.

2 INTRODUCTION

The important aspect in emergency management is to prevent by Technical & Organizational measures, the unintentional escape of hazardous materials out of the facility and minimize accidents and losses.

Emergency planning also demonstrates the organizations commitment to the safety of employees and public and increases the organizations safety awareness.

The format and contents of the Disaster Management Plan (DMP) have been developed taking into consideration the guidelines of National Disaster Management Authority & Plan, and other accepted industry good practice principles formulated as a result of lessons learned in actual emergencies requiring extensive emergency response.

This master document is to be studied in advance and used for training purpose also. This master document will be upgraded once in every three years by reviewed annually.

2.1 Objectives of DMP

The objective of DMP is to describe the facility emergency response organization, the resources available and response actions applicable to deal with various types of emergencies that could occur at the facility with the response organization structure being developed in the shortest time possible during an emergency. Thus, the objectives of emergency response plan can be summarized

- ③ Rapid control and containment of the hazardous situation.
- ③ Minimizing the risk and impact of event / accident.
- ③ Effective rehabilitation of the affected persons and preventing of damage to property.

In order to effectively achieve the objectives of the emergency planning, the critical elements that form the backbone of the DMP are

- ③ Reliable and early detection of an emergency and careful planning.
- ③ The command co – ordination and response organization structure along with efficient trained personnel.
- ③ The availability of resources for handling emergencies.
- ③ Appropriate emergency response actions.
- ③ Effective notification and communication facilities ③ Regular review and updating of the DMP ③ Proper training of the concerned personnel.

FOREWORD

"The document On-site Disaster Management Plan is prepared with the objective of defining the functions and responsibilities of all concerned managerial, operational and supporting services department personnel with respect to detection and effective implementation of action plan. The ultimate goal is the effective containment of the emergency situation by proper mitigative action at the place of occurrence, cautioning people in adjoining affected locations, prompt rescue and medical aid to affected persons and communication to civil authorities for rushing in help from outside. All concerned are hereby requested to carefully study and thoroughly familiarize themselves with it in order to ensure its effectiveness in times of emergency"

Chairman

DEENDAYAL PORT TRUST

Date: ____/____/2019

2.2 Responsibility Nodal officer

Responsibility for establishing and maintaining a state of emergency preparedness belongs to the DC. He is responsible for maintaining distribution control of the plan, and for ensuring that the plan and applicable implementing procedures are reviewed annually. The Fire Safety In charge is responsible for the training of personnel to ensure that adequate emergency response capabilities are maintained in accordance with the plan. He is also responsible for ensuring the adequacy of the conduct of drills, as outlined in the On-site Disaster Management Plan. All employees of various departments are responsible for carrying out their responsibilities, as defined in this Plan.

Contact details of Deputy Conservator as a NODAL OFFICER for any port related contingencies/ incidents are as under

Name Capt T Srinivas

Phone : 02836-233585

Fax : 02836-233585

Cell : 9825232982

E mails : dyconservator@deendayalport.gov.in , srini_takes@yahoo.com , signalkpt@gmail.com

3 FACILITY DESCRIPTION PORT PROFILE

3.1 Introduction

3.1.1 Unique Location

The Major Port of Kandla situated about 90 km off the mouth of Gulf of Kachchh in the Kandla Creek at Latitude 23 degree 1minute North and Longitude 70 degree 13 minutes east, is the lone Major Port on the Gujarat coast line along the West Coast of the country. Amongst the 12 Major Ports in the country, Kandla occupies an enviable position, both in terms of international maritime trade tonnage handled and financial stability and self-sufficiency attained year after year. A gateway to the north-western part of India consisting of a vast hinterland of 1 million sq. km stretched throughout 9 states from Gujarat to Jammu & Kashmir, the Port has a unique location advantage. The Port's hinterland is well connected with infrastructural network of broad gauge and railway system as well as State and National Highways

3.1.2 The Evolution

January 20, 1952, Pandit Jawaharlal Nehru, the then Prime Minister of India, laid the foundation stone at Kandla for the new port on the western coast of India. It was declared as a Major Port on April 8, 1955 by Late Lal Bahadur Shastri, the then Union Minister for Transport. The DEENDAYAL PORT TRUST was constituted in 1964 under the Major Port Trusts Act, 1963. Since then, this Major Port of Kandla has come a long way in becoming the 'Port of the New Millennium'.

3.1.3 The Strengths to Anchor On

Excellent infrastructural facilities, well-connectivity with the rest of the country by road and rail networks, all-round services provided with efficiency and transparency, lowest port tariff and the envious cost-effectiveness are the major strengths of Kandla Port.

3.1.4 Vision

"To be Asia's Supreme Global Logistic Hub"

3.1.5 Mission

To transform the Port of Kandla into a most globally competitive logistics hub with international excellence leaving imprints in the international maritime arena by exploring its fathomless growth potentialities.

HAZARD RISK VULERNABILITIES

3.2 Business Horizon

As the portal to the West and North India and due to its unique location advantage, a vast hinterland of 1 million sq. km can be assured for from Kandla.

The hinterland of the Kandla Port consists of the states of J &K, Punjab, Himachal Pradesh, Haryana, Rajasthan, Delhi, Gujarat and parts of Madhya Pradesh, Uttaranchal and Uttar Pradesh.

Kandla Port is the gateway port for the vast granaries of Punjab and Haryana and the rich industrial belt of West and North India.



3.2.1 Advantage Deendayal Port



ISO 9001 – 2008& ISO 14001:2004 Certified Port.



All weather port – 365 days, 24 hours.



Protected and safe harbor.



16 berths stretching 2.55 km in a straight line



Facilities for liquid cargo, POL products, chemicals and edible oil.



Storage facility for LPG to the tune of 30,000 cu.m.



Port with highest liquid storage capacity in the country.

Excellent road and rail connectivity.

High capacity cranes for dry cargo.

Transparent and notified tariff.

13 meter draught.

Security by CISF. ISPS Compliant

3.3 Port Logistics

3.3.1 Navigation Facilities



Round-the-clock navigation.



Permissible draught 13 meters.

Ships with 330 meters length overall and 75,000 DWT are accommodated presently.



Safe, protected and vast anchorage at outer harbour for waiting and lighter age purpose.



22 lighted navigational buoys with solar lights, as per IALA system, are provided in the navigational channel.



VTS PMS & Pilot Personal Unit as an aid for night navigation.



Fully equipped signal stations operational round-the-clock. With VTS GOK Port Monitoring Stations

3.3.2 Flotilla

10 Harbor tugs of various sizes. (inclusive Vadinar

2 high speed pilot launches.

One state of the art fully computerized survey launch

FRP mooring launches.

Four general service launches.

One heave up barge for maintenance of navigational aids.

3.4 Strategic & Climatic Advantage

- ✚ All-weather port.
- ✚ Tropical and dry climatic conditions to handle any type of cargo throughout the year.
- ✚ Temperature varying from 25 degree Celsius to 47 degree Celsius.
- ✚ Scanty rainfall facilitates round-the-year operations.
- ✚ Uninterrupted and smooth port operations on 365 days a year.
- ✚ No adverse wave effect, being a protected and sheltered harbour situated in the Creek.
- ✚ The only Indian Major Port nearest to the Middle East and Europe.


3.5 Port Location

- ✚ Latitude: 23°01"N
- ✚ Longitude: 70°13"E


Kandla Port is situated in the Kandla Creek and is 90km from the mouth of the Gulf of Kutch.

3.5.1 Location - Latitude : 23° 1' N, Longitude : 70° 13' E

Figure 1 – Over view of DEENDAYAL PORT TRUST






3.6 Future Vision of KPT as per Business Plan






3.7 Steel Floating Dry Dock

The existing steel floating dry dock caters to the need of Port crafts as well as outside organizations and has capacity to accommodate vessels of following parameters.

-  LOA maximum up to 95 meters.
-  Breadth maximum up to 20 meters.
-  Draught maximum up to 4.5 meters.

Lift displacement maximum up to 2700 tones.

3.8 Infrastructure Advantages at Kandla Port







-  16 dry cargo berths are available, with quay length of 2532 meter.
-  Six oil jetties.
-  Total custom bonded port area inside the custom fencing is 253 hectares.

THREE cargo moorings in the inner harbor area for stream handling.

3.8.1 Chemical & Liquid handling Complex



 Total storage capacity : 21.89 Lakh KL

- Private sector storage terminals – 9.81 Lakh KL.
- Public sector and cooperative undertaking – 12.08 Lakh KL.



-  Loading arms for simultaneous loading and unloading.
-  Near zero waiting period for vessels.
-  Capacity utilization at international levels ensuring demurrage free handling.
-  Excellent discharge rates and faster turnaround.
-  Lowest vessel related charges and wharfage charges.
-  Suitable for A, B, C, LG, NH, EO classes of liquid and chemicals.

Chemical storage tank farms in the vicinity of liquid jetties.

Tanks for storage of all categories of liquid cargoes like chemicals LPG, cryogenic cargoes, ammonia, acids, petroleum products, edible oils. Etc.

-  Efficient handling ensuring minimum losses.
-  Sophisticated pipeline network (including stainless steel pipes) Sufficient parking space inside and outside the storage facilities.

3.9 Road Network

-  Four lane National Highway No: 8-A extended right up to the Ports main gates.
-  Fully developed road network, both in and around the Port area to facilitate faster movement of cargo.

- Inside Cargo Jetty Area – 30 km. ○ Outside Cargo Jetty Area – 31 km. ○ Railway Inside Cargo Jetty Area – 13 km.

3.10 Storage Facilities

Kandla Port offers excellent and vast dry cargo storage facilities inside the custom bonded area for storage of import and export cargoes.

The existing storage facilities at the dry cargo jetty area are:

Sr No	Description	No	Area (Sq MTRS)	Capacity in (Tones)
01	Warehouses	35	2.03 Lakhs	6.47 Lakh
02	Open storage space	67	16.63 Lakhs	36.27 Lakh

3.10.1 Private Sector Liquid Storage Facilities

Sr No	Name of the Terminal Operator	No of Tanks	Capacity in (KL)
-------	-------------------------------	-------------	------------------

01	CRL (Chemicals & Resins Ltd)	112	247000
02	FSWAI (Friend Salt Works & Allied Industries)	132	271650
03	Kesar Enterprise	44	90081
04	N P Patel Pvt Ltd	09	38497
05	FOCT (Friend Oil & Chemicals Terminal	21	39263
06	USTTL – Liquid Terminal	22	63038
07	Agencies & Cargo Care Limited	27	50000
08	J K Synthetics	14	25176
09	IMC Limited	04	25288
10	J R Enterprises	15	25320
11	Indo Nippon Chemicals Ltd	10	17200
12	Liberty Investment	06	16016
13	Bayer ABS Ltd	11	13310
14	Deepak Estate Agency	09	13212
15	Tejmalbhai & Company	08	12577
16	Avean International Care Ltd	11	12160
17	USTTL Gas Terminal	04	5720
18	Parker Agrochem Export Ltd	06	15000
Total Capacity		465	980508

3.10.2 Public Sector Liquid Storage Facilities


Sr No	Name of the Terminal Operator	No of Tanks	Capacity in (KL)
01	Indian Oil Corporation	38	575838
02	Bharat Petroleum Corporation	21	230000
03	Hindustan Petroleum Corporation	28	204000
04	IOC – LPG	02	30000
05	IFFCO	11	110000
06	NDDB	09	58530
Total Capacity		109	1208360

3.11 Container Handling Facilities HAS BEEN AWARDED TO KANDLA INTERNATIONAL CONTAINER TERMINAL : OPERATIONAL

Fully operational Container Terminal Operated by KICT

3.12 Port Equipments

3.12.1 Wharf Cranes

 12 wharf cranes of the following capacities:

- Two of 12 tones.
- Four of 16 tones.
- Six of 25 tones.

- 2 MOBILE CRANES OF 63 TONNES EACH
- ✚ The rated capacity of the 16 ton crane is 400 tones / hour.
- ✚ The rated capacity of the 25 ton crane is 400 tones / hour.

3.12.2 Weighbridges

- ✚ Nine weighbridges inside the port, which includes:
 - Two Weighbridge of 40 MT capacities.
 - ○ One Weighbridge of 50 MT capacity
 - ○ Two Weighbridge of 60 MT capacity
 - ○ Two Weighbridge of 80 MT capacity
 - ○ Three Weighbridge of 100 MT capacities.

3.12.3 Other Support Equipment

- ✚ Easy availability of other support loading equipments such as Forklifts, Tractor - Trailers, Pay-loaders of various capacities.
- ✚ Private handling, equipments like Mobile Cranes, Top lifters, pay-loaders, Forklifts, Heavy-duty Trailers etc. available on hire at competitive rates.

3.13 Berths at Kandla Port

3.13.1 Details of Draught

Sr No	Name of Berth	Draught (in Meters)	DWT (In Metric Tons)
1	Cargo Berth No.1	10.0	45000

2	Cargo Berth No.2	9.80	45000
3	Cargo Berth No.3	9.80	45000
4	Cargo Berth No.4	9.80	45000
5	Cargo Berth No.5	10.0	35000
6	Cargo Berth No.6	12.0	35000
7	Cargo Berth No.7	12.00	55000
8	Cargo Berth No.8	12.00	55000
9	Cargo Berth No.9	12.00	55000
10	Cargo Berth No.10	12.00	55000
11	Cargo Berth No.11	13.00	65000
12	Cargo Berth No.12	13.0	65000
13	Cargo Berth No.13	13.0	75000
14	Cargo Berth No. 14	13.0	75000
15	Cargo Berth No.15	13.0	75000
16	Cargo Berth No. 16	13	75000
15	Oil Jetty No. 1 (Nehru Jetty)	10.0	40000
16	Oil Jetty No. 2 (Shastri Jetty)	09.00	52000
17	Oil Jetty No. 3 (Indira Jetty)	09.80	40000
18	Oil Jetty No. 4 (Rajiv Jetty)	10.70	56000
19	Oil Jetty No. 5 (IFFCO)	10.10	45000
18	Oil Jetty No. 6 (IOCL)	10.10	45000

3.13.2 Details of Berths

No of Berth	No of Bollard		No of Panels	Length of Each Panel	Length of Berth (m)	Draught (in Meters)	DWT (In Metric Tons)
1	1 to 8	08	08	22.866	182.93	9.80	45000
2	8 to 16	08	08	22.866	182.93	9.80	45000
3	17 to 24	08	08	22.866	182.93	9.80	45000
4	25 to 32	08	08	22.866	182.93	9.80	45000
5	33 to 41	09	09	22.866	205.79	9.10	35000
6	42 to 50	09	09	22.866	205.79	9.10	35000
7	51 to 58	08	08	(30.440 x 7) + 22.56 + (3.00)	238.64	12.00	55000
8	59 to 68	10	06	(45.72 x 3) + 30.44 + 27.44 + (18.00)	213.04	12.00	55000
9	69 to 76	08	05	(45.72 x 3) + 25.72 + (18.05)	182.93	12.00	55000
10	77 to 85	09	05	(59.10 x 2) + (43.20 x 2) + (4.81)	209.41	12.00	55000
11	86 to 98	13	05	(59.00 x 4) + (45.00)	281.00	12.50	65000
12	-----	---	---		264.00	12.50	65000
13						13.0	75000
14						13.0	75000
15						13.0	75000
16						13.0	75000





3.13.3 Details of Existing Godown

Sr No	Godown No	Size of Godown (in M)	Area in Sq Meters	Capacity in (Tons)
1	Godown – 1 (WH-A)	152.44 x 36.59	5578	9817
2	Godown – 2 (WH-B)	152.44 x 36.59	5578	10500
3	Godown – 3 (W.H -C)	152.44 x 36.59	5578	10500
4	Godown – 4 (W.H.D)	152.44 x 36.59	5578	10500
5	Godown – 6 (C.F.S. - II)	90.00 x 36.00	3240	12400
6	Godown – 7 (C.F.S. – I)	90.00 x 36.00	3240	12400
7	Godown – 8 (F.B.S.S)	236.00 x 30.00	7080	13300
8	Godown – 9 (Bagging Plant)	287.00 x 19.20	5510	10400
9	Godown – 10	132.00 x 22.50	2970	11400
10	Godown – 11	186.00 x 22.50	4185	7900
11	Godown – 12	170.00 x 22.50	3825	7200
12	Godown – 13	162.00 x 22.50	3645	6900
13	Godown – 14	192.00 x 22.50	4320	8100
14	Godown – 15	162.00 x 22.50	3645	6900
15	Godown – 16	192.00 x 22.50	4320	9100
16	Godown – 17	174.00 x 22.50	3915	15000
17	Godown – 18	138.00 x 45.00	6210	23800
18	Godown – 19	192.00 x 22.50	4320	8100
19	Godown – 20	192.00 x 22.50	4320	8100
20	Godown – 21	192.00 x 22.50	4320	8100

21	Godown – 22	192.00 x 22.50	4320	8100
22	Godown – 23	174.00 x 22.50	3915	7400
23	Godown – 24	156.00 x 45.00	7020	26900
24	Godown – 25	132.00 x 22.50	2970	5600
25	Godown – 26	99.06 x 36.55	3621	13900
26	Godown – 27		1943	6995
27	Godown – 28	173.88 x 30.50	5503	19092
28	Godown – 29	137.55 x 50.00	6888	24797
29	Godown – 30	126.00 x 49.00	6174	22226
30	Godown – 31	140.00 x 50.00	7000	25200
31	Godown – 32	307.45 x 40.00	12298	44273
32	Godown – 33	133.00 x 40.00	5320	19152
	Total Available Presently		158349	434052

3.14 Various Private Terminal Storages at Kandla & the chemicals POL products handled.




3.14.1 Bharat Petroleum Corporation Ltd

-  Motor Spirit (MS)
-  HSD – High Speed Diesel
-  SKO – Superior Kerosene Oil
-  Ethanol (Ethyl Alcohol)
- Naphtha
- LDO – Light Diesel Oil







3.14.2 CRL

-  Benzene
-  Toluene
-  Aniline
-  Butanol (Butyl Alcohol)
-  H Phenol
-  CTC – Carbon Tetra Chloride
-  Caster Oil
-  CPS
-  Phenol
-  De Alcohol (Denatured Alcohol)
-  IPA – Iso Propyl Alcohol
- Butyl Acetate
- MEK (Methyl Ethyl Ketone)
- Methyl Alcohol / Methanol
- Hexane
- Vinyl Acetate
- MIBK
-  BAM
-  Propylene
-  Cyclo Hexane
-  Caustic Soda (Sodium Hydroxide)
-  Acetic Acid
- Nonene
- EDC (Ethylene Di Chloride)








3.14.3 United Storage & Tank Terminals Ltd

-  LPG – Liquefied Gas Storage & Handling terminal
-  1:3 Butadiene
-  Crude C 4 Mix
- Butane – 1

3.14.4 Indo Nippon Chemicals Co Ltd




-  ISO Butanol
-  A – Olefin
-  Waksol (Parafin)
-  VAM – Vinyl Acetate Monomer
-  MDC – (Methyle Metacrylate)
-  Toluene
- Naphtha
- IPA

3.14.5 Rishi Kiran Logistics (P) Ltd




















-  Butyl Cellsolve
-  Chloroform
-  DO Wanol
-  HNP
-  N – Parafin
-  Methanol
-  Polyether Polyol
- Papi 27 Polymeric
- Tri chloric ethylene Vinyl
chloride monomer.

3.14.6 Ineos ABS (India) Ltd

Chemicals Stored

-  Styrene
-  ACN
-  Chloroform
- Parafin

Chemicals Proposed

-  Methyl Ethyl Ketone (MEK)
-  Benzene
-  Methanol
-  HNP
-  Acetone
-  Butyl Acrylate
-  Butanol
-  1 – Butanol
-  CTC (Carbon Tetra Chloride)
-  Cyclo Hexanol
-  Cyclo Hexanone
-  Cumene
-  Di Octylphthalate
-  Ethanol – IPA (Mix)
-  Ethanol
-  Ethyl Hexanol
-  Ethyl Benzene
-  Hexane
-  Heptane
- Iso Propanol

P – Xylene

Propylene Trimer

C – 9 – Hydrocarbons

Toluene










Vinyl Acetate

Mixed xylene

N – Tetra Decane

Polvoal

3.14.7 Friends Oil & Chemical Terminal (P) Ltd

-  Furnace Oil
-  Styrene
-  C – Palm Oil
-  Mix – HSD & Naphtha
-  CPO (NEG) – Crude Palm Oil
-  Acrylate Bam
-  Butyle Glycol
-  Mosstanoll
-  Butyl Glycol

Cubutol

Methyl Methacr




ISO Nanano

CDSBO

3.14.8 Indian Oil (LPG)






-  LPG

3.14.9 Indian Oil FST












-  Motor Spirit (MS)
-  High Speed Diesel (HSD)
-  SKO (Superior Kerosene Oil)

LAN

3.14.10 Hindustan Petroleum Company Limited

-  Furnace Oil (FO)
-  High Speed Diesel (HSD)
-  Light Diesel Oil (LDO)
-  SKO (Superior Kerosene Oil)
-  Motor Spirit (MS)

3.14.11 Friends Salt Works & Allied Industries

-  Naptha
-  Toluene
-  N – Proanol
-  HNP
-  Mixed Parafin
-  Solvent – CS
-  Iso Propyl Alcohol (IPA)
-  Methenol
-  N – Parafin C9 – C
-  M – xylene
-  High Speed Diesel (HSD)

Mosstanol

Methylene Chloride

Ethyl Acetate

Vinyl Acetate

HA – 100

MEK

Acetone

Crude Benzene

Heavy Aromatics

Butyl Acrylate

Shell Sarasol – 4

Carbon Tetra Chloride (CTC)

HA – 170

MBK

De Natured Spirit

Nonene

Condensate

Caradol SC- 56 – 0

N – Parafin

Butyl Acetate



LAB



Naptha



Hexane



ISO – Decyl Alcohol



Sodium Hydroxide (Caustic Soda)



Methyl Met



Butyl Arylate









MIBK

DHSO – But

Crude PEG

CPKO Crude
PNEG

3.14.12 IFFCO

 Anhydrous Liquid Ammonia
 Phosphoric Acid
 Potash
 Urea
 Hydrochloric Acid
 Sulphuric Acid
LSHS Furnace Oil

3.14.13 IOC (Marketing)

No list of chemicals is provided

3.14.14 JRE Tank Terminal (P) Ltd (Liquid Storage Terminal)




No list of chemicals is provided


3.14.15 United Storage & Tank Terminals Ltd (Liquid Terminal)




No list of chemicals is provided

3.15 Offshore Oil Terminal (OOT) Vadinar


KPT had commissioned off shore oil terminal facilities at Vadinar in 1978, jointly with Indian Oil Corporation, by providing single bouy mooring (SBM) system having capacity of 54 MMTPA, which was the first of its kind in India. A significant quantum of infrastructural up gradation has since been effected and excellent maritime infrastructure created for the 32 MMTPA Essar Oil Refinery at Vadinar.

-  A draught of up to 33 meters at SBMs and lighterage point operations (LPO) Three SBMs available.
-  2 Oil Handling Berths of 1,00,000 DWT draft of 20 mtrs
-  Handling VLCCs of 300000 DWT and more.

Providing crude oil for the refineries of Koyali (Gujarat), Mathura (UttarPradesh), Panipat (Haryana) and Essar Refinery, Jamnagar (Gujarat)  2nd SBM was commissioned in the year 1998.

-  3rd SBM at Vadinar is for importing crude for the oil refinery of Essar Oil.
-  Simultaneous handling of three VLCCs possible at the SBMs. 3 SBMs interconnected by sub-sea pipeline
-  Vast crude tankage facility.

Two 35 tone and four 50 tone state of art BP SRP pull back tugs are available for smooth and simultaneous shipping operations on the SBMs and product jetty.

-  Excellent infrastructure and tranquil waters facilitate transshipment operations even during the monsoon.

4 IDENTIFICATION OF EMERGENCIES

4.1 Overall Methodology

In order to undertake this study DPT has used ALOHA (Aerial Locations of Hazardous Atmospheres) a computer program designed especially for use by people responding to chemical releases, as well as for emergency planning and training. ALOHA models key hazards — toxicity, flammability, thermal radiation (heat), and overpressure (explosion blast force) — related to chemical releases that result in toxic gas dispersions, fires, and /or explosions.

4.1.1 Dispersion Modeling

ALOHA air dispersion model is intended to be used to estimate the areas near a short-duration chemical release where key hazards—toxicity, flammability, thermal radiation, or overpressure—may exceed user-specified Levels of Concern (LOCs).

(Note: If the released chemical is not flammable, toxicity is the only air dispersion hazard modeled in ALOHA.)

ALOHA is not intended for use with radioactive chemical releases, nor is ALOHA intended to be used for permitting of stack gas or modeling chronic, low-level ("fugitive") emissions. Other models are designed to address larger scale and/or air quality issues (Turner and Bender 1986). Since most first responders do not have dispersion modeling backgrounds, ALOHA has been designed to require input data that are either easily obtained or estimated at the scene of an accident. ALOHA's on-screen help can assist you in choosing inputs.

4.1.1.1 What is Dispersion

Dispersion is a term used by modelers to include advection (moving) and diffusion (spreading). A dispersing vapor cloud will generally move (advent) in a downwind direction and spread (diffuse) in a crosswind and vertical direction (crosswind is the direction perpendicular to the wind). A cloud of gas that is denser or heavier than air (called a heavy gas) can also spread upwind to a small extent.

ALOHA can model the dispersion of a cloud of pollutant gas in the atmosphere and display a diagram that shows an overhead view of the regions, or threat zones, in which it predicts that key hazard levels (LOCs) will be exceeded. This diagram is called a threat zone plot. To obtain a threat zone estimate, you must first choose at least one LOC. (ALOHA will suggest default LOCs, and you may keep those or choose up to three other LOCs.) For toxic gas dispersion scenarios, an LOC is a threshold concentration of the gas at ground level—usually the concentration above which a hazard is believed to exist. The type of LOC will depend on the scenario. For each LOC you choose, ALOHA estimates a threat zone where the hazard is predicted to exceed that LOC at some time after a release begins. These zones are displayed on a single threat zone plot. If three LOCs are chosen, ALOHA will display the threat zones in red, orange, and yellow. When you


use ALOHA's default LOCs, the red zone represents the worst hazard.

There are two separate dispersion models in ALOHA: Gaussian & Heavy Gas.

4.1.1.2 Gaussian Model:

ALOHA uses the Gaussian model to predict how gases that are about as buoyant as air will disperse in the atmosphere. Such neutrally buoyant gases have about the same density as air. According to this model, wind and atmospheric turbulence are the forces that move the molecules of a released gas through the air, so as an escaped cloud is blown downwind, "turbulent mixing" causes it to spread out in the crosswind and upward directions. According to the Gaussian model, a graph of gas concentration within any crosswind slice of a moving pollutant cloud looks like a bell-shaped curve, high in the center (where concentration is highest) and lower on the sides (where concentration is lower). At the point of a release, the pollutant gas concentration is very high, and the gas has not diffused very far in the crosswind and upward directions, so a graph of concentration in a crosswind slice of the cloud close to the source looks like a spike. As the pollutant cloud drifts farther downwind, it spreads out and the "bell shape" becomes wider and flatter.


Gaussian distribution (left) & Gaussian Spread (right)



4.1.1.3 Heavy gases:

When a gas that is heavier than air is released, it initially behaves very differently from a neutrally buoyant gas. The heavy gas will first "slump," or sink, because it is heavier than the surrounding air. As the gas cloud moves downwind, gravity makes it spread; this can cause some of the vapor to travel upwind of its release point. Farther downwind, as the cloud becomes more diluted and its density approaches that of air, it begins behaving like a neutrally buoyant gas. This takes place when the concentration of heavy gas in the surrounding air drops below about 1 percent (10,000 parts per million). For many small releases, this will occur in the first few yards (meters). For large releases, this may happen much further downwind.

Cloud spread as a result of gravity.



The heavy gas dispersion calculations that are used in ALOHA are based on those used in the DEGADIS model (Spicer and Havens 1989), one of several well-known heavy gas models. This model was selected because of its general acceptance and the extensive testing that was carried out by its authors.

4.1.1.4 Classification of Heavy Gases:

A gas that has a molecular weight greater than that of air (the average molecular weight of air is about 29 kilograms per kilomole) will form a heavy gas cloud if enough gas is released. Gases that are lighter than air at room temperature, but that are stored in a cryogenic (low temperature) state, can also form heavy gas clouds. If the density of a gas cloud is substantially greater than the density of the air (the density of air is about 1.1 kilograms per cubic meter), ALOHA considers the gas to be heavy.

4.1.2 Fires & Explosions

ALOHA version 5.4, can model fire and explosion scenarios as well as toxic gas dispersion scenarios. This section provides information about fires and explosions, and then explains how to model fires and explosions in ALOHA.

ALOHA allows to model chemical releases from four types of sources: Direct, Puddle, Tank, and Gas Pipeline.

- ③ Direct: chemical release directly into the atmosphere (bypassing ALOHA's source calculations).
- ③ Puddle: chemical has formed a liquid pool.
- ③ Tank: chemical is escaping from a storage tank.
- ③ Gas Pipeline: chemical is escaping from a ruptured gas pipeline.

ALOHA Sources & Scenarios

Source	Toxic Scenarios	Fire Scenarios	Explosion Scenarios
Direct			
Direct Release	Toxic Vapor Cloud	Flammable Area (Flash Fire)	Vapor Cloud Explosion
Puddle			
Evaporating	Toxic Vapor Cloud	Flammable Area (Flash Fire)	Vapor Cloud Explosion
Burning (Pool Fire)		Pool Fire	
Tank			
Not Burning	Toxic Vapor Cloud	Flammable Area (Flash Fire)	Vapor Cloud Explosion
Burning		Jet Fire or Pool Fire	
BLEVE		BLEVE (Fireball and Pool Fire)	
Gas Pipeline			
Not Burning	Toxic Vapor Cloud	Flammable Area (Flash Fire)	Vapor Cloud Explosion
Burning (Jet Fire)		Jet Fire	

4.1.2.1 Fire

A fire is a complex chain reaction where a fuel combines with oxygen to generate heat, smoke, and light. Most chemicals fires will be triggered by one of the following ignition sources: sparks, static electricity, heat, or flames from another fire. Additionally, if a chemical is above its auto ignition temperature it will spontaneously catch on fire without an external ignition source.

There are several properties that measure how readily—that is, how easily—a chemical will catch on fire. Here we'll discuss three of these properties: volatility, flash point, and flammability limits. Volatility is a measure of how easily a chemical evaporates. A flammable liquid must begin to evaporate—forming a vapor above the liquid—before it can burn. The more volatile a chemical, the faster it evaporates and the quicker a flammable vapor cloud is formed. The flash point is the lowest temperature where a flammable liquid will evaporate enough to catch on fire if an ignition source is present. The lower the flash point, the easier it is for a fire to start. Flammability limits, called the Lower Explosive Limit (LEL) and the Upper Explosive Limit (UEL), are the boundaries of the flammable region of a vapor cloud. These limits are percentages that represent the concentration of the fuel—that is, the chemical—vapor in the air. If the chemical vapor comes into contact with an ignition source, it will burn only if its fuel-air concentration is between the LEL and the UEL. To some extent, these properties are interrelated—chemicals that are highly volatile and have a low flash point will usually also have a low LEL.

Once the chemical catches on fire, three things need to be present to keep the fire going: fuel (the chemical), oxygen, and heat. This is often referred to as the fuel triangle. If any one of those components is eliminated, then the fire will stop burning.

Like other reactions, a fire can also generate byproducts—smoke, soot, ash, and new chemicals formed in the reaction. Some of these reaction byproducts can be hazardous themselves. While ALOHA cannot model all the complex processes that happen in a fire (like the generation and distribution of byproducts), it can predict the area where the heat radiated by the fire—called thermal radiation—could be harmful.

Thermal radiation is the primary hazard associated with fires. However, it is also important to consider the hazards associated with any secondary fires and explosions that may occur.

4.1.2.2 Thermal Radiation Levels of Concern:

A Thermal Radiation Level of Concern (LOC) is a threshold level of thermal radiation, usually the level above which a hazard may exist. When you run a fire scenario, ALOHA will suggest three default LOC values. ALOHA uses three threshold values (measured in kilowatts per square meter and denoted as kW/m²) to create the default threat zones:

- ③ Red: 10 kW/m² (potentially lethal within 60 sec);
- ③ Orange: 5 kW/m² (second-degree burns within 60 sec); and
- ③ Yellow: 2 kW/m² (pain within 60 sec).

The thermal radiation effects that people experience depend upon the length of time they are exposed to a specific thermal radiation level. Longer exposure durations, even at a lower thermal radiation level, can produce serious physiological effects. The threat zones displayed by ALOHA represent thermal radiation levels; the accompanying text indicates the effects on people who are exposed to those thermal radiation levels but are able to seek shelter within one minute.

ALOHA's default thermal radiation values are based on a review of several widely accepted sources for this topic (e.g., American Institute of Chemical Engineers 1994, Federal Emergency Management Agency et al. 1988, and Lees 2001).

Thermal Radiation Burn Injury Criteria.

Radiation (kW/m ²)	Intensity	Time for Severe Pain (S)	Time for 2 nd Degree Burns (S)
1		115	663
2		45	187
3		27	92
4		18	57
5		13	40
6		11	30
8		7	20
10		5	14
12		4	11

Note: The durations that correspond to effects like pain or second-degree burns can vary considerably, depending on circumstances. The effects above were observed on bare skin that was exposed directly to the thermal radiation. Some types of clothing can serve as a protective barrier against thermal radiation and can affect the exposure duration. However, exposure duration should be kept to a minimum, even at low levels of thermal radiation.

4.1.3 Overpressure

A major hazard associated with any explosion is overpressure. Overpressure, also called a blast wave, refers to the sudden onset of a pressure wave after an explosion. This pressure wave is caused by the energy released in the initial explosion—the bigger the initial explosion, the more damaging the pressure wave. Pressure waves are nearly instantaneous, traveling at the speed of sound.

Although a pressure wave may sound less dangerous than a fire or hazardous fragments, it can be just as damaging and just as deadly. The pressure wave radiates outward like a giant burst of air, crashing into anything in its path (generating hazardous fragments). If the pressure wave has enough power behind it, it can lift people off the ground and throw them up against nearby buildings or trees. Additionally, blast waves can damage buildings or even knock them flat— often injuring or killing the people inside them. The sudden change in pressure can also affect pressure-sensitive organs like the ears and lungs. The damaging effects of the overpressure will be greatest near the source of the explosion and lessen as you move farther from the source.

ALOHA predicts an explosion's effects, assess the surroundings at the explosion site as you interpret ALOHA's threat zone plot. Large objects (like trees and buildings) in the path of the pressure wave can affect its strength and direction of travel. For example, if many buildings surround the explosion site, expect the actual overpressure threat zone to be somewhat smaller than ALOHA predicts. But at the same time, more hazardous fragments could be generated as the blast causes structural damage to those buildings.

4.1.3.1 Overpressure Levels of Concern

An Overpressure Level of Concern (LOC) is a threshold level of pressure from a blast wave, usually the pressure above which a hazard may exist. When you run a vapor cloud explosion scenario, ALOHA will suggest three default LOC values. ALOHA uses three threshold values to create the default threat zones:

- ③ Red: 8.0 psi (destruction of buildings);
- ③ Orange: 3.5 psi (serious injury likely); and
- ③ Yellow: 1.0 psi (shatters glass).

ALOHA's default overpressure values are based on a review of several widely accepted sources for this topic (e.g., American Institute of Chemical Engineers 1994, Federal Emergency Management Agency et al. 1988, and Lees 2001).

Explosion Overpressure Damage Estimates


Overpressure* (psig)	Expected Damage
0.04	Loud noise (143 dB); sonic boom glass failure.
0.15	Typical pressure for glass failure.
0.40	Limited minor structural damage.
0.50-1.0	Windows usually shattered; some window frame damage.
0.70	Minor damage to house structures.
1.0	Partial demolition of houses; made uninhabitable.
1.0-2.0	Corrugated metal panels fail and buckle. Housing wood panels blown in.
1.0-8.0	Range for slight to serious laceration injuries from flying glass and other missiles.
2.0	Partial collapse of walls and roofs of houses.
2.0-3.0	Non-reinforced concrete or cinder block walls shattered.
2.4-12.2	Range for 1-90% eardrum rupture among exposed populations.
2.5	50% destruction of home brickwork.
3.0	Steel frame building distorted and pulled away from foundation.
5.0	Wooden utility poles snapped.
5.0-7.0	Nearly complete destruction of houses.
7.0	Loaded train cars overturned.
9.0	Loaded train box cars demolished.
10.0	Probable total building destruction.
14.5-29.0	Range for the 1-99% fatalities among exposed populations due to direct blast effects.
* These are peak pressures formed in excess of normal atmospheric pressure by blast and shock waves.	

4.2 Effect at different Heat Radiations & Overpressure

4.2.1 Emergency Response Planning Guidelines (ERPGs)

ERPGs were developed as planning guidelines, to anticipate human adverse health effects caused by exposure to toxic chemicals.

The ERPGs are three-tiered guidelines with one common denominator: a 1-hour exposure period. The tiers are defined as follows:



Interpreting ERPG:

The ERPG guidelines do not protect everyone. Hypersensitive individuals would suffer adverse reactions to concentrations far below those suggested in the guidelines.


The guidelines are focused on one period of time: 1 hour. Exposure in the field may be longer or shorter. However, the ERPG committee strongly advises against trying to extrapolate ERPG values to longer periods of time.

ERPGs do not contain safety factors usually incorporated into exposure guidelines such as the TLV. Rather, they estimate how the general public would react to chemical exposure. Just below the ERPG-1, for example, most people would detect the chemical and may experience temporary mild effects. Just below the ERPG-3, on the other hand, it is estimated that the effects would be severe, although not lifethreatening. The TLV, on the other hand, incorporates a safety factor to prevent ill effects to exposed workers.







4.2.2 Temporary Emergency Exposure Limit (TEEL)

TEELs are temporary levels of concern designed to be used as toxic exposure limits for chemicals for which Acute Exposure Guideline Levels (AEGLs) or Emergency Response Planning Guidelines (ERPGs) have not yet been defined. Like AEGLs and ERPGs, they are designed to represent the predicted response of members of the general public to different concentrations of a chemical during an incident.

Each TEEL includes four tiers, defined as follows:



4.3 Various emergencies that may be expected at the port area

-  Leak / Spill and fire and explosion at the chemical jetties of hazardous chemicals. Fire at Berth/Storage area/warehouse/goodowns
-  Medical Injury
-  Terrorism/Sabotage
-  Civil disturbance
-  Hostage situation
-  Severe Weather
- Earthquake
- Tsunami
- Ships Accidents in the channel.

4.4 Leak / Spill and Fire & Explosion of Hazardous Chemicals at the Jetties

✚ Consequence analysis of impact distances for selected maximum credible loss scenarios of some selected chemicals handled at the chemical berths. ✚ The distance worked are indicative and to be used as a guide line.

4.5 Important assumptions considered for the Study

1. Representative chemicals have been chosen at each jetty. The distance shown in the table / map are applicable to any jetty (1 to 6) where the same chemical could be handled.

If the port is ready to handle the indicated distances for the chosen chemicals, then it can handle any other chemical emergency also under any weather conditions except storm / cyclone etc.

2. Wind speed 10m/sec from SW at 3 meter height.

3. Ground roughness – Open / Concrete

4. Cloud cover – Partial (5 Tenths)

5. Ambient Temperature – 40 degree C Average

6. Atmospheric stability Class “C”

7. Relative Humidity – 50%

8. Leak of 1000 litres of chemical

9. State of chemical at the time of leak – Liquid

10. Source: Direct Source

11. Source: Evaporating Puddle

- Downwind toxic effects
- Vapour cloud flash fire
- Overpressure from vapour cloud explosion

12. Source: Burning Puddle

- Thermal Radiation

13. Puddle diameter Average – 10 M

14. Puddle volume 1000 Litres.

4.6 Maximum Credible Loss Scenarios

The Maximum Credible Loss Scenarios (MCLS) give the possible failure scenarios, which takes into account the maximum inventory that can get released at the time of such a failure considering the intervention time based on safety systems provided at the facility.

The most hazardous chemicals taken into consideration for the study are:

Berth No: 1 – LPG & Toluene

Berth No: 2 – Benzene, ACN & Aniline

Berth No: 3 – Methanol, 1,3 Butadiene & Acetone

Berth No: 4 – VCM & Propylene

Berth No: 5 – Ammonia & HSD

Berth No: 6 – Motor Spirit & SKO

4.7 Impact Distances for MCLS under study

4.7.1 Jetty No – 1 Instantaneous Release / Evaporation Puddle / Burning Puddle for LPG

Chemical		Dispersion Distances			LEL Distances		Overpressure Distances			Pool Fire Heat Radiation Distance for		
		TEEL - 3 33000 ppm	TEEL - 2 17000 ppm	TEEL - 1 5500 ppm	60%	10%	8 psi	3.5 psi	1.0 psi	10.0kW/m ²	5.0kW/m ²	2.0kW/m ²
		m	m	m	m	m	m	m	m	m	m	m
Jet ty On e	LPG (Instantaneous Release)	31	46	88	68	204	LOC not exceeded	48	61	----	-----	----
	LPG (Evaporation Puddle)	13	24	54	35	130	LOC not exceeded	21	42	----	-----	----
	LPG (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	34	42	57

- Emergency equipment should be placed more than 60 meters away from the unloading hoses / source of leak to prevent damage to them due to over pressures.
- All fire fighting operation should be carried out from a 57 meter distance from the unloading hose, unless fire suits and close proximity suits are used by the fire fighting personnel.
- Whatever is the emergency (fire) at the berth, the sprinklers / water curtain at the berth edge should be activated. • All persons not directly connected with the operation should be moved beyond 88 meters from the fire / leak
- There should be no source of ignition in the chemical jetty (1 to 6) areas.
- The complete chemical jetty complex is a flame proof zone at all times.

4.7.2 Jetty No – 1 Instantaneous Release / Ev TOLUENE

[illegible]

Jet ty On e	TOLUENE (Instantaneous Release)	208	395	1.0Km	71	233	LOC not exceeded	52	72	-----	-----	-----
	TOLUENE (Evaporation Puddle)	< 10	21	73	< 10	< 10	No part of the cloud was above the LEL	No part of the cloud was above the LEL	No part of the cloud was above the LEL	-----	-----	-----
	TOLUENE (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	29	35	47

- All emergency equipment should be placed more than 72 meters away from the source of leak.
- Fire fighting should be carried out from a distance of more than 47 meter unless fire suits / fire proximity suits are worn by the fire fighting personnel.
- All persons not directly connected with the emergency operation should be moved more than 1 km away from the source of leak.
- All other fire fighting precautions should be adhered to.

4.7.3 ACRYLONITRILE (ACN)

Chemical		Dispersion Distances			LEL Distances		Overpressure Distances			Pool Fire Heat Radiation Distance For		
		ERPG - 3 75 ppm	ERPG - 2 35 ppm	ERPG - 1 10 ppm	60%	10%	8 psi	3.5 psi	1.0 psi	10.0kW/m ²	5.0kW/m ²	2.0kW/m ²
		m	m	m	m	m	m	m	m	m	m	m
Jet ty Tw o	ACN (Instantaneous Release)	1.0 Km	1.5 Km	2.8 Km	62	211	LOC not exceeded	41	61	-----	-----	-----
	ACN (Evaporation Puddle)	49	76	148	< 10	< 10	No part of the cloud was above the LEL	No part of the cloud was above the LEL	No part of the cloud was above the LEL	-----	-----	-----
	ACN (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	19	23	30

- In case of an emergency involving Acrylonitrile in the form of a major leak with or without a fire, all fire fighters handling the emergency must wear Breathing apparatus, in addition to the usual fire suits.
- All persons not connected with the emergency operation should move beyond 2.8Km distance.

- All supporting personnel must be ready with BA sets.
- The nearby shanty should be evacuated.
- All security staff must have respiratory protection.
- All persons handling the emergency should be sent to the Kandla Port Hospital for checking for CAN poisoning.

4.7.4 ANILINE

Chemical		Dispersion Distances			LEL Distances		Overpressure Distances			Pool Fire Heat Radiation Distance For		
		TEEL – 3 20 ppm	TEEL – 2 12 ppm	TEEL – 1 8 ppm	60%	10%	8 psi	3.5 psi	1.0 psi	10.0kW/m ²	5.0kW/m ²	2.0kW/m ²
		m	m	m	m	m	m	m	m	m	m	m
Jet ty Two	ANILINE (Instantaneous Release)	1.8 Km	2.3 Km	2.7 Km	72	237	LOC not exceeded	53	73	-----	-----	-----
	ANILINE (Evaporation Puddle)	12	20	29	< 10	< 10	No part of the cloud was above the LEL	No part of the cloud was above the	No part of the cloud was above the	-----	-----	-----

							LEL	LEL			
ANILINE (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	20	23	31

- All persons handling the emergency must wear full protection suits to avoid skin contact. BA should be worn by the persons handling the emergency.
- The adjoining shanty should be evacuated.
- Persons handling the emergency should check up if their nails, lips, earlobes have turned blue. If so, immediately move them to Kandla Port hospital.

4.7.5 BENZENE

Chemical	Dispersion Distances	LEL Distances	Overpressure Distances	Pool Fire Heat Radiation Distance For
----------	----------------------	------------------	------------------------	--

		ERPG - 3 1000 ppm m	ERPG - 2 150 ppm m	ERPG -1 50 ppm m	60% m	10% m	8 psi m	3.5 psi m	1.0 psi m	10.0kW/m ² m	5.0kW/m ² m	2.0kW/m ² m
Jet ty Tw o	BENZENE (Instantaneous Release)	228	625	1.1 Km	80	265	LOC not exceeded	61	76	-----	-----	-----
	BENZENE (Evaporation Puddle)	23	81	145	< 10	20	No part of the cloud was above the LEL	No part of the cloud was above the LEL	No part of the cloud was above the LEL	-----	-----	-----
	BENZENE (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	29	35	47

- A Benzene fire gives out dense black smoke which could reduce the visibility. All fire fighters must wear a chemical protection suit while handling the emergency, wear BA.

- All those not connected with the emergency handling should move beyond 1.1 km up wind.
- Initial fire fighting should be from a distance of 47 meter, unless fire suits, proximity suits are worn. All security staff must have respiratory protection.
- All persons handling the emergency should be sent to the Kandla Port hospital for urine test to check for Benzene poisoning.

4.7.6 1:3, BUTADIENE

Chemical		Dispersion Distances			LEL Distances		Overpressure Distances			Pool Fire Heat Radiation Distance For		
		ERPG - 3 5000 ppm	ERPG - 2 200 ppm	ERPG - 1 10 ppm	60%	10%	8 psi	3.5 psi	1.0 psi	10.0kW/m ²	5.0kW/m ²	2.0kW/m ²
		m	m	m	m	m	m	m	m	m	m	m
Jetty There	1:3, BUTADIENE (Instantaneous Release)	92	524	2.4 Km	62	206	LOC not exceeded	48	63	-----	-----	-----

1:3, BUTADIENE (Evaporation Puddle)	22	157	736	13	53	LOC not exceeded	< 10	21	-----	-----	-----
1:3, BUTADIENE (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	34	42	57

- Initial fire fighting should be from a distance of more than 57 meters. The fire fighters should wear BA sets and chemical protection suits.
- The shanty should be evacuated beyond 2.4 Km distance.

4.7.7 ACETONE

Chemical		Dispersion Distances			LEL Distances		Overpressure Distances			Pool Fire Heat Radiation Distance For		
		TEEL - 3 5700 ppm	TEEL - 2 3200 ppm	TEEL - 1 200 ppm	60%	10%	8 psi	3.5 psi	1.0 psi	10.0kW/m ²	5.0kW/m ²	2.0kW/m ²
		m	m	m	m	m	m	m	m	m	m	m
Jet ty Th re e	ACETONE (Instantaneous Release)	97	134	591	56	190	LOC not exceeded	40	56	-----	-----	-----
	ACETONE (Evaporation Puddle)	10	17	111	< 10	22	No part of the cloud was above the LEL	No part of the cloud was above the LEL	No part of the cloud was above the LEL	-----	-----	-----

ACETONE (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	20	24	32
--------------------------------	-------	-------	-------	-------	-------	-------	-------	-------	----	----	----

- Fire fighters should note that acetone and methanol fires are non luminescent and there could be a tendency to go nearer to the puddle /pool on fire. This should be done by fire fighters fully equipped with fire suits / proximity suits. Acetone / Methanol are water soluble, which is advantageous for fire fighting.

4.7.8 METHANOL

Chemical	Dispersion Distances			LEL Distances		Overpressure Distances			Pool Fire Heat Radiation Distance		
	ERPG - 3 5000 ppm	ERPG - 2 1000 ppm	ERPG- 1 200 ppm	60%	10%	8 psi	3.5 psi	1.0 psi	10.0kW/m ²	5.0kW/m ²	2.0kW/m ²

		m	m	m	m	m	m	m	m	m	m	m
Jet ty Th re e	METHANOL (Instantaneous Release)	178	431	1.0 Km	49	190	LOC not exceeded	LOC not exceeded	33	----	-----	----
	METHANOL (Evaporation Puddle)	< 10	33	89	< 10	< 10	No part of the cloud was above the LEL	No part of the cloud was above the LEL	No part of the cloud was above the LEL	----	-----	----
	METHANOL (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	11	12	15

- Fire fighters should note that acetone and methanol fires are non luminescent and there could be a tendency to go nearer to the puddle /pool on fire. This should be done by fire fighters fully equipped with fire suits / proximity suits. Acetone / Methanol are water soluble, which is advantageous for fire fighting.

4.7.9 Jetty No – 4 Instantaneous Release / Ev PROPYLENE

Chemical		Dispersion Distances			LEL Distances		Overpressure Distances			Pool Fire Heat Radiation Distance For		
		TEEL - 3 20000 ppm	TEEL- 2 10000 ppm	TEEL -1 1500 ppm	60%	10%	8 psi	3.5 psi	1.0 psi	10.0kW/m ²	5.0kW/m ²	2.0kW/m ²
		m	m	m	m	m	m	m	m	m	m	m
Jet ty Fo ur	PROPYLENE (Instantaneous Release)	51	80	233	74	253	LOC not exceeded	52	66	-----	-----	-----
	PROPYLENE (Evaporation Puddle)	30	53	163	51	194	LOC not exceeded	29	52	-----	-----	-----
	PROPYLENE (Burning	-----	-----	-----	-----	-----	-----	-----	-----	33	41	55

	Puddle)											
--	---------	--	--	--	--	--	--	--	--	--	--	--

- All emergency handling should be from a distance of more than 66 meters unless full fire suits / proximity suit is worn.
- **All personnel not directly connected with the emergency should be moved beyond 233 meters from the leak area.**

4.7.10 Jetty No – 4 Instantaneous Release / Ev VINYL CHLORIDE (VCM)

Chemical		Dispersion Distances			LEL Distances		Overpressure Distances			Pool Fire Heat Radiation Distance		
		ERPG - 3 5000 ppm	ERPG - 2 1000 ppm	ERPG - 1 200 ppm	60%	10%	8 psi	3.5 psi	1.0 psi	10.0kW/m ²	5.0kW/m ²	2.0kW/m ²
		m	m	m	m	m	m	m	m	m	m	m
Jetty Four	VCM (Instantaneous Release)	47	108	376	45	152	LOC not exceeded	30	48	-----	-----	-----
	VCM (Evaporation Puddle)	< 10	15	52	< 10	23	No part of the cloud was above the LEL	No part of the cloud was above the LEL	No part of the cloud was above the LEL	-----	-----	-----

VCM (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	< 10	< 10	< 10
----------------------------	-------	-------	-------	-------	-------	-------	-------	-------	------	------	------

- VCM is highly toxic, hence all persons handling the emergency involving VCM should wear full respiratory protection (BA sets) and handle the emergency from a distance of more than 48 meters.
- Nearby shanty should be put on the alert for evacuation in case emergency evacuation is needed.
- All persons handling the emergency should be sent to the Kandla Port hospital for VCM poisoning check up.

4.7.11 Jetty No – 5 Instantaneous Release / Ev AMMONIA

Chemical	Dispersion Distances			LEL Distances		Overpressure Distances			Pool Fire Heat Radiation Distance For		
	AEGL - 3 1100 ppm	AEGL - 2 160 ppm	AEGL - 1 30 ppm	60%	10%	8 psi	3.5 psi	1.0 psi	10.0kW/m ²	5.0kW/m ²	2.0kW/m ²

		m	m	m	m	m	m	m	m	m	m	m
Jet ty Fiv e	AMMONIA (Instantaneous Release)	219	589	1.4 Km	33	80	LOC not exceeded	LOC not exceeded	26	-----	-----	-----
	AMMONIA (Evaporation Puddle)	96	260	617	< 10	16	No part of the cloud was above the LEL	No part of the cloud was above the LEL	No part of the cloud was above the LEL	-----	-----	-----
	AMMONIA (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	< 10	11	13

- Emergencies involving Ammonia will be mostly leakage / spillage.
- Ammonia is flammable with difficulty.
- Ammonia emergencies should be handled by wearing BA sets.
- Ammonia is soluble in water, which will make it easier to handle the emergency.
- Do not direct water jet onto the liquid ammonia puddle, this could cause spurting of the liquid. Let the ammonia vapours come into the water spray / fog.

AEGLs represent threshold exposure limits for the general public and are applicable to emergency exposure periods ranging from 10 minutes to 8 hours. AEGL-2 and AEGL-3, and AEGL-1 values as appropriate will be developed for each of five exposure periods (10 and 30 minutes, 1 hour, 4 hours, and 8 hours) and will be distinguished by varying degrees of severity of toxic effects. It is believed that the recommended exposure levels are applicable to the general population including infants and children, and other individuals who may be susceptible.

The three AEGLs have been defined as follows:

AEGL-1 is the airborne concentration, expressed as parts per million or milligrams per cubic meter (ppm or mg/m³) of a substance above which it is predicted that the general population, including susceptible individuals, could experience notable discomfort, irritation, or certain asymptomatic nonsensory effects. However, the effects are not disabling and are transient and reversible upon cessation of exposure.

AEGL-2 is the airborne concentration (expressed as ppm or mg/m³) of a substance above which it is predicted that the general population, including susceptible individuals, could experience irreversible or other serious, long-lasting adverse health effects or an impaired ability to escape.

AEGL-3 is the airborne concentration (expressed as ppm or mg/m³) of a substance above which it is predicted that the general population, including susceptible individuals, could experience life-threatening health effects or death.

Airborne concentrations below the AEGL-1 represent exposure levels that can produce mild and progressively increasing but transient and nondisabling odor, taste, and sensory irritation or certain asymptomatic, nonsensory effects. With increasing airborne concentrations above each AEGL, there is a progressive increase in the likelihood of occurrence and the severity of effects described for each corresponding AEGL. Although the AEGL values represent threshold levels for the general public, including susceptible subpopulations, such as infants, children, the elderly, persons with asthma, and those with other illnesses, it is recognized that individuals, subject to unique or idiosyncratic responses, could experience the effects described at concentrations below the corresponding AEGL.

4.7.12 Jetty No – 5 Instantaneous Release / Evaporation Puddle / Burning Puddle for HSD

		Dispersion Distances			LEL Distances		Overpressure Distances			Pool Fire Heat Radiation Distance For		
		TEEL 8600 ppm	TEEL 3300 ppm	TEEL 400 ppm	60%	10%	8 psi	3.5 psi	1.0 psi	10.0kW/m ²	5.0kW/m ²	2.0kW/m ²
		3	2	1								
		m	m	m	m	m	m	m	m	m	m	m
Jetty Five	HSD (Instantaneous Release)	59	112	370	73	240	LOC not exceeded	53	71	-----	-----	-----
	HSD (Evaporation Puddle)	<10	15	85	14	48	LOC not exceeded	10	19	-----	-----	-----

	HSD (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	35	42	58
--	-----------------------------------	-------	-------	-------	-------	-------	-------	-------	----	----	----

- High Speed Diesel fires should be handled with care, by wearing fire suits / proximity suits.
- Foam should be used for fire fighting.

4.7.13 Jetty No – 6 Instantaneous Release / Evaporation Puddle / Burning Puddle for MOTOR SPIRIT

Chemical	Dispersion Distances	LEL Distances	Overpressure Distances	Pool Fire Heat Radiation Distance
----------	----------------------	------------------	------------------------	-----------------------------------

		TEEL - 3 1500 ppm m	TEEL - 2 610 ppm m	TEEL - 1 610 ppm m	60% m	10% m	8 psi m	3.5 psi m	1.0 psi m	10.0kW/m ² m	5.0kW/m ² m	2.0kW/m ² m
Jet ty Six	MOTOR SPIRIT (Instantaneous Release)	159	258	258	68	227	LOC not exceeded	51	66	-----	-----	-----
	MOTOR SPIRIT (Evaporation Puddle)	51	85	85	16	70	LOC not exceeded	11	24	-----	-----	-----
	MOTOR SPIRIT (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	37	45	61

- Motor spirit fires should be handled with care, by wearing fire suits / proximity suits.
- Foam should be used for fire fighting.

[illegible]

Jet ty Six	SKO (Instantaneous Release)	141	159	209	74	239	LOC not exceeded	54	73	-----	-----	-----
	SKO (Evaporation Puddle)	< 10	< 10	< 10	< 10	< 10	No part of the cloud was above the LEL	No part of the cloud was above the LEL	No part of the cloud was above the LEL	-----	-----	-----
	SKO (Burning Puddle)	-----	-----	-----	-----	-----	-----	-----	-----	28	35	48

- SKO fires should be handled with care, by wearing fire suits / proximity suits.
- Foam should be used for fire fighting.


4.8 Coal Storage at Open Yard

4.8.1 General Characteristics of Coal

Coal is a fossil fuel extracted from the ground by underground mining or open pit mining. It is a readily combustible, black or brownish – black sedimentary rock. It is composed primarily of carbon along with assorted other elements.

Carbon forms more than 50% by weight and more than 70% by volume of coal.

Coal usually contains a considerable amount of incidental moisture, which is the water trapped within the coal in between the coal particles. The structure of a coal molecule is represented as follows:



Methane gas is another component of coal. Methane in coal is dangerous as it can cause explosion and may cause the coal to spontaneously combust.

4.8.2 Effects of Coal Burning

Combustion of coal, like any other compound containing carbon, produces CO_2 , along with minor amount of SO_2 .

Coal can be set on fire by spontaneous combustion

4.8.3 Spontaneous Combustion in Coal

The risk from fire exists where significant amounts of coal are in use or storage. Coal is a combustible material, making it susceptible to a variety of ignition scenarios. One of the most frequent and serious causes of coal fires is spontaneous combustion, which has been responsible for a number of incidents within the department in recent years.

Preventing spontaneous combustion coal fires involves attention to many different factors. Among the most critical are the type, age and composition of coal, how it is stored and how it is used. Given the right kind of coal, oxygen, and a certain temperature and moisture content, coal will burn by itself.

Spontaneous combustion has long been recognized as a fire hazard in stored coal. Spontaneous combustion fires usually begin as “hot spots” deep within the reserve of coal. The hot spots appear when coal absorbs oxygen from the air. Heat generated by the oxidation can initiate the fire.

Such fires can be very stubborn to extinguish because of the amount of coal involved (often hundreds of tons) and the difficulty of getting to the seat of the problem. Moreover, coal in either the smoldering or flaming stage may produce copious amounts of methane and carbon monoxide gases. In addition to their toxicity, these gases are highly explosive in certain concentrations, and can further complicate efforts to fight this type of coal fire.

Even the most universal fire fighting substance, water, cannot be used indiscriminately, because of the remote possibility of a steam explosion; it is advisable that water be applied carefully and from a safe distance. Certain chemicals such as carbon dioxide or nitrogen may mitigate fire effects, but their use has had mixed success from a DOE (Department of Energy) perspective. The above information suggests that coal fires require awareness and prior planning to extinguish efficiently, completely, and safely.

4.8.4 Causes of Spontaneous Coal Fires

The following general factors have been mentioned as contributing causes:

- ③ Coal handling procedures allowed for long-time retention of coal, which increases the possibility of heating

- ③ New coal added on top of old coal created segregation of particle sizes, which is a major cause of heating
- ③ Too few temperature probes installed in the coal bunker resulted in an excessive period of time before the fire was detected.
- ③ Failure of equipment needed to fight the fire
- ③ Ineffective capability and use of carbon dioxide fire suppression system
- ③ Delay in the application of water

4.8.4.1 Preventing Spontaneous Combustion in Stored Coal

High quantities of coal are stored in bunkers, silos, hoppers and open air stockpiles. How susceptible such stocks of coal are to fire from spontaneous combustion depends on a number of factors, from how new the coal is to how it is piled.

4.8.5 Recommendations for Coal Storage

- ③ Storing coal with low sulphur content is helpful. Sulphur compounds in coal liberate considerable heat as they oxidize.
- ③ Air circulating within a coal pile should be restricted as it contributes to heating; compacting helps seal air out.
- ③ Moisture in coal contributes to spontaneous heating because it assists the oxidation process. Moisture content should be limited to 3 %; sulphur content should be limited to 1 %, “as mined.” Coal having high moisture content should be segregated and used as quickly as possible. Efforts should be made to keep stored coal from being exposed to moisture.
- ③ Following the “First in, First out” rule of using stock reduces the chance for hot spots by helping preclude heat build up for portions of stock which remain undisturbed for a long term. The design of coal storage bins is important in this regard.

- ③ A high ambient temperature aids the spontaneous heating process. Remove coal as quickly as possible. The longer large coal piles are allowed to sit, the more time the spontaneous process has, to work.
- ③ The shape and composition of open stock piles can help prevent fires. Dumping coal into a big pile can lead to problems. Rather, coal should be packed in horizontal layers (opinions range from 1 ½' to 3' high) which are then levelled by scraping and compacted by rolling. This method helps distribute the coal evenly and thus avoids breakage and segregation of fine coal. Segregation of coal particles by size should be avoided, as it may allow more air to enter the pile and subsequent heating of finer sizes.
- ③ The height of the coal pile/stock is also important; limit un - layered, un - compacted high grade coal to a height of 15' maximum height.
- ③ Properly inspect, test and maintain installed fire protection equipment.
- ③ Maintain an updated pre-fire plan and encourage regular visits to coal facilities by the site or local emergency response force.

4.8.6 Roll Packing

Roll packing helps to exclude O₂ and thus to prevent fires by discouraging spontaneous combustion. Coal is distributed by a grab bucket or by other means in a uniform layer. The layer is then levelled by scraping and compacted by rolling. Distributing the coal evenly avoids breakage and segregation of the coal. The firm packing helps shed water.

4.8.7 Checking Temperature

Steam rising from a pile or the odour of burning coal is an indication of spontaneous heating, but an earlier or more reliable indication is obtained by checking the temperature/ hot spots/CO detection.

Rise of temperature can be noted by use of thermocouples. Hot spots can be detected by use of IR coal fire monitors. CO detectors can indicate that coal combustion has started.

4.9 Risk Analysis for Coal Fires in Storage Yard Berth 14

Data used for calculation of impact distance for coal fires. Type of coal – Bituminous (Medium Volatile)

Emissivity Constant (ϵ)	=	0.9 for Bituminous Coal
Stefan Boltzmann constant	=	$5.6 \times 10^{-8} \text{ kW/m}^2 \text{ K}^4$

FQ 4.9.1 Formula used for Calculation of Impact Distance (D) ✓ /

Where D	=	Distance from flame centre to receiving point.
Where F	=	Fraction of heat radiation = 0.15 (Conservative)
Where Q	=	Total Heat Generated / Emitted by Coal
Where K	=	Thermal Radiation level

Maximum temperature attained by flame of Coal $T_f = 900^\circ\text{C} = 1173\text{K}$

Ambient surrounding temperature $T_a = 27^\circ\text{C} \text{ to } 35^\circ\text{C} = 300\text{K} - 308\text{K}$

$$Q = \sigma A \epsilon (T_f^4 - T_a^4)$$

$$\sigma = 5.68 \times 10^{-8} \text{ kW/m}^2 \text{ K}^4$$

$$T_f^4 = (1173)^4 \text{ K}$$

$$T_a^4 = (300)^4 \text{ K}$$

For active coal burning area = 10m^2

$$Q = 5.6 \times 10^{-8} \times 0.9 \times 10 (1173^4 - 300^4)$$

$$Q = 950 \text{ kW}$$

For Heat radiation 4 kW/m^2 impact distance D

$$D = \sqrt{(950 \times 0.15) / (4 \times 3.14 \times 4)} = 1.68 = 1.7\text{m}$$

For Heat radiation 12.5 kW/m^2 impact distance D

$$D = \sqrt{(950 \times 0.15) / (4 \times 3.14 \times 12.5)} = 0.9527 = 1 \text{ m}$$

For Heat radiation 37.5 kW/m^2 impact distance D

$$D = \sqrt{(950 \times 0.15) / (4 \times 3.14 \times 37.5)} = 0.55\text{m}$$

For active coal burning area – 100 m^2

$$Q = 5.6 \times 10^{-8} \times 0.9 \times 100 (1173^4 - 300^4)$$

$$= 9500 \text{ kW/m}^2$$

For Heat radiation 4 kW/m^2 impact distance D

$$D = \sqrt{(9500 \times 0.15) / (4 \times 3.14 \times 4)} = 5.32 \text{ m}$$

For Heat radiation 12.5 KW/m^2 impact distance D

$$D = \sqrt{(9500 \times 0.15) / (4 \times 3.14 \times 12.5)} = 3.012 \text{ m}$$

For Heat radiations 37.5 KW/m² impact distance D

$$D = \sqrt{(9500 \times 0.15) / (4 \times 3.14 \times 37.5)} = 1.74 \text{ m}$$

The Damage Effects Due to Thermal Radiation of Varying Intensity

Incident Radiation Intensity (kW/m ²)	Type of Damage
37.5	Sufficient to cause damage to process equipment unless the equipment is fully thermally fire protected (Insulation, fire proofing, sprinkler protection etc)
12.5	Minimum energy required for piloted ignition of wood, melting plastic tubing, etc.
4.5	Sufficient to cause pain to personnel if unable to reach within 20 seconds, blistering of skin (1st degree burns) is likely.

4.9.2 Summary:

Heat Radiation Impact distance for	Active Burning Coal Area	
	10 m ²	100 m ²
4 kW/m ²	1.7 m	5.3 m
12.5 kW/m ²	1.0 m	3.0 m


37.5 kW/m ²	0.5 m	1.74 m

Assuming that 100m² surface area of the coal stock is smouldering no person should approach the stock within 6 m distance.


All fire fighting should be done from more than 5.3 m away from the affected coal stock unless the fire fighter is fully clothed with fire protective clothing and respiratory protection

Please note that CO could also be emitted during a coal fire due to incomplete combustion. Hence adequate respiratory protection should be used like canister gas mask or Self Contained Breathing Apparatus –SCBA

4.10 Fire & Explosion Response Plan



4.11 Fire & Toxic Leakage



PROCESS

- | | |
|--|--|
| (1) Master or informer raises alarm | (2) Informs control room at the Fire Station |
| (3) Advises D.C. and H.M and Action Group | (4) Action group commences to use protective clothing in area
-Spray water-stop cargoes/Isolate – locate leak-repair test |
| (5) Declare crisis level | (6) Crisis level endorsement by crisis management group |
| (7) If crisis level declared is greater | (8) Mutual aid partners contacted and district emergency plan initiated |
| (9) If necessary evacuation commenced partial or full. | |

4.12 Details of Fire Fighting Equipment available at Kandla Port

4.12.1 Fire Water Tender – 6 Nos

Water Tank Capacity: 6000 liters. (Discharge Capacity 2250 liters/PER MIN at 7.5kg/cm² & 300 liters at 40kg/cm²).

Fire Monitor Discharge capacity 2750 lpm at 7kg/cm² with effective throw/Jet of minimum 45 meters.

Fire Fighting Equipments:

- RRL Hose 15mtrs X 63mm (ID)
- Foam AFFF 3%
- Various type of Branches
- Hose Fittings
- Small Gears
- Personnel Protective equipment (PPE)
- Additional Foam Fighting System
- Communication System
- Public Address system
- Extension Ladder

4.12.2 Foam Fire Tender – 3 Nos

Water Tank Capacity: 5000 liters. (Discharge Capacity 2250 liters at 7.5kg/cm² & 300 liters at 3.5kg/cm²).

Foam Tank Capacity: 1000 liters.

Fire Monitor Discharge capacity 2750 lpm at 7kg/cm² with effective throw/Jet of minimum 45 meters.

Additional CO₂ Extinguishing System.

Fire Fighting Equipments:

- RRL Hose 15mtrs X 63mm (ID)
- Foam AFFF 3%
- Various type of Branches
- Hose Fittings
- Small Gears
- Personnel Protective equipment (PPE)
- Additional Foam Fighting System
- Communication System
- Public Address system
- Extension Ladder

4.12.3 Multi Purpose Fire Tender – 1 No

Water Tank Capacity: 5000 liters. (Discharge Capacity 2000 liters at 10kg/cm² & 300 liters at 3.5kg/cm²).

Foam Tank Capacity: 1000 liters.

Fire Monitor Discharge capacity 2750 lpm at 7kg/cm² with effective throw /Jet of minimum 45 meters.

Additional CO₂ Extinguishing System.

Additional Dry Chemical Powder Extinguishing System.

Fire Equipments:

- RRL Hose 15mtrs X 63mm (ID)
- Foam AFFF 3%
- Various type Branches
- Hose Fittings
- Small Gears
- Personnel Protective equipment (PPE)
- Addition Foam Fighting System
- Communication System
- Public Address system
- Extension Ladder

4.12.4 SURVEYED OFF NEW PROCUREMENT IN PROCESS

4.12.5 Tank Lorry - 01 No.

- Tank Capacity 12,000 liters.
- Anti Pollution Scheme.

4.12.6 Fire Jeep – 01 No.

Pump Discharge Capacity 1800 liters at 7kg/cm².

Fire Fighting Equipments:

- RRL Hose 15mtrs X 63mm (ID)
- Various type of Branches
- Hose Fittings
- Small Gears
- Personnel Protective equipment (PPE)
- Communication System
- Public Address system
- Extension Ladder

4.12.7 Safety Jeep – 01 No.

For proper Coordination, Inspection, in around the Port (Oil & Chemical Tank Farm & Administrative Works).

Fire Fighting Equipments:

- Small Gears
- Personnel Protective equipment (PPE)
- Communication System
- Public Address system

4.12.8 Ambulance – 01 No.

For Transportation of Injured Ship Official, Ship Crews and Victims.

4.13 Station wise Manpower Break Up (Manned Round The Clock)

4.13.1 Emergency Response Centre / Old Kandla Fire Station (Liquid Cargo Jetty)

- Fire cum Safety Officer – 01
- Deputy Fire Officer – 01
- Station Officers – 02 Nos
- Leading Fireman– 02 Nos
- Pump Operator cum Driver – 03 Nos
- Fireman – 08 Nos

Oil Jetty No. 1 (LPG Jetty)

- Leading Fireman – 01
- Pump Operator cum Driver – 01
- Fireman– 04 Nos

Oil Jetty No. 2

- Leading Fireman– 01
- Fireman– 04 Nos
- Pump Operator cum Driver – 01

Oil Jetty No. 3

- Leading Fireman – 01
- Fireman– 04 Nos

Oil Jetty No. 4

- Leading Fireman – 01

- Pump Operator cum Driver – 01
- Fireman– 04 Nos

Oil Jetty No. 5 (IFFCO Jetty)

- Leading Fireman – 01
- Pump Operator cum Driver – 01
- Fireman– 04 Nos

While LPG Tanker is discharging the LPG at Oil Jetty No.1, a Station Officer shall be in charge till the unberthing of LPG Vessel.

Above Fire Crews will be posted at Oil Jetties depending upon the Nature of Risk Cargo Handled.

4.13.2 Tilak Fire Station (Dry Cargo Jetty).

- Station Officers– 01 No
- Leading Fireman– 01 No
- Pump Operator cum Driver– 02 Nos
- Fireman – 04 Nos

For Running & Maintenance of First Aid, Fire Equipments installed at various work places of Kandla Port.

- Leading Fireman– 01 No
- Fireman – 02 Nos

4.13.3 Azad Fire Station (Dry Cargo Jetty).

- Station Officers– 01 Nos

- Leading Fireman– 01 No
- Pump Operator cum Driver– 02 Nos
- Fireman – 04 Nos

4.14 Fire fighting facility at Chemical / Oil Handling Berths

4.14.1 Oil Jetty No: 1

Fixed 2 nos water/foam monitors mounted on towers at each end of each berth.

There are three vertical turbine pumps each of 500m³/hr capacity. One each of Electrical Fire Water Pumps, Diesel Engine Fire water pumps, Electrical flushing pumps.

Jetty one LPG side – 12 DCP – 5Kg Fire Extinguishers, 2 DCP – 150 Kg Trolley mounted fire extinguishers.

4 Fire suits, 2 BA sets with 2 spare respirable air cylinders.

Fire equipment Room:

- Foam / DCP – 15 Nos fire extinguishers
- Helmets – 6 Nos
- Hose length (15 meters) 10 Nos
- Manual Siren – 1No
- Gum Boots – 6 Pairs
- Ropes
- Foam compound 1000 Liters
- Hose fittings
- Branch Pipes
- Fire Axe

- Safety shower – 1 No
- Water curtains
- Fire suits – 2 Nos
- Canister gas mask – 1 No
- Telephone
- Mobile foam trolley – 100 Liters

4.14.2 Oil Jetty No: 2

Fixed foam / water remote controlled monitors mounted on towers at each end of each berth.

There are two vertical turbine pumps each of 800m³/hr capacity, two jockey pumps of 25m³/hr capacity, two foam pumps each of 22m³/hr capacity, two foam /water remote controlled tower monitors, and six jumbo curtains installed at the jetty face.

Fire equipment Room:

- Foam /DCP – 10 Nos each fire extinguishers
- Helmets – 6 Nos
- Fire Hoses - 10 Nos
- BA set – 1No
- Gum Boots – 6 Pairs
- Foam making branch pipes – 2 Nos
- Female coupling –8 Nos
- Jet branch pipes –5 Nos
- Fire suits -2 Nos
- Foam compound - 50 x 30 Liters
- Chemical Suits- 2 Nos
- Fire Axe- 1No
- DCP Fire extinguishers – 10 Nos

- Foam Fire extinguishers – 10 Nos
- Fire Buckets – 10 Nos
- Oil Dispersant – 10 x 20 Liters
- Rubber hand gloves – 6 Nos
- Hose length – 15 meters (10 Nos)

4.14.3 Oil Jetty No: 3, 4 & 5

In Oil Jetty No: 3, there are two foam pumps, with foam tank, 2 remote controlled tower monitors for foam / water spray, 2 sets of jumbo curtains at jetty face, one flame detection system, one 50KW DG set and control console.

Oil Jetty No: 4, there are three vertical turbine pumps each of 500m³/hr capacity, 2 foam pumps with foam tank, 2 remote control tower monitors of capacity 3000 liters per minute of water, 3 jumbo curtains at jetty face, 50 KW DG set and control console.

Oil Jetty No: 5, there are two fire water pumps each of 270m³/hr capacity, (One electrical driven pump, and one diesel engine pump each).

Fire equipment Room:

- Fire buckets – 8 Nos
- Manual Fire Sirens – 1 No
- Foam branch pipes – 4 Nos
- Mechanical foam generator – 2Nos
- Foam compound – 1000 Liters
- BA set – 1 No
- Gum Boots – 6 Pairs
- Helmets – 6 Nos
- Hose length (15 Meters) – 10 Nos
- DCP fire extinguishers – 10 Nos

- Foam fire extinguishers – 5 Nos
- Fire suits – 2 Nos
- Dispersant chemicals - 6 x 20 Lets
- Double female couplings – 8 Nos
- Male coupling – 2 Nos
- Diffuser – 2 Nos
- Water Curtain – 1 No
- Jet Branch Pipe – 2Nos
- Canister Gas Masks – 1 No
- Portable foam / water monitor – 1 No
- Mobile foam generator
- Safety Shower – 1No

4.14.4 Oil Jetty No: 6

- 2 – Nos Diesel engine fire water pumps 820m³/hour each.
- 1 – HP Jockey pump electrical 80m³/hour
- Fire blankets (water jel)
- Smoke detectors in fire pump house
- Hand tool set
- Water curtains nozzles – 2 Nos • AFFF foam
- DCP fire extinguishers – 6 Nos
- Trolley mounted DCP fire extinguishers – 4 Nos
- CO₂ fire extinguishers – 6 Nos
- Foam fire extinguishers – 6 Nos

4.15 General Fire fighting guidelines at the Oil Jetty

1. Stop all loading / unloading operations and close valves.
2. All fire fighters will be apprised of the chemicals and POL products normally handled at the jetties. A set of MSDS is available at the fire station.
3. As a general rule all fire fighting will be carried out from a distance of 60 meter (Average heat radiation experience of 2kw/m^2). If the fire fighters are required to go closer to the fire then fire suits / close proximity suit must be worn. If necessary, water cover could be provided to the fire fighters going closer to the fire.
4. The water curtain along the edge of the berth will be activated for fire / leak / spill emergency at the berth.

and any available tug should be immediately put on s/by.

5. All emergency equipment should be placed beyond the over pressure distance of about 60 meters (Average overpressure distance for 1.0 psi experience) to avoid damage to them.
6. The remote water / foam monitor should be operated to control the fire at the jetty. If properly used the fire will be immediately controlled.
7. All persons not connected with handling the emergency should be moved beyond the TEEL – 1 / ERPG – 1 level distance which is an average distance of 1 Km. But if toxic chemical release takes place then the people from the shanty should be moved beyond 3 Km distance of the fire.
8. All security staff (CISF) should also have access to respiratory protection as they may not be able to leave their post.
9. External help should be obtained as soon as it is felt that the emergency is grave.

10. CISF guards will keep note of all incoming aid equipment.
11. After the emergency is over the Deputy Conservator / Harbour Master will assign a senior management team to verify that there is no longer a threat of further fire / leak / spill, to assess damage and initiate repairs

as needed.
12. Any emergency at the chemical jetties or at the dry cargo berths will be informed to the Deputy Conservator / Harbour Master, who will activate the DMP if necessary.

4.16 General guidelines in case of Toxic Chemical spill / leak

1. Stop all loading / unloading operations and close valves.
2. All emergency operation should be carried out from up wind direction. This may always not be possible. All persons handling a chemical leak / spill should wear chemical protection suit and respiratory protection like gas mask / BA sets.
3. any available tug should be put on alert or pressed into operation.
4. Deputy Conservator / Harbour Master should be informed of a chemical spill however small it may be.
5. CISF should have access to respiratory protection as they may not be able to leave their post.
6. In case of a major chemical leak / spill the neighbouring shanty should be evacuated especially if chemicals like, Acrylonitrile, Benzene, Aniline, 1:3 Butadiene, Vinyl Chloride, Styrene has spilled.
7. Attempts could be made to salvage the spilled chemical or dispersant could be applied to the spill.

8. The chief fire officer should be kept informed of the chemicals being loaded / unloaded at the port chemical berths on a daily basis.

Important fire fighting methods and spill handling methods of the concerned chemicals should be then informed to the fire fighters. They should also be apprised of the health effects and water solubility of the concerned chemicals.

IDENTIFICATION OF EMERGENCIES AT THE OIL & CHEMICAL FACILITIES AROUND THE KANDLA PORT

5.1 Impact Distances

Under the Risk Assessment Study for the DEENDAYAL PORT TRUST carried out by Tata AIG Risk Management Services Ltd in the year 1999, various failure scenarios have been identified for different facilities around the port and these have been simulated using Phast / Safeti software. These failure scenarios have been categorized into Maximum Credible Loss Scenarios (MCLS) and Worst Case Scenarios (WCS).

These failures can be due to number of reasons like material failure, human error. The failures could also be on account of natural disasters like earthquake, flood etc or they could be due to external factors like missile attack or terrorist attack. On failure due to any account mentioned above and depending on the extent of damage, there can be partial or total loss of confinement of hazardous materials handled in the port.

5.2 Maximum Credible Loss Scenarios (MCLS) considered for the study

5.2.1 Scenario 1 – Butadiene Sphere of United Storage and Tank Terminals Ltd.

There are 4 Butadiene Spheres in the terminal. We have considered the 1000 M.T. sphere for the study. Butadiene is stored at 3 to 4 Degree C and pressure in the sphere is maintained at 0.8 bar. The temperature of Butadiene is controlled by brine chillers cooled by Freon refrigeration system. The probability of BLEVE is very remote, considering there are two compressors and DG set is provided to take care of full power load of terminal in case of power failure. However, for Consequence Analysis study, we have considered BLEVE of 1000 M.T. Butadiene Sphere. It is assumed that the catastrophic rupture of the sphere takes place at a pressure of 25 bar.

Initial temperature (K) : 395. Initial pressure (bar (g))
: 25.0

5.2.1.1 Radiation Effects: Bleeve / Fire Ball

Sr. No.	Radiation levels (Kw/sq m)	Distance in meters	
		5m/s C	2m/s D
1.	4	1558	1558
2.	12.5	919	919
3.	37.5	526	526

5.2.1.2 Explosion Effects

Sr. No.	Over pressure		Distance in meters	
	BAR(g)	PSI (g)	5.0m/s;C	2.0m/s; D
1.	0.0207	0.3	3246	3246
2.	0.1379	2	841	841
3.	0.2068	3	650	650

Comments:

1. In case of BLEVE a radius of 526 m. could be subjected to heat radiation, intensity of 37.5 kw/m². This would affect the facilities of Synthetics and chemicals, Indo Nippon, Kesar Enterprises, Bayer ABS & Chemicals and Resins. A portion of IFFCO facility (boundary) would also be subject to 37.5 KW per m² radiation intensity. This could cause fires in the neighbouring areas and this is likely to lead to domino effect. Employees within a radius of 1.5 km. from the sphere would suffer burn injuries.
2. Structural damage is likely within a radius of 650 m. from the sphere. This would damage nearby tanks, buildings and is likely to lead to domino effect which could aggravate the emergency. Upto a distance of 3.2 k.m there would be window glass breakage.

3. The possibility of BLEVE is less likely as the Horton spheres are maintained at low temperatures and at low temperature. There is also a standby DG set to take care of 100% electrical load of the terminal. The spheres are protected by water spray ring system along with a hydrant system.

5.2.2 Scenario 2 - Phenol storage of United Storage and Tank Terminals Ltd.

In the United storage terminal there is a phenol storage tank. In the event of bottom nozzle rupture or a large overflow from the tank, phenol would spill out and the contents would be within the dyke.

5.2.2.1 Dispersion Distance for PHe nol

Sr. No.	Concentration of interest ppm	Dispersion Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	100	103	90

5.2.2.2 Radiation Effects – Pool Fire

Sr. No.	Radiation levels (Kw/sq m)	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	4	32	32
2.	12.5	25	22
3.	37.5	12	12

Comments:

Phenol has IDLH of 100 ppm concentration and the vapours are toxic. Toxic vapour of 100 ppm. Concentration would disperse upto 90 to 103 meters in the downward direction. This scenario may have a moderate off site implication due to toxic vapours.

5.2.3 Scenario 3 - Toluene storage of United Storage and Tank Terminals Ltd.

It is assumed that the tank has a diameter of 15 m. and dyke dia of 30 meters. In case of bottom nozzle failure of large overflow toluene would accumulate in the dyke. In case, the pool encounters the source of ignition, a pool fire would result.

5.2.3.1 Dispersion Distance for Toluene

Sr. No.	Concentration of interest Vol %	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	1.2 (LEL)	63	72

5.2.3.2 Radiation Effects – Pool Fire

Sr. No.	Radiation levels (Kw/sq m)	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	4	59	44
2.	12.5	25	22
3.	37.5	20	19

5.2.3.3 Flash Fire

Sr. No.	Distance (m)	Distance in meters (1/2 LEL Distance)	
		5.0m/s;C	2.0m/s; D

1.	Furthest extent (m) for flash fire	111	121
----	------------------------------------	-----	-----

Comments:

In case of a pool fire, the radiation effect is likely to be contained within the site. A flash fire distance is approximately 120 m. This means that a flammable cloud could cause a flash fire due to source of ignition within 120 m. in the downward direction. The flash fire would result in a pool fire.

The terminal has its own independent fire protection and fire fighting system which can reduce the affected distance by immediate actions like spray of foam compound over the pool formed in the dyke to prevent ignition and reduce the rate of evaporation.

5.2.4 Scenario 4 – Acrylonitrile storage of Bayer ABS

Acrylonitrile polymerises in the presence of light and at high temperature. If polymerization takes place in the tank, it could explode resulting in large release of Acrylonitrile. Acrylonitrile could also be released in the event of bottom nozzle failure of tank or overflow into the dyke.

5.2.4.1 Dispersion Distance for Acrylonitrile

Sr. No.	Concentration of interest ppm	Dispersion distance in meters	
		5.0m/s;C	2.0m/s; D
1.	4 (IDLH)	4026	12000

5.2.4.2 Radiation Effects – Pool Fire

Sr. No.	Radiation levels (kW/sq m)	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	4	80	85

2.	12.5	57	53
3.	37.5	42	32

5.2.4.3 Flash Fire

Sr. No.	Distance (m)	Distance in meters (1/2 LEL Distance)	
		5.0m/s; C	2.0m/s; D
1.	Furthest extent (m) for flash fire	118	125

Comments:

1. Acrylonitrile has boiling point of 77Degree C and IDLH 4 ppm concentration. However, it should be noted that on polymerization and in fire condition, Acrylonitrile would decompose to release hydrogen cyanide and NOx.
2. The dispersion distance for 4 ppm concentration of Acrylonitrile vapours could be 12 kms if the wind speed is 2 m/sec and atmospheric stability D. However, this distance could be reduced if timely action is taken.
3. Bayer ABS maintains a good safety code of practice. They have conducted various safety studies and have a good maintenance system. Moreover the emergency management plan is well prepared and rehearsed in house. The standard of housekeeping in the terminal is good. The personnel working in the terminal have a good knowledge of the actions to be taken in the event of an emergency.

5.2.5 Scenario 5 - Styrene storage of Bayer ABS

Bayer ABS has a 1210 KL styrene tank. Styrene can undergo violent polymerization above 65 degree C, which could be explosive. It is assumed that the tank diameter is 12.5 m. and bund is 22.5 x 22.5 m². In case of bottom nozzle failure, overflow, shell rupture, the material would accumulate in the dyke and if it would encounter the source of ignition, a pool fire would result.

5.2.5.1 Radiation Effects

Sr. No.	Radiation levels (Kw/sq m)	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	4	52	43
2.	12.5	26	21
3.	37.5	23	17

Comments:

1. The radiation effect would be restricted to the site and is not likely to have off site implication. However, on polymerization and fire condition, styrene generates enormous quantity of soot and splinter could fly off. This could affect neighboring areas.
2. The high safety standards maintained and observed at site would go a long way in preventing catastrophic scenarios.

5.2.6 Scenario 6 - Benzene storage of Indo Nippon

In Indo Nippon terminal Benzene is stored in an 1800 KL tank. Pool fire scenario has been considered for the tank assuming tank diameter as 12 m. and dyke dia as 25 m.

5.2.6.1 Dispersion Distance for Benzene

Sr. No.	Concentration of interest Vol%	Dispersion Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	1.3	119	120

5.2.6.2 Radiation Effects: Pool Fire

Sr. No.	Radiation levels (Kw/sq m)	Distance in meters	
		5.0m/s;C	2.0m/s; D

1.	4	55	42
2.	12.5	23	20
3.	37.5	20	16

5.2.6.3 Flash Fire

Sr. No.	Distance (m)	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	Furthest extent (m) for flash fire	175	175

Comments

In case of pool fire radiation effect would be restricted to site.

5.2.7 Scenario 7 - Methanol storage of Indo Nippon

Methanol is stored in 2500 KL tank, dyke dia is assumed as 30 m. And tank dia as 15 m.

5.2.7.1 Dispersion Distance for Methanol

Sr. No.	Concentration of interest Vol%	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	6	36	47

5.2.7.2 Radiation Effects: Pool Fire

Sr. No.	Radiation levels (Kw/sq m)	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	4	66	73

2.	12.5	48	48
3.	37.5	37	34

5.2.7.3 Flash Fire

Sr. No.	Dispersion (m)	Dispersion Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	Furthest extent (m) for flash fire	172	83

5.2.7.4 Explosion Effects – Late Ignition

Sr. No.	Over pressure		Distance in meters	
	BAR(g)	PSI (g)	5.0m/s;C	2.0m/s; D
1.	0.0207	0.3	110	137
2.	0.1379	2	80	95
3.	0.2068	3	78	91

Comments:

1. In case of pool fire, the radiation effect would be restricted to the site.
2. Methanol has a low boiling point i.e. (65oC.), hence if timely action is not taken, a large amount of Methanol would vaporize and unconfined vapour cloud would be formed which if it encounters a source of ignition would explode.
3. In case of unconfined vapour cloud explosion there may be a moderate implication on the surrounding facilities (Synthetics & chemicals and J R Enterprises).

5.2.8 Scenario 8 - Refrigerated Butadiene storage tank of Synthetics and chemicals

There are two atmospheric storage tanks of Butadiene having capacity of 2000 MT each. The storage temperature is maintained at minimum 8oC. Ammonia is used as refrigerant. The tank is double walled

tank, catastrophic rupture of the tank is improbable. It is assumed that if the roof of the tank fails and a pool fire has taken place whose diameter equals the diameter of the tank.

5.2.8.1 Radiation Effects: Pool Fire

Sr. No.	Radiation levels (Kw/sq m)	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	4	46	74
2.	12.5	41	41
3.	37.5	33	19

5.2.8.2 Flash Fire

Sr. No.	Distance (m)	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	Furthest extent (m) for flash fire	97	4

Comments:

The radiation distance would be contained within the site.

5.2.9 Scenario 9 - IFFCO Ammonia Sphere

IFFCO has refrigerant ammonia storage tanks. There are two 1500 m/tons Horton Spheres. In case of external fire, the sphere would be heated up. The external fire would cause the shell above the liquid level to get weakened.

5.2.9.1 Dispersion Distance for Ammonia

Sr. No.	Concentration of interest ppm	Distance in meters	
		5.0m/s;C	2.0m/s; D

1.	500 (IDLH)	10440	9908
----	------------	-------	------

Comments:

1. A toxic ammonia cloud of IDLH concentration (500 ppm) would disperse upto 10 km. in the downward direction.
2. Considering that ammonia is highly soluble in water and it is a light gas, the severity of the scenario could be greatly reduced by timely action. I.e. application of water spray to ammonia cloud.
3. The ammonia storages are well protected. The company has its own fire and safety department with fire engines and fire fighting personnel on duty round the clock. The company has a good preventive maintenance programme. Safety training is given to all employees.

5.2.10 Scenario 10- Phenol storage of Kesar Enterprises

Kesar Enterprises terminal phenol is stored in a 566 KL steam jacketed tank. In case of overflow or bottom nozzle failure, phenol would accumulate in the dyke.

5.2.10.1 Dispersion Distance for Phenol

Sr. No.	Concentration of interest ppm.	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	100 (IDLH)	103	90

5.2.10.2 Radiation Effects: Pool Fire

Sr. No.	Radiation levels (kW/sq m)	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	4	32	32
2.	12.5	25	22
3.	37.5	12	12

Comments:

1. Phenol vapour of IDLH 100 ppm would disburse upto 131 to 197 m. in downward direction. This may have a moderate off-site implication.

5.2.11 Scenario 11 - Acrylonitrile storage of Kesar enterprises.

In Kesar terminal, Acrylonitrile is stored in a 2526 KL tank. Acrylonitrile polymerises in the presence of light and at high temperature. In case of polymerization, the distances affected could be as follows.

5.2.11.1 Dispersion Distance for Acrylonitrile

Sr. No.	Concentration of interest ppm	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	4	4075	12150

5.2.11.2 Radiation Effects: Pool Fire

Sr. No.	Radiation levels (kW/sq m)	Distance in me ters	
		5.0m/s;C	2.0m/s; D
1.	4	91	96
2.	12.5	65	58
3.	37.5	46	35

5.2.11.3 Flash Fire

Sr. No.	Distance (m)	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	Furthest extent (m) for flash fire	119	126

Comments

1. The dispersion distance for Acrylonitrile for a cloud of 4 ppm concentration is approximately 12 km in the downwind direction, if the wind speed is 2 m/s at atmospheric stability is D. However, this would be greatly reduced if timely action is taken.
2. The polymerization products include Hydrogen Cyanide and Nox.

5.2.12 Scenario 12 - Aniline storage - JK Synthetics Terminal

Aniline is stored in the JK Terminal. The tank diameter is considered 12m and dyke diameter as 25m.

5.2.12.1 Dispersion Distance for Aniline

Sr. No.	Concentration of interest ppm	Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	100	92	177

Comments:

1. In case of overflow of tank or bottom nozzle rupture aniline would accumulate in the dyke.
2. Aniline has an IDLH value of 100 ppm. Toxic vapour of aniline would disperse upto 177 m. in the downwind direction, if the wind speed is 2m/sec.
an atmospheric stability D.
3. The rate of evaporation could be reduced by blanketing with water.

5.2.13 Scenario 13 - BLEVE of LPG road tanker

LPG Road Tankers are filled up at the IOCL terminal. In case of over pressurization of the bullets a BLEVE could take place. Over pressurization could take place because of external fire. In case of an accident of the road tanker on the road, LPG would spill out and could result in an unconfined vapour cloud explosion. One 10 ton LPG road tanker has been considered for the study.

5.2.13.1 Radiation Effects – Bleeve / Fireball

Sr. No.	Radiation levels (Kw/sq m)	Distance in meters	
		5m/sC	2m/s D
1.	4	345	345
2.	12.5	196	196
3.	37.5	108	108

5.2.13.2 Explosion Effects

Sr. No.	Over pressure		Distance in meters	
	BAR(g)	PSI (g)	5.0m/s;C	2.0m/s; D
1.	0.0207	0.3	707	707
2.	0.1379	2	183	183
3.	0.2068	3	141	141

5.2.14 Scenario 14 - Naphtha storage of BPCL

In case of a dyke fire or tank roof fire of a naphtha storage tank in BPCL terminal the damage distances would be as follows.

Sr No	Commodity	Scenario	Wind Speed (M/S)	Damage Distance for Pool fire(Meters)		
				4 kW/m ²	12.5 kW/m ²	37.5 kW/m ²
1.	Naphtha	Dyke fire	3	205	71	31
2.	Naphtha	Tank Roof	3	188	65	29

		Fire				
--	--	------	--	--	--	--

5.2.15 Scenario 15 - Catastrophic rupture of 15000 MT cryogenic LPG tank of IOCL

The possibility of catastrophic rupture of the cryogenic LPG tank is very remote. However in case of such a scenario the damage distances would be as follows.

5.2.15.1 Explosion Effects

Sr. No.	Over pressure		Distance in meters	
	BAR(g)	PSI (g)	5.0m/s;C	2.0m/s; D
1.	0.0207	0.3	316	302
2.	0.1379	2	169	176
3.	0.2068	3	157	166

5.2.16 Scenario 16 - Catastrophic rupture of ammonia road tanker

In case of catastrophic rupture of ammonia road tanker the damage distances would be as follows.

5.2.16.1 Dispersion Distance for Ammonia

Sr. No.	Concentration of interest ppm	Dispersion Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	500	1866	1592

5.2.17 Scenario 17 - Leak from Acrylonitrile road tanker

In case of leak from one compartment (Capacity 3 tons) from an Acrylonitrile road tanker, the affected distances would be as follows.


5.2.17.1 Dispersion Distance for Acrylonitrile

Sr. No.	Concentration of interest ppm	Dispersion Distance in meters	
		5.0m/s;C	2.0m/s; D
1.	400	574	1508

6 TOXIC HAZARD RANKING FOR HAZARDOUS CHEMICALS HANDLED AT PORT PREMISES

6.1 Hazard Ranking


6.1.1 Propane



6.1.2 Butane

CHEMICAL PROFILES | Hazard Rankings

Chemical: [BUTANE](#)
CAS Number: 106-97-8



Human Health Rankings

[Toxicity and exposure potential](#)

[Worker Exposure Hazard Score \(IRCH\)](#)



Ecological Health Rankings

[Toxicity and persistence](#)


[Environmental Hazard Value Score \(IRCH\)](#)



Integrated Environmental Rankings

[Combined human and ecological scores](#)

[Total Hazard Value Score \(IRCH\)](#)




6.1.3 Toluene

CHEMICAL PROFILES | Hazard Rankings

Chemical: [TOLUENE](#)

CAS Number: 108-88-3



Human Health Rankings

Toxicity only

[Ingestion Toxicity Weight \(RSEI\)](#)



[Inhalation Toxicity Weight \(RSEI\)](#)



[Human Health Effects Score \(UTN\)](#)



Toxicity and exposure potential

[Noncancer Risk Score - Air Releases \(EDF\)](#)



[Noncancer Risk Score - Water Releases \(EDF\)](#)



[Worker Exposure Hazard Score \(IRCH\)](#)



Ecological Health Rankings

Toxicity only

[Ecological Effects Score \(UTN\)](#)



Toxicity and persistence

[Environmental Hazard Value Score \(IRCH\)](#)



Integrated Environmental Rankings

Combined human and ecological scores

[Total Hazard Value Score \(IRCH\)](#)




[Total Hazard Value Score \(UTN\)](#)



CHEMICAL PROFILES|Hazard Rankings

Chemical: [ACRYLONITRILE](#)
CAS Number: 107-13-1




Human Health Rankings

[Toxicity only](#)



[Toxicity and exposure potential](#)



Ecological Health Rankings

[Toxicity only](#)




[Toxicity and persistence](#)




Integrated Environmental Rankings

[Combined human and ecological scores](#)




CHEMICAL PROFILES | Hazard RankingsChemical: [ANILINE](#)

CAS Number: 62-53-3

**Human Health Rankings**Toxicity only[Ingestion Toxicity Weight \(RSEI\)](#)[Inhalation Toxicity Weight \(RSEI\)](#)[Human Health Effects Score \(UTN\)](#)Toxicity and persistence[Human Health Risk Screening Score \(WMPT\)](#)Toxicity and exposure potential[Cancer Risk Score - Air Releases \(EDF\)](#)[Cancer Risk Score - Water Releases \(EDF\)](#)[Noncancer Risk Score - Air Releases \(EDF\)](#)[Noncancer Risk Score - Water Releases \(EDF\)](#)[Worker Exposure Hazard Score \(IRCH\)](#)**Ecological Health Rankings**Toxicity only[Ecological Effects Score \(UTN\)](#)Toxicity and persistence[Environmental Hazard Value Score \(IRCH\)](#)[Ecological Risk Screening Score \(WMPT\)](#)**Integrated Environmental Rankings**Combined human and ecological scores[Total Hazard Value Score \(IRCH\)](#)[Total Hazard Value Score \(UTN\)](#)

CHEMICAL PROFILES | Hazard RankingsChemical: [BENZENE](#)


CAS Number: 71-43-2

**Human Health Rankings**Toxicity only[Ingestion Toxicity Weight \(RSEI\)](#)[Inhalation Toxicity Weight \(RSEI\)](#)[Human Health Effects Score \(UTN\)](#)Toxicity and persistence[Human Health Risk Screening Score \(WMPT\)](#)Toxicity and exposure potential[Cancer Risk Score - Air Releases \(EDF\)](#)[Cancer Risk Score - Water Releases \(EDF\)](#)[Noncancer Risk Score - Air Releases \(EDF\)](#)[Noncancer Risk Score - Water Releases \(EDF\)](#)[Worker Exposure Hazard Score \(IRCH\)](#)**Ecological Health Rankings**Toxicity only[Ecological Effects Score \(UTN\)](#)Toxicity and persistence[Environmental Hazard Value Score \(IRCH\)](#)[Ecological Risk Screening Score \(WMPT\)](#)**Integrated Environmental Rankings**Combined human and ecological scores[Total Hazard Value Score \(IRCH\)](#)[Total Hazard Value Score \(UTN\)](#)

6.1.7 1: 3, Butadiene


CHEMICAL PROFILES | Hazard Rankings

Chemical: [1,3-BUTADIENE](#)
CAS Number: 106-99-0




Human Health Rankings

Toxicity only



Toxicity and exposure potential




Ecological Health Rankings

Toxicity only




Toxicity and persistence



Integrated Environmental Rankings


Combined human and ecological scores



CHEMICAL PROFILES | Hazard Rankings

Chemical: [ACETONE](#)

CAS Number: 67-64-1



Human Health Rankings

[Toxicity only](#)

[Human Health Effects Score \(UTN\)](#)



[Toxicity and persistence](#)

[Human Health Risk Screening Score \(WMPT\)](#)



[Toxicity and exposure potential](#)

[Noncancer Risk Score - Air Releases \(EDF\)](#)



[Noncancer Risk Score - Water Releases \(EDF\)](#)




[Worker Exposure Hazard Score \(IRCH\)](#)



Ecological Health Rankings

[Toxicity only](#)

[Ecological Effects Score \(UTN\)](#)



[Toxicity and persistence](#)

[Environmental Hazard Value Score \(IRCH\)](#)



[Ecological Risk Screening Score \(WMPT\)](#)



Integrated Environmental Rankings

[Combined human and ecological scores](#)

[Total Hazard Value Score \(IRCH\)](#)




[Total Hazard Value Score \(UTN\)](#)



CHEMICAL PROFILES | Hazard Rankings


Chemical: [METHANOL](#)
CAS Number: 67-56-1



6.1.10 Propylene

CHEMICAL PROFILES|Hazard Rankings

Chemical: PROPYLENE
CAS Number: 115-07-1




Human Health Rankings

Toxicity only




Toxicity and exposure potential



Ecological Health Rankings

Toxicity only



Toxicity and persistence



Integrated Environmental Rankings

Combined human and ecological scores




6.1.11 Vinyl Chloride

CHEMICAL PROFILES | Hazard Rankings

Chemical: [VINYL CHLORIDE](#)

CAS Number: 75-01-4



Human Health Rankings

Toxicity only

[Ingestion Toxicity Weight \(RSEI\)](#)



[Inhalation Toxicity Weight \(RSEI\)](#)



[Human Health Effects Score \(UTN\)](#)



Toxicity and persistence

[Human Health Risk Screening Score \(WMPT\)](#)



Toxicity and exposure potential

[Cancer Risk Score - Air Releases \(EDF\)](#)



[Cancer Risk Score - Water Releases \(EDF\)](#)



[Noncancer Risk Score - Air Releases \(EDF\)](#)



[Noncancer Risk Score - Water Releases \(EDF\)](#)



[Worker Exposure Hazard Score \(IRCH\)](#)



Ecological Health Rankings


Toxicity only

[Ecological Effects Score \(UTN\)](#)



Toxicity and persistence

[Environmental Hazard Value Score \(IRCH\)](#)




[Ecological Risk Screening Score \(WMPT\)](#)




Integrated Environmental Rankings

Combined human and ecological scores

[Total Hazard Value Score \(IRCH\)](#)




[Total Hazard Value Score \(UTN\)](#)



6.1.12 Ammonia


CHEMICAL PROFILES|Hazard Rankings

Chemical: [AMMONIA](#)
CAS Number: 7664-41-7




Human Health Rankings

[Toxicity only](#)



[Toxicity and exposure potential](#)




Ecological Health Rankings

[Toxicity only](#)




[Toxicity and persistence](#)




Integrated Environmental Rankings

[Combined human and ecological scores](#)




6.1.13 Ethanol



6.1.14 Phenol

CHEMICAL PROFILES | Hazard Rankings

Chemical: [PHENOL](#)
CAS Number: 108-95-2




Human Health Rankings

[Toxicity only](#)

[Ingestion Toxicity Weight \(RSEI\)](#)



[Inhalation Toxicity Weight \(RSEI\)](#)



[Human Health Effects Score \(UTN\)](#)



[Toxicity and persistence](#)

[Human Health Risk Screening Score \(WMPT\)](#)



[Toxicity and exposure potential](#)

[Noncancer Risk Score - Air Releases \(EDF\)](#)



[Noncancer Risk Score - Water Releases \(EDF\)](#)



[Worker Exposure Hazard Score \(IRCH\)](#)



Ecological Health Rankings

[Toxicity only](#)

[Ecological Effects Score \(UTN\)](#)



[Toxicity and persistence](#)

[Environmental Hazard Value Score \(IRCH\)](#)




[Ecological Risk Screening Score \(WMPT\)](#)



Integrated Environmental Rankings

[Combined human and ecological scores](#)

[Total Hazard Value Score \(IRCH\)](#)



[Total Hazard Value Score \(UTN\)](#)




6.1.15 Methyl Ethyl Ketone

CHEMICAL PROFILES | Hazard Rankings

Chemical: [METHYL ETHYL KETONE](#)

CAS Number: 78-93-3



Human Health Rankings

Toxicity only

[Ingestion Toxicity Weight \(RSEI\)](#)



[Inhalation Toxicity Weight \(RSEI\)](#)



[Human Health Effects Score \(UTN\)](#)



Toxicity and exposure potential

[Noncancer Risk Score - Air Releases \(EDF\)](#)



[Noncancer Risk Score - Water Releases \(EDF\)](#)



[Worker Exposure Hazard Score \(IRCH\)](#)



Ecological Health Rankings

Toxicity only

[Ecological Effects Score \(UTN\)](#)



Toxicity and persistence

[Environmental Hazard Value Score \(IRCH\)](#)



Integrated Environmental Rankings

Combined human and ecological scores

[Total Hazard Value Score \(IRCH\)](#)



[Total Hazard Value Score \(UTN\)](#)




6.1.16 Vinyl Acetate

CHEMICAL PROFILES | Hazard Rankings

Chemical: [VINYL ACETATE](#)

CAS Number: 108-05-4



Human Health Rankings

[Toxicity only](#)



[Toxicity and exposure potential](#)



Ecological Health Rankings

[Toxicity only](#)



[Toxicity and persistence](#)



Integrated Environmental Rankings


[Combined human and ecological scores](#)



6.1.17 Caustic Soda

CHEMICAL PROFILES | Hazard Rankings

Chemical: [CAUSTIC SODA](#)
CAS Number: 1310-73-2



Human Health Rankings

[Toxicity and exposure potential](#)

[Worker Exposure Hazard Score \(IRCH\)](#)



Ecological Health Rankings

[Toxicity and persistence](#)

[Environmental Hazard Value Score \(IRCH\)](#)



Integrated Environmental Rankings

[Combined human and ecological scores](#)

[Total Hazard Value Score \(IRCH\)](#)




6.1.18 Acetic Acid

CHEMICAL PROFILES|Hazard Rankings

Chemical: [ACETIC ACID](#)

CAS Number: 64-19-7



Human Health Rankings

[Toxicity and exposure potential](#)

[Worker Exposure Hazard Score \(IRCH\)](#)



Ecological Health Rankings

[Toxicity and persistence](#)


[Environmental Hazard Value Score \(IRCH\)](#)



Integrated Environmental Rankings

[Combined human and ecological scores](#)

[Total Hazard Value Score \(IRCH\)](#)




6.1.19 Nonene

CHEMICAL PROFILES|Hazard Rankings

Chemical: [NONENE](#)

CAS Number: 27215-95-8



Ecological Health Rankings

[Toxicity and persistence](#)

[Ecological Risk Screening Score \(WMPT\)](#)




6.1.20 Ethyl Di Chloride (EDC)

CHEMICAL PROFILES | Hazard Rankings

Chemical: [1,2-DICHLOROETHANE](#)

CAS Number: 107-06-2



7 SABOTAGE & CIVIL DISTURBANCE

Access to the Kandla Port is controlled by walls / fence. The entrances are manned by CISF guards.

If a civil disturbance or sabotage threatens or actually damages the port property – the Harbour Master will communicate with local civil authorities or will request immediate assistance from police, coast guard, navy / air force.

7.1 Bomb Emergency Management

In the event of receiving a bomb threat by telephone call, the following should be asked and noted for relaying it to the army/air force/navy:

In view of the high priority given to Ports, they have high risk of becoming targets of the terrorist groups. Therefore the possibility of receiving bomb threats cannot be ruled out. The golden rule is consider all bomb threats as genuine and act accordingly keeping in mind the safety of the people in the Port and the property.

The objective is:

- a) To avoid/minimize any loss or damage to lives and property
- b) To eliminate panic and build up confidence.
- c) To be prepared for proper handling of any critical situation.

7.2 Immediate actions:

- a) Bomb threats may be received in writing email, SMS or may be received on phone.
- b) When the call is received on phone, keep the caller on the line as long as possible. Request him to repeat the message, listen carefully as every word spoken by the person has to be recorded mentally and penned down.

- c) If the caller does not indicate the location of the bomb or the time of possible detonation, it is advisable to try to ask him for this information.
- d) Inform the caller that the port area is occupied and the detonation of a bomb would result in death or serious injury to many innocent persons.
- e) Pay particular attention to peculiar background noises such as motors running, background music and any other noise which may give a clue as to from where the call is being made.
- f) Listen closely to the voice (male, female), voice quality (calm, excited), accents and speech impediments. Immediately after the caller hangs up report should be made to the security officer on duty about all the above details.
- g) Fill up the bomb threat call details in the format as given below.
- h) Call all identified personnel (As indicated for any emergency)
- i) As soon as an emergency is envisaged /occurs the Emergency chief or his alternate shall promptly communicate the information by a telephone or any other quickest mode of communication to the Inspector of Police, highest administrative officer, fire brigade and the nearby installations. The

91

information should include the location of the installation and the degree of emergency (anticipated, eminent or actual).

7.3 Bomb Threat Report Form

7.3.1 Actions on Receiving Bomb Threat Call

1. Do not put down receiver or cut off caller
2. Put on tape-recorder /USE CELL PHONE RECORDING
3. Alert nearest colleague
4. Keep Form and pen ready to fill
5. Note time and duration correctly
6. Obtain as much information as possible
7. Keep caller engaged in conversation as long as possible

(Apologise for bad line, ask him to speak up etc.)

Time of call..... Date..... Exact words of caller.....

Was any one called for by name or designation () Yes () No. If so, who?

7.3.2 Questions to Ask Caller

1. Who is calling from where?
2. When is the bomb set to go off?
3. Where is the bomb placed?
4. What kind of bomb is it?
5. How does it look like?
6. Why are you doing this?
7. Whom do you represent?
8. How do you know so much about the bomb?
9. How can we get rid of the bomb?
10. Do you know that the bomb will kill innocent people?

7.3.3 Details of Caller

- Sex: () Male () Female Approximate age:years.
- Origin of call: () inside plant, () outside local, () outside long distance.
- Voice characteristic: () fast, () slow, () stutter, () distinct, () disguised, () educated, () uneducated, () loud, () soft.
- Language used, accent, manner: ()calm, ()angry, ()emotional, ()laughing, ()deliberate, ()normal, ()abnormal, ()other
- Is voice familiar? () yes, () no.
- Background sound: ()street, ()telephone booth, ()airport, () railway station, ()residence, ()cannot identify, ()others

CISF Commandant/Officer informed at: Name of the person receiving call signature.....

(Keep these forms with all Telephone Operators/All designations having direct line?)

7.4 Responsibility of the CISF Commandant / Officer of Kandla port

- a) Advise the Emergency chief (Chairman/Dy. Chairman/Dy. Conservator/Harbour Master) and keep him apprised of the actions being taken.
- b) Immediately make elaborate preparations near the threatened area for
 - ③ Fire fighting
 - ③ Casualty handling
 - ③ Rescue operations
 - ③ Search operations
- c) Prepare for partial/total evacuation if required. Emergency chief or his alternate will authorize these activities.
- d) Designate the team for bomb search. Initiate search operations with Fire and safety/security officers if time is available.

7.5 Action Plan

Two situations are possible.

- a) When no time limit is given.
- b) When bomb threat call has time limit specified.

As soon as the call is received the concerned area-in-charge will make fire fighting/first aid preparations immediately.

1. In the first case if there is no time limit specified for bomb explosion, as soon as the Emergency chief gives a clearance the following action should be initiated.
 - ③ Emergency shutdown of the Port sections likely to be affected.
 - ③ Evacuation of the employees and visitors to safer locations.
 - ③ Bomb search taking all the precautions.

7.5.1 Action plan when time limit is specified:

In such case the concerned officers should search the area along with safety and security officers.

7.5.2 Search procedures:

- Search must be conducted by employees of the concerned department since they are familiar with the area and would be in a better position to notice a foreign object faster.
- Two teams could be formed to search various parts of the area. Stand quietly for some moments to listen for any clockwork device before starting the search.
- As far as practical do not cause any disturbance in the environment till the search is over.
- Do not go into dark rooms and turn on lights. Use a flashlight instead.
- If any foreign or suspicious object is located, do not move or touch it. The removal/disarming of a bomb must be left to professionals. Report the location and description of the object immediately to the emergency control centre/Security gate.
- If possible place sand bags or mattresses around the bomb. Do not cover it.
- Identify the danger area and block it off with clear zone of at least 100 meter.

7.6 Important Telephone Nos of Police Authorities

Name and Designation of Officer	Fax	Telephone Nos. (Office)	Telephone Nos. (Residence)
District Collector, Bhuj. 9978406212	250430	(02832) 250020	02832- 250350
Resident Add. Collector, Bhuj Mob.9978405099	250430	250650	
Parixita Rathore (IPS) S. P.-(East),9978405690		280233	
Mr. Dy. SP (Anjar)9825304239	243254		
Mr. Dy. SP(HQ)9825225071			
Mr.) Dy. SP.9824543004	0837- 224040		
Control Room(DC-5)Purab	280287		

Mr. Vinod Chawda, M.P.,Kachchh		(m)	
Dy.Collector, Anjar Mob. 9825228049		243345	243363
Mamlatdar, Anjar Mob. 9879278174		242588	243362
Mamlatdar, Gandhidham 7567003975		250475 250270	222875 250475
Collector, Jamnagar		2555869	2554059
Collector's Control Room, Bhuj.		2252347 2231733	-
Dy. Mamlatdar, Gandhidham		250475 250270	9427719800
Civil Defence, Gandhidham		220221	
PGVCL, Gandhidham		221728 222809	
GW&SB, Gandhidham		220975	
GSRTC, Gandhidham		220198	
Duty Officer, All India Radio, Bhuj		221412	
State Information Dept. (Shri Sony) (m) 9879012714		224859 250954	253034 252855
Air Force,Duty Officer, Bhuj		252501 252502	
Air Force, Bhuj		223450	
Air Port, Bhuj		254550	
Aerodrome Officer, Kandla		238370	223247
Indian Navy, Jamnagar		550263 to 5	550825
Airforce, Jamnagar		550245 to 7	550247


S. No	Designation	Present incumbent	Contact Telephone Numbers
----------	-------------	----------------------	---------------------------

			Office	Res	Mobile
01	CISF Commandant		271037	229140	9825227282
02	CISF Dy. Commandant		271036	220192	9825227045
03	Asst. Commandant		270440	271041	8000954482
04	Control Room		271040		
05	North Gate		270440		
06.	West Gate – I		271039		
07.	West Gate II		270876		

7.6 Contact Telephone Nos of Bomb Detection & Disposal Squad

Sr. No	Area	Telephone
01	GNADHIDHAM	9979928800
02	Rajkot	0281 – 245777
03	Ahmadabad	079 – 2210019

8 HOSTAGE SITUATION



8.1 Commandant CISF Responsibilities

- Apprise - Chairman, Deputy Chairman, Deputy Conservator, Harbour Master of contemplated action.
- Prepare threatened area for fire fighting, casualty handling, search and rescue operations
- Inform Police and requisition help with regard to negotiators/snipers, etc.
- CISF to cordon off area and deny access to persons hampering operations especially media and onlookers.
- Buy time for negotiators to arrive or for formalizing proper plan of action.
- Police/CISF shall assess the situation and based on the assessment, Chairman may permit operation deemed fit to free hostages.


9 SEVERE WEATHER SITUATION

9.1 Act of God Perils (Cyclones Tsunami

9.1.1 Storms / Cyclone

Even though Kandla is within the cyclone area of storms originating in the Arabian Sea and those that enter across the Indian Peninsula from the Bay of Bengal, cyclones are not as severe or frequent as in the Bay of Bengal. Historically, there has been major cyclone in the region in the year 1998.

Hence the exposure to this peril is High.



















Tropical Storm







- Zone 1: SS 1 (118-153 km/h)
- Zone 2: SS 2 (154-177 km/h)
- Zone 3: SS 3 (178-209 km/h)
- Zone 4: SS 4 (210-249 km/h)
- Zone 5: SS 5 (≥ 250 km/h)

Probable maximum intensity
(SS: Saffir-Simpson hurricane scale
with an exceedance probability
of 10% in 10 years (equivalent
to a 'return period' of 100 years)

9.1.1.1

			Type of	Description
Signal No.	Symbol Day	Symbol Night	Warning	

I			Cautionary	There is a region of squally weather in which a storm may be forming.
II			Warning	A storm has formed.
III			Cautionary	Port is threatened by squally weather.
IV			Warning	The Port is threatened by storm, but it does not appear that the danger is as yet sufficiently great justifying extreme measures of precautions.
V			Danger	The Port will experience severe weather from a storm of slight or moderate intensity that is expected to cross the coast to the south of the port.
VI			Danger	The Port will experience severe weather from a storm of slight or moderate intensity that is expected to cross the coast to the north of the port.
VII			Danger	The Port will experience severe weather from a storm of slight or moderate intensity that is expected to cross over or near to the port.
VIII			Great danger	The Port will experience severe weather from a storm of great intensity that is expected to cross to the south of the port.

IX			Great danger	The Port will experience severe weather from a storm of great intensity that is expected to cross the coast to the north of the port.
X			Great danger	The Port will experience severe weather from a storm of great intensity that is expected to cross over or near to the port.
XI			Failure of communication	Failure of Communication with Meteorological head quarters has broken down and the local officer considers that there is danger of bad weather.



Red Light,




White Light

9.1.2 Earthquake

As per Munich Re world map for Natural hazards the Gandhidham region comes under the Zone III of the earthquake classification as per Indian Standards which is relatively high. However, seismic experts have opined that the Indian land mass is being constantly compressed between the sea and Himalayas and thus the developed stresses are being released in the form of earthquakes in the least expected areas.

Thus taking the dynamic seismic scenario in to consideration risk exposure can be considered as High.




9.1.3 Lightning

As per Munich Re World Map for Natural hazards, Gandhidham region is in Zone – I which means on an average there are 2 - 6 lightning strikes per km area per year which signifies moderate risk exposure.


2

Thus risk exposure can be considered as moderate.



Tsunami is large submarine earthquake or large submarine landslides, which are often triggered by earthquakes, and volcanic eruption in the sea or on the coast. The waves spread out in all directions and at great speed, which increases with the depth of water. In great ocean basins the average speed is about 700km/h.

Thus risk exposure can be considered as moderate.



Gujarat is prone to tsunami risk due to its long coastline and probability of occurrence of near and offshore submarine earthquakes in the Arabian Sea. Makran Subduction Zone (MSZ) - South West of Karachi is an active fault area which may cause a high magnitude earthquake under the sea leading to a tsunami. In past, Kandla coast was hit by a Tsunami of 12 mtrs height in 1945, due to an earthquake in the Makran fault line. Tsunami prone areas in the State include coastal villages of Kutch, Jamnagar, Rajkot, Porbandar, Bhavnagar, Anand, Ahmedabad, Bharuch, Surat, Navsari and Valsad districts.

When severe weather is predicated or threatened preparation is made by site personnel.

The most probable severe weather events at the Kandla Port will involve High winds, Heavy rains, Cyclone, Storm, Tsunami, and Lightning & Earthquake.

There is a possibility of surface water accumulation and ingress into buildings and equipment. In addition the above severe hazard conditions can create significant personnel hazards loss of power.

PREPAREDNESS & RESPONSE

9.2 Internal Action Plan in case of Cyclone / Flood & Any other Natural Calamity

As soon as the message on anticipated cyclone/flood/natural calamity is received from the State Government Authority/Indian Meteorological Department/Cyclone Warning Centre/Indian Navy, etc. by any official of the Port Trust, the same shall immediately be informed to the Deputy Conservator (Nodal Officer), who in turn shall get such message confirmed from the above sources and apprise the Chairman and Dy. Chairman accordingly. On approval of Chairman, the Action Plan as stipulated hereunder shall be put into operation for which the Deputy Conservator shall inform all the officers-in-charge of the Control Rooms as well as the Heads of Departments, including Chief Operation Manager, OOT, and Vadinar about the decision of the Chairman as per Point No: 9.2.1.

9.2.1 Particulars of the Action Plan Committee Members

Sl No	Name	Designation	Telephone Nos.			
			Office	Residence.	Fax	Mobile
1	Mr. SANJAY MEHTA,IFS	Chairman	02836-233001 234601	02836-233002	235982	
2	Mr.	Dy. Chairman	234121 236323	234218 236346	236323	

3	Capt. T Srinivas	Deputy Conservator	233585 220235	232806	233585	9825232982
4	Mr. A Krishnan	Deputy FA&CAO	220214	223854		9825227036
5	Mr. Ajay Gupta	Sr. DD(EDP)	239623	234116		9825227095
6	Mr Bimal Kumar Jha	Secretary	220167	231939	233172	8141084794
7	Mr. Suresh Balan	Sr.Dy. Secy (G)	221375	236086		9825227044
8	Mr. Rajendra Singh	Dy. Secy	220033			9422056830
9	Mr. Deepak Rane	Sr. Asst. Secy	221679	234691		8238057380
10	Mr. N M Parmar	SE(C-I)		252624		9825227046
11	Mr. Y K Singh	PO.	223828	228584		9825227079
12	Mr.	Traffic Manager	270625 270246	263006	270475	
13	Mr. Krupananda Swami	Sr. Dy Traffic Manager	270270	235100		9825227049
14	Mr. D N Sondhi	FA&CAO	233174		220047	9825214726
15	Capt. S K Pathak	Harbour Master I/C	270201	231310		9825503499
16	Mr	Dy.Hydl. Engr	270277	225389		9825227201
17	Mr. Sunil Kumar	Flotilla Supdt.	270280	226121		7874627756
18	Mr. K Varughese	FCSO	270176 270178	227512	270176	9825227041

19	Mr. SSP PATIL	Chief Engineer	233192	228777	220050	9825227243
20	Mr. MANOJ MISHRA	Dy. CE	233569			7420027171
21	Mr. K J Todarmal	Exe Eng (R)	236165	220670		8980049099
22	Mr. N M Parmar	SE (PL)	222535	252624		9825227046
23	Mr. V R Reddy	DY.CE (G)	270429	228869		9825227038
24	Mr.B. Rajendra Prasad	Exe Eng (D), ENVIRONMENT	220038	232880		9725338260
25	Mr.	CME	270632 270184	231043	270184	9825226944
26	Shri S C NAHAK	Dy CME	270426	226067		9825235196
27	Mr. P Srinivasu	SE (E)	271010			9825204316
28	Mr. B J Solanki	SE (M)	270352			9726188222
29	Dr. Kalindi Gandhi	CMO	225767 220072	234598		9825505795
30	Dr CHELLANI	Sr Dy CMO	236346	220558		9825505796
31	Dr S B Suryavanshi	AMO	220072	233099		9687606995
32	Dr. Mahesh Bapat	A.M.O	220072	228167		9687607528
33	Mr.	Comdt. CISF	271037	229140		9825227282

Based on the past experience, after detailed discussions and experience sharing process, the actions suggested in the plan have to be taken immediately by the concerned staff members/officials as shown against their names/Designations as soon as the warning of cyclone or any other natural calamity is issued. All staff members/officials should know that they shall come into action on their own as soon as the warning is issued, without waiting for any further instructions. Failure on the part of any employees/officials to carry out the earmarked action plan shall attract severe consequences, which all must note.

9.3 Control Room

There shall be three control rooms, one at Kandla at Signal Station Seva-Sadan-III, and second one at AO Building, Gandhidham and third at A O Building Off Shore Oil Terminal, and Vadinar. The Control Room at Kandla shall be under the direct supervision Harbour Master, whereas Dy. Secy. (G) will be the overall in charge of the control room at A O Building, Gandhidham. XEN (M&E) will be the overall in charge of control room at Vadinar. They shall rush to the respective control rooms as soon as the action plan is put into force. The officials named in the duty roster of various departments elsewhere in this Action Plan shall also report to the respective HODs for coordination and to perform duties as may be assigned by the higher authorities. The overall in charge should draw up roster of the said employees and assign duties for the coming five days. The staff should report to the respective control rooms. The Radio Radar Technician will remain in control room to attend all communication equipments.

9.3.1 Duty Roster for Staff of General Administrative Department

01	Mr. Kamalesh S Bajaj, Senior Clerk	220416		
02	Assistant	220010		
03	Assistant	220010		
04	Senior Clerk	220010		
05	Sr. Clerk	220010		
06	Junior Clerk	220010		
07	Messenger	220010		
08	. Junior Clerk	220010		
09	, LWA	270872		

List of Duty Roster of Marine Department (Ministerial Staff)

Sr No	Name	Office	Residence / Mobile
01	PA to DC	220235	9428032483
02	Mr. AR Jadeja, Signal Supdt	270549	9825427400
03	Office Supdt.	221971	
04	Assistant	221971	
05	Sr. Clerk	221971	
06	Messenger	221971	

9.3.2 Pilots

Sr No	Name	Residence	Mobile
01	Shri. S. K. Pathak	231310	9825803499
02	Capt V Tyagi		7065965924
03	Capt. A K Sharma	238154	9879603642
04	Capt. Vipul M. Madaan	221478	9879603643

9.3.3 List of Telephone Nos & Address of DC, HM & Pilots

Sr No	Name of Officer / Pilots	Address of Gandhidham Res	Tel Nos: Cell / Landline
-------	--------------------------	---------------------------	--------------------------

01	Capt T Srinivas DC	A – 7, Gopalpuri	9825232982 232806
02	Shri S K Pathak HM	C – 32, Gopalpuri	9825803499 231310
03	Capt S K Pathak Pilot		
04	Capt D C Bhatt. Pilot	C – 38, Gopalpuri	9879603641 235653
05	Capt A K Sharma Pilot	C – 40, Gopalpuri	9879603642 238154
06	Capt V Madaan, Pilot	C – 31, Gopalpuri	9879603643 221478
07	AVAILABLE CONTRACT PILOTS WILL BE CONTACTED BY THE SIGNAL STATION.		
08			
09			
10			

9.3.4 Contract / Empanelled Pilots

Sr No	Name	Mobile
01	AVAILABLE CONTRACT PILOTS WILL BE CONTACTED BY SIGNAL STATION	

9.3.5 List of Duty Roster of Mechanical Engineering Department

Designation	Office
CME	270632

Addl. CME	270426
PA to CME	270184
SE(Electrical)	270209
SE (M)	270354
Dy M M	234114
XEN(E)	270469
XEN(DD) I/C	270285
AXEN(M)	270285
Asstt. Engr (M)	234199
AXEN	270165
AXEN (E)	
AE(E)	270322
Office Supdt	270245
Div. Accountant	270245
Div. Accountant	270342
Steno	270184
Junior Clerk	270245
AE(E)	270469
AE(E)	270458
AE(M)	270010
AE(M)	270370
JE(M)	270127
Head Clerk	270342
Head Clerk	270498

Div. Accountant	270498
Head Clerk	270484
Div. Accountant	270484

9.3.6 List of Duty Roster of Civil Engineering Department

Designation	Office	Mobile
Chief Engr	233192	9825227243
Supdt. Engr.(P)	233569	9825325390
Supdt. Engr.(C)	270787	9825227038
Supdt. Engineer (Const)	270419	9825227203
PA To CE (T)	220016	--
P.A. To CE	220050	9426737553
Supdt Engineer (Harbour)	270429	9825227046
Exe. Engr (R)	236165	9825706255
Exe. Engineer (Design)	220038	9725338260
Ex.Engr (TD)	223912	9427205610
Dy.Secretary(E)	221758	9825227044

Asst.Estate Manager	221598	
------------------------	--------	--

9.4Kandla Control Room

Designation	Office	Residence	Fax No	Mobile
Harbour Master	270201	231310	270624	9825232982
Signal Supdt	270549, 270194	232551	270624	9825427400
Signalman at Signal Station	270549, 270194		270624	9825227246

9.5 A.O. Building, Control Room (Gandhidham)

Designation	Office	Residence	Fax No	Mobile
Dy. Secretary (G)	221375	236990	-----	9825505969
Accounts Officer	220908	226199	-----	-----
DMM	231362			

9.4 Vadinar Control Room

Designation	Office	Residence	Fax No	Mobile
Signalman	0288- 2573026			9825212359
Exe. Engineer	0288-			

(E&M)	2573005			
A. F. S.	0288			9712824782
Pilot in Station				

The overall in charge of the Control Rooms shall ensure the presence of the staff, to which various duties have been assigned. They should attend the meetings as and when called. In case of absence of the staff, the matter should be informed to the disciplinary authority, who shall take disciplinary action against the erring employees.

9.5 The Control Room shall have the following Facilities

Control Room	Telephone Nos	Fax No	VHF
Kandla	02836 – 270549/270194, Cell 9825227246	02836- 270624	8,10,12,16
Gandhidham	02836 – 238055/239055	02836- 239055	-----
Vadinar	0288-2573026, 9825212359		12, 16, 8, 10

The above facilities will remain as permanent assets of the Control Rooms. The overall in charge for setting up of Control Room at Kandla will be Dy. Conservator and Secretary for A. O. Building, Gandhidham. They should ensure setting up the Control Rooms at the respective places within two hours of warning and the matter reported to Chairman/Deputy Chairman.

Commandant, CISF to remain in contact with In charge of Control Room at Kandla regarding the positions of the Cyclone.

9.6 Functions of the Control Room

1. It shall remain in touch with the Indian Meteorological Department (Telephone numbers given at Point No: 11.8.1) and also offices and officials as at Point No: 9.8.2, 9.8.3, 9.8.4, 9.8.5 & 9.8.6 on need basis.

9.8.1 Important Telephone Numbers of Indian Meteorological Department

Designation	Address	Office	Resi.	Fax
Director (ACWC)	-do-	022- 22150405	022- 22150452	
Director (I/c)	Met Center Ahmadabad	07922865012 22865165		07922865449 22865012 22861413
Met I/C	MET Centre, Ahmadabad	22861413		
Duty Officer		22865012		
Meteorologist	Ahmadabad	22861413		

Websites

www.imd.gov.in

9.8.2 The Telephone Numbers of Some of the VIP S

Sr. No.	Name and Designation	Fax	Telephone (Office)	Telephone (Resi)
1	District Collector, Bhuj	02832-250430	250020	250350
2	Dy. Collector, Mob. Bhuj 9825300729	02832-252704	250650	
3	Add. Collector, Bhuj Mob. 9825049360	02832-252704	252704	251348
4	Superintendent Police, of Ghandidham,	9978405690	227934	
5	Asstt. Supdt. Of Police		253405	250850
6	Dy. Collector, Anjar		243345	243363
7	Dy. S. P., Anjar		243254	242596
8	Mamlatdar, Gandhidham	9879278174	242588	243362
9	Mamlatdar, Gandhidham		250475 250270	222875 250475
10	Port Co-coordinator, OCC		234313	232808
11	Terminal Manager, IOC	234396	231871	236442
12	Air Force Commander, Jamnagar		2550245	-
13	Collector, Jamnagar		555869	554059
14	Station Commander, Air Force, Bhuj		244005 to 244010	
15	Commandant, B Gandhidham		223845	

9.8.6 Gujarat State Disaster Management Authority Telephone Numbers of Senior Officials

24 hrs 079- 23251900 - 20

Sr.No	Name of Officers	Designation	Contact No
1	Anuradha Mall, IAS	CEO	079-23259502
2	Shri L.G.Ambujakshan	PS to CEO	079-23259276
3	Shri G. C. Brahmabhatt, IAS	Addl. CEO	079-23259451
4	Shri P.B.Thakar, IAS	Addl. CEO	079-23259292
5	Shri G B Mungalpura, GAS	Director (Admin)	079-23259292
6	Shri J. J. Shelat	Director Finance	079-23259278
7	Shri H.K.Chauhan	Controller of Account	079-23259219
8	Shri Nisarg Dave	Deputy Director	079-23259501
9	Shri Sumedh Patil	Deputy Director	079-23259279
10	Shri Piyush Ramteke	Sector Manager	079-23259283
11	Shri Santosh Kumar	Sector Manager	079-23259220
12	Shri Ankit Jaiswal	Sector Manager	079-23259246
13	Shri Anil Kumar	Sector Manager	079-23259220
14	Ms. Akanksha Jain	Sector Manager	079-23259306
15	Ms. Ambika Dabral	Sector Manager	079-23259246
16	Mr. Bhushan Rauisinghani	Sector Manager	079-23259283
17	Ms. Disha Dwivedi	Sector Manager	079-23259283
18	Shri Nehal Desai	Asst. Manager (Admin)& Asst. Director- H & L (i/c)	079-23259286

2. Information from the above Offices/Officers will be collected and transmitted to the overall in charge of Control Rooms/ Dy. Conservator/Harbour Master/ Traffic Manager/Senior Commandant, CISF/Chief Mechanical Engineer on hourly basis. The information should also be passed on to Secretary/Dy. Chairman/Chairman on every 03 hours.
3. Two telephones should be kept in the Control Rooms, one for receiving and the other for outward calls.

4. Each control room will enter messages in Log Books continuously and simultaneously report to the overall in charge after every one-hour. The information shall be passed on to Chairman/Deputy Chairman directly depending upon the importance. It shall be the responsibility of the Control Room Staff to ensure that timely information is passed on and timely proper monitoring done.

9.9 Continuous Monitoring Process

Immediately after the initial signal for Cyclone storm is received, the following officials shall continuously monitor the movement of Cyclone on hourly basis.

Sr. No.	Designation	Office	Mobile
1	Dy. Conservator	233585 / 220235	9825232982
2	Harbour Master	270201	9825803499
3	Pilot	270549	
4	Signal Supdt	270194, 9825227246	9825427400

These officials shall obtain the information from the following sources and The Telephone Numbers of I.M.D. is given in (Point No: 9.8.1)

1. State Meteorological Control Room, Ahmadabad,.
2. Meteorological Control Room, Delhi.

The information so collected shall be maintained by making hourly log entry in a register.

9.10 Monitoring Through Internet

1. As soon as the cyclone warning Signal No. 5 or above is hoisted, the HM nd Pilot should monitor it through internet and give two hourly print out to Dy. Conservator, Secretary, Chief Engineer, FA & CAO, Dy. Chairman and Chairman. Dy. Director (EDP) along with Junior Engineer (PMC) and Mr. B. Rajendra Prasad Exe. Engineer (Design) will monitor the website in the A. O. Building, Gandhidham.

The following are the website codes, through which the required information regarding the position of the Cyclone can be ascertained:

1. www.imd.gov.in

9.11 Inmarsat Mini – M – Terminal Kandla - 00873762092789

9.11.1 Control Room, Gandhidham

1	IDS No	762092789	-	VOICE
		762092790	-	FAX
		762092791	-	DATA

9.11.2 Control Room, Vadinar

1	IDS No	762092777	-	VOICE
		762092778	-	FAX
		762092779	-	DATA

9.12 Plotting of Information on Map

The following officers shall be deputed in the Control Room immediately on starting of the control room with relevant charts.

Sr. No.	Designation	Office	Residence	Mobile
1	Harbour Master	270201	231310	9825803499
2	Pilot			
4	Signal Supdt.	270549 / 270194	232551	9825427400 / 9825227246

The above persons shall immediately reach the Control Room and stay there till the emergency is called off. They shall plot the movement of cyclone on hourly basis and bring the position to the notice of Traffic Manager, Chief Mechanical Engineer, Dy. Conservator and Dy. Chairman/Chairman.

After scrutinizing the movement of Cyclone on the Charts, Dy. Conservator shall, in consultation with Chairman / Dy. Chairman, if required, take a decision for evacuation of ships immediately as soon as the Cyclone is in close proximity to the danger line as defined above.

All pilots should remain stand by as soon as the warning of Cyclone No. 5 level and above is received. All pilots shall be stationed at Kandla and shall not leave the port without prior permission.

Dy. Conservator shall station himself at Control Room at Kandla and remain continuously in touch with the pilots. The pilots should be in a position to mobilize themselves for evacuation of vessels and securing all Port crafts at shortest possible time.

9.13.1 Leave for Class 1 Class II Officers

All Class-I & Class-II Officers, the Technical Staff, the essential staff and other persons assigned with specific functions under this plan who want to avail leave in the month of May, June and July should invariably submit their leave program in April every year. Secretary shall issue a circular in the first week of April every year to all the Class-I and Class-II Officers and ascertain the period for which officers would like to proceed on leave during the months of May, June and July of that year.

9.13.2 Immediate stopping of operations at the Port

All the Pilots of the Port should reach Kandla immediately in case of emergency. Any Pilot not traceable in emergency shall be liable for disciplinary action.

Dy. Conservator/Harbour Master/Pilots should be available at Kandla during emergency. (i) Removal of vessels whenever the Cyclone is located in close proximity to the danger line plotted between 65 degree E Longitude 18.2 degree N Longitude and 73 degree E Longitude 18.2 degree N Longitude. Map showing the above position is given at (Annexure XXX (to be inserted by KPT)).

- i. Under such a situation, the ships shall be removed during the first/next available tide. It will be the duty of Harbour Master and Dy. Conservator to ensure that the ships are removed during the first/next available tide as soon as the storm approaches in the close proximity to the danger line as defined above without seeking any further instructions from higher authorities. This action shall be taken automatically and suo-motto without any confusion and for this purpose Traffic Manager shall stop all loading and unloading operations immediately upon instructions from Dy. Conservator so as to enable him to remove the vessels in time. The removal shall be done with the help of all the available pilots plus all contract/empanelled pilots together at one go in the shortest possible time so as to ensure that all the vessels cross the bar before the tide restriction sets in.
- ii. Dy. Conservator shall ensure that all ships are moved out of the Harbour at the earliest. All pilots shall immediately report at Kandla and stay there till the Action Plan is in operation. Dy. Conservator/Harbour Master shall immediately plan removal of vessels to the OTB as soon as the Action Plan is put into operation irrespective of the signal number, which must be hoisted. If it is impossible to remove them, then all other steps should be taken to ensure safety of the vessels at the Port, as also it would not cause any damage to the Port.
- iii. S E (M) shall enlist the Engine side staff of the Floating crafts to be kept stand by for shifting of crafts to safer places. He will be in charge of manning these crafts as per the requirement.

For shipping tugs, Marine Engineer / Engineer In charge (Tugs) / will be the in charge for manning the engine side staff for operation of the shipping tugs as per the requirement. Assistant Engineer (DT) and, Assistant Executive Engineer (FC) shall co-ordinate with Marine Engineer / Engineer In charge (Tugs).

- iv. After the Cyclone warning Signal No. 5 or above is hoisted at the Port Traffic Manager shall ensure that the loading/unloading operations at the Port are stopped immediately, hatches closed, ships' derricks properly secured and all labourers evacuated from the port area. Public address system shall be installed at the cargo jetty area, which shall be under the charge of TM. He shall use it for necessary arrangements relating to the evacuation. Senior Commandant, CISF shall ensure that Public Address System is fitted on jeeps provided to CISF.

Traffic Manager should ensure that responsible persons make announcements in a proper way so as not to create any misunderstanding / panic.

9.14 Securing of Cranes

Chief Mechanical Engineer shall ensure that immediately the cranes are secured and properly locked after closing of loading and unloading operations from ships as per procedure and report submitted to Chairman/Dy. Chairman after the operation of this action plan.

The following officers shall constantly monitor the safety of Cranes:

Sr. No.	Designation	Office	Residence	Mobile
1	S E (M)	270354	222771	9825227255
2	S E (E)	271010	229038	9427205563

The above officials and, Assistant Engineer (Elec.) shall arrange to secure all the cranes and keep them properly locked as per the procedure and send a report to the Chief Mechanical Engineer.

Executive Engineer (Dry Dock) and, AE (Mech) shall arrange to secure the cranes at maintenance Jetty as well as Bunder Area.

9.14.1 Securing of all Crafts

Dy. Conservator/Harbour Master shall immediately arrange for securing all the Port Crafts at safer places so that there is no loss to the port and send a report to the Chairman/Dy. Chairman as early as possible after operation of this action plan. Flotilla Superintendent shall be overall in charge of each craft for ensuring their safety.

For parking of crafts in emergency, there places are mainly identified, viz. Bunder Basin, Launch Jetty and maintenance Jetty (As per):

1. Maximum number of crafts such as Mooring Launches, G. S. Launches, and Pilot Launches will be placed in Bunder Basin.
2. In the inner side of Passenger Jetty, one Pilot Launch and one G.S. Launch will be kept.
3. Three Tugs will be kept in the inner side of Maintenance Jetty.

Priority will be given to the Port Crafts for parking in the Bunder Basin and other areas. Rest of the places available in the northern side of Bunder basin area will be allotted to the self propelled barges and private crafts. Dumb barges will be allowed on the beach between maintenance jetty and oil jetty area.

Berthing Supervisor will render all possible assistance to FS, being the overall in charge of the crafts. The following flotilla staff will take care of;

1	Mr. T. Sunil Kumar	F.S
2	Mr JAYDEEPSINH GOHIL	B.S
3	Mr. R B Chauhan	AFS
4	Mr. KENIYA	AFS

9.15 Private Barges / Crafts

The parties who have been given license by the Dy. Conservator to keep their barges and crafts inside the Port limit are given below:

9.15.1 **ALL** HARBOUR CRAFT License Holders to keep their Crafts inside the Port Area

Necessary instructions shall be issued to all those people have valid license immediately. The work of informing these parties will be carried out by Office Superintendent of Dy. Conservator's Office and will personally ensure that the instructions are carried out and report to HM within two hours of the Action Plan coming into operation. The representatives of the above parties shall reach Kandla at once, failing which Dy. Conservator shall cancel the license granted to them and take over the barges/crafts of the party who violate the instructions.

9.16 Evacuation of People from Kandla Area during Emergency – Action Plan

In Kandla Area, there is Residential Habitation in the following areas:

9.16.1 Places of Habitation

9.16.1.1 Saltpan Units

Considerable numbers of Salt Workers are engaged in the following Salt Manufacturing Units.

1. Kutch Salt Works.
2. New Kandla Salt Works.
3. Vijay Salt Works.
4. Friends Salt Works.

5. United Salt Works on KPT Land.
6. United Salt Works on State Government Land.
7. Small Salt Works of State Government, Near Nakti Creek.

The approximate number of Salt Workers that are being engaged/ residing in these Salt Works will be around 2575.

9.16.1.2 Sirva Labour Camp

Plots in Shirva Labour Camps (Near Mosque) have been allotted by DEENDAYAL PORT TRUST on L&L Basis. Population: 450 (approx). There are also some un-authorized hutments in the area.

9.16.1.3 Sirva Railway Hutments

The Shirva Railway Hutments (alongside Main Road) is a cluster of un-authorized Hutments erected on the Railway Land: Population 700 (approx).

9.16.1.4 G – Type Quarters & Housing Societies

The G-Type Quarters are constructed by DEENDAYAL PORT TRUST in early 1950s and were allotted to some persons who were engaged in Port related activities in those days.

DEENDAYAL PORT TRUST has allotted land to Two Housing Societies known as Kandla Port Workers Co-operative Society and Dr. Jaynat Khatri Co-operative Housing Society in Kandla area. Population: 1000 (approx).

9.16.1.5 New Kandla Port Colony P & T & Customs Colonies

The KPT employees, Customs employees etc are residing in these areas.

9.16.1.6 Hutments in the Land of PGVCL

There is a cluster of unauthorized Hutments to the Northern side of wahiya creek and southern side of M/s ABS Bayers Limited and this land belongs to PGVCL. Population: 100 (approx).

9.16.1.7 Banna Fishermen Hutments

There are unauthorized Fisherman hutments situated on the Bank of Kandla Creek towards Southern side of NDDDB Colony. Population: 800 (approx).

9.16.1.8 Hutments near IFFCO Plant

There is a cluster of unauthorized hutments near IFFCO Plant. Population: 500 (approx).

9.17 Population of Kandla

The population of Kandla Area is basically a mixture of people from various places and they can be generally divided in the following three groups;

People belonging to nearby villages like (i) Tuna (ii) Kharirohar (iii) Mithirohar (iv) Chirai and (v) Gandhidham City.

People belonging to other States like (i) Andhra Pradesh (ii) Rajasthan (iii) Uttar Pradesh and (iv) Bihar.

People working in Government establishments residing in the colonies of their organizations.

Most of the people residing in Shirva Labour Camp, Shirva Railway Hutments and Thermal Hutments etc are engaged as Private Labours in the Port and Port related ancillary activities and petty business.

9.17.1 People of Nearby Villages

People of the Port and nearby lease areas belonging to nearby villages like (i) Tuna (ii) Kharirohar (iii) Mithirohar (iv) Chirai and (v) Gandhidham City will have to be sent back to their respective village by providing them Trucks and/or ST Bus facilities in consultation with State Govt. Agencies.

9.17.2 People of Other States

People belonging to other States like (i) Andhra Pradesh (ii) Rajasthan (iii) Uttar Pradesh and (iv) Bihar may not have any relatives or other accommodations facilities in the nearby places like Gandhidham, Adipur.

Hence, they will have to be provided Temporary Shelter in the Schools/community centres as may declared as Temporary Rehabilitation Centre/ Temporary shelters by the State Govt. Authorities.

9.17.3 Action Plan for Evacuation of People from Kandla

On Hoisting of No. 5 Signal or above in Kandla Port, immediately action shall have to be initiated for evacuation of people in the following areas by the persons responsible as mentioned hereunder:-

The evacuation of the inhabitants of the following areas at Kandla is to be done as these areas are sensitive and prone to natural calamities like cyclone, high-tide and other disaster like Gas Leak, etc.

OSD(Estate) and Mr. Bhatia, Asst. Engineer (C) shall ring up all salt lease holders directing them to evacuate their people from their Kandla sites and a report thereof submitted to the Chairman/ Dy Chairman. The Dy Secretary (Estate) will be overall in-charge of the proposed action.

9.17.3.1 List of Salt Lessees

Sr. No	Name of Salt Works	Contact Person	Tel. No. Office	Tel. No. Residence
1	Asstt. Salt Commissioner, Gandhidham	Mr. Jagdish Tripathi	233670	263690
2	M/s. Kanoria Chemicals and Ind. Ltd., Plot No.220, Sector -4, Gandhidham	Mr. B. N. Singh, Mr. J. Singh Factory -	229470	283325 9825225841
3	Shree Krishna Salt Industries, Central Bank	Mr. Kantibhai Thakkar Mr. Vikash Patel	234727 233990	235315 234089

	Compound, Gandhidham	Mb: 9825206214		
4	M/s. Chirai Salt Works, DBZ-S-46, Jawahar Chock, Gandhidham.	Mr.Sureshbhai Mr.Parasbhai Mb: 9825225181 Mr.Mayajar	221109 221267 9826214709	234386 233081
5	M/s. Bhuvneshwari Salt Works, TCX-S-62, Gandhidham	Mr.Sreechandji Jain 9825222269	237114 235203	233605 236860
6	M/s. Dungershee Salt Works, Shop No. D-93, P.B.No.9, Gandhidham	Mr.Hiralal Parekh Mb: 9825019661 Mr. R.B.Agrawal Mb: 9825019662 Mr. Bhikhabhai (Salt Area)	222765 223440 9825225667	232767
7	M/s. Shree Laxmi Salt Allied Ind., "Shree Sadan", 207 / 12-B, Gandhidham	Mr. Rajubhai Rathi Mr. Rameshbhai Rathi Mob.: 9824214901	232167	232167 235482
8	M/s. Jyoti Salt Industries, "Sukh Sadan", Opp. Hotel President, Gandhidham	Mr.Acharya Sukhdevbhai Mr. Sukhdevbhai Acharya Mb: 9825226075	223776 221082 221089 223094	221876

9	M/s. New Kandla Salt and Chemical Co., "Maitri Bhavan", Plot No.18, Sector 8, Gandhidham	Mr. Babulalji Sanghvi 9825226091 Mr. Sukhrajbhai 98252 26011	232227 231588 234087	234325 231814 232122
10	M/s. Kutch Salt Works, New Kandla	Mr. Mitenbhai Mb: 9825225990 Mr. S.P.Giria, Works Manager, Mb: 9825228085	234659 02222040561 22041598 270371	238633

11	M/s. Vijay Salt Works and Allied Industries, "Friends House", P.No. 50, Sector -1A, P.B.No.106, Gandhidham	Mr. Harishbhai Chaturani Mb: 9825064241 Mr. Babulal Nahata	231119 252247 223743	234856 9825228398
12	M/s. Rajesh Salt Works, "Chandan Chambers" National Highway, Plot No.18, 12/A, Gandhidham.	Mr. Kishorbhai Thakkar Mob: 9825177081 Mr. Rameshbhai Mb: 9825226026	220586 221048 222301	234387
13	M/s. Western Chemical, DBZ-S-151, Gandhidham	Mr. Naranbhai Mb: 9825226092	233185 230913	230141
14	M/s. Urvakunj Nicotine Ltd., Central Bank Compound, Plot No.31, Sector No.9, Gandhidham	Mr. Mahendrabhai Patel 9825206214	234727	234480

		Mr. Vikash Patel Mb: 9825226214		
15	M/. Friends Salt Works, "Maitri Bhavan", Plot No.18, Sector No.8, Gandhidham	Mr. Babulalji Mb: 9825226015 Mr. Ashokbhai Mb: 9825226091 Mr. Sukhrajbhai Mb: 9825226011	232227 231588 234087	231646 231814
16	Smt. Savitri H.Pandya, DBZ-N-21/A, GIM	Mr. Jagdihbhai	220212 238112	255612
17	Smt. Vimlaben.H. Pandya, DBZ-N-21/A, Gandhidham	Mr. Jadishbhai Mr.Amrityal Pandya Mb: 9825225212	220212/238 112 238212 255612	- /
18	M/s. Rajendra Salt Works, D-125, Jawahar Chowk, Gandhidham	Mr. Tarachand	-	-
19	Mr. Natwarlal Agrawal, TCX-S-75, Gandhidham	Mr. Natwarlal Mb: 9825393555	222672	231564
20	Mr. Indrumal Khubchand, C/o Gulab Salt Works, D-125, Jawahar Chowk, Gandhidham.	Mr. Tarachand	233041 234388	234937
21	Mr. Virji Khimji C/o Ajit Salt works, D-75, Gandhidham	Mr. Kirtibhai	220310	-

22	Mr. Girdharilal.S. Agrawal, Plot No.126, Ward – 12/B, Gandhidham	Mr. Girdharilal	232862	234755
23	Mr. Vijay Kumar.D. Palan & Mri Jagdish Kumar.D.	Mr. Navrotambhai Palan	220310	-
24	M/s. Satya Salt Works, DBZ-S-183, Gandhidham	Mr. Candubhai Mb: 9825225911	224055 221445	234739 234469
25	Shri Premji Gangji Soni, DBZ-S-183, Gandhidham	Mr. Mahes Soni	221263	-
26	Smt. Geetadevi Chaturani Plot No.13, Sector 1, Gandhidham	Mr. Romesh / Ashwin Mr. Dayalbhai Chaturani, Mb:9825064245	221048 256713 220586 256706 Fax: 222930	-
27	Shri Rashmin A.Pandya DBZ-N-21/A, Gandhidham	Mr. Jagdis Pandya	220212 238112 238212	-
28	M/s. Neelkant Enterprise, DBZ-S-60, Gandhidham	Mr. Shamjibhai Mb: 9825 25711	220421 220103 Fax: 223560	231485
29	Dayalal G.Chaturani Shop No.1 to 4, "Chandan Chamber" Plot No.18, Ward No.12, Gandhidham	Mr. Dayal	221048 220588	-

30	Shri Punamchand, DBZ-N-197, Gandhidham	Chaganlal	Mr. Chaganlal	220545	-
----	---	-----------	---------------	--------	---

Safety Officer & Librarian shall inform the Public/Private Sector Tank Farms in Kandla about the situation and advise them to shift their people out of the respective areas to safe places.

9.17.3.2 List of Private / Public Tank Farm Owners

Sr. No.	Tank Farm Owners	Persons to be contacted in case of emergency		
		Name and Position	Telephone No.	Mobile No.
1	Kesar Enterprises Ltd., Near Oil Jetty, Old Kandla (Kutch)- 370210	Mr. R.K. Gupta Gen. Manager	270435 (O) 295676 (R)	9375349181
2	Kessar Enterprises Ltd, Terminal II, Plot No. 5 &6 Old Kandla	Mr. R.K. Gupta G.M	270435 (O) 270177 (O)	9375349181

3	Chemical & Resins Pvt. Ltd Terminal –I, Near Oil Jetty, Old Kandla, Kutch Terminal – II, Near West Gate, New Kandla – Kutch	Lt. Col. Pramod Kumar (Retd), GM,	270505(O) 236831(R) 270916 (O)	9825225676
4	Indo-Nippon Co. Ltd., Plot No.2, K.K.Road, Old Kandla,	Mr. R.N. Pathak Asst. Terminal Manager	270795(O) 235818(R) 270295(O)	9879571295
5	J. R. Enterprise, Plot No.3, Old Kandla,	Mr. Devendra Dadhich, Terminal In-charge	653528 (O) 257152 ®	9898238380
6	Friends Oil & Chemical Terminals Pvt. Ltd., Near Booster Pump Station, Old Kandla, Kutch	Mr.S.Ramakrishnan Terminal Manager	270987 (O) 257249 ®	9879572107

7	Indian Oil Corporation Ltd., Main Terminal, GIM Foreshore Terminal, Kandla KBPL LPG Import Plant	Mr. AK. Khanna Sr. Term. Manager Mr. KS Rao, Sr.TM Mr. PS Negi Plant Manager	233274 (O) 229002 (R) 270394 (O) 270628 (O) 270477 (O) 233359 ® 270978 (O) 236944	9427216637 9426416108 9426725342
8	United Storage & Tank Ltd Near IOC Foreshore Terminals, New Kandla Gas Terminal, Plot No. 4 Old Kandla	Mr. Manoj Gor Terminal Manager Mr. G. Chudasama	270609 (O) 653525 (O) 651238 ® 653529 (O)	989850029 9904366855
9	IFFCO Kandla Unit, Kandla, Kutch	Mr. L. Murugappan, G.M.(NPK-I) Mr. Brahmbatt Manager (F & S)	270711 270352(O) 270381 (O)	982506922 9099019861

10	BPCL, KK Road, GIM	Mr. RG. Dekate Sr. Manager Operations	234313 (O) 223235 (R)	9099929634
11	HPCL KK Road, GIM	Mr. Murthy Manager (Installation)	230936 (O) 220084 (O) 233078 Ext	
12	INEOS ABS (I) Ltd Plot No. 8 Old Kandla	Mr. Vineeth Nair Dy. Manager	270087 (O) 234409 (R)	9825237029

13	Liberty Investments Pvt. Ltd., Plot No. 1 & 2, Block 'H', New Kandla	Mr. Jitendra Vaidya Terminal Manager	270151 (O) 270464 (O) 270468 (R)	9825025645
14	Avean International Pvt. Ltd., Liquid Storage Tank Terminal, Plot No. B-1, New Kandla	Mr. Bharat Rathod Terminal Manager	270537 (O)	9375310260

15	Rishi Kiran Logistics Pvt Limited, Plot No. 7, Link Road Old Kandla	Mr. RH. Pandya GM (Terminal)	270223 (O) 270443 (O)	9879104556
16	N.P.P. Pvt. Ltd., Old Kandla	Mr. MD.Nagvekar	270347 (O) 257807 ®	9825227649
17	Friends Salt Works and Allied Industries, KK Road, Old Kandla	Mr. NJ.Zinduwadia Sr. Manager Mr. HA. Mehta,S.M	270814 (O) 262698 (R) 271260 (O)	9825506361 9825506360
18	IMC Ltd, Cargo Jetty New Kandla	Mr. Anil Brahmhat	270369(O) 653524 (O) 296079 (R)	9898126243
19	Agencies & Cargo Care Ltd., Plot No.3, New Kandla.	Mr.Shivkumar Menon, Terminal Manager	270714 (O)	9825226765

20	Dipak Estate Agency Plot No. 5-6, Block – A New Kandla	Mr. Narendra Thacker	270375 (O)	9879611243
21	Parker Agrochem Exports Ltd, Plot No. 3 –4,Block- H New Kandla	Mr. Bharat Thacker	270486 (O) 270528 (O) 231876 (R)	9825238260
22	Tejmalbhai & Co New Kandla	Mr. Ankitbhai Chandan	271330 (O) 230090 (R)	9825225101
23	Parker Agrochem Product Pvt. Ltd, Plot 7-9/A,N.Kandla	Mr. Raja Babu Dy Manager	270528 (O) 231876 (R)	9979158543
24	Mother Dairy Fruit & Vegetable Pvt. Ltd, Near Oil Jetty, Old Kandla	Mr. Saju Therattu	270654 (O) 270655 (O) 230979(R)	9974022681

Traffic Manager/ Additional Traffic Manager shall arrange to inform all the Stevedores / Agents and other Stakeholders to remove their workers from the operational areas at Kandla.

9.17.3.3 List of Stevedores in the Port

Sr. No.	Name	Address	Fax No.	Telephone Nos.	
				Office	Resi.

1	M/s. Cargo Movers	"Cargo House" BBZS-32A, Gandhidham	231687	220453 231365	261280
2	M/s. DBC & Sons (P) Ltd.	Seva Sadan-II, Room No. 303 / 304, New Kandla	270631	270503 270263 270348	-
3	M/s. A.V.Joshi & Co.	Plot No. 18, Sector-8, Maitry Bhavan, Nr. Post Office, Gandhidham – Kutch	233924	231070 232227 231588	234909
4	M/s. ACT Shipping P. Ltd	Seva Sadan-II, Room No. 206/207, New Kandla	232175	270111 270112 270015 229967	261308 231416
5	M/s. Cargo Carriers	214/215, Rishab Corner, Plot 93, Sector- 8, GIM	230030	220816 231649 230030	231694
6	M/s. Cargo Clearing Agency (Gujarat)	Plot No. 271, Ward 12- B, Gandhidham	233034	221721 220655	231452
7	M/s. Chotalal Premji Stevedores Pvt. Ltd	C-8, Shaktinagar, GIM	231509	270009	-
8	M/s. Hiralal Maganlal & Co.	C-11, GIDC Area, Gandhidham – Kutch	223914	223914 231832	223878 232430

9	M/s. New Dholera Shipping Company	Goyal Commerce Centre Building - 1, Plot No.259, Ward 12B, Gandhidham - Kutch	-	222637 232267	237284
10	M/s. J.M. Baxi & Co.	Seva Sadan – II, Room No. 301 / 306, New Kandla	270646	270630 270550 270448	260427
11	M/s. Pestonjee Bhicajee (Kutch)	Seva Sadan-II, 203, New Kandla	270650 270556	270257 270367	262914
12	M/s. OTA Kandla Pvt. Ltd.	BBZ-N-324, Gandhidham	223241	220145 270560	223241
13	M/s. Purshotamdas Jeramdas & Co.	5, Vaswani Chamber, 16, Sector-8, GIM	222850	238242 222598	220598
14	M/s. R. Tulsidas & Co.	Ahit Building , Plot No.323, Gandhidham – Kutch	232308	222717 221943	-
15	Rishi Shipping	Plot 50, Sector 1/A GIM	238943	229830 229831	
16	M/s. Vinsons	BBZ-S-25, Gandhidham – Kutch	231948	220466	222395 239460
17	Sical Logistics Ltd	403, 4th Floor, Madhuban Compex, OSLO, GIM	234416	234646 234194	

18	Parekh Marine Agency	C-8, Shaktinagar GIM	231509	229297 221158	
19	Krishna Shipping and Allied Services	Transport Nagar, NH GIM	233135	230501 223814 229085	
20	Kevar Handling & Transport	Shop 24, Tolani Chamber, Sector –8, GIM	228298	228298	
21	Trinity Shipping & Allied Industries	Trinity House, Plot 46 Sec 1/A, GIM	232060	230911 230910	
22	Velji P & Sons(P)Ltd	2nd Floor, Deepak Complex, 315, 12/B GIM	236168	231545 231546 225466	
23	Asean Marine Services	Ashit Bldg, Plot 33 Sector 1/A, GIM	232308	222717 221943 222145	
24	Rishikiran Roadlines	Kiran House, Plot 8 Sector 8, GIM	231422	231894 234108	
25	Universal Shipping Services	Hotel Sea Bird, Plot 173, Sector 1/A, GIM	235251	230663 226050 226037	
26	Seaways Shipping (P) Ltd	2nd Floor, Plot 351 Ward 12/B, GIM		226183 237147	

27	Seacrest Shipping Services Pvt. Ltd	216, 2nd Floor Om Corner, Plot 336 Ward 12/B, GIM	227028	233325	
28	Shree Maruti Shipping Services	18/21, Swaminarayan Bldg, Sector 9, GIM	234107 250690	233245 237247 250690	
29	Liladhar Pasoo Forwarders P.Ltd	Plot 4, Sector –1 KASEZ, GIM	252383 253506	252286 252297 252612	
30	Shree Radhey Shipping Company	14-16/C, GF Green Park, GIM	232967	222919 228919 238883	
31	Pearl Shipping	220, Rishab Corner, Plot 93, Sector 8 GIM	235570	225283 225284	
32	Patel Shipping Agency	Patel Avenue, Floor 2,Plot 170, Sector 1/A, GIM	231143	224024	
33	Ashirvad Shipping	18-21, Swaminarayan Bldg, Sector- 9, GIM	250690	233245 237247 222822	
34	M/s. Swaminarayan Vijay Trade	1st Floor, H-6, Op. Tejas Society, Ghatlodia,	079- 231983	231981, 231982	

	Carrier	Ahmadabad			
--	---------	-----------	--	--	--

9.17.3.4 List of Liner & Steamer Agents at Kandla Port

Sr. No.	Name	Fax No.	Tele. No.	Mobile
01	M/s ACT Shipping Ltd Mr. Harshad Gandhi	232175/ 270597	270111 270115-6 229967 231734	9825226141
02	M/s Admiral Shipping Ltd	233596	230552 232823	
03	M/s Areadia Shipping Ltd	232542	234254 223486	
04	M/s Ambica Maritime Ltd Mr. Amit Vyas	252447	252479 252349	9825225210
05	M/s APL (India) Pvt Ltd., Mr. Murli Krishnan	236361	224601/2 236357 236355	9825225753
06	M/s Arebee Star Maritime Agencies Pvt Ltd. Mr. Anil Talwar	235831	220465 235832	9824229109
07	M/s Ashit Shipping Ser. Pvt Ltd. Mr. Sanjay Thakkar	232308	221943 222717 222145	9825225698
08	M/s Atlantic Shipping Pvt Ltd	223372	230552	
09	M/s Asia Shipping Services. Mr. Mohan Karia239326	231285	234526 230954	

10	M/s Bayland Freight Systems Pvt Ltd., Mr. Danendran Gopalan	239326	225522/ 23	9825230880
11	M/s B D Vithlani Shipping Services Pvt Ltd.	234104	232220 221081	
12	M/s Cargo Conveyors Mr. Shekhar Ayachi Mob. 9825226102	233034	221460 220655	
13	M/s CCA Shipping Services Mr. K C Varghese	233034	221721 220655	9825225217
14	M/s Chowgule Brothers Mr. C R Soman	229227	278521 225051 232365	9825361782
15	M/s Coastline Services (India) Pvt Ltd.	221137	232095 222853	
16	M/s Container Marine Agency Pvt Ltd	234541	230026 220416	
17	M/s Conftreight Shipping Agency (India) Pvt Ltd. Mr. K T R Nair	-	233615 236157	
18	M/s Cresent Shipping Agency (India) Pvt Ltd Mr. Sanjay Salve.	224506	221290 221957	9825227311
19	M/s DBC Freight International	230832	230832 230639	

20	M/s DBC Sons (Gujarat) Pvt Ltd. Mr. R C Vazirani	270631	270263 270503	
21	M/s Depe Global Shipping Agency Pvt Ltd. Mr. Jaydeep Roy	232079	231528 233608 234582	9825228121

22	M/s Evershine Shipping Services. Mr. Kishan Motwani	234083	221588 237408	
23	M/s Forbes Gokak Ltd	231464	222634 235004	
24	M/s Freight Connection (India) Pvt Ltd	231357 270726	222247 222545 270727	
25	M/s GAC Shipping (India) Pvt Ltd. Mr. V C Rao	231429	231427 237244	9825225136
26	M/s Ganges Liners Pvt Ltd	233437	231608 233436	
27	M/s German Exp. Shipping Agency Pvt Ltd	236040	223269 236040	
28	M/s Goodrich Maritime Pvt Ltd	222875	222882 222883	
29	M/s G P Dave & Sons (Shipping)	234382	234288 234382	
30	M/s Greenways Shipping Agencies Pvt Ltd	232079	233608 234585	
31	M/s K. Shipping Services Pvt Ltd	233632	231933	
32	M/s Halar Ship & Freight Forwarders. Mr. Tejas Shrma	270224	270192 270568	9825212646
33	M/s Hind Shipping Agencies. Mr. Mahesh Vyas	234795	232710 235375	
34	M/s Hindustan Shipping Services. Mr. M D Sorathiya	239110	239110 222821	9824214994

35	M/s Interocean Shipping India Pvt Ltd. Mr. Suresh Tripathy	232579	235201 230589	9825225583
36	M/s Intra Trade Pvt Ltd. Mr. B P Vasavda	233295	233313 231255	9825226129
37	M/s Trades Shipping Pvt Ltd	231463	235572 233606	
38	M/s James Mackintosh Marine (A) Pvt Ltd. Mr. Satish Nair	270793	270792 270846	9825226077

39	M/s J MBaxi & Co. Mr. D P Mitra	270646	270630 270635 270525	9825225107
40	M/s Kutch Shipping Agency Pvt Ltd. Mr. Azad Khan	233339	221148 250226/ 7/8	
41	M/s Liladhar Passop Forwarders Pvt Ltd. Mr. S. Chakraborty	252383	252297 252402 252288	9825020523
42	M/s Maersk (India) Ltd. Mr. Dinesh Joshi	231388	231387 236192 233963	9825270419
43	M/s Maheshwari Handling Agency Pvt Ltd. Mr. Chaggan Maheshwary	230575 234633	223228 230393	9825227111
44	M/s Maltrans Shipping Agencies India Pv Ltd.	230606	220147 230336 235022	
45	M/s Mathurdas N. & Sons Forwarders Ltd.	252221	252224 252350	

46	M/s Meridian Shipping Agency Pvt Ltd	230212	220305 230220	
47	M/s Mitsutor Shipping Agency Pvt Ltd	230411	220110	
48	M/s M M Shipping Services	235255	231385 238385	
49	M/s Modest Shipping Agency Pvt Ltd	-	230576	
50	M/s NLS Agency India Pvt Ltd. Mr. Sanjay Salve	232413	231318 220305	9825237311
51	M/s Orient Express Lines Ltd	230359	232186 232805	
52	M/s Orient Ship Agency Pvt Ltd. Mr. H G Digrani	233518	223430 223487	9824214801
53	M/s Oscar Shipping Agencies.	231812	226959/6 0 232123	
54	M/s Parekh Marine Agencies Pvt Ltd. Mr. Mitesh Dharamshi	231509	221409 235341	9825226557
55	M/s Patel Handling Agency (Capt. Kalra)- 9825062912	231143	224024 231004 221718	
56	M/s Patvolk (Mr. Shreekumar Nair)	231464	222624 235004	

57	M/s Pearl Shipping Agency. Capt. Kalra	231143	224024 221718	9825062912
58	M/s Penguin Shipping Agencies Pvt Ltd.	230606	230336 220147	

59	M/s Pestonjee Bhieajee (Kutch) Mr. R K Kewalramani	270650 270556	270221 270257 270367	9825226962
60	M/s Prudential Shipping Agencies Pvt Ltd. Mr. Siddharth Mishra	232911	230479 233982	9825226477
61	M/s P&R Nedlloyed India Pvt Ltd	232207	224906/7 232128	
62	M/s R T Bhojwani & Sons Mr. Gopichand Bhijwani	232423	223831 220839	9825225639
63	M/s Sahasu Shipping Services Pvt Ltd	236358	225224 237854	
64	M/s Sai Shipping Co. (P) Ltd Mr. S T Hingorani	231972	221369 231739	9825228681
65	M/s Samrat Shipping Co Pvt Ltd	232890	231983 222939	
66	M/s Samsara Shipping Pvt Ltd. Mr. Pranesh Rathod	233165	228602	9825225755
67	M/s Scorpio Shipping Agency	-	223085	
68	M/s SDS Shipping Pvt Ltd	231542	221326 221087	
69	M/s Seanay Shipping Pvt Ltd	270026	270788	
70	M/s Seabridge Maritime Agencies Pvt Ltd	231509	221409 221158	
71	M/s Seafreight Pvt Ltd	222850	233530 222393	

72	M/s Sealand Agencies India Pvt Ltd	230584	231179 230584	
73	M/s Seamar Shipping India	255563	-	
74	M/s Seatrade Shipping	234171	233810	
75	M/s Sentrans Maritime Pvt Ltd	236129	230002 220702	
76	M/s South India Corporation (Agencies) Ltd Mr. Antony	234416	221276 234646 231494	9825226256
77	M/s Spoonbill Maritime Agencies Pvt Ltd	234167	221049 222058 234454	
78	M/s Star International	231395	233948 232402	
79	M/s Taipan Shipping Pvt Ltd	236040	223269 227010	
80	M/s Taurus Shipping Services. Mr. Sukhveersingh	231266	221334 223074	9825227325
81	M/s Oceanic Shipping Agency Pvt Ltd	270631	270263 270503	
82	M/s TICC Container Line (Kandla) Pvt Ltd	237854	237854	
83	M/s Total Transport Systems Pvt Ltd	231463	222634	
84	M/s Transocean Shipping Agency Pvt Ltd	-	230832	
85	M/s Transworld Shipping Services India Pvt Ltd Mr. Sandeep Rajvanshi	231913	229824 221290	9825225733
86	M/s Trinity Shipping & All. Services Pvt Ltd Mr. Soly	222060	230911 223703	9825225245

87	M/s Unimarine Agencies (Gujarat). Mr. Jaikumar Ramdasani	224633	224631/ 32 223113	9825225216
88	M/s Unique Shipping Services Pvt Ltd	-	232729 232730	
89	M/s United Liner Agencies of India Pvt Ltd Capt Rakesh Kumar	236040	227779 223269	9825225741
90	M/s Universal Freight Systems	252383	252288 252297	
91	M/s Universal Shipping Services Mr. Anil Pillai	235251	230663 231708	9824215168
92	M/s Velhi P. Sons (Agencies) Pvt Ltd	255328	255327 231545	
93	M/s Vibhuti Shipping Pvt Ltd Mr. Vinod	236219	236719 230035 232424	9825226536
94	M/s Worldwide Cargo Care Pvt Ltd	231913	221290 221479	

9.18 Core Team

Asstt. Commandant-CISF, OSD (Estate), Ex. Engineer (Roads)-KPT, Executive Magistrate of State Govt. of Gujarat i.e. the Mamlatdar, Gandhidham and Police Inspector, Kandla shall jointly ensure evacuation of people from Kandla areas. The persons entrusted with the evacuation programme as indicated here below will have to report the progress in evacuation to the Dy. Secretary (E) who shall appraise all developments in this regard to Chairman and Dy. Chairman, KPT over telephone from time to time.

The Evacuation of People from different areas at Kandla shall be looked after by the officers named below.

9.18.1 Banna Fishermen Hutments

ACTION BY, Junior Engineer, and CISF

9.18.2 Saltpans (Including Major & Minor)

ACTION BY: Asstt. Estate Manager, Mr. AB Pradhan, Labour Officer and CISF.

9.18.3 Sirva Camp & Sirva Railway Hutments

ACTION BY: OSD (Estate), Estate Inspector and CISF

9.18.4 G Type Quarters of DEENDAYAL PORT TRUST

ACTION BY: Assistant Engineer and CISF

9.18.5 New Kandla KPT Colonies, Customs & Hutments in PGVCL Land

ACTION BY: Assistant Engineer/InspectorVigilance with CISF

9.18.6 Hutments near IFFCO Plant

ACTION BY: Junior Engineer and CISF

9.18.7 Cargo Jetty & Oil Jetty Areas

ACTION BY: Traffic Manager – Private Workers/ Shore Workers

AAO, CHD - CHD Workers

HOD/Dos - The Employees of their respective deptt.

The Traffic Manager/ Commandant CISF shall ensure that the Cargo/ Oil Jetties are completely evacuated and there is no fresh entry into the operational areas.

9.19 Public Announcement

The Public Announcement for faster evacuation is to be made by (a) CISF on behalf of DEENDAYAL PORT TRUST and (b) Police Inspector, Kandla Police Station in consultation with KPT officials.

9.20 Temporary Shelters

The Temporary Evacuation Centres (TEC) will be set up in the Gandhidham area in places like Schools/ Community centres etc as may be decided in consultation with the State Govt. Officials.

Executive Engineer (TD) will have to ensure the following;

Opening cleaning and providing water facility in the Temporary Shelters at Gandhidham in premises coming under the administrative jurisdiction of Kandla Port that may be identified for the purpose by the Collector/Mamalatdar/concerned state govt. authority. The toilet blocks attached to these buildings are to be kept in usable condition.

Executive Engineer (Electrical) shall ensure providing of lights and continuous electric supply in the Temporary Shelters as mentioned above.

Mr. A B Pradhan, Labour Officer and the Head Master of BVM School will have to ensure opening of the School and shifting of school furniture as may be directed.

The requirement of amenities/ medical aid etc in the Temporary Evacuation Centres will be taken care of by the Executive Engineer(TD)/ (R), Senior Engineer (PL), updt Engineer (E) and Doctors of Medical Department.

9.21 Transport Facility

The Traffic Manager shall provide sufficient number of Trucks and Dumpers as may be requested by Dy. Secretary (E) for evacuation purpose.

The hired buses of KPT shall be deployed for evacuation. In case of additional requirement the Dy. Secretary (G) will co-ordinate with Mamlatdar, Gandhidham for obtaining sufficient number of ST Buses for evacuation purpose.

Secretary shall co-ordinate the above activities.

Ensuring the functioning of TELEPHONES

The name and telephone No. of the Officer Telephone Department to be contacted in case of any problem:

1. General Manager, Bhuj(O) 231201/231648 (R)

2. District Engineer, Bhuj(O) 525410

3. SDO (P), Gandhidham(O) 232453/229666 (R)

Dy. Secretary (Personnel) shall ensure that the telephone of all the Head of Departments and other responsible officers of different Departments are functioning properly by ringing personally. In case any of the telephones does not function or give satisfactory service, he shall take up the matter with the higher authorities immediately.

9.22 Traffic Movement

Commandant, CISF with the help of Police shall ensure that all incoming traffic to the Port is stopped except those which are coming for rescue operations and essential services at three places i.e. KASEZ Junction, Railway crossing and Kharirohar Road. He shall immediately erect two temporary tents and post sufficient number of personnel of CISF in coordination with Police, who shall identify which person has to be allowed. Commandant, CISF shall also ensure that those allowed do not cause any hindrance for those who are supposed to function as per the Internal Action Plan.

Staff Attendance

From experience it is observed that several times many officials do not turn up for work under one or the other pretext. This would be viewed very seriously. Immediately on operationalising this Action Plan, even if, it is a Public Holiday, the following staff shall report for duty.

All Operational Staff particularly those of Floating craft Section and Power Supply Section.

All Head of Departments and all Class-I & Class-II Officers shall be present in their office timings. Besides, a list of very essential officers, who will be required to be present even beyond the normal duty hours, as and when required, shall be prepared.

All P.A.s/Stenographers/Peons of Head of Departments and Deputies.

All Office Superintendents/Superintendents (Accounts)

All Head Clerks and Divisional Accountants.

The above officials shall be present in the office, unless otherwise directed.

The Staff attendance on days when the Action Plan is in the operation shall be collected from P.A. to HODs and compiled by Asstt. Secretary (G). The daily position will be reported to Chairman/Dy. Chairman every day with separate list of absentees. Assistant Secretary (G) should ensure presence of staff by following the required action.

All Head of Departments may hold a meeting with Class-I, & Class-II and staffs and explain their functions as per the provisions of Action Plan during the Natural Calamity and submit a Compliance Report to Chairman/Dy. Chairman on priority basis.

The following officers will ensure timely supply of Drinking Water/Food Packets to the staff during the operation of the Action PLAN:

Asstt. Executive Engineer- For the staff of Traffic/Mech./Civil

Engineering Department

AFS- For the Flotilla Staff /SIGNAL STATION

Company Commander, CISF- CISF

FcSO- For Fire Brigade Staff

The above officers shall be responsible for placing order for procurement of Food Packets. They should ensure that there is no shortage on this account. They shall come in to action on their own. They are also responsible for placing advance order, preparation of food packets, transportation, and distribution in time and report compliance to Secretary for the previous day.

9.24 Sanction of Advance

All Head of Departments would make a judicious assessment regarding the requirement of funds by them to meet the different exigencies, which they may have to handle on account of the Natural Calamity situation. The HoDs would inform the FA&CAO on telephone or in writing or through a messenger regarding their requirement of advances. The FA&CAO in turn would examine the advances sought by the Head of Departments and sanction the advances early without any delay. The FA&CAO would keep the Chairman and Dy. Chairman informed about the amount released by him and seeks approval.

9.25 Vehicle Pool

As soon as this Action Plan comes into force, the vehicle pool stands formed; the vehicle pool shall be controlled by Senior Engineer (Pipeline) and Senior Labour Officer. The following vehicles will be there in the Pool:

All Ambulances Under CMO

9.26 Private Vehicles Buses { To be arranged by Labour Section}

9.26.1

List of Civil, Electrical & Mechanical Contractors

Sr. No	Name & Address of Contractor			
		Office	Resi	
1	Mr. Dilip Bhandbe, M/ Mukund Ltd.	223412		
2	M/s. Maheshwari Const. Co., SDX-N-5, Gandhidham-Kutch Mr. Rameshbhai	232134		
3	M/s. Apex Engineers, Bajaj Chambers, 12/B, Gandhidham – Kutch (Mr. Vishal)	222002 222223	—	9898226666
4	M/s. Gadhvi Constructions, Plot No.524, Sector – 5, Gandhidham – Kutch	235772	—	9426215258
5	M/s. Advance Builders Contractors, B-23, Apnanagar, Gandhidham – Kutch.		232864 234242	9825255934
6	M/s. Mohan Construction Co., 415, 2/B, Adipur (Mr. Mohan)	—	264140	9825174351
7	M/s. Star Decorators, 17, Plot No.5, 12/A, National Highway, Gandhidham – Kutch (Mr. Vinod Bajaj)	221450	—	—

8	M/s. Kamal P. Chellani, DBZ-S-81-A, GandhidhamKutch (Mr. Kamal)	_____	_____	9825221542
9	M/s. K.K.Construction, E-71, Gujarat Housing Society, Devi Krupa, Sector –5, Gandhidham (Mr. Milanbhai)			230064
10	M/s. Mepabhai Madan, Plot No. 21/22, Sector-9, Opp. KPT Office, Gandhidham Mr. Rajubhai	222209 222210		233627
11	M/s. S. B. Singh, B-110, Sapna Naga Gandhidham – Kutch	239351	_____	_____
12	M/s. Dipesh Construction Co., 11, Apurva Chambers, Ganga Gate, Anjar – Kutch. (Mr. Parth) (Mr. Sukhdevbhai)	242997	243319	9824294260 9825179040
13	M/s. Raj Construction Co., Deepak Complex, Plot No.315, Ward 12/B, Gandhidham-Kutch Mr. Rajesh Makhijani	220911		
14	M/s. M. V. Rajani,444, 2/B, Matruchhaya,Rambaugh Road, Adipur – Kutch (Mr. Narayan)	260800 262920	_____	9825225690

15	M/s. Bhimji Velji Sorathia, 21, Nilesh Park, Plot No.80, Sector – 8, Near New Court Building, Gandhidham – Kutch (Mr. Bhimji Velji)	231383	_____	9825225948
16	M/s. Sollone & Parco Engg. Co., CCX-165, Adipur – Kutch (Mr. Ravi Solanki)	261298 263248		9825222919
17	M/s. Mahesh Construction, Plot No. 415, 2/B, Adipur- Kutch (Mr. Mahesh)	_____	264140	9825091599
18	M/s. Patel Construction Co. Zanda Chowk, Gandhidham (Mr. Tejabhai Kangad)	220421	_____	9825227199
19	M/s. M. G. Bhavnani, Plot No.102, Sector 1/A, Gandhidham – Kutch	_____	_____	9825191636
20	M/s. Patel Engineering Works, Gandhidham	231832		
21	M/s. H.M.G. Gandhidham	235710 234609		
22	M/s. Mukund Limited Mumbai	022- 25347373		
23	M/s. Bajaj Electric Mumbai	022- 23724192		
24	M/s. Mishra Brothers Gandhidham			

		221172		
25	M/s. Sonu Electricals 18, K.P.Shopping Centre, Near Jivan Bharati School, Karelibaug, Vadodara-390018 Shri Jayendrasingh.B. Thakker	02652464108	2647886	
26	M/s. Ravi Electronics, "Prashant", 20, New Jagnath Rajkot – 360 001 Mr. G.K.Patel	465256 460 253		
27	M/s Megha Technicals, CCX - 165, Adipur - Kutch (Mr. Ravi Solanki)	261298 263248	—	9375320232
28	M/s Maruti Construction, Gandhidham – Kutch	—	—	9824893851
29	M/s Ramesh Meghji Sorathia, Anjar – Kutch	—	—	9825225948
30	M/s Mohit Construction, B-168, Shaktinagar, Gandhidham - Kutch	—	—	9825227072

Senior Engineer (Pipeline) should ensure the availability of the Drivers and the Vehicles and report to the Secretary. All Vehicles whether it is of KPT or hired should be parked in the location as decided by the Senior Engineer (PL) and Senior Labour Officer(PO), from where it can be taken for immediate use as soon as the people move into action. The list of travel agencies is given below:

9.26.2 The list of Travel Agencies

Sr. No.	Name of Agency	Phone No.	
01	M/s. Rathod Tours and Travels, Gandhidham	222444	222959
02	M/s. Gayatri Tourist, plot No. 720/721, Valmikinagar, Bharatnagar, Gandhidham.		231715 230252
03	M/s. Panch Tirth Tours, BBZ-S12, Gandhidham	232215 230760	9825234455
04	M/s. Maheshwari Travels, Plaza Centre, Shop No. 110, 1st floor, Plot No. 110, Sector No.8, Gandhidham	232211 234455	252120 253433
05	M/s. Titan Travels, Behind Shyam Electric Stores, Jhanda Chowk, Gandhidham	222832	236911
06	M/s. Rohit Enterprises, Plot No. 99, Sector No. 4, Near IOB, Gandhidham	228550 237538 237547	234140 9825225121
07	M/s. Jai Somnath Travels, Mr. Mishra		9727304414
08	M/s. Agrawal Tourists, Gandhidham	221311 220068	
09	M/s. Ashirwad Travels Gandhidham. Shri Laxma Singh	225608 225609	9825225608
10	M/s. Krishna Travels Gandhidham	220683 234838	
11	M/s. Shiv Tourists, Gandhidham	221454	

12	M/s. Thakker Gandhidham Travels,	225097	9825271072
----	----------------------------------	--------	------------

9.27 Contact with Railway & GSRTC

Secretary, Dy. Secretary (G) & Dy. Secretary (P) should ensure for the smooth movement of workers/employees for which he may get in touch with the following officers of Western Railway/GSRTC and apprise them about the situation so that the movement of Staff is not suffered.

Transport	Contact Person	Telephone Nos.	
		Office	Residence
Western Railway	Area Manager	221340	236237
	Control Room	232578	
	Enquiry	131/220011	
GSRTC, Anjar	Depot Manager	241192	243746
GSRTC, Bhuj	Depot Manager	220002/220102	
GSRTC, G'dham	Depot Manager	220198	

9.28 Generator Sets

Generators of following capacities have been installed at Kandla, Gandhidham, and Gopalpuri to supply power to various installations in case of power failure:

1. Cargo Jetty Area - 2 Nos of 1000 KVA EACH:

These Generators can cater power inside Cargo Jetty Area, Seva Sadan-III, Nirman Building, and Old C.D.C. Building restricted up to 2000 KVA.

2. Kandla Hospital - 25 KVA
3. A O Building- 200 KVA
4. Gopalpuri Hospital- 45 KVA
5. Guest House- 25 KVA
6. Old Kandla Fire Brigade- 5 KVA

In addition to above, if any additional Generator Sets are required at Kandla or Gopalpuri, the following officers shall be contacted who shall immediately hire/procure or provide in whatever manner the D.G. Sets giving preference to the operational area.

- (i) Deputy Chief Mechanical Engineer
- (ii) S E (Electrical)
- (iii) Executive Engineer (Mechanical)
- (iv) Asstt. Executive Engineer (Electrical) Shri AK Sharma

The above officers shall also be responsible for operation and maintenance of Generators provided at various locations and submits daily report to the Chief Mechanical Engineer about the working of Generators.

Additional requirement will be assessed by Dy CME/S.E (Electrical) and submitted to Chief Mechanical Engineer for approval. Necessary Fuel (POL) shall be procured and stored in advance by the concerned officials of Mechanical Engineering department.

9.29 Fire Dewatering Pumps

There are 10 Nos. of Dewatering Fire Pumps available with Fire-Cum-Safety Officer at various points. The details of which are as under:-

Dewatering Pump	Old Kandla Fire Station	Tilak Station (West Gate-I)	Fire Azad Station (West Gate -II)
-----------------	----------------------------	-----------------------------------	--

Portable Fire Pump Capacity:270 LPM	04	01	01
Trailer Fire Pump Capacity:1800 LPM	-	01	01
Trailer Fire Pump Capacity:2250 LPM	02	-	-

The Portable Fire Pump single delivery having capacity of 270 litre per minute are useful for dewatering the congested places like ship holds, barges and other intricate areas.

All the above Fire Pumps will be operated by the Fire-Cum-Safety-Officer. The maintenance of major nature and breakdown will be attended by Executive Engineer (Mechanical).

Fire cum Safety Officer(O) 270176 Mob: 98252-27041

Dy. Fire Officer (O) 270176/270178 (R) 226478

9.30 Shipping Navigational Aid Section

Executive Engineer (Dry -dock) shall ensure that heave-up barge "Bhimsen" is shifted to Bunder area and secured properly; Assistant Engineer (Mechanical) shall attend the above work.

Steel Floating Dry Dock

Executive Engineer (Dry Dock) and AE(DD) shall ensure that the Steel Floating Dry Dock and the Electric Wharf Cranes at the maintenance jetty are properly secured as per procedure and compliance reported to Chief Mechanical Engineer and Dy. Chief Mechanical Engineer shall monitor the safety of the Steel Floating Dry Dock.

9.31 Periodical Reporting by all HODS

All Head of Departments shall have to send Action Taken Report to the Secretary / Control Rooms in writing by Fax or through telephone with regard to the action taken by them as per the Action Plan. If the report is not received from the Head of Departments, the Officer In-charge, Control Room shall obtain the

information, compile it and submit the same to the Chairman / Dy. Chairman on 12 hourly basis i.e. twice a day.

9.31.1 Chief Engineer

The Chief Engineer shall ensure through Superintending Engineers that all Road Blockades are not cleared as also he should ensure that blockades caused in Port quarters due to the falling of trees, walls, sheds, etc. are got removed immediately. He will ensure that the colonies are got cleared and wherever logging of water is found, the water is pumped out and disinfected. A report shall be submitted to the Chairman / Dy. Chairman every day.

9.31.2 Chief Mechanical Engineer

Chief Mechanical Engineer, Dy. CME/S.E (E) shall ensure that all Generator Sets are properly functioning at A.O. Building, Seva Sadan-III, P&C Building, Hospitals, and Guest House. They will ensure quick restoration of Power supply arrangements by keeping close liaison with the officials of Pachim Gujarat Vija Co. Ltd. They will report to the Chairman / Dy. Chairman every day.

9.31.3 Action Plan – Land Fire Station

The Port Fire Brigade has its Head Quarter at Old Kandla Oil Jetty area with two Sub- Stations at Dry Cargo Jetty at New Kandla.

The contact Numbers are as under:

Main Station (Emergency Response Centre) - 270176, 270178, 271377

Cargo Jetty – West Gate No. 1- 270439

Cargo Jetty – West Gate No. II - 295974

Fire cum Safety Officer - 270176 (O))/ 98252 27041(M)

Dy. FcSO- 270178(O) / 226478 (R)

9.31.4 Resources Available

Refer 4.12 to 4.14.4

In case of any fire, or other crisis an information is received through telephone - or VHF channel - Fire Station Control Room, the Duty telephone attendant raises the fire alarm bell and lights the vehicle indicating light (turn-out bell and Turn out light)

The Duty Station Officer proceeds to the scene of fire with fire Tenders and crew. Station Telephone Attendant should inform other officers like Fire-cum-Safety Officer, Dy. Conservator and Port Control. Telephone Attendant should inform hospital and if fire is in wharf should inform Traffic Manager. Fire cum Safety Officer after apprising the situation should inform Deputy Conservator directly or through the Telephone Attendant immediately.

9.31.5 Ensuring the Functioning of Telephones

The name and telephone No. of the Officer Telephone Department to be contacted in case of any problem:

1. General Manager, Bhuj(O) 231201/231648 (R)
2. District Engineer, Bhuj(O) 525410
3. SDO(P), Gandhidham(O) 232453/229666 (R)

Dy. Secretary (Personnel) shall ensure that the telephone of all the Head of Departments and other responsible officers of different Departments are functioning properly by ringing personally. In case any of the telephones does not function or give satisfactory service, he shall take up the matter with the higher authorities immediately.

9.32 Accidents in the Channel

9.32.1 Fire on Board Tanker / Anchor / OTB

The Ship Master - Pilot should raise & alarm and inform Kandla Tower/SIGNAL STATION on VHF Channel 8 or 16 about the intensity and location of fire.

Kandla Tower will inform the Dy. Conservator, Harbour Master and FCSO. & TM

Master should immediately ensure that the loading/discharging operation is suspended and all the connected valves are closed.

Master of the vessel should immediately gear up his firefighting equipment and post his staff for extinguishing the fire. CO₂ should be injected in the affected compartments.

Dy. Conservator after contacting the ship will inform Chairman and Dy. Chairman about the situation.

Harbour Master, will arrange for availability of chemical dispersant and its equipments and keep them in readiness in case of any oil spillage.

TUGS, with personnel and equipments should immediately start for tanker. Harbour Master on board Tug also to reach the tanker.

Dy. Conservator to remain in constant touch with the Master/Pilot of the Tanker to assess the situation.

In case no power is available on deck, the floating hoses connected on board can be disconnected by means of mechanical puller. Hose can be heated up slightly and the weight can be taken off. The Special Clamps on the flange can be removed. This operation takes about 20 Meters for each hose.

If it found necessary to safeguard jetty and the tanker is required to be removed from the jetty, one tug should remain near to tow the tanker and when given orders should pick up the fire spring and take the weight off the moorings. Master and the Pilot should take due precautions and safety measures and by using Fireman's suits to send the personnel to forward of the vessel for unmooring the tanker. Two lines to be

passed on to the Tug for towing to a safe anchorage. In case, the magnitude of fire is more and beyond the control, other agencies such as Indian Coast Guard, ONGC to be called for assistance.

9.32.2 Grounding of a Tanker

Master or Pilot of the vessel should immediately contact Kandla Tower on VHF Channel 8 or 16 and give the detailed information and the seriousness of grounding. Kandla Tower Signal Station will in turn inform Traffic Manager, Dy. Conservator and Harbour Master, Kandla Port Trust. Dy. Conservator will inform Chairman/Dy. Chairman.

Harbour Master will immediately proceed to site and will immediately board the vessel and after assessing the situation will inform Dy. Conservator about the seriousness of the crisis.

Dy. Conservator in the meantime will remain at Kandla Tower and will be in constant touch with the vessel and if required give necessary guidance to Master/Pilot.

Dy. Conservator to direct Sr. Hydrographic Surveyor to proceed to grounded vessel and check the exact position of the ship and also the grounding around.

Tugs and Launches available at Kandla should remain in readiness and wait for the order of action from Dy. Conservator /Harbour Master.

Fire-Cum-Safety-Officer along with staff and equipment salvage pumps etc to remain on board fire float.

Master of vessel to obtain soundings of all the tanks and to maintain a record of the same to ensure any leakage. He should also take hand lead surroundings around the ship and plot them on the chart.

Master should inform his Chief Engineer to change over to high sea suction for cooling water.

If found necessary, Dy. Conservator can decide and ask for a small tanker/salvage tug which can be brought alongside of the grounded ship and part of cargo can be discharged to this daughter ship. This will help to lighten the grounded ship.

Master should instruct his staff to prepare all her ropes including insurance wire for towing, pulling operation.

Tug to immediately to proceed to grounded vessel and take towlines and start pulling the vessel under the instruction of Harbour Master. If required, Dy. Conservator can decide and send more than one Tug also to the grounded ship for assistance. In case the vessel cannot be re-floated within a day, a navigational warning should be sent to the Chief Hydrographer, Dehradun and the same will be transmitted through Mumbai Radio and Navtex.

9.32.3 Breaking / Ground of a Ship outside Kandla Port Limit

Kandla Port has not had any major incident of grounding/sinking or breaking of a ship in recent past. However, minor incidence of grounding could be tackled by Port's own personnel and equipments.

If there is any major breaking or grounding of a ship outside the limits of Kandla Port, the Port can activate its own crisis management plan to deal with the situation. On receiving message from the Master of the Vessel/ or from Principal Officer, MMD or Coast Guard, Mumbai, Dy. Conservator/Harbour Master, KPT will immediately inform Chairman/Dy. Chairman, Kandla Port Trust.

Harbour Master will instruct Flotilla Superintendent/Tug Master, Fire-Cum-Safety Officer to keep the tugs, launches in readiness. Crafts with chemical dispersant spraying system at Kandla and Vadinar should rig the booms etc, Store enough stock of chemical dispersant and stay in readiness. In case, there is any major oil spillage port to activate its oil spill crisis management plan.

Port Signal Station to be made Control Room and to remain in constant touch with the Ship. Master should immediately send messages and inform nearest Port or Coast Guard about the latest situation of the Ship.

Port command team headed by Dy. Conservator will mobilize the resources available with Port to help the Ship.

Indian Coast Guard, to utilize the services of Helicopter and indicate the location and magnitude of the oil spill. They should keep the nearest port informed about the oil spill/sleek.

If the oil slick is dangerous/approaching the limits of Kandla Port Trust, the Harbour Master along with one Senior Pilot and Safety Inspector (antipollution Scheme) to proceed on chemical dispersant Spraying craft and to reach oil slick and under his guidance all available port crafts can spray chemical dispersant. They can go up & down and try to stop/minimize the oil slick danger to port, Harbour Master to keep Dy. Conservator informed about the situation.

Indian Coast Guard, IOC, ONGC and other agencies who have the system to recover the floating oil should be directed with oil recovery vessel to the area.

If it is necessary, Dy. Conservator can requisition a privately owned small tanker or tank barge, which can recover the oil, store it for eventual disposal ashore. If the oil slick is very large and beyond the control of the Port, the Chairman should inform the Ministry and seek their guidance for mobilizing equipments from outside Parties.

STRENGTHENING DISASTER RISK GOVERNANCE

9.33 Contingency plans in grave situation

Immediately on the occurrence of a crisis, the local Internal Action Plan under the Disaster Management Act, 2005 would be put into effect by the local/District and the state authorities. If the situation has wider ramifications and warrants response at the State/National level, the Chairman/ Deputy Chairman will contact the Nodal Ministry of the State / Central Government and seek the required help. The concerned authorities would activate its control room, call for a meeting of the Crisis Management Group and put into operation its contingency Plan.

9.33.1 First Information

As and when a critical crisis situation develops, the first information would be sent by the Chairman/Deputy Chairman to the State/Central Nodal Ministry through Wireless/Cellular Mobile Phone/Fax/e-mail or any other quickest possible means.

Security measures at Vital Installations are inspected by I.B. periodically. The Deputy Conservator and Traffic Manager shall implement the recommendations of I.B. with the help of CISF, made from time to time for beefing up/strengthening the security at important vital installations.

9.33.2 Authorities responsible for sending of First Information

Crisis	Authorities responsible for reporting	Remarks
Natural Disasters	District Magistrate or District Collector Indian Meteorological Department State/Central Water Commission	Information relating to forecasting/warning of the natural calamity will be sent by the IMD, State/Central Water Commission to the Relief Commissioner as laid down in the contingency Action Plan of the State/Central Ministry.
Chemical/Biological/RADIO ACTIVE Disasters	Chairman / Deputy Chairman	The Chief of the Public Sector/Undertakings would be equally responsible to send the first information through his channel to the Nodal Ministry.
Major Disaster having off-site implications	Chairman/Deputy Chairman	
Break-down in Power Generation/Supply	Chief Mechanical Engineer and Executive Engineer (Electrical) through Gujarat Electricity Board Authority.	

An Installation	Oil	Chief or In-charge of the Oil Installation through his channel to the Nodal Ministry.	
Hijack of an Indian Merchant ship or Indian Crew in a Foreign ship		Chairman/Deputy Chairman	Commandant of CISF, Traffic Manager, Deputy Conservator would inform to Chairman/Deputy Chairman immediately.

9.33.3 List of Members NDMA

Contact Details of NDMA Officers

Name	Office	Fax	Mob.	E.mail id
Shri R K Jain, IAS (Retd), Member	011-26701710	011-26701716		secretary@ndma.gov.in

Sh. S K Gulati, PPS	011-26701711,	011-26701716		
Mr. D S Butola PA	011-26701713			-
Lt Gen (Retd) N C Marwah, PVSM, AVSM, Member	011-26701775	011-26701783		marwahnc.ndma@nic.in
Smt Seetha Mahesh, PS to Member	011-26701721	011-26701783		seetham.ndma@nic.in
Shri Vijaya Kumaran, PA to Member	011-26701782	011-26701783		
Dr. D N Sharma, Member	011-26701738	011-26701767		dnsharma@ndma.gov.in
Smt. Shashi A Kumar PSO to Member	011-26701761	011-26701767		
Shri Kamal Kishore, Member	011-26701740	011-26701754	9818143429	kkishore@ndma.gov.in
Shri Harish Kumar Arora PPS to Member	011-26701751	011-26701754	9910226153	
Shri Basudev Rajbhar PA to Member	011-26701753		8285642447	

JOINT SECRETARIES

Name	Office	Fax	Mob.	E.mail id
Shri B Pradhan, IAS, JS (Admin & Capacity Building and Training)	011-26701780	011-26701795		jsadm@ndma.gov.in b.pradhan@nic.in
M.Mushtaq, PPS	011-26701876			
Shri A.K.Sanghi,ITS JS (Mitigation, IT& Comn)	011-26701718	011-26701864		mitigation@ndma.gov.in
Shri Munendar Kumar, PA	011-26701720			
Maj Gen Anurag Gupta, Advisor (Ops)	011-26701886	011-26701742	8527892258	advopscomn@ndma.gov.in

Ms Archana, PA	011-26701267			
Ms. Mamta Kundra, Joint Secretary (Policy & Plan)(Additional Charge)	011-26701777	011- 26701816	09599946299	jspp@ndma.gov.in
Ms Indira, PA	011-26701747			
M.Sanjay Singh, PA	011-26701816		9899403773	

FINANCIAL ADVISOR

Name	Office	Fax	Mob.	E.mail id
Smt. Aastha S Khatwani, FA,	011-26701709	011-26701715		fa@ndma.gov.in
Sh. Bharat Bhushan, PPS	011-26701712			

JOINT ADVISORS

Name	Office	Resi	Mob.	E.mail id
Lt Col Vikrant Lakhanpal, JA (IT & Comn)	011- 26701743			jaitcomn@ndma.gov.in , vikrant.lakhanpal@ndma.gov.in
Col Ranbir Singh, JA (CBT)	011- 26701823			ranbir@ndma.gov.in
Vinay Kajla, JA (RR & NDRF)	011- 26701815			vinay.kajla@ndma.gov.in ,
Dhirendra Singh Sindhu, JA (OPS)	011- 26701218			dssindhu@ndma.gov.in
Sachida Nand Singh, JA(MP & P)	011- 26701798			jampp@ndma.gov.in
Alice Kujur, DIR (PP)	011- 26701722			-
S K Singh, Dir (Finance)	011- 26701778			
Yogeshwar Lal,	011- 26701833			

DS (Admin)				
Bhupinder Singh, DS (PR & AG)	011-26701878			

NCRMP

Name	Office	Fax	Mob.	E.mail id
Ms. Mamta Kundra Project Director	011-26701777 011-26714321			pd.ncrmp@gov.in
Shri S.S. Jain Dy. Project Director	011-26701792			dpd.ncrmp@gov.in
Shri Ashok Kumar Sarkar, Project Accountant cum Admn. Officer	011-26701744			adm.ncrmp@gov.in

NDMA CONTROL ROOM

Name	Office	Fax	Mob.	E.mail id
Control Room	011-26701728 011-1078	011-26701729	9868891801 9868101885	controlroom@ndma.gov.in , ndmacontrolroom@gmail.com ,

10 PRESS MANAGEMENT

A Cell shall be created and headed by TP&PRO. The following staff member shall remain in the Press Cell.

(1) Dy. Secretary. (P) (2) PRA (3) Sr. Clerk (BDC) (4) Photographer

The Press Room shall come into operation immediately in the chamber of BDC. The Press Cell shall issue Daily Bulletin at 2:00pm and 07:00pm every day. The photographer should collect photos and develop every day, which will depict the situation as well as the work done by the Officers. P.R.A will accompany the photographer and bring the photos to the Cell every evening. He shall also bring daily Paper cuttings of reports. All Media people, Press, Journalists, etc. shall be attended to by the Dy. Secretary (P).

BDC Section will hire videographers and keep them standby for videography. They will accompany Chairman and Dy. Chairman also. One videographer will be placed at Kandla and another at Gandhidham. Similarly, BDC section will also ensure to keep one additional photographer at Kandla for taking photographs and these people should be hired as soon as Signal No. 5 is hoisted.

Secretary will be the overall In-charge of Liaison work with the Central / State Government officials / IMD, Ahmadabad / Pune Laboratory / Delhi Laboratory in which he can take the help of Dy. Secretary (P), Assistant Secretary (P) and report the matter to Chairman / Dy. Chairman immediately. They shall remain present in all the meetings relating to the Action Plan and report the proceedings of the Meeting to the Chairman/Dy. Chairman. They shall also communicate the action to be taken to the concerned Head of Departments. List of IMD Telephone is given below:

10.1 Important Telephone Numbers of Indian Meteorological Department Ahmedabad

Director Incharge,
Meteorological Centre,
RS/RW building
Airport colony
Ahmedabad, - 382745

Phone - Weather enquiry : (i) Interactive voice response system : 1800 180 1717



 (ii) Duty Officer (AMO) : 22861413

The OSD (Estate), Land Section and, Asstt. Estate Manager should ring up major salt leaseholders and advising them to evacuate their labourers and report the action to the Chairman within two hours. Action taken should be confirmed in writing thereafter, Dy. Secretary (G) will guide them and will do the overall supervision of this job.

Librarian shall ring up all the private/public sector companies of the area and inform them about their situation and tell them to evacuate their people and take necessary steps. List of private/public sector companies is as shown in Point No:

9.17.3.2

Senior Labour Officer, Labour Officer along with Executive Engineer (R) and Headmasters of BVM School shall ensure that temporary evacuation centers are established in the school/community center of Gandhidham-Kandla area.

11.1.1 List of Schools in Gandhidham – Kandla Complex

Sr. No.	Name of School	Contact Person	Telephone No.
1	Dr. C. G. High School	Principal	220271
2	SVP Gujarat Vidhyalaya	Principal	220242
3	M.P. Patel Kanya Vidhyalaya	Principal	220705
4	Adarsh Maha Vidhyalaya	Principal	234172
5	Adarsh Kanya Vidhyalaya	Principal	220175
6	Bhartiya Vidhya Mandir, Kandla Bhartiya Vidhya Mandir, Gopalpuri	Head Master Head Master	271049 233684
7	Central School, (IFFCO)	Principal	221288
8	Central School (Railway)	Principal	220657
9	Modern School	Principal	220284
10	Mount Carmel School	Principal	234262
11	Aum Vidhyalaya, IFFCO	Principal	221104
12	Saint Xavier's School, Adipur	Principal	260265
13	Maitri Maha Vidhyala, Adipur	Principal	260445
14	Maitri Kanya Vidhyalaya, Adipur	Principal	260612

15	Model Excelsior High School, Adipur	Principal	260707
16	Gujarat Vidhyalaya, Adipur	Principal	261312
17	Nagarpalika High School, Anjar	Principal	242510
18	Adarsh Nivasi School, Gandhidham	Principal	223246
19	P.N.Amersey School	Principal	223646
20	Shree Gurunanak English School	Principal	238421
21	Swaminarayan Gurukul	Principal	228098
22	Kairali English School	Principal	221050
23	Sarvodaya Pradhamic Shala Near Oslo Cinema, Gandhidham	Mr. Kangodia	227958
24	Ganeshnagar Pr.Shala, G'nagar	Mr. Kangodia	
25	Jagjivan Pra. Shala, Sapnanagar, Gandhidham	Mr. Kangodia	
26	Cargo Pra. Shala, Sapnanagar, Gandhidham	Mr. Kangodia	
27	Old & New Sunderpuri Schools	Mr. Srimali, HM	224867
28	G'dham Pr. Shala, Near Shivaji Park, Gandhidham	Mrs. Arunaben.	229255
29	Adipur Prathmic Shala, Adipur	Mr.C.M.Rami	264525 264181
30	Kandla Pr. Shala, Shirva Camp & Thermal Colony & United Salt Works	Mrs. Shantaben	253198

Dy. Secretary (P) shall ensure that the telephone of all the Head of Departments and other responsible officers of different Department are functioning properly by ringing personally. In case of any of the telephone does not function or gives satisfactory service; he shall take up the matter with the Higher Authority of Telephone Department.

The staff attendance on days when the Action Plan is in operation shall be collected from PA to HoDs and complied by Asstt. Secretary and reported to Chairman/Dy. Chairman every day with separate list of

absentees. Secretary will do the overall supervision of the work and report compliance to the Chairman/Dy. Chairman within two hours of the warning received.

Secretary will be the overall in charge for liaison work with central/state government officials/IMD, Ahmadabad/Pune Laboratory/ Delhi Laboratory in which he can take the help of Dy. Secretary (P) and Dy. Hydraulic Engineer and report the matter to the Chairman/Dy. Chairman immediately. They shall remain present in all the meetings relating to the Action Plan and report the proceedings of the meetings to the Chairman/Dy. Chairman. They shall also communicate the action to be taken to the concerned Head of Departments. List of IMD telephone numbers is shown below:

11.1.2 List of Important Telephone Nos of Indian Meteorological Department

Websites – www.imd.gov.in, <http://www.imdahm.gov.in/index.html>

All Head of Department shall have to send Action taken report to the Secretary/Control rooms in writing by fax or on telephone with regard to the action required of them as per the Action Plan. If the report is not received from any of the HoDs, the Officer In charge, Control Room shall obtain the information, compile it and submit the same to the Chairman/Dy. Chairman on 12 hourly bases i.e. twice a day.

11.2 Contacts of Officials of GAD following nodal officer will form a team

Sr. No.	Designation	Present incumbent	Contact Telephone Numbers		
	Mr Bimal Kumar Jha	Secretary	220167	231939	233172
01	Mr. Suresh Balan	Dy. Secy (G)	221375	236086	
02	Mr. DEEPAK RANE	Sr. Dy. Secy	220033	234730	

11.3 Duty Roster for Staff of General Administrative Department

AS ABOVE

11.4 Central Industrial Security Force (CIF)

The Sr. Commandant shall remain in contact with in charge of control room at Kandla (HARBOUR Master) regarding the position of the cyclone / calamity.

The Sr. Commandant shall ensure that Public Address System is fitted on Jeeps provided to CISF. He will make arrangements for announcements, with the coordination of police through Public Address System mounted on at least 03 vehicles. The CISF personnel will procure truck with the help of TM. The list of fleet owners and major lift operators are given below:

11.4.1 List of Major Heavy Lift Operators at KPT

Name of Party	Name of Contact Person	Phone Number
Swastik Heavy Lifters	Mr. Jigneshbhai Mr. Aslambhai	9825758151 9825228421
Kutch Carrier Transport Co	Mr. C. R. Thackar	9825225591
Agarwal Handling Agency	Mr. Rakesh Thackar	9426928728
Active Cargo Movers	Mr. Narendra	9825220411
Raghuvirsingh & Sons	Mr. Harcharan	9879104853
Thacker Brothers	Mr. Kamleshbhai	9825296107
Kiran Roadlines	Mr. Pankaj Gadvi	9879104552
Regal Shipping	Mr. Ashok Dudi	9825326328
Rathore Freight Carriers		220759/ 220380

11.4.1.1 Additional list of firms for pay loaders / cranes

M/s Mahalaxmi Transport Co., Plot No. 35, Sector No. 8, Behind Hotel Fun & Food, Gandhidham	Mr. H K Rathod	(O)222387 (R)233500
M/s Kandla Earth Mover, DBZ-S-151, Gandhidham	Mr. Sanjay Goyal	(O)221759 (R)222338 (M) 9825020550

Mr. Lalji Bhavanji Sathwara, Laljibhai Sathwara, Plot No. 27, Shop No.5, Sector9/A, Gandhidham		(O)234118 (R)232566 (M) 9825225957
--	--	--

11.4.1.2 Equipments available with ABGKCTL TABE REMOVED

11.4.2 List of Fleet Owners at KPT

Sl. No.	Name of Company	Contact Person	Tel. Office	Tel. Resi.	Mobile
01	M/s A V Joshi & Company	Mr. Ramesh Singhvi Mr. Thacker MR. Harshandhu	231386 232605 233147	234176 221451 234325	98251 91325 98252 26105 98252 26013
02	M/s Rishi Shipping	Mr. B. K. Manshukhani Mr. Manoj Manshukhani	220843 229830 238943	234889 235587	98252 25170
03	M/s Maheshwari Handling Agency	Mr. C. P. Maheshwari Mr. Chandan Maheshwari	223228 230393	222339	98252 27111
04	M/s ABC	Mr. Latif Mr. Mithu Mr. Kasam	220483 221390 270190	234163 231477 251684	98252 26707
05	M/s Ganesh Transport	Mr. Hira Rabari Mr. Visa Rabari	223638 223915	260425	
06	M/s Kewar Carrier		220483 227553	234163	

07	M/s Krishna Transport Service	Mr. K. M. Thakker Mr. Pankaj Thacker	223814 224938	220998 234988	98250 19699 98252 25228
08	M/s Gautam Freight Ltd	Mr. Ramesh Singhvi	220163 230345	230328 234176	98251 91325

11.5 Contact Nos of CISF Officials

S. No	Designation	Contact Telephone Numbers		
		Office	Res	Mobile
01	Commandant	271037	229140	9825227282
02	Dy. Commandant	271036	220192	9825227045
03	INSPECTORS			8500495813, 9045696584
04	Control Room	271040		
05	North Gate	270440		
06.	West Gate – I	271039		
07.	West Gate II	270876		

11.6 Finance Department

As soon as the Calamity/Cyclone warning Signal No. 5 is hoisted the Dy. Director (EDP) should monitor it through Internet and give two hourly printouts to Dy. Conservator, Secretary, Chief Engineer, FA&CAO, Dy. Chairman and Chairman. And Dy. Director (EDP) will monitor the website in the A O Building, Gandhidham.

All Head of Departments would make a judicious assessment regarding the requirement of funds by them to meet with the different exigencies, which they may have to handle on account of the Cyclone/Calamity situation. The Head of Departments would inform the FA&CAO on telephone or in writing or through a Messenger regarding the requirement of advances. The FA&CAO in turn would examine the advances

sought by the Head of Departments and sanction the advances early without any further delay. The FA&CAO would keep the Chairman and Dy. Chairman informed about the amount released by him and seeks approval.

11.7 Medical Department

Two Casualty Emergency Wards, one at Gopalpuri and other at Kandla Hospital shall start functioning as soon as warning of Cyclone is received. Chief Medical Officer will ensure that no Doctor is given leave during the emergency period. These casualty emergency wards will function round the clock with posting of Doctors and Staff round the clock. Chief Medical Officer will ensure the functioning of casualty emergency wards at Gopalpuri and Kandla. A Register shall be maintained at both the places where in the record of patients attended would be maintained. Adequate number of chlorine pills should be distributed after Cyclone to avoid epidemic from spreading. Chief Medical Officer shall submit a report every evening to Chairman/Dy. Chairman.

11.8 During Disaster

1. Maximum alertness of staff members for their safety.
2. Ambulances/vehicles with Drivers to be kept standby awaiting further orders.
3. Liaison with: - Control Room, Disaster Site/Spot, P.A.s to all HoDs, New Kandla Hospital.

(Action: P.A. to CMO)

11.9 Post Disaster Phase

11.9.1 Tackling of Patients

1. Use of ambulance will be purely on priority basis. The A.C. Ambulance can be used as an Emergency Mobile Van for carrying medicines along with a doctor and other essential Para-medical staff, to the site of crisis.

(Action: Dr. Sunil Suryavanshi)

2. Line of treatment to be decided by attending Doctors, such as Indoor/Outdoor/Under observation etc.

(Action: All Doctors)

3. Cases will be attended depending upon the gravity of injury/condition of case, i.e. very serious, stable. (Action: All Doctors)
4. To ensure supply of adequate medicines and any other items. (Action: AMO Stores / S P S K)
5. Dead bodies to be shifted to Govt. Hospital, Rambaug promptly for identification, disposal, and issue of death certificate etc.

(Action: Mamlatdar/PSI/Medical Supdt. Rambaug Hospital/PA to CMO)

6. If needed be, liaison with local Medical Practitioners, Local Hospitals, etc. (Action: P. A. to CMO.)
7. If need be, to arrange for outside ambulance, in consultation with FA&CAO to whom details have been submitted earlier.

(Action: P. A. to CMO.)

8. Transfer of serious patients to Govt. Hospital/Private hospitals , Bhuj/ Rajkot/ Jamnagar be made but such transfer to be restricted.

(Action: All Doctors on approval by CMO)

9. To mobilize additional nursing /Para-medical staff to cope with additional workload.

(Action: CMO PA to CMO)

10. Re-deployment of Manpower from Gopalpuri Port Hospital to Kandla Hospital and vice versa.

(Action: C.M.O.)

11.10 Prevention of Epidemics

1. Chlorination of drinking water at source. (Action: Sr. Engr. (P/L) & Estate office In-charge)
2. Mass Survey of residents of Port Colonies at Kandla and adjoining areas. (Action: Dr. Malik & Volunteers)

3. To get chlorine tablets from DHO-Bhuj and arrange for distribution thereof. (Action: Dr. S. B. Suryavanshi and Volunteers)

4. To educate residents/public to promote hygienic condition in and around their dwelling place, use boiled water

(Action: C.M.O. and Volunteers)

5. To shift cases afflicted by contagious or infectious diseases to Govt. Hospital / Private hospitals and notify such cases to the notice of State Authorities.

(Action: C.M.O.)

6. To ensure hygienic condition/cleanliness in both hospitals and colony in coordination with concerned staff of respective Estate Office.

(Action: Dr. Suryavanshi & Dr. Malik with in charges of respective Estate Officers)

7. In Rehabilitation Centre, Medical care will be looked after by Dr. Mahesh P Bapat & AMO besides supply of Chlorine Tablets.

8. To provide on the spot medical-aid at New/Old Kandla Port colonies. (Action: SMO In

9. Antidotes of all the poisonous gases to be kept ready. (M.O. (P)/Safety Officers/AMO)

10. Any further actions depending upon the conditions and restoration in the matter being decided by Administration.

11. Re-deployment on services as mentioned before.

12. In life threatening condition of Staff members - their evacuation.

11.11 Marine Department

As soon as warning of Cyclone Signal No. 5 or above is received, following measures shall be taken:

- Setting up of Control Room at Signal Station.
- Pilots and other Supervisory personnel in Flotilla Section should reach Kandla even if they are on leave, to tackle emergency, if any.
- Evacuation of Ships and securing all Port Crafts at Shortest possible time.
- Essential Staff (Fire Brigade) will not be given any kind of leave.
- The following personnel of Marine Department will not be granted any leave and they shall report for duty including holidays, during such time when Action Plan is put into operation.

⇒ All Operational Staff in Flotilla Section and Signal Station.

⇒ Ministerial Personnel at Point No: 11.11.1

11.11.1 Particulars of the Action Plan Committee Members

- For dewatering, if required, Fire-Cum-Safety-Officer will make arrangements by operating the dewatering Fire Pumps available with him.

11.12 Ships

- All the Pilots of the Port should reach Kandla immediately in case of emergency.
- Dy. Conservator/Harbour Master/Pilots should be available at Kandla during emergency.
- Removal of vessels whenever the cyclone is located in close proximity to the danger line plotted between 65 degree E longitude 18.2 degree N latitude and 73 degree E longitude 18.2 degree N latitude. Map showing the above position is given at Annexure-XXX.

Under such a situation the ships shall be removed during 1st/next available tide. It will be the duty of Harbour Master and DC to ensure that the ships are removed during 1st/next available tide as soon as the storm reaches to close proximity to the danger line as defined above without seeking any further instruction from the higher authorities. This action shall be taken automatically and suo-moto without any confusion and for which purpose Traffic Manager shall stop all loading and unloading operations immediately upon instructions from Dy. Conservator, so as to enable him to remove the vessels in time. The removal shall be done with the help of all the available Pilots plus all empanelled Pilots together at one go in the shortest possible time, so as to ensure that all the vessels cross the bar before the tide restriction sets in.

Dy. Conservator shall ensure that all ships are moved out of the Harbour at the earliest. All pilots shall immediately report at Kandla and stay there till the Action Plan is in operation. Dy. Conservator/Harbour Master shall immediately plan removal of vessels to the OTB as soon as the Action Plan is put into operation irrespective of the Single number, which must be hoisted. If, it is impossible to remove them, all other steps should be taken to ensure safety of the vessels at the Port as also it would not cause any damage to the Port. Dy. Conservator shall also ensure adequate stock of fuel for all crafts.

11.13 Securing of all Crafts

Dy. Conservator /Harbour Master shall immediately arrange for securing all the Port Crafts at safer places, so that there is no loss to the Port and send a report to the Chairman/Dy. Chairman as early as possible after operation of this Action Plan. Flotilla Supdt. (Mr. I. D. Bhagchandani) shall be overall in charge of each craft for ensuring their safety.

For parking of crafts in emergency, three places are mainly identified, viz. Bunder Basin, Launch Jetty and Maintenance Jetty as per:

11.13.1 Placement of Port Crafts on Cyclone Warning

(A)	Shipping Tugs	All 35 BP tugs and Hired tugs	Bunder Area
			Maintenance Jetty (West side)
(B)	Pilot Launches & Survey Launches	All Launches	Floating Crafts Jetty Inside area
			Bunder Basin
			Inside Bunder Area North

			Side.
(C)	G.S. Launches & Mooring Launches	M. L. Mrinal	Inside Bunder Area North Side on Pilot Launches
		M.L. Vaishali M L Alli M L Thamrai	Inner Side of Floating Craft Jetty
		M. L. Vijay M. L. Priyadashani PL Prahari, Rakshak	Inside Bunder Area North on G. S. and Pilot Launches.

Maximum number of crafts such as mooring launches, GS launches and pilot launches will be placed in Bunder Basin.

In the inner side of Passenger Jetty, one pilot launch and one G S launch will be kept.

Three tugs will be kept in the inner side of maintenance jetty.

Priority will be given to the Port crafts for parking in the bunder basin and other areas. Rest of the places available in the Northern side of bunder basin area will be allowed to the self propelled barges and private crafts. Dumb barges will be allowed on the beach between maintenance jetty and oil jetty area.

BS will render all possible assistance to FS, being the overall in charge of the crafts. The following flotilla staff will take care of the crafts.

11.13.2 Flotilla Staff Will be decided by FS as per available team with mooring crew

11.14 Private Barges / Crafts

The parties who have been Harbour Crafts License by the DC have to keep their barges and crafts inside the port limits being earmarked for the purpose.

Necessary instructions shall be issued to all these people having valid license immediately. The work of informing these parties will be carried out by the Office Supdt. of Dy. Conservator's office and will personally ensure that the instructions are carried out and reported to Harbour Master within two hours of the Action Plan coming into operation. The representatives of the above parties shall reach Kandla at once, failing which the Dy. Conservator will cancel the license granted to them and take over the barges/crafts of the party who violates the instructions.

The position shall be appraised to Chairman / Dy. Chairman within two hours of the receipt of warning and at frequent intervals.

11.14.1 List of Duty Roster of Marine Department (Ministerial Staff)

Sr No	Name	Office	Residence / Mobile
01	PA to DC	220235	9428032483
02	Mr. AR Jadeja, Signal Supdt	270549	9825427400
03	Office Supdt.	221971	
04	Assistant	221971	
05	Sr. Clerk	221971	
06	Messenger	221971	

11.14.2 List of Telephone Nos & Addresses of DC, HM & Pilots

Sr No	Name of Officer / Pilots	Address of Gandhidham Res	Tel Nos: Cell / Landline
01	Capt T Srinivas DC	A – 7, Gopalpuri	9825232982 232806
02	Shri S K Pathak HM	C – 32, Gopalpuri	9825803499 231310
04			
05	Capt A K Sharma Pilot	C – 40, Gopalpuri	9879603642 238154
06	Capt V Madaan, Pilot	C – 31, Gopalpuri	9879603643 221478
07	ALL AVAILABLE CONTRACT PILOTS WILL BE CONTACTED THROUGH SIGNAL STATION		
08			
09			
10			
11			
12			
13			
14			
15			
16			

11.14.3 Contract / Empanelled Pilots WILL BE CONTACTED BY SIGNAL STATION

11.14.4 Sections

1. Flotilla Section 270280

,

Mr. Sunil Kumar	Flotilla Supdt.	270280	226121		7874627756
-----------------	-----------------	--------	--------	--	------------

2. Signal Station 270549/270194/9825227246 Fax 270624

3. Fire Station 270176/270178/270439/550421/271244/271377

In case of Natural Calamity, first start with rescue operations, restoration activities on war footing on the advice of Chairman/Dy. Chairman, Dy. Conservator/ Harbour Master/Fire-Cum-Safety-Officer/Flotilla Supdt as the case may be.

11.15 Traffic Department

After, the warning of Cyclone or any other Natural calamity is issued at the Port, Traffic Manager shall ensure that the loading/unloading operations at the Port are stopped immediately, hatches closed, ships derricks properly secured and all labourers evacuated from the Port Area. Public Address System shall be installed at the Cargo Jetty Area, which shall be under the charge of Traffic Manager. He shall use it for necessary arrangements relating to evacuation. Traffic Manager should also ensure that responsible persons make announcements in a proper way, so as not to create any misunderstanding/panic.

Notwithstanding above, Traffic Manager shall stop all loading and unloading operations immediately upon instructions from Dy. Conservator, so as to enable the latter to remove the vessels in time.

The responsibility of evacuating the Port Shore Workers and Private Shore Labourers rest with Traffic Manager. He along with, Dy. Traffic Manager, Mr. Gulrajani, Safety Officer and Dy. Commandant, CISF should ensure that the Port is completely evacuated and there is no fresh entry in the Custom bounded area. Dy. Traffic Manager should get in touch with the Main Contractors in the regard.

Traffic Manager shall render necessary help to procure requisite number of Trucks for Public Announcement and evacuation.

Traffic Manager shall inform all the Stevedores List given below:

11.15.1 List of Stevedores

Sr. No.	Name	Address	Fax No.	Telephone Nos.	
				Office	Resi.
1	M/s. Cargo Movers	"Cargo House" BBZS-32A, Gandhidham	231687	220453 231365	261280

2	M/s. DBC & Sons (P) Ltd.	Seva Sadan-II, Room No. 303 / 304, New Kandla	270631	270503 270263 270348	-
3	M/s. A.V.Joshi & Co.	Plot No. 18, Sector-8, Maitry Bhavan, Nr. Post Office, Gandhidham – Kutch	233924	231070 232227 231588	234909
4	M/s. Agarwal Handling Agencies	DBZ-N-47, Gandhidham – Kutch	232749	220282 233187	232749
5	M/s. ACT Shipping P. Ltd	Seva Sadan-II, Room No. 206/207, New	232175	270111 270112 270015 229967	261308 231416

		Kandla			
6	M/s. Cargo Carriers	214/215, Rishab Corner, Plot 93, Sector- 8, GIM	230030	220816 231649 230030	231694
7	M/s. Cargo Clearing Agency (Gujarat)	Plot No. 271, Ward 12-B, Gandhidham	233034	221721 220655	231452
8	M/s. Chotalal Premji Stevedores Pvt. Ltd	C-8, Shaktinagar, GIM	231509	270009	-
9	M/s. Hiralal Maganlal & Co.	C-11, GIDC Area, Gandhidham – Kutch	223914	223914 231832	223878 232430
10	M/s. New Dholera Shipping Company	Goyal Commerce Centre Building - 1, Plot No.259, Ward 12B, Gandhidham - Kutch	-	222637 232267	237284
11	M/s. J.M. Baxi & Co.	Seva Sadan – II, Room No. 301 / 306, New Kandla	270646	270630 270550 270448	260427
12	M/s. Pestonjee Bhicajee (Kutch)	Seva Sadan-II, 203, New Kandla	270650 270556	270257 270367	262914

13	M/s. OTA Kandla Pvt. Ltd.	BBZ-N-324, Gandhidham	223241	220145 270560	223241
14	M/s. Purshotam das Jeramdas & Co.	5, Vaswani Chamber, 16, Sector-8, GIM	222850	238242 222598	220598
15	M/s. R. Tulsidas & Co.	Ahit Building , Plot No.323, Gandhidham – Kutch	232308	222717 221943	-
16	M/s. Robinsons	101 / 102, Maritime House, Plot No.45, Sector – 9A, Gandhidham – Kutch	234394	221578 223836	231767
17	Rishi Shipping	Plot 50, Sector 1/A GIM	238943	229830 229831	
18	M/s. Vinsons	BBZ-S-25, Gandhidham – Kutch	231948	220466	222395 239460
19.	Sical Logistics Ltd	403, 4th Floor, Madhuban Compex, OSLO, GIM	234416	234646 234194	
20	Parekh Marine Agency	C-8, Shaktinagar GIM	231509	229297 221158	

21	Krishna Shipping and Allied Services	Transport Nagar, NH GIM	233135	230501 223814 229085	
22	Kevar Carrier Handling & Transport	Shop 24, Tolani Chamber, Sector –8,GIM	228298	228298	
23	Trinity Shipping & Allied Industries	Trinity House, Plot 46 Sec 1/A, GIM	232060	230911 230910	

24	Velji P & Sons(P) Ltd	2nd Floor, Deepak Compex, 315, 12/B GIM	236168	231545 231546 225466	
25	Asean Marine Services	Ashit Bldg, Plot 33 Sector 1/A, GIM	232308	222717 221943 222145	
26	Rishikiran Roadlines	Kiran House, Plot 8 Sector 8, GIM	231422	231894 234108	
27	Universal Shipping Services	Hotel Sea Bird, Plot 173, Sector 1/A,GIM	235251	230663 226050 226037	
28	R.T.Bhojwa ni &Sons	DBZ –S- 146, GIM	232423	222211 221831	
29	Logistic Enterprises (P) Ltd	C-8, Shaktinagar, GIM	231509	235341 230587	

30	Seaways Shipping (P) Ltd	2nd Floor, Plot 351 Ward 12/B, GIM		226183 237147	
31	Seacrest Shipping Services Pvt. Ltd	216, 2nd Floor Om Corner, Plot 336 Ward 12/B, GIM	227028	233325	
32	Shree Maruti Shipping Services	18/21, Swaminarayan Bldg, Sector 9, GIM	234107 250690	233245 237247 250690	
33	Liladhar Pasoo Forwarders P.Ltd	Plot 4, Sector –1 KASEZ, GIM	252383 253506	252286 252297 252612	
34	Shree Radhey Shipping Company	14-16/C, GF Green Park, GIM	232967	222919 228919 238883	
35	Pearl Shipping	220, Rishab Corner, Plot 93, Sector 8 GIM	235570	225283 225284	
36	Patel Shipping Agency	Patel Avenue, Floor 2, Plot 170, Sector 1/A, GIM	231143	224024	
37	Ashirvad Shipping	18-21, Swaminarayan Bldg, Sector- 9, GIM	250690	233245 237247 222822	

38.	M/s. Swaminara yan Vijay Trade Carriar	1st Floor, H-6, Op. Tejas Society, Ghatlodia, Ahmadabad	079- 231983	231981, 231982	
-----	--	--	----------------	-------------------	--

11.16 Mechanical Engineering Department

- Marine Engineer/Engineer In charge should be available in emergency cell and remain in constant touch with Chief Mechanical Engineer/Signal Station and Assistant Engineers posted on Shipping Tugs.
- All Assistant Engineers (D/T & F/C) should be available on operational tugs irrespective of their duties. They should keep main engines and associated equipment in readiness all the times.
- Assistant Engineers posted in tugs should contact Superintending Engineer (Mech)/ Engineer In-charge for all technical & personal problems.
- Assistant Engineer (F/C) will be responsible for timely supply of food packets and drinking water to officers and staff of tugs.
- SE (Electrical) will be responsible for Securing Cranes at Cargo Jetty. He may, if need be inform about requirement of advance and to draw accordingly. He will be responsible to run 2 X 1000 KVA Generator Sets at Cargo Jetty Area in case of Power failure and also maintain additional Generator sets required at Kandla/Gopalpuri and Attending work of maintenance of major nature and breakdown.
- Asstt. Executive Engineer (Mech.) and JE (Mech) will be responsible for timely supply of Drinking Water/Food Packets to the staff of Mechanical Engineering Department during operation of the action plan.
- Assistant Engineer (Mech.) will be responsible to attend breakdown of Fire Fighting Pumps and DG Sets of 2 X 1000 KVA at Kandla.
- Steel Floating Dry Dock and one Electric Wharf Crane at maintenance jetty and one crane at bunder area are to be properly secured by Executive Engineer (Dry Dock) with help of his team mentioned below, as per prescribed procedure and concerned officers shall constantly monitor the safety of the

Steel Floating Dry Dock and Electric Wharf Cranes in side Bunder Area. He shall ensure all the required wedges, wire ropes, shackles etc.. and other fixtures as required to be kept ready so that the same can be fixed without loss of time & to check the site for the requirement, from time to time.

Action: XEN (DD) and Asstt. Engineer (FC) will lead the team of JE(Mech) and will be in contact with Executive Engineer (Mech) and Chief Mechanical Engineer/Deputy Chief Mechanical Engineer.

- All the V.H.F. and other Wireless Sets, and other required equipments of VHF Unit, including the sets kept at S.F.D.D. should be kept in perfectly working condition and the batteries are fully charged and to be kept in ready position and staff will remain in touch with control room till the emergency is called off to attend all communication equipments. It shall be responsibility of the Control Room Staff to ensure that timely information is passed on and timely and proper monitoring is done.

Action:, Assistant Engineer (DD) and R./R. Technician will render all possible assistance to Ex. Engineer(DD) during the course of calamity period.

- All the vehicles belonging to the Mechanical Engineering Department to be kept in perfectly working condition and sufficient stock of fuel and lubricant to be kept in ready position.

Action: Assistant Engineer (Mech.) with the help of Junior Engineer (Mech.) Garage

- During the course of calamity all the vehicles lying inside the premises of Auto Workshop should be kept in the parking ways meant for parking the individual vehicles and inside the shed. No vehicle is to be parked under any tree or under any such structure where there is possibility of falling such structure or tree over the vehicles. All the concerned drivers to be informed accordingly well advance to avoid such possible damage to vehicles and to remain present at duty place in consultation, Vehicle –in-charge of Pipeline Division.

Action: Assistant Engineer (Mech) with the help of Junior Engineer (Mech) Garage.

- Record of attendance of the employees during these periods to be kept ready and to be fed to the Control Room or any official responsible for such duties.

Action: Assistant Executive Engineer (Mech), Assistant Engineer (Mech) with the help of Head Clerk (Mechanical Division) and Divisional Accountant for all sections.

- Assistant Engineer (DD) to remain in Control Room at New Kandla to attend the communications with help of R/R Technician.

- Assistant Executive Engineer (Mech) and, Assistant Engineer (Mech) are to be associated with Executive Engineer (M) to constantly monitor the safety of the Port Crafts.
- The heave up water barge "BHIMSEN" is shifted to Bunder Area and secured properly in Naval Aid Salvage Section and Floating Craft. Absent/Present report of the above staff will be reported to the concerned section immediately on

starting of each shift and maintenance of major and breakdown etc... Action: Mr. Manohar Dana, Assistant Engineer (Mech)

- All the telephones and intercom telephones and their allied communication systems and equipments should be kept in perfect working condition to ensure that timely information is passed on and timely and proper monitoring done till the emergency is called off. He will ensure quick restoration of telephones by keeping close liaison with the concerned personnel. He will report to the Executive Engineer (Electrical) every day and to carry out all work assigned by the Executive Engineer (E) in case of emergency.

Action: Assistant Engineer (Instru).

- SE (E) and Executive Engineer (E) shall be responsible for liaison with the PGVCL for receiving power in case of power failure. In the event of disturbance in the distribution network necessary arrangements shall be made by them as per the requirement depending upon the situation.
- If any additional Generator Sets are required at Kandla or Gopalpuri, the following officers shall be contacted who shall immediately hire/procure or provide in whatever manner the DG Sets giving preference to the operational area.

1. Superintending Engineer(E)

2. Executive Engineer (Electrical)

3. Executive Engineer (Mechanical)

4. AXEN(E)

The above officers shall also be responsible for operation and maintenance of Generators provided at various locations and submits daily report to the Chief Mechanical Engineer about the working of Generators.

Additional requirements, if any, will be assessed by Dy. CME and the same shall be submitted to Chief Mechanical Engineer for hiring, well in advance so that XEN (E) can take necessary action for hiring, installation etc...

- After the warning of Cyclone or any other Natural Calamity is issued at the Port, Chief Mechanical Engineer shall ensure immediately that the cranes are secured and properly locked as per procedure and report submitted to the Chairman/Deputy Chairman after the operation of the Action Plan.

The following officers shall constantly monitor the safety of the cranes;

1. Executive Engineer (Electrical)

2. Executive Engineer (Mechanical)

The responsibility of evacuating all Mechanical/Electrical and Civil workers rests with Chief Mechanical Engineer with the assistance of respective Executive Engineers.

The maintenance of major nature and de-watering fire pumps operated by FireCum-Safety-Officer will be attended by Executive Engineer (Mech).

Executive Engineer (Dry Dock) and, AE(DD) shall ensure that the Steel Floating Dry Dock and Electric Wharf Cranes at the maintenance jetty are properly secured as per the procedure and compliance reported to the Chief Mechanical Engineer immediately. SE (Mech) shall monitor the safety of Steel Floating Dry Dock.

The following staffs have to report for duty even if it is a public holiday to actively participate in the Action Plan and they shall be responsible for record keeping of attendance, preparation, and submission of reports etc.

1. P A to CME

2. Office Superintendent

3. Superintendent Accounts

4. Sr. Clerk

5. Junior Clerk

11.16.1 List of Duty Roster of Mechanical Engineering Department As formed by CME on available officers

Name of Officer	Designation	Office	Resi.	Fax
Mr. SAROJ DAS	CME	270632 270184	231043	270184
Shri A Ramaswami	Dy CME	270426	226067	
Mr. P Srinivasu	SE (E)	271010		
Mr. B J Solanki	SE (M)	270352		
ABOVE OFFICERS WILL BE FORMULATING A TEAM				

11.17 Civil Department

Based on the practical experience and seriousness of the two Natural Calamities - the devastating Cyclone in 9th June 1998 and the Earthquake on 26th January 2001, the following Action Plan for Civil Engineering Department, is proposed to be implemented.

As soon as the message on anticipated Cyclone/Natural Calamity is received from concerned authorities, the same will be intimated to all the concerned under the Civil Engineering Department and will be instructed to be alert. All the staff members/officers should note that they will come into action on their

own as soon as the Warning is issued without waiting for any further instructions. Failure on the part of any employee/officer to carry out the earmarked Action Plan shall attract severe consequences.

Immediately after receiving the information on the Natural Calamity, nobody will be granted any kind of leave and the persons who are already on leave will be called back after canceling the leave.

Absent/Present report of the staff and the officers will be reported to the concerned Section immediately on starting of each shift for this purpose, Sectional Heads of all Divisions will be responsible to report the matter to P. A. to Chief Engineer for compilation of the information and onward transmission to General Administration Department.

The Engineering Department will assist in shifting of the persons to safe places in the event of such action is required.

Water Supply arrangements will be made to various colonies/sites of work/camps where the workers are shifted, etc. The Senior Engineer (Pipeline) will be the in charge for supply of water to various destinations.

Sufficient number of vehicles will be arranged for transportation workers/staff/officers. This arrangement will also be made by the Senior Engineer (Pipeline).

The Engineering Department will ensure that all Road blockades are got cleared as also blockades caused in Port Quarters due to failing of trees, walls, shed, etc. are got removed immediately. Further, it will be ensured that the colonies are got cleared and whatever logging of water is found is pumped out and disinfected. A report will also be submitted to Chairman/Dy. Chairman.

11.17.1 The following officers are to be contacted in the event of any such problems

Area	Designation	Office	Resi.	Mobile
New	XEN(R)	236165	222056	9913949700
Kandla				
Gopalpuri	XEN (TD)	223912	235683	9427205610
Old	Senior Engineer	220013	232880	9825225962
Kandla	(Pipe Line)			

Cargo Jetty	Executive Engineer (Harbour)	270429	252624	9825227046
-------------	---------------------------------	--------	--------	------------

11.17.2 List of Duty Roster of Civil Engineering Department CE will form a team as per

Mr. SSP PATIL	Chief Engineer	233192	228777	220050	9825227243
Mr. . V R Reddy	Dy. CE	270429	228869		9825227038
Mr. K J Todarmal	Exe Eng (R)	236165	220670		8980049099
Mr.	SE (PL)	220013	229164		9825225962
Mr	SE (H)				
Mr.B. Rajendra Prasad	Exe Eng (D)	220038	232880		9725338260


Periodical Meetings will be conducted with the Executive Engineer's/ DSOs/Staff Member to assess the progress made during the day and to instruct further course of action in the matter.

12 RESPONSE TO MARINE OIL SPILLS

12.1 Sources of Petroleum Hydrocarbons

The best estimate for the total input of petroleum to marine environment from all sources is some 3.2 million metric tons per year. By far the biggest contribution comes from terrestrial sources, mainly in the form of municipal and industrial wastes. Accidental spills from ships, together with offshore exploration and production activities, account for about 0.47 million metric tons which is a relatively small amount considering the world's current production of three million metric tons, half of which is transported by sea.

Major Inputs of Petroleum to the Marine Environment. (Figure)



12.1.1 Accident Spills from Tankers

Accidental spills from tankers contribute an estimated 4,000,000 tonnes annually. Analysis of tanker spills occurring throughout the world shows that the majority (some 75%) occur in port during routine ship operations such as loading, discharging and bunkering. Most of these spills are, however, relatively small: over 92% are less than 7 tonnes given in the table below and probably, in total, contribute less than 20,000 tonnes annually. In comparison, accidents such as collisions and groundings give rise to less than 10% of all spills from tankers, but a quarter of these are larger than 700 tonnes given in the table below. In fact, a few large accidents give rise to the majority of the oil spilled and hence there is considerable annual variation in this figure below:

Comparison of Incidence of World Oil Spills from Tankers, 1974 – 1985, resulting from Routine Operations & Major Accidents

	< 7 Tones)	7 – 700 (Tones)	> 700 (Tones)	Total
Loading / Discharging	2236 (90%)	227 (9%)	11 (1%)	2474 (100%)
Bunkering	442 (95%)	22 (5%)	-----	464 (100%)
Collision	39 (17%)	134 (59%)	54 (24%)	227 (100%)
Grounding	69 (25%)	134 (49%)	70 (26%)	273 (100%)
Total	2786 (81%)	517 (15%)	135 (4%)	3438 (100%)


12.2 Forecasting Slick Movement

It is equally important to be able to forecast the probable movement of a slick as well as the likely changes in the properties of oil after it has been spilled. This allows sensitive resources in the path of the slick to be identified and, if appropriate, response measures to be put into effect. The task of forecasting the position of the oil can only be accomplished if data on winds and currents are available since both contribute to the movement of floating oil.

12.2.1 Effect of wind, Tidal currents

It has been found empirically that floating oil will move downwind at about 3% of the wind speed. In the presence of surface water currents, an additional movement of the oil equivalent to the current strength will be superimposed on any winddriven motion. Close to land, the strength and direction of any tidal currents must be taken into account but further out to sea their contribution is usually less significant because they are cyclic and so tend to cancel out over time. Thus, with knowledge of the prevailing winds and currents, it is possible to predict the rate and direction of movement of floating oil from a known position, as shown in Figure given below, overleaf.

The influence of 3% of the wind speed combined with 100% of the current speed results in the movement of oil from A to B



12.2.1.1 Computer Models

This simple calculation can be easily done by hand but becomes very timeconsuming if tidal currents have to be taken into account since it must be recalculated at regular intervals as currents change. Computers can be used to speed up such calculations by storing information on water movement and coastal outline for a specific geographic area. Wind data and the spill location are then the only additional information required at the time of a spill. The reliability of such models depends upon the accuracy of water movement and wind data. Often they are combined with mathematical models simulating weathering processes to provide a forecast of the overall fate of a spill.


12.3 Aerial Surveillance at Sea

However reliable an oil spill model may be predictions of the fate and movement of oil slicks at sea should be verified through regular surveillance of the oil. This should be conducted from the air since observation from a vessel is highly inefficient.

12.3.1 Search Pattern

12.3.1.1 Ladder Search

A 'ladder search' is frequently the most economical method of surveying a large sea area. Since floating oil has a tendency to become aligned in long narrow windrows parallel to the direction of the wind, a ladder search across the wind will increase the chances of oil detection.



Movement of oil from A to position B three days later, predicted by combining 100% of the current speed and 3% of the wind speed as shown. The arrows from A represent current, wind and oil movement for one day. A cross-wind ladder search pattern is shown over position B.

12.4 Effect of Sunlight, Search Altitude

Haze and dazzle off the sea often affects visibility and the position of the sun may dictate the best direction to fly a search pattern. Sun glasses can give some relief from eye strain caused by strong light. Polarizing lenses can assist the detection of oil at sea under certain light conditions due to the differences in light reflected from oil and water. The search altitude is generally determined by the visibility. In clear weather 500 meters (1600 feet) frequently proves to be optimum for maximizing the scanning area without losing detail.

12.4.1 Navigation

However, it is necessary to drop to half this height or lower in order to confirm any sightings of floating oil or to examine its appearance. Over the open sea, away from any obvious reference points, it is easy to become disoriented. Ideally an observer will be able to consult the aircraft instrumentation for speed, direction and position, but it is worth ensuring beforehand that the instruments can be read without difficulty. In the absence of such aids, an observer with a suitable chart can keep track of course changes and positions by communicating with the pilot using the aircraft intercom.

12.5 Visual Quantification of Floating Oil

It is important that the port personnel estimate the amount of release for planning mitigating measures and allocating resources effectively. An accurate assessment of the quantity of floating oil is virtually impossible due to the difficulty of gauging its thickness. At best, the correct order of magnitude can be estimated by considering certain factors. Oil spreads rapidly and most liquid oils will soon reach an average thickness of about 0.1 mm, characterized by a black or dark brown appearance. Similarly, the color of sheen roughly indicates its thickness.

12.5.1 Appearance versus thickness, Cold water effects

A reliable estimate of water content in a 'mousse' is not possible without laboratory analysis but accepting that figures of 50% to 80% are typical, approximate calculations of oil quantities can be made, given that most typical floating 'mousses' are 1 mm or more thick. However, it should be emphasized that the thickness of 'mousse' and other viscous oils is particularly difficult to gauge because of their limited spreading. Indeed in cold waters some oils with high pour points will solidify into unpredictable shapes and the appearance of the floating portions will belie the total volume of oil present.

12.5.1.1 A Guide to the Relation between Appearance, Thickness and Volume of Floating Oil

Oil Type	Appearance	Approximate Thickness (mm)	Approximate Volume (m ³ /km ²)
Oil sheen	Silvery	0.0001	0.1
Oil sheen	Irridescent	0.0003	0.3
Crude and fuel oil	Black/dark brown	0.1	100
Water-in-oil emulsions ('mousse')	Brown/orange	>1	>1000

12.5.2 Surface area, Percentage cover

In order to estimate the amount of floating oil it is necessary not only to gauge thickness, but also to determine the percentage area of the sea surface covered by oil, water-in-oil emulsion and sheen. Again, accurate estimates are complicated by the patchy incidence of floating oil. To avoid distorted views, it is necessary to look vertically down on the oil when assessing its distribution. By estimating the percentage coverage of each form of oil, the area covered relative to the total sea area affected can be calculated from timed overflights at constant speed or from position fixing equipment.

12.6 Spill Control Management

12.6.1 Contingency Planning

12.6.1.1 Tankers

Plans covering areas where a wide range of oil types are handled or where tankers pass in transit, cannot anticipate the impact of a spill. It is therefore important that the type of oil spilled is established at the earliest opportunity so that its fate can be predicted and the appropriate clean-up techniques employed.

12.6.2 Fixed Installations

For oil terminals where a limited number of oil types are involved, an appreciation of the likely fate of potential spills is valuable when drawing up contingency plans. Information on the prevailing winds and currents throughout the year will indicate the resources where oil spill impact is most likely. Data on the types of oil handled can enable predictions to be made regarding the lifetime of slicks and the quantity and nature of the residue, which may require a clean-up response. It will also assist in the selection of appropriate clean-up equipment to be held in readiness for spills.

12.6.3 Priorities for protection, Sensitivity maps

Because of the difficult decisions that will be required during an oil spill in order to mitigate damage and to resolve conflicts of interest, much can be done at the contingency planning stage to identify sensitive areas and to determine priorities for protection. The mapping of sensitive areas can be a useful starting point. Detailed consideration should be given to the likely impact that a spill would have on each habitat or activity, taking into account any seasonal variability. Attention should then be given to identifying areas to be protected and their order of priority. This will never be easy since the value of each resource to the community will depend upon the weight given to environmental, recreational, economic and political considerations. This may require a wide range of data to be gathered and evaluated.

If properly conducted, such studies of the resources at risk in an area can also form a basis for quantifying any damage caused by a spill at risk in an area can also form a basis for quantifying any damage caused by a spill.

12.6.4 Response decisions

Having determined priorities for protection, attention can be given to designating appropriate clean-up measures. It is necessary to make a realistic assessment of the feasibility of employing various techniques since a recommendation to avoid the more ecologically damaging response options may result in the adoption of ineffective techniques and greater damage to other habitats or activities.

12.6.5 Containment

The containment of floating oil for subsequent recovery or its diversion away from sensitive areas calls for the use of some form of barrier. Many different types of oil barriers have been developed. These include commercially available floating booms, netting systems, sorbent booms, improvised booms and barriers, bubble barriers and chemical barriers. Selection of the most appropriate barrier will depend upon the particular conditions as well as availability. Since commercially available booms are the most common form of barrier used in oil spill control they are described in greatest detail in this section.

12.7 Commercially Available Booms

Design features


Designs vary considerably but all normally incorporate the following features:

1. Freeboard to prevent or reduce splash over;
2. Sub-surface portion (skirt) to prevent or reduce escape of oil under the boom;
3. Floatation by air or some buoyant material;
4. Longitudinal tension component (chain, wire or boom fabric itself) to withstand effects of winds, waves and currents.

Boom designs fall into two broad categories:


12.7.1 Curtain Booms

Curtain Booms provide a continuous sub-surface skirt or flexible screen supported by a solid or air floatation chamber usually of circular cross-section. Air floatation booms take up only a small storage area when deflated, whereas solid floatation booms, although more resistant to damage, are bulky in storage. Curtain booms generally have good wave-following capabilities, moderate escape velocities and are reasonably easy to clean.



12.7.2 Fence Booms

Fence Booms with a flatter cross-section are held vertically in the water by integral or external buoyancy. Solid floatation is most frequently used for fence booms but if external floats are used, turbulence may be generated leading to escape of oil at low water velocities. Such designs are bulky in storage and difficult to clean. In general, fence booms are more suitable for calmer waters where current velocities are low.




12.7.2.1 Common features

Many curtain and fence booms have similar features including bracing struts and/or integral ballast to keep them upright in the water, connectors for joining sections together as well as towing and anchoring points.

12.7.3 Performance/Limitations

12.7.3.1 Currents, Wind, Waves, Turbulence

The most important characteristic of a boom is its oil containment or deflection capability, determined by its behavior in relation to water movement. It should be flexible to conform to waves yet be sufficiently rigid to retain as much oil as possible. No boom can contain oil against water velocities much above 1 knot (0.5 meters per second) acting at right angles to it. The way in which oil escapes, and its relation with water velocity is as much a function of oil type as boom design. Low viscosity oils escape at lower velocities than more viscous materials. With the latter, the oil tends to accumulate at the boom face and to flow vertically down and under the skirt whereas low viscosity oils are carried under the boom as droplets sheared from the underside of the oil layer. Besides river and tidal currents, wind and waves can generate water velocities in excess of the escape velocity as well as causing splash over of contained oil. Oil escape can also result from turbulence along a boom and therefore a uniform profile without projections is desirable.



Escape of oil from a boom:

1. Splash over by wave action
2. Flow down the face of the boom
3. Droplets sheared from the underside of the contained slick

12.7.3.2 Boom size

The size and length of boom sections are also important considerations. The optimum size of a boom is largely related to the sea state in which it is to be used. As a general rule, the minimum freeboard to prevent oil splash over should be selected. The depth of skirt should be of similar dimensions to the freeboard. While short section lengths can make booms easier to handle and can protect the integrity of the boom as a whole should one section fail, these advantages must be weighed against the difficulty and time taken to connect sections effectively. Connections interrupt the boom profile and, wherever possible, should not coincide with the point of heaviest oil concentrations. The design of connectors should allow easy fastening and unfastening during deployment and whilst the boom is in the water.

12.7.3.3 Strength, Ease of deployment

Other important characteristics are strength, ease and speed of deployment, reliability, weight and cost. A boom must be sufficiently robust for its intended purpose and it must tolerate inexperienced handling, since

trained personnel are not always available. Structural strength and durability are required particularly to withstand the forces of water and wind on a boom when it is either towed or moored. Ease and speed of deployment combined with reliability are clearly very important in a rapidly changing situation and may strongly influence the choice made.

12.8 Netting Systems

12.8.1 Advantages


The use of nets to recover solid tar balls is an obvious application and the extension of their use to contain viscous oils theoretically presents a number of advantages over the use of conventional booms. In particular, the open structure should offer less resistance to water movement so that light but strong sections could be manufactured which might realistically be long enough to enclose oil scattered over a wide area of sea. As a result of the lower resistance of nets to movement through the water, it should also be possible to operate in faster currents or to sweep or trawl the sea surface at higher speeds than can be achieved with conventional booms.

12.8.2 Designs


Two basic designs of net have so far been developed which draw on experience from the fishing industry a long double net based on the purse seine method of fishing which can be used to corral or collect floating oil or which can be moored to protect sensitive areas; and a trawl net with a detachable 'cod-end' which can be towed along the sea surface.

12.8.3 Experience

Although neither design has yet been fully evaluated during an actual oil spill, large scale field trials show some promise, especially in the case of the purse seine type when used to corral and retain floating oil. However, once oil has been adsorbed onto the net the mesh becomes blocked and the oil retention capabilities are similar to conventional booms.



Netting system of the purse seine type for oil containment and recovery using two vessels to corral floating oil.




Oil trawl for collecting floating solid oil into a detachable cod-end.

12.9 Sorbent Booms

12.9.1 Construction, Uses

Sorbent booms usually consist of a tube of netting or some other fabric filled with a synthetic or natural sorbent material. Booms constructed of sorbent material have little inherent strength and, in some application, may require additional support. Some also need extra floatation to prevent them sinking when they become saturated with oil and water. They are normally only used in areas of low current velocity to collect thin films of oil, since their recovery efficiency decreases rapidly once the outer layers of the sorbent material become saturated with oil. The handling and disposal of oil-soaked sorbent booms can also cause considerable problems. The use of sorbents is further discussed in the section on Recovery.




Fixed oil barrier constructed with straw bales and wire netting nailed to wooden stakes.

12.9.1.1 Recovery

The rapid recovery of contained oil is vital to prevent its escape and the contamination of other areas. Recovery can be achieved using skimmers, pumps, sorbents, manual techniques and non-specialized mechanical equipment, such as vacuum trucks.


12.10 Skimmers

ADHESION DEVICES




Belt skimmers

A belt conveys the oil from the water surface by adhesion. Upward rotating belts carry the oil to their top limit where it is scraped or squeezed off into a storage tank. Conversely, downward rotating belts first submerge the oil which then surfaces behind the belt, due to its buoyancy, into a defined area within the vessel. Operational limit – for upward rotating belts 0.5 knots, sea state 1; for downward rotating belts 2 knots, sea state 2. Preference – medium viscosity oils but upward rotating belts also tolerate heavier material.



Oleophilic rope skimmers


A central tension core rope, through which is interwoven oleophilic strands forming a long continuous mop. The floating mop is pulled by powered rollers around a return pulley. The rollers squeeze the oil into a storage tank. Operational limit – sea state 3. Sensitive to increasing viscosity. Preference medium viscosity oils.



Disc skimmers


Discs rotate through the oil/water interface. Oil adheres to the disc surface, is removed by scraper to a central collection point and is pumped to storage. Operational limit – sea state 2. Sensitive to emulsified oils, waves, debris. Preference – medium viscosity oils.

SUCTION DEVICES




Weir skimmers

Oil flows over a self-levelling weir into the well of the skimmer and is pumped to storage. Operational limit – sea state 1. Sensitive to higher viscosity oils, emulsified oils, waves and debris. Preference – free-flowing oils.



Vortex skimmers

A vortex induced by an impeller causes the oil to concentrate at the centre of the vortex due to centrifugal effects. The collected oil is pumped from the top and the free water released from the bottom. Operational limit – sea state 2 and 0.5 kt water movement. Sensitive to debris. Preference – free-flowing oils.




Air suction skimmers

Vacuum system or an air conveyor attached to a hose which may be fitted with specially designed skimmer heads. The pumping of more viscous materials is possible by increasing the water content. Operational limit – sea state 3. Vacuum systems more sensitive to debris. Preference – light to medium viscosity oils but air conveyors can tolerate high viscosity oils.

12.10.1 Design features

All skimmers incorporate an oil recovery element, some form of floatation or support arrangement and a pump to transfer collected material to storage. More complicated designs may be self-propelled and may have several recovery elements, integral storage tanks or oil/water separation facilities.



12.10.2 Suction skimmers

Two basic approaches can be recognized: SUCTION and ADHESION. The simplest concept is a suction device whereby oil is collected by a pump or air suction system from the water surface directly or via a weir. These designs tend to collect large volumes of water together with the oil. This can be an advantage when recovering viscous oils since the presence of excess water helps to maintain the flow of oils which would otherwise tend to block hoses and pipe work. Large storage is required to receive and separate the water which frequently represents more than 90% of the collected material. For oil spill control purposes, simple gravity separation in settling tanks is adequate.

12.10.3 Adhesion skimmers, Oil types

In contrast, skimmers which incorporate oleophilic materials into belts, drums, discs or synthetic ropes often achieve a higher ratio of recovered oil in relation to water. In general, they work best with medium viscosity oils between 100 and 2000 centistokes although skimmers with toothed discs or chain link belts have been designed specifically for the recovery of heavy oils. These high viscosity oils, such as heavy bunker oil, are extremely sticky and can prove difficult to remove from the adhesion surfaces, whereas, in contrast, viscous water-in-oil emulsions can be almost non-adhesive. Although low viscosity oils like diesel and kerosene can be collected, they do not accumulate on the oleophilic surfaces of skimmers in sufficiently thick layers for high recovery rates to be obtained.

12.10.4 Waves /swell, Currents

Skimmers are designed so that the oil recovery element is positioned at the oil/water interface. This is usually achieved by a self-levelling arrangement and although swell alone does not generally affect performance, none is effective in steep waves.

Small units are easily swamped and pitched around, whilst larger skimmers have greater inertia and cannot follow the wave profiles. The performance of skimmers is also adversely affected by currents in much the same way as for booms. This limitation is partly overcome in some self-propelled skimmers where a

sorbent mop array or belt is rotated so that its velocity relative to the floating oil effectively reduced when the vessel is underway.

12.10.5 Self-propelled skimmers

Other designs of self-propelled skimmers can be effective in the calmer waters of ports and harbours. Because they are comparatively expensive they often combine some secondary function such as debris or waste oil collection. Such vessels are often an integral part of response arrangements for oil terminals and refineries where the pollution risk is more predictable.

12.10.6 Power source

Skimmers require power for the recovery element or for transferring the collected oil to a storage tank. Many systems are designed with an integral power pack. Diesel power can be used directly or to drive electric, hydraulic or pneumatic systems. All except petrol engines can be built to conform with safety regulations imposed in refineries, tank farms and other restricted areas where there may be a risk of fire and explosion. When used in potentially dangerous atmospheres, regular tests should be carried out with explosion meters to ensure safe operating conditions, since spark sources can never be completely eliminated.

13 ROLE OF INDUSTRIAL TERMINALS ON KPT LAND

13.1 Roles & Responsibility

Sr. No.	Tank Farm Owners	Persons to be contacted in case of emergency		
		Name and Position	Telephone No.	Mobile No.
1	Kesar Enterprises Ltd., Near Oil Jetty, Old Kandla (Kutch)370210	Mr. R.K. Gupta Gen. Manager	270435 (O) 295676 (R)	9375349181
2	Kessar Enterprises Ltd, Terminal II, Plot No. 5 &6 Old Kandla	Mr. R.K. Gupta G.M	270435 (O) 270177 (O)	9375349181
3	Chemical & Resins Pvt.Ltd Terminal –I, Near Oil Jetty, Old Kandla, Kutch Terminal – II, Near West Gate, New Kandla – Kutch	Lt. Col. Pramod Kumar (Retd), GM,	270505(O) 236831(R) 270916 (O)	9825225676
4	Indo-Nippon Co. Ltd., Plot No.2, K.K.Road, Old Kandla,	Mr. R.N. Pathak Asst. Terminal Manager	270795(O) 235818(R) 270295(O)	9879571295
5	J. R. Enterprise, Plot No.3, Old	Mr. Devendra Dadhich,	653528 (O) 257152 ®	9898238380

	Kandla,	Terminal In-charge		
6	Friends Oil & Chemical Terminals Pvt. Ltd., Near Booster Pump Station, Old Kandla, Kutch	Mr.S.Ramakrishnan Terminal Manager	270987 (O) 257249 ®	9879572107

7	Indian Oil Corporation Ltd., Main Terminal, GIM	Mr. AK. Khanna Sr. Term. Manager Mr. KS Rao, Sr.TM	233274 (O) 229002 (R) 270394 (O)	9427216637 9426416108
---	---	--	--	------------------------------

190

Upgraded Emergency Plan / DMP for Kandla Port Gandhidham (Kutch)

	Foreshore Terminal, Kandla KBPL LPG Import Plant	Mr. PS Negi Plant Manager	270628 (O) 270477 (O) 233359 ® 270978 (O) 236944 ®	9426725342
--	---	------------------------------	--	------------

8	United Storage & Tank Ltd Near IOC Foreshore Terminals, New Kandla	Mr. Manoj Gor Terminal Manager	270609 (O) 653525 (O) 651238 ®	989850029
	Gas Terminal, Plot No. 4 Old Kandla	Mr. G. Chudasama	653529 (O)	9904366855
9	IFFCO Kandla Unit, Kandla, Kutch	Mr. L. Murugappan, G.M.(NPK-I) Mr. Brahmbatt Manager (F & S)	270711 270352(O) 270381 (O)	982506922 9099019861
10	BPCL, KK Road, GIM	Mr. RG. Dekate Sr. Manager Operations	234313 (O) 223235 (R)	9099929634
11	HPCL KK Road, GIM	Mr. Murthy Manager (Installation)	230936 (O) 220084 (O) 233078 Ext	
12	INEOS ABS (I) Ltd Plot No. 8 Old Kandla	Mr. Vineeth Nair Dy. Manager	270087 (O) 234409 (R)	9825237029
13	Liberty Investments Pvt. Ltd., Plot No. 1 & 2, Block 'H', New Kandla	Mr. Jitendra Vaidya Terminal Manager	270151 (O) 270464 (O) 270468 (R)	9825025645

14	Avean International Pvt. Ltd., Liquid Storage Tank Terminal, Plot No. B-1, New Kandla	Mr. Bharat Rathod Terminal Manager	270537 (O)	9375310260
15	Rishi Kiran Logistics Pvt Limited, Plot No. 7, Link Road Old Kandla	Mr. RH. Pandya GM (Terminal)	270223 (O) 270443 (O)	9879104556
16	N.P.P. Pvt. Ltd., Old Kandla	Mr. MD.Nagvekar	270347 (O) 257807 ®	9825227649
17	Friends Salt Works and Allied Industries, KK Road, Old Kandla	Mr. NJ.Zinduwadia Sr. Manager Mr. HA. Mehta,S.M	270814 (O) 262698 (R) 271260 (O)	9825506361 9825506360
18	IMC Ltd, Cargo Jetty New Kandla	Mr. Anil Brahmbhat	270369(O) 653524 (O) 296079 (R)	9898126243
19	Agencies & Cargo Care Ltd., Plot No.3, New Kandla.	Mr.Shivkumar Menon, Terminal Manager	270714 (O)	9825226765
20	Dipak Estate Agency Plot No. 5-6, Block – A New Kandla	Mr. Narendra Thacker	270375 (O)	9879611243

21	Parker Agrochem Exports Ltd, Plot No. 3 –4,Block- H New Kandla	Mr. Bharat Thacker	270486 (O) 270528 (O) 231876 (R)	9825238260
22	Tejmalbhai & Co New Kandla	Mr. Ankitbhai Chandan	271330 (O) 230090 (R)	9825225101
23	Parker Agrochem Product Pvt. Ltd, Plot 7-9/A,N.Kandla	Mr. Raja Babu Dy Manager	270528 (O) 231876 (R)	9979158543
24	Mother Dairy Fruit & Vegetable Pvt. Ltd, Near Oil Jetty, Old Kandla	Mr. Saju Therattu	270654 (O) 270655 (O) 230979(R)	9974022681

The individual terminal will have to ensure the following in the event of emergencies arising out of:

- a) Natural disaster
- b) Toxic release
- c) Flammable vapour release
- d) Road tanker / Rail tank truck transportation accident
- e) Fire
- f) Flooding

13.1.1 Natural Disasters

- Ensure that adequate staff are posted at the terminal to meet any eventuality
- Ensure all operations are shut down
- If possible, ensure disconnecting pipelines
- Provide 48 hours food supply as well as portable water supply at the terminal

13.1.2 Toxic Release

- Ensure that the staff is evacuated in the direction opposite or as far as possible at 90 degree to the direction of the wind
- The staff located at the site to ensure safe operation, should be provided with gas masks
- Do's and Don'ts should be posted outside the control room to ensure minimum loss to life

13.1.3 Flammable Vapour Release

- It should be ensured that all possible help is rendered to the affected site / terminal
- The fire and safety officer at Kandla Port fire station should be informed
- Information pertaining to fire should be relayed to Main Emergency Control room at Gandhidham
- Information regarding fire incident should also be relayed to Kandla Free Trade Zone fire station
- Security personnel of the individual terminals should also be on standby to assist in fire fighting if the need be
- Mutual Aid Agreement should be signed between all the terminals as well as the KPT
- IOC LPG terminal should assist the affected terminal by way of sharing their experience in terms of plugging a chemical/gas leak
- The terminal Manager of the terminal next to the affected terminal should also inform the CISF

13.1.4 Road Tanker / Rail Tank truck transportation accident

- The dispatch terminal to whom the cargo belongs is responsible for attending to the mishap
- The dispatcher has to inform the exact location of the accident to the Main Emergency Control Centre as well as to the local emergency control room at Kandla
- CISF Commandant has to be informed by the dispatcher of the site of accident
- The Fire and Safety Officer stationed at Kandla Port should also be informed with specific name of the chemical
- In case the road tanker involved happens to be containing POL products then HPCL, BPCL and IOCL should be contacted immediately
- Accident involving rail tank truck i.e. LPG should be informed to the IOCL LPG Terminal Manager immediately
- In case of any leakage reported from LPG road tanker or rail tank truck the same should be arrested by the IOCL team

13.1.5 Fire

- Inform the Kandla Port Fire and Safety Officer
- Ensure that information pertaining to the Chemical involved in fire is passed to the Main Emergency Control Centre at Gandhidham as well as Kandla
- Information should be relayed to CISF regarding the fire
- In case it is a fire related to POL product then the oil majors i.e. HPCL, BPCL and IOCL should be contacted
- In the event of chemical fire it would be the collective responsibility of the DEENDAYAL PORT TRUST as well as the dispatcher to ensure that the spill is controlled and collected

13.1.6 Flooding

- Terminal should have trolley mounted pumps preferably of flame proof type to ensure dewatering of the site
- Gum boots should be supplied to the staff at the terminal
- The electricity supply to the terminals should be shut off to avoid short circuit
- The trolley mounted pump should have DC supply in order to ensure continuous operation
- It should be ensured that all the drains should be cemented and free of any debris which could hamper the flow of water

The following occupiers shall be a part of the emergency team for rendering expert advice. (This composition may be changed once in three years on rotation basis.)

13.2 Toxic Team

- IFFCO
- Chemical & Resins Ltd.
- United Storage & Tank Terminals Ltd.
- Bayer ABS

13.3 Fire Team

- Kesar Terminal I
- Indo Nippon

- Friends Oil & Chemicals Ltd. (FOCL)
- Friends Salt Works & Allied Industries Ltd. (FSWAI)

13.4 Transportation Team

- IOCL POL TERMINAL
- HPCL
- BPCL

13.5 Natural Disaster Team

- J. R. Enterprise
- J. K. Synthetics
- Synthetic Chemicals

Individual terminals shall be responsible for ensuring that safe shut down has been affected aftermath of a disaster in the neighborhood.

In case of dry docks KPT shall assume the charge of the emergency controller along with P&O to ensure that all the staff is evacuated from the area barring the security and the emergency team.

The emergency team would be drawn essentially from CISF and Marine Department i.e. at the behest of Harbour Master as well as P&O. In the event of an impending natural disaster like cyclone only CISF personnel to be stationed at the wharf. For the ships berth at the dock please refer to the cyclone disaster plan as annexed.

The emergency team should have the following:

- a) Chemical data sheet
- b) Protective clothing
- c) Breathing Apparatus
- d) Safety Harness

- e) General tools and flash light
- f) Leak plugging equipment like wood plugs
- g) Analytical equipment like explosivemeter
- h) Flood light with generator
- i) First Aid kit
- j) Portable diesel operated fire water pump

The responsibility of the various teams mentioned above would be to follow the following procedure:

- a) Keep people away
- b) Inform incident Controller i.e. at Main Control Room
- c) Contain the chemicals
- d) Avoid igniting the chemicals by ensuring muffler on the exhaust
- e) Obtain chemical data sheet

The communication parameters which need to be relayed to the Emergency Control Centre

- a) Place and time of the incident
- b) Chemicals involved
- c) Condition of the container
- d) Injuries or deaths
- e) Area surrounding (open country, town)
- f) Weather conditions
- g) Assistance available (police, fire services)
- h) Means of maintaining contact

Logistic Team

The function of Logistic Team is to ensure necessary supplies are available to Response Team during the emergency. In addition to above mentioned, the function is also responsible for organising and maintaining the staging area where emergency material and equipment is to be temporarily stored and assembled

before rapid deployment. The Logistic Coordinator will be reporting to the Emergency Chief Incident Controller and keep him updated on the availability of supplies and equipment or of any anticipated need.

Typical list of emergency equipment and material is given below:

- Fire extinguishers
- Fire fighting agents
- Fire hoses and nozzles
- Personal protection apparatus like fire suit (proximity suit)
- Chemical resistance protective clothing
- Self contained breathing apparatus
- Respirators
- Emergency lights
- Power generators
- Portable radios and cellular mobile phones
- Spill control agents for decontamination of toxic spills
- Plastic containers and lining material for diking and damming
- Earth moving machinery
- Fuel and gasoline for operation of vehicles and machinery

14 LINKS BETWEEN THE ARMY, COAST GUARD & AIR FORCE

Aftermath of any disaster the recovery and relief operations are conducted on a war footing.

The task involved usually demands rough and tough and dedicated personnel who are trained professionals to meet any challenge be it evacuating people marooned due to flood or making shelters or transporting relief to inaccessible areas. It is for this purpose that the army, air force and the coast guard would be required to assist the Kandla Port Administration.

The Chairman / Deputy Chairman would be the coordinating officials for liaising with the Station Commander (army, navy as well as air force) after consulting the District Administration.

While seeking assistance from the army, air force or the coast guard the following documents should be kept ready for reference:


- ③ Overall plot plan of the Kandla Port
- ③ Clear demarcation of the affected area on the plot plan
- ③ VHF link frequency for establishing contacts with the signal room as well as CISF commandant.
- ③ List of all the important telephone numbers.
- ③ In the event of Cyclone, keep the task force updated on the weather condition.
- ③ Ensure that the emergency team is extending their full co-ordination to the task force.
- ③ For ready reference the Secretary should nominate a person who should be made responsible to taking notes on what is happening and what sequence.
- ③ The areas, which could be used as temporary shelters should be indicated to them.
- ③ Open space which can be used as staging area should be indicated to them.
- ③ All the medical staff should be kept on standby and they should be asked to act after consulting the Army or the Air force teams.
- ③ In the event of air evacuation requirement it should be ensured that the people being evacuated are listed and the number of sorties required is noted.
- ③ In the event of a cyclone and an resultant Ammonia Gas leak it should be noted that the Army and the Air force should be provided with gas mask (if the need be).
- ③ Data pertaining to the number people in the affected areas (an approximate) should be made available to the Army / Air force.

The flow of information for co-ordination:

Chairman District Collector Chief Secretary Secretary - Ministry of Surface Transport Governor / Chief Minister of the state ARMY/AIRFORCE.

197

Upgraded Emergency Plan / DMP for Kandla Port Gandhidham (Kutch)



15 PROCEDURE FOR CO-ORDINATION

The overall responsibility of the Emergency management lies with the Chairman, Kandla Port. He assumes the responsibility of Chief Site Controller on receipt of the information of an emergency or an impending emergency.

Some of the critical functions are:

- ③ Activation of the emergency response organization
- ③ An ongoing emergency assessment, including upgrading or downgrading of the emergency alarm level
- ③ Notification of outside governmental agencies
- ③ The decision to ask for outside help and resources
- ③ The decision to evacuate the people
- ③ Decisions involving the safety of off-site vulnerable points (e.g. recommendations to evacuate or take shelter, in the case of a toxic vapour release).
- ③ Decisions to shut down/restart the Port.

The Chairman i.e. the Chief Site Controller shall be responsible for designating the Incident Controller, the Field Controller as well as the Liaison Officer as well as Public Relations Officer.

Functions like

- ③ Communication
- ③ Fire, Safety and Rescue
- ③ Special hazard
- ③ Utilities
- ③ Engineering / technical function
- ③ Medical function
- ③ Logistic function
- ③ Security function


③ Administrative function


EMERGENCY NOTIFICATION SHEET	
1.	Plant / Location Name _____ Unit _____ Address of Plant / Site _____
2.	Date _____ Time of Call _____
3.	Caller's Name _____ Caller's Position _____ Caller's Telephone Number _____
4.	Time (or Anticipated Time) of Accident / Emission _____ Projected Duration of Accident / Emission _____

5.	Type of Accident / Emission _____
6.	Emergency Alert Level (EAL) : Check One ALERT <input type="checkbox"/> SITE EMERGENCY <input type="checkbox"/> GENERAL EMERGENCY <input type="checkbox"/>
7.	In case of Toxic Release :
	Chemical Name of Substance Released _____ Amount and/or Rate of Release _____ Estimated Duration of Release _____ Type of Release (Gas, Liquid or Solid) _____ Toxicity / Flammability _____ Potential Impact on Offsite Area _____ Estimated Area Affected by the Release _____

8.	Weather Condition _____ Wind Speed _____
9.	Casualties / Damages _____
10.	Brief Description of the Accident _____ _____ _____
11.	Assistance Requested _____ _____ _____ _____
12.	Signature _____ Date _____ Time _____

15.1 Procedure for Co – ordination





16 ASSEMBLY POINTS & ESCAPE ROUTES

1. There are two main escape routes from the port side i.e. by land:



Kharirohar road.



Main NH 8 i.e. leading to Gandhidham.

2. The sea route would be the Kandla creek and other creeks i.e. Phang creek, Sara Creek or Rohar Creek or Nakti Creek connecting the same.
 3. Air evacuation can be undertaken by Helicopter or from Kandla Aerodrome.
 4. KPT to prepare list of all the personnel in their port colony and have it posted at the assembly area.
 5. The assembly points in the Cargo Dock for the workers in the area between the North Gate and the plot number five would be the area in front of the Railway Station.
 6. The assembly point for the port township could be between block E&D and at the intersection of Block 'B'.
 7. The assembly point for each of the adjoining berth would be on the road i.e. used for moving between the warehouse A,B,C,D and the berthing area.
 8. However for the workers working in the warehouses as mentioned above the assembly point would be the central road between the two streams of warehouses.
 9. The workers working in the bins i.e. open storage the assembly point would be the area in front of the West Gate # 2.
 10. For bins closer to the West Gate #2 fire brigade station the staging area for the fire station would be used as assembly point.
-

11. Computer should be installed in the rooms next to the assembly point connected to the time office for a list of people inside the port and the same should be made available at the railway station.
12. Railway station should have emergency evacuation counter all the personnel being evacuated from the area should be asked to check-in at the counter before they board the train.
13. The PA system at the assembly area should be used to announce “do not carry any luggage or belongings just carry as much as bare essential in clothing”.
14. The point of departure from the Dry cargo area would be West Gate 1 & 2 as well as North Gate and in an extreme case one would have to use the jetty being used by the pilots for evacuation by sea.

RECOVERY AND BUILDING BACK

17 RECOVERY FACILITY RE-ENTRY RESTORATION OF SERVICES

)

&

The recovery and re-entry phase will begin after the declaration of termination of emergency situation. This determination would be made by the Chief Incident Controller. The recovery plan would be flexible enough to adapt to existing conditions. All of the conditions that may be encountered in an emergency situation cannot be anticipated in advance. Detailed plans and procedures for recovery operations would be prepared at the time they are needed.

Re-entry operations would be performed by the Re-entry Team, which would be same as that of green team under the leadership of the Chief Incident Controller.

The team shall consist of personnel knowledgeable in procedures and facility layout. In the Re-entry planning process, the team will gather available information on the nature of the emergency and its present status by methods such as discussions with the operations personnel on-shift. Necessary protective clothing and equipment would be available for the team before re-entry is authorized.

Specific procedures for recovering from an emergency and re-entering the facility can hardly be provided, since they will have to be determined on a case by case basis, depending on the type of accident and the severity of the damage suffered. However, provision would be made for the following:

- Organising a re-entry team
- Inspecting the damaged area
- Declaring the emergency concluded and making the "all clear" known to the facility employees and the community
- Deciding which employees would report to work and notifying them
- Beginning an investigation into the causes of the emergency
- Assessing the damage to the facility
- Transferring necessary operations to alternative locations
- Decontaminating the damaged area
- Restoring services to the damaged area
- Clearing up the debris
- Salvaging material and equipment affected by the emergency
- Restoring the parts of the facility affected by the emergency
- Determining responsibilities and instituting possible insurance and damage claims

In case of an aftermath of a toxic release, it should be ensured that Chief Incident Controller and the party carrying out the re-entry to ascertain the termination of emergency, should be carrying self-contained breathing apparatus as well respiratory masks.

Please note in the event of a natural disaster the recovery team would involve the usage of ARMY or other paramilitary forces the same would be under the control of the station commander and the overall Controller shall be the District Collector.

CAPACITY DEVELOPMENT

18 MAINTAINING

CAPABILITIES

EMERGENCY

RESPONSE

In order to ensure a prompt and professional emergency response capability, port personnel are required to be knowledgeable of the possibility of various emergencies and emergency actions. General safety training should be provided to all employees to familiarize them with alarms, evacuation routes, safe assembly points, etc. In addition, personnel who are a part of the Emergency Response Organization are required to have additional training and should participate in periodic drills and exercises.

18.1 Training & Education

Regular training should be provided to all personnel who have a role in planning and operational response to an emergency. The main goal of training for emergencies is to enable the participants to understand their roles in the response organization, the tasks associated with each position and the procedures for maintaining effective communications with other response functions and individuals.

The training objectives are:

1. To familiarize personnel with the contents and manner of implementation of the Plan and its procedures.
2. To train personnel in the performance of the specific duties assigned to them in the plan and in the applicable implementing procedures.
3. To keep personnel informed of any changes in the plan and the implementing procedures.
4. To maintain a high degree of preparedness at all levels of the Emergency Response Organization.
5. Train new personnel who may have moved within the organization.

6. Test the validity, effectiveness, timing and content of the plan.

7. Update and modify the plan on the basis of experience acquired through exercises and drills.

Selected port personnel should receive instruction in the use of the fire fighting and emergency equipment available at the site. All personnel working at the site should receive instructions in fire prevention and in basic fire fighting techniques. Periodic refresher training should be provided and supplemented by fire drills.

Crews of tugs, which can be used for fire fighting, should receive instruction and training in fighting petroleum fires in co-operation with land based fire-fighting services. In order to utilize fully the tugs firefighting equipment and capability during an emergency, it may be necessary to supplement the crew with trained shore personnel. Opportunities should be provided at frequent intervals for combined practices involving the tugs and shore fire fighting services. Opportunities may arise whereby a combined fire practice or conference can be arranged between shore personnel and crew members of tanker at berth without imposing an operational delay on either the berth or the tanker. This should help make the tanker personnel familiar with the firefighting equipment ashore. Shore personnel should also have the opportunity of becoming familiar with the types and locations of firefighting equipment on and of being instructed in any design features on tankers which may require special attention in case of fire.

18.2 Drills & Exercises

Emergency drills and integrated exercises have the following objectives. These constitute another important component of emergency preparedness. They refer to the re-enactment, under the assumption of a mock scenario, of the implementation of response actions to be taken during an emergency.

1. To test the adequacy of the effectiveness, timing, and content of the plan and implementing procedures.
2. To ensure that the emergency organization personnel are familiar with their duties and responsibilities by demonstration.
3. Provide hands-on experience with the procedures to be implemented during emergency.
4. Maintain emergency preparedness.

The frequency of the drills should vary depending on the severity of the hazard. However, drills should be conducted once in a year. Scenarios may be developed in such a manner as to accomplish more than one event objective.

Drills and exercises will be conducted as realistically as is reasonably practicable.

Planning for drills and exercises should include:

- ③ The basic objectives
- ③ The dates, times and places
- ③ The participating organizations
- ③ The events to be simulated
- ③ An approximate schedule of event
- ③ Arrangements for qualified observers
- ③ An appropriate critique of drills/exercises with participants

Evaluation of drills and exercises should be carried out which should include comments from the participants and observers. Discrepancies noted by the drill observers during the drill shall be pointed out during the drill. A written evaluation of the drill or exercise should be prepared by the individual responsible for conducting the drill or exercise. The evaluation should include assessments and recommendations on:

- ③ Areas that require immediate correction.
- ③ Areas where additional training is needed.
- ③ Suggested modifications to the plan or procedures.
- ③ Deficiencies in equipment, training, and facilities.

The evaluation of a drill or exercise shall be submitted to the Main Controller for review and acceptance who shall then determine the corrective actions to be taken and assign the responsibility to appropriate personnel.

The Chief Fire Officer should track all approved drill and exercise corrective actions as a means of assuring that corrections are made in a reasonable amount of time, and shall advise Main Controller of the status of implementation of corrective actions.

Records of drills, exercises, evaluations, and corrective actions should be duly maintained.

18.3 Review of the plan

The Plan and associated implementing procedures should be reviewed to ensure compliance with relevant regulations and applicable state and local emergency plans and written agreements with mutual aid companies also.

The plan should be reviewed under the direction of the Chairman who should encompass the plan, response procedures, equipment, training, drills and interfaces with local emergency management agencies. The need for changes is based upon the following aspects:

- ③ Written evaluations of drills and exercises which identify deficiencies or more desirable methods, procedures, or organizations.
- ③ Changes in key personnel involved in the organization.
- ③ Changes in the facility organization structure.
- ③ Changes in state regulations.
- ③ Modifications to the facility which could affect emergency planning.
- ③ Recommendations received from other organizations and state agencies.

18.4 Emergency Control Center

The Emergency Control Centre is located in the Board Room of Administrative Office Annexure Building at First Floor.

This room will have seating arrangements for all members of Disaster Management Group.

It will have the following:

1. Adequate number of telephones. One of these telephones shall be used for outgoing telephone calls only.
2. Internal telephones, telex, fax.
3. VHF transceiver having marine band capable of being operated by mains or battery.
4. Hot line linking deputy commissioner of the district.
5. Internal and external telephone directories.
6. Emergency manuals.
7. Emergency light.
8. Wind direction and speed indicator.
9. Plan of the port showing:
 - ③ Berths/Areas where hazardous materials are handled
 - ③ Sources of safety equipment's
 - ③ Personal protective equipment such as aprons, gloves, gum boots, etc. ③ The fire fighting system
 - ③ Stocks of other fire-extinguishing materials
 - ③ Site entrance and roadways, updated at the time of the emergency to indicate roads which are to be used and which are not to be used.
 - ③ Assembly points and routing ③ Medical centers.
 - ③ Layout of pipelines in the Port area

③ Lorry parks and rail sidings

③ Port location in relation to the surrounding community (5 km map)

19 DEENDAYAL PORT TRUST OFF SHORE OIL TERMINAL – VADINAR PORT

19.1 Vadinar Port Information

Vadinar Port is an important port in DEENDAYAL PORT TRUST Group of ports under the control of Kandla Port Trust, Kandla. The port is just 55 Kms from Jamnagar city.

Latitude: 22 Degree 26'25' North

Longitude: 69 Degree 40' 15' East

Charts – Gulf of Kutch Chart No: 203

19.1.1 Metrological Data

1. Temperature: Summer Maximum 38 Degree C, Minimum 19 Degree C
2. Temperature: Winter Maximum 36 Degree C, Minimum 14 Degree C
3. Annual rainfall: Average 241.2 mm
4. Average Wave Height: 30 Centimeter (Summer)
5. Average Wave Height: 25 Centimeter (Winter)
6. Maximum Wave Height: 45 Centimeter
7. Maximum Tide – 6.12 Meter
8. Minimum Tide – 0.02 Meter
9. Wind Speed – Average Wind Speed – 16 knots/hour
 - Summer – 25 knots / hour
 - Winter – 18 knots /hour

10. Anchorage: Anchorage areas are about 4.5 miles from shore.

19.1.2 Off Shore Oil Terminal (O O T) Vadinar

The DEENDAYAL PORT TRUST has commissioned the off shore oil terminal facilities in 1978 jointly with Indian Oil Corporation by providing Single Buoy Mooring (SBM) system having a capacity of 10MMTPA was first of its kind in India. The following are the salient features of the operations at OOT Vadinar.

- A draft of upto 30 meters at SBMs and Lighterage Point Operations (LPO) • The Single Buoy Moorings can handle vessels having length of 335 meters. 2 NOS OF OIL BERTHS OF NAYRA (EX ESSAR)
- Handling VLCCs upto 3,00,000 DWT
- Providing crude oil intake for the refineries of M/s. IOCL at Koyali (Gujarat), Mathura (Uttar Pradesh), and Panipat (Haryana). & VADINAR OIL REFINERY OF NAYRA (EX ESSAR)
- Commissioned the first SBM on 27th August 1978.
- M/s. IOCL Commissioned the second SBM on 25th October 1997.
- Commissioned the third SBM (Essar) on 29th December 2006.
- Simultaneous handling of 3 vessels at three of SBMs
- Vast crude tankage facility of M/s. IOCL having capacity of 11, 44,000 KL.
- 4 High powered Tug of 50 Ton BP.
- Two Tugs of 35 ton BP &
- Two 50 Ton BP tugs for smooth operation is being acquired.

19.1.3 Export Jetty (Essar)

- One Ro - Ro / Lo - Lo Jetty for handling of project cargo / construction material / spare parts.
- Product Jetties (Private Berths at the Port)
- Essar Jetties are used for tankers Loading of POL product cargo by alongside.
- The Jetty No 1 – commissioned on 6th December 2006.
- The Jetty No 2 – commissioned on 29th December 2009.

19.2 Control Room –Vadinar Port

There is one control room at A.O. Building, Vadinar Jetty under the direct supervision of Pilot, stationed at Vadinar. In absence of Pilot, the other Pilot posted at Vadinar and XEN (M&E) shall be responsible for the direct supervision of the Control room at Vadinar, in association with Marine Engineers Grade - II. They shall rush to the Control room as soon as the Action plan is put into force. Two persons viz. one Assistant, Flotilla Supervisor and one Signaller shall report for duty to the In-Charge of Control Room immediately, as soon as the Control room comes into operation. The In-Charge should draw-up rosters of the said employees shift-wise and assign duties to them. The In-Charge shall ensure the presence of the staff as to whom various duties have been assigned. They should attend the meetings as and when called. In case of absence of the staff, the matter should be informed to the C.O.M. (OOT), who shall take disciplinary action against the erring employees.

The Control room has the following assets

Telephone	Fax	VHF Signal
0288-2573026		Marine Channel 12,16,8,10
Mobile Phone Nos. 9825212359 / 9825212360 /		
Xerox Machine / STD telephone		

Inmarsat Mini M. Terminal and / or V.Sat Terminal Antenna are required to be set up and installed at Vadinar.

Manning at Vadinar Control Room Jetty

Any one of the AVAILABLE Contract Pilots is available at Vadinar

Designation
XEN(M&E)
M.E. Grade-II
Office Supdt
A.F.S

A.F.S
Signalman
Signalman
Signalman
Signalman

19.2.1 Obtain Information from following Sources

1. State Meteorological Control Room, Ahmadabad
2. Control Room, KPT, Kandla / Gandhidham 9. Meteorological Section, New Kandla,
3. signal station, New Kandla.

The information so collected shall be maintained by making hourly log entry in a register.

19.2.3 Control Room Assets

1. Xerox machine
2. STD telephone
3. Fax machine
4. Inmarsat Mini M. Terminal / and or V. Sat Terminal antenna, are required to be set up at Vadinar jetty

The In-Charge of Control room should ensure setting up of the Control room at Vadinar jetty immediately on receiving warning and matter be reported to C.O.M. who in turn apprise the Dy. Chairman and Chairman, KPT.

The control room shall remain in touch with various authorities / agencies like State Govt. / Distt. Authorities / and local authorities. Besides, Naval Authority OkhaPorbundar should also be contacted on VHF/UHF frequency, round the clock. In the prevailing set up of CISF Security control staff at Vadinar, Officer-in-charge of C.I.S.F. Unit of KPT Vadinar along with his entire CISF Security Personnel will remain in contact with In-charge of Control Room for posting of CISF Security Personnel at various locations as per the requirements and they will carry out the duties and responsibilities as required & assigned under this Action Plan.

In case the Marine Signal No.8 is issued, the Vadinar jetty area will be evacuated including the Control Room, which shall be shifted to Room No.5 of Port Guest house at Vadinar colony. In this regard, XEN (E&M) shall pre-plan installation of VHF Antenna and drawing extension line of there available Telephone Nos. (02833)-256533 / 256714 at Port Guest House at Colony and ensure laying of cable with suitable connectors with the Wireless Sets duly tested and thereafter to be set up there at Guest House.

19.3 Functions of Control Room –Vadinar Port

Control room shall remain in touch with State level / District level Meteorological Department / Masters of ships at Vadinar, Navy / Coast Guard at Porbandar / Vadinar and also with the Control Room of KPT at Kandla/Gandhidham.

Telephone numbers of concerned contact persons are as under:

STD code: Jamnagar (0288), Vadinar (0288)

Sr. No	Name of Organization / Contact person	Office	Residence
01	Chairman, Mutual Aid District Collector, Jamnagar	2555869	2554059
02	Joint Chair Person, Mutual Aid Commissioner, JMC, Jamnagar	Fax No.2554454 2552321	2552372
03	Distt. Supdt. of Police, Jamnagar	2554203	2555868
04	Police Control Room, Jamnagar	2550200	
05	Police Control Room, Sikka	2344249	
06	The Dy. Chief Controller, Civil Defense, Jamnagar	2540371 2674758	2671828
07	Control Room, Collector Office Jamnagar	2553404	
08	Port Officer, GMB, Jamnagar.	2712815 Mobile:9426239289	2554942

09	Commandant, Home Guard, Jamnagar	2553862	
10	Mamlatdar, Khambhalia	234788	234736
11	Dy. Collector, Khambhalia	234577	
12	Police Station, Khambhalia	234735	
13	Fire Officer, Fire Station, Jamnagar	2662690 Mobile:9879531101	2550340
14	DEAN, Irwin Group Hospital, Jamnagar (Now Guru Gobind Singh Hospital)	2553515	2553676
15	Indian Air Force, Jamnagar Extension: 222/257 Wing Commander	2720003 to 009 2720004-2720005	
16	Duty Officer, INS, Valsura Jamnagar	2550263-222 extn.	
17	CISF, Coast Guard, Vadinar		
18	DGM, IOC, Vadinar	02833-256527	02833- 256567
19	Chief Operation Manager, IOC, Vadinar	02833-256984	02833- 256559
20	Dy. Manager (operation), IOC, Vadinar	02833-256545	02833- 256530
21	Fire Brigade, IOC, Vadinar	02833-256542	02833- 256559
22	Main Board of M/s Essar Oil Limited, Vadinar	02833-241444	
23	Security Control Room, Essar, Vadinar.	02833-241917	02833- 241191

24	Vice President, (P&Admr ESSAR Vadinar Refinery.	02833-241107 02833-241167	028332550976 028332662856
25	M/s. Reliance Petro. Ltd., Moti Khavdi	0288-6610101	

Information from the above officers will be collected and transmitted to the C.O.M. (OOT) on hourly basis between 0800 to 2000 hours & 2000 hours to 0800 hours respectively. The said information shall be passed on to Dy. Chairman / Chairman on three hourly basis.

The Vadinar control room shall maintain logbook of messages received from and to Control Room at Gandhidham continuously and report to the COM (OOT) every hour. The information shall be passed on to Dy. Chairman / Chairman depending upon the importance. It shall be the responsibility of the Control Room staff to ensure that the information is passed on timely and proper monitoring is done.

The following are the Website addresses through which the required information regarding the position of the Cyclone can be ascertained.

<http://www.imd.gov.in/> <http://www.supertyphoon.com/indian.html>
<http://www.npmoc.navy.mil/products>
<http://www.solar.ifa.hawaii.edu/tropical/tropical.html>
<http://www.wunderground.com/tropical>

19.4 Stopping of Port Operations

In case of emergency situation, local port authorities like COM (OOT) will decide about the stoppage of the port operations which will be stopped after consulting DGM, IOC / Essar, and ordered by Dy. Chairman / Chairman. In case COM (OOT) is not available in the emergency situation, senior most Executive Engineer is authorized to take such decisions in consultation with Gandhidham officials. Under such situation COM (OOT) in co-ordination with officials of Indian Oil Corporation Ltd. and M/s. Essar, shall get the operation at all three SBMs stopped and also get the hoses dis-connected from the tanker berthed at SBMs and un-berth tanker from Product jetty of Essar. Pilot of KPT on board the tankers will immediately take action to castoff the tanker from SBMs/Product berths and tankers will be directed to go to suitable safer place in that situation. All the ships waiting at own anchorage or working at anchorage will be asked by Vadinar control to go off in open sea at least 5 Nautical miles away from SBM. The tankers carrying out transshipment operation at LPO (Lighterage point), will be asked to stop the operation immediately and be on their own power to be away from other ships in the vicinity.

19.5 Securing of Ships / Crafts / Tugs etc

Pilot / M.E. Grade-II / both the AFS, should be available at Vadinar in case of Action Plan is in operation and situation like emergency. Immediate action for stopping the shipping operation should be taken by informing concerned agencies like IOC, ESSAR, and Shipping Agencies and also to KPT Tug / Craft working for the shipping operations at SBMs / LPO point and Product berth of Essar at Vadinar.

Both the AFS and AXEN (Mech.) should ensure that all the big crafts are moved out of Pathfinder Creek and all Port crafts & small crafts of private parties are placed at inner and outer side of the Vadinar Berthing Jetty or any other suitable location pre-decided and notified. If it is impossible to remove them, then all other steps should be taken to ensure safety of vessel / crafts at the Vadinar port, as also it would not cause any damage to the port. For the purpose of securing of ships / all crafts, pilots assisted by Marine Engineers Grade-II and XEN (E&M) will jointly assess the situation and get the crafts/tugs secured accordingly. The Pull Back tugs shall be secured safely at the Berthing Jetty and Crafts/dumb barge of outside agencies will be placed at safer places in this area. Both AFSs, will ensure while directing all the flotilla staff to take care of the safety of Floatilla. They will look after Pull back tugs and all other Masters will look after the Port flotilla with the help of team of Lascars, Serangs, Quarter Masters and Engine staff. The private Tugs & dump barges engaged by M/s. Essar and M/s. IOC and placed at approach jetty or RO-RO LO-LO jetty shall be ensured to secure at a place decided well in advance by XEN (E&M) and AFS after consulting authority of M/s. Essar and M/s. IOC. A compliance report of securing all crafts at safe places should be furnished to Control Room immediately on issuance of Cyclone Signal No.5.

Both the AFS should ensure the sufficient stock of mooring ropes and heaving lines, etc. to meet operational requirements during the emergent situation and sufficient number of life buoy, life jackets, etc. kept in easily accessible places in each crafts and at various other places on shore too.

19.6 Communication

XEN(E&M) and XEN (Civil-II) shall ensure on hourly basis by ringing personally that the telephones of signal station, AO Building, Estate Office, Hospital, Electric and Water supply are functioning, failing which they shall take up the matter with concerned BSNL authorities. In case of any difficulty in communication system, COM (OOT) should be contacted.

The satellite phone or V-Sat communication network should be established and put into operation at the earliest, by the following Signalmen:

1. Shri P.C. Kothari.
2. Shri Krishna Prajapati.

They will ensure the charging of walkie-talkie, Mobile telephones, as well as satellite phone available at the Signal Station, Vadinar.

The staff at Jamnagar Liaison office shall remain present on 12 hourly shift basis round the clock; to carry out the liaison work during the Action Plan is in operation and any other work as may be assigned during the period of Calamity. S/Shri V.M. Mehta, Assistant shall communicate with the Gandhidham/Kandla officials in case Vadinar communication is cut off from that of Gandhidham/Kandla

Traffic Movement & Security

XEN(C-II) and In-charge of CISF (KPT) Vadinar unit shall ensure that all incoming traffic to the Port jetty of Vadinar is stopped except those which are coming for rescue operations and essential services. They shall ensure posting of adequate security personnel, at various security points in co-ordination with the local police authority. XEN (Civil-II) and S.I. (W&W) should ensure safety of essential service premises like water overhead tanks / Main Store / Electric Station at colony. In addition, the in-charge of CISF Unit (KPT) Vadinar in co-ordination with XEN (Civil-II) shall ensure the posting of Security personnel with arms at all strategic locations, such as Control Station room at Jetty & Port Colony, Water supply tower, etc.

Medical Aid at Vadinar Port Health Center

Medical Officer (O.O.T.) being Officer in-charge at Health Center, Vadinar & other complete Health Center staff will remain in state of readiness to deal with any casualty by setting up a Casualty Emergency Room at the Health center, Port Colony, Vadinar. The Casualty Emergency Room shall start functioning as soon as Action Plan is put in operation and warning of the calamity is received. No staff of the Health center will be given leave during the period and Casualty Emergency room will function round the clock with posting of Doctor and staff round the clock. Medical Officer shall remain present and, apart from attending the patients, will allocate various duties to the available medical & Para-medical staff, such as maintaining records of patients attended and preparing a report thereof. Adequate number of chlorine pills should be distributed after the calamity is over, to avoid epidemic from spreading. M.O. (OOT), being Officer in-charge shall pre-plan for assessment & urgent requirements of all kind of the medicines to meet with the situation which may arise in case of any Natural Calamity. He should arrange to obtain the advance approval for immediate procuring of such medicines and the same should be procured & stocked readily available in advance.

Action to be taken by Pilots

In case of receiving cyclonic weather warning i.e. on declaration Weather Warning signal No.5 at Port, Pilot on the Board at SBM should un-moor the tankers and direct the Master of vessel to move the vessels to safer places i.e. away from the SBM. While returning to the Jetty by the Port craft, the Pilot should ensure that all the Port crafts are secured properly and safely at both inner and outer sides of the jetty. He should also ensure that ropes are doubled up and the tugs are manned at all times and engines are kept in readiness to move out in case of emergency.

Meanwhile, till the time the Pilot returns to the Jetty, the AFS on duty will not waste time and initiate action to secure the smaller crafts, which will further be inspected by the Pilots. Masters of all the smaller crafts should also be directed to ensure proper fendering arrangements are provided and if required extra fendering to the crafts may be provided. AFS shall ensure that the proper fendering arrangements are provided to all crafts before on set of inclement weather. Port crafts will get the priority over the private crafts to come alongside jetty. If any space is available, the private crafts can be allowed to come alongside the jetty.

After observing/monitoring weather conditions, intensity, speed and direction of propagation of Cyclone, necessary arrangement for abandoning the crafts may be made and on declaration of weather warning Signal No.8, the Vadinar jetty area will be evacuated including jetty Control Room, which shall be shifted to Room No.5 at Port Guest House at Vadinar Colony. In the month of April every year, Signalmen under guidance of XEN (M&E), shall inspect & ensure working of all the equipments meant for Control Room of Jetty as also readiness of all the electric connections / charging points at the above alternate location of Control Room at Colony.

Generator Set

Wherever Generator sets are required due to power failure at Port Jetty and colony, AXEN (Electrical), JE (Electrical) shall be contacted who shall immediately arrange to provide the DG set already procured & available with Electrical section, giving preference to the operational area. However COM (OOT) shall be free to hire additionally required DG sets for a suitable period, if the same is not found adequate available in store.

AXEN (E), JE (Elect.) shall prepare a roster of staff of Electrical section for putting the D.G. sets installed & commissioned at the following destinations in operation and attending faults, if any occurs, during the operation of Action Plan and ensure readiness for meeting with emergency situation in case of power failure. Diesel oil drums, connecting cables with lugs etc. and any other such materials are to be kept readily available/accessible for use.

1. Jetty
2. Colony
3. Guest House
4. Health Center
5. Water supply complex at colony

Provision of sufficient emergency spares and cables, terminals, portable lights (Handle torch, emergency lights), tools, tackles, etc. should be ensured well in advance in planned manner to combat the situation. All precautionary measures should be taken to protect the D.G. sets from detrimental effect of thunderstorm, heavy rain showers and such cyclonic conditions. Sufficient stock of waterproof spread sheets, tarpaulins, canvas, etc. to protect the electrical gear from water showers/moistures, etc. should be planned, procured and kept at easily accessible place for instant use.

Power supply staff should be well equipped with jigs and fixtures, such as portable tower ladders, insulated axe, gumboots, hand gloves, shockproof accessories. All the above urgent items should be got procured & kept readily available, well in advance in association with Assistant Executive Engineer (Mech), to cater for emergent situations. XEN (E&M) shall take advance action for procurement of one No. DeWatering Pump (Diesel Driven) and the same should be kept stand-by along with its suction & discharge hoses connected for use

Vehicle Pool

As soon as the Action plan comes into force, the vehicle pool shall be formed and vehicles as allocated as per ([List of Vehicles available with Chief Operations Manager \(OOT\) Vadinar](#)) shall remain stationed at the said places along with operating staff. The pool shall be controlled by Assistant Executive Engineer (M) / AXEN (E) to be assisted by Junior Engineer (Mech) / (Elect), and following staff will render their services for posting of drivers and allocating of vehicles as per ([List of Vehicles available with Chief Operations Manager \(OOT\) Vadinar](#))

Apart from the above, XEN (E&M) / XEN (Civil-II), shall hire vehicles, if needed for emergency work, from the private vehicle contractors. The list of private vehicles contractors is shown as Annexure – VII. Assistant Executive Engineer (M) / AXEN (E) should ensure the availability of drivers and vehicles and submit compliance report to the COM (OOT). All hired vehicles should be stationed at the location as decided by XEN (E&M) / AXEN (M), from where it can be taken for immediate use at the required places.

Temporary Evacuation Centre

The temporary evacuation center shall be looked after by XEN (Civil-II) and Assistant Executive Engineer (Civil) who will be assisted by the Principal of St. Ann's School & his staff and the following KPT staff members assisted by the volunteer's employees as mentioned in the Annexure-III, for setting up temporary evacuation centers and rendering required services for the same. They shall ensure that temporary evacuation centers are established immediately, in the school and staff club of Vadinar Port colony. Port vehicles such as Trucks, Buses, Ambulances, etc. will be put into operation for immediate evacuation of people from Port Jetty as well as colony, as the need be.

1. Sr. Clerk
2. Assistant
3. Junior Clerk
4. Junior Engineer (Civil)
5. Junior Engineer (Civil)
6. Junior Engineer (Civil)
7. Junior Engineer (Civil)

Assistant Engineer (Water Supply sub division, Vadinar) shall ensure for providing adequate quantity of water supply at all the temporary evacuation centers.

Medical Officer (O.O.T) with the help of internees and staff of Health Centre shall ensure to provide necessary medicines / medical assistance to affected persons and ensure about the hygienic conditions at the temporary evacuation centers.

XEN(Civil-II) being Officer-in-Charge of Temporary Evacuation Centre, with the assistance of following staff members and volunteers employees mentioned in the Annexure-III, shall take care of the requirements of food/water etc. and supply the same for the evacuees in the temporary evacuation centers.

1. Senior Clerk.
2. Electrician.
3. Junior Clerk.

4. Lascar.
5. Chowkidar.

The Officer-in-charge of C.I.S.F. Unit of O.O.T. Vadinar and SI(W/W) should arrange to make announcements regarding cyclone warnings with the co-ordination of local police, by vehicles mounted with public address systems and also should arrange for requisitioning and providing trucks for shifting peoples, as soon as Internal Action Plan comes in action.

Spray of Dis-infecticides / BHC powder etc will be looked after by Assistant Engineer (Civil) Building Sub. Division along with staff of Estate office i.e. Jr. Engineers and other staff.

19.13 Press & Media Management

There will be a Press cell headed by C.O.M. (OOT). The following officers/employees shall remain in the Press cell.

1	XEN (M&E), as Officer-in-Charge
2	PA to COM
	Signalman

The press cell shall come into operation in the chamber of COM (OOT). The press cell shall issue daily press note with the knowledge and approval of Chairman / Dy. Chairman. If needed, a photographer be engaged, who will take photograph / video shooting everyday, which will depict the situation as well as the relief work undertaken by the officers. All media people of press, journalist etc. shall be taken care of by XEN (Civil-II).

As regards to their transportation, lodging / boarding and other hospitality, he shall take required advance amount from Accounts Officer (O.O.T.) and submit the bills thereof subsequently. Accounts Officer (O.O.T.) along with Superintendent of Accounts / D.A. will be the custodian of cash drawn and kept in their custody for the disbursement for various emergency payments to the designated Officers and the record of such advances to such individual Officers.

XEN (Civil-II), Vadinar and Pilot posted at Vadinar, shall remain present in all KPT meetings relating to the Action Plan. XEN (Civil-II) and Pilot in-charge shall remain in touch with State Governments / District Authority and Mutual aid scheme members, on daily basis, for sorting out the difficulty / problems of cyclone/calamity relief work in consultation with COM (OOT).

19.14 Action to be taken by Accounts Officer (OOT)

As soon as the Cyclonic Weather warning Signal No. 5 is declared, Accounts Officer (OOT) shall arrange for the cash amount to be disbursed as advances to various officers. All Officers-in-charge, should make a judicious assessment regarding requirement of funds by them to meet with different exigencies which they may have to handle on account of the situation arises due to Cyclone / natural calamity. A.O. (OOT) in turn, would examine the advances sought by the officers and disburse the advances immediately without delay and intimate C.O.M (OOT) and F.A & C.A.O about amount released by him and obtain sanction thereof.

19.15 Advance Planning

19.15.1 For stocking required equipments / machinery / material & medicines

Assistant Engineer (Civil) in association with Store Keeper, should ensure the advance stocking of Diesel, Petrol, Kerosene, Lubricant Oil, Emergency lights as well as Torches & Cell, required tools & tackles, jigs and fixtures etc. in sufficient quantity to meet with the emergency requirements of Vehicles, Generators as stipulated under action at Sr. No.8 & 10 above and all such other services. All the Officers-in-Charge, must list out the materials required well in advance, to facilitate procurement & stocking in, sufficient quantity of the same by Assistant Engineer

(Civil).

19.15.2 For securing of ships / crafts / tugs etc

A safe place to secure ships/crafts/tugs etc. on issuance of Cyclone Signal No. 5, should be decided & notified well in advance (By April end) by XEN (E&M), in association with both Assistant Flotilla Supervisors. The sequences of operations for shifting of all crafts shall be planned in advance by all the Masters along with related Marine staff, under the guidance & instructions of above officials.

19.15.3 Post Calamity Operations

19.15.3.1.1 Marine Operations

Immediately after the Calamity subsides, Marine Engineers Grade-II along with both the Assistant Flotilla Supervisors & related Marine staff shall carry out the inspection of all the Floating Crafts and check if the crafts can be put into operation for checking the condition of SBMs and hoses. Accordingly, a report to that effect, shall be submitted by both Marine Engineers Grade-II, to the Control Room at Vadinar, who in turn, after taking approval of C.O.M., will transmit the same to the Dy. Chairman/Chairman at Gandhidham/Kandla. C.O.M. shall co-ordinate with officials of M/s. IOC/Essar Vadinar, for their all Okey reports or otherwise, as regard to SBMs/Product Berth, Pipelines and their clearance for resumption of shipping operation & project works at Vadinar.

19.15.3.1.2 Other than Marine Operations

XEN (Civil-II), after taking the stock of situations, arrange for all relief/restoration measures for the damages caused during the Calamity. An advance planning of work-force (Work team/Volunteers by name), list of materials required and the arrangement of effecting the relief/restoration, shall be checked out & notified to all the connected persons in this operations.

For coping up with the immediate restoration work in Post-calamity period, an advance approval of Chairman, KPT, shall be obtained by XEN (Civil-II) by processing the case file, for authorizing the Chief Operations Manager (OOT) to engage Daily rated labour of various discipline in Un-Skilled, Semi-Skilled and Skilled category, at the fixed daily wage for each category personnel.

Further, to hire equipments such as Vehicles/Mobile cranes / Dumpers / JCBs / Pay Loaders etc. for immediate relief/restoration work at the required places at Vadinar, XEN (Civil-II) shall also process case file in advance, for obtaining approval of Chairman, KPT, to hire such equipments, for immediate restoration work in PostCalamity period at Vadinar.

19.16 Action Plan – Land Fire Station

In case of any fire, the Control Room shall immediately establish a communication with C.I.S.F., Fire Brigade of M/s. IOCL and M/s. Essar Oil Ltd., Vadinar and immediately summon CISF In-charge of OOT to directly reach the site of the fire along with his Security Personnel & co-ordinate with fire fighters, for cordoning the site of fire and take actions to provide rescue and containment of fire.

CISF In-charge of KPT (OOT) Dept., Vadinar should keep informing the Control Room and C.O.M (OOT) from time to time about the gravity of situation and extent of control over the situation.

19.16.1 List of all the officers in charge & designated officers & employees covered

Sr. No.	Name & Designation	Tele. No. at Office	Tele. No. Residence
1.	C.O.M.	0288-2573001 0288-2573031 FAX	
2.	, XEN(M&E)	0288-2573005	
3.			
4.	XEN(Civil)	0288-257006	
5.	AXEN(E)	0288-2573011	
6.	Shri NAYAK, M.E. Gr.II	0288-2573007	
7.	A.O.(OOT)	0288-257008	
8.	Dr Medical Officer.	256313 (Vadinar)	
9.	AXEN (Civil)		
10.	A.E.©		
11.	A.E.©		-----
12.	Shri A.XEN.(Mech)		2915231 (Jamnagar)
13.	PA to COM		
14.	O.Supt.		256483 (Vadinar)

15.	Supdt. A/cs.		
16.	(Store Keeper)		
17.	A.F.S.		256517 (Vadinar)
18.	, AFS		256817 (Vadinar)
19	Signalman		
20.			
21.	Signalman		
22.	Signalman		
23.	J.E.©		
24.	J.E. © Gr-1.		
25.	J.E.©		
26.	KPT Guest House at colony.		
27.	Shed Master		
28.	Assistant,KPT Liaison office at Jamnagar		
29.	Time Keeper		
30.	(Clerkcum-Time keeper).		
31.	, Maistry		

19.16.2 List of Press Reporters & News Services at Jamnagar

Sr.No	News Service	Name and address	Telephone nos.
01	District Information Officer, Jamnagar.	Shri K. A. Karamata, District Information Center, Jamnagar.	2556827 2672939
02	Times of India, PTI	Shri Darshan Thakar, Journalist society, Jamnagar	2555731 9824232632
03	Indian Express, Jansatta & Financial Express	Shri Bipin Sukhpariya Limda lane, Jamnagar	2553717
04	Phulchaab	Shri Dinesh Vora,	2550320
		Nr. Old Railway station, Jamnagar	
05	Sandesh	Smt. Bhavnaben Soni, Opp. Apsara Talkies, Jamnagar	2553106 9825280456
06	Jay Hind	Shri Bharatbhai Raval, Nr. Old Railway station, Jamnagar	2557447
07	Sanj Samachar	Shri Mukeshbhai Joiser, Near Old Rly. Station, Jamnagar	2554109 9824219999
08	Bhoomi	Shri Dolarbhai Raval, Limda lane, Jamnagar	2679080
09	Nobat	Shri Pradeep Madhwani, Pancheshwar tower road, Jamnagar	2555924 2670924 2553752 (Fax)

10	Gujarat Samachar	Shri Vipul Hindocha Opp. Madras hotel, Teen batti Jamnagar	2670634
11	Ajkal	Shri Praful Tankaria, City Point, Near Town Hall, Jamnagar	2665602 2665603
12	Lokvat	Shri Jay C. Chauhan, New Super Market, Jamnagar	3092114
13	Sahara Samay	Shri Darshan Thakar, Journalist Society, Jamnagar	2555731
14.	Divya Bhaskar	Shri Mukesh Joiser, Near Old Rly. station, Jamnagar	9824219999

19.16.3 List of School & Buildings available at Vadinar for Shelter purpose

1. St. Ann's School, Vadinar Port colony Telephone No. 256568 / 256514
2. Staff club, Vadinar Port Colony.

19.16.4 List of volunteers employees at Vadinar (Dist Jamnagar) To be formed by COM

19.16.5 List of Vehicles available with Chief Operations Manager (OOT) Vadinar : To be arranged by XEN (M&E) as per availability

Name of Driver (Motor) & their Residence Telephone No : To be arranged by XEN (M&E) as per availability

19.16.6 Names of local contractors working at OOT Vadinar

1. Rajlaxmi Construction, P.O. Vadinar. Phone No. 02833-256789/256505 - Contact person: Shri C.R. Jadeja.
2. Shree Shakti Construction, P.O. Meghpar (Padana) Ph. No. 246314 / 246411 Contact Person: Shri Pradumansinh G. Zala.
3. M/s Jai Chamunda Enterprises, Vadinar 361010 Contact person: Ranmal Vira, Ph. No. 02833-256719
4. Shri Kama Mala, Vadinar 361010.
5. Shri M. B. Jadeja, Vadinar 361010.
6. Shri Ganesh Construction, Village-Kajurda, Tal. Khambhalia Contact person: Shri Kherajbhai
7. Shri Hira Punja Rathod, Vadinar 361010
8. M/s. Shiraji Construction, Vadinar.
9. Shree Ashapura & Co Vadinar 361010 Ph No. 02833-256711
10. M/s. Bariya & Co., Near KPT colony, Vadinar.



19.16.7 Important Telephone Nos of IMD <http://www.imdahm.gov.in/index.html>













19.16.8 List of Vehicle Hire / Transport Travel Contractors at Jamnagar









Sr.No	Name and address of Transport / traveler	Telephone
1	Pavan Travels, Pancheshwar tower, Jamnagar	2552002
2	Patel Travels, Pancheshwar tower. Jamnagar	2552419 /


		2660243
3	Ashwamegh Travels, Jamnagar	2670613
4	Sheenath Travels, Jamnagar	2663315 / 2662215
5	Royal Travels, Opp. Town Hall, Jamnagar	2553333 / 2553636
6	Pruthvi Travels, Sikka Patia, SIKKA (Jamnagar.)	244466
7	Shree Divya Travels, Jamnagar	2677601
8	Payal Travels, Jamnagar	2551514 / 2551415
9	Gujarat Travels, Jamnagar	2664315
10	Abhishek Travels, Jamnagar	2564380
11	Shiv Shakti Travels, Jamnagar	2566611
12	Sapan Travels, Jamnagar	2558558
13	Tulshi Travels, Jamnagar	2541054
14	Samay Travels, Jamnagar	2551925

19.16.9 Chart of Weather Warnings

Signal No.	Symbol Day	Symbol Night	Type of Warning	Description
I			Cautionary	There is a region of squally weather in which a storm may be forming.

II			Warning	A storm has formed.
III			Cautionary	Port is threatened by squally weather.
IV			Warning	The Port is threatened by storm, but it does not appear that the danger is as yet sufficiently great justifying extreme measures of precautions.
V			Danger	The Port will experience severe weather from a storm of slight or moderate intensity that is expected to cross the coast to the south of the port.
VI			Danger	The Port will experience severe weather from a storm of slight or moderate intensity that is expected to cross the coast to the north of the port.
VII			Danger	The Port will experience severe weather from a storm of slight or moderate intensity that is expected to cross over or near to the port.

VIII			Great danger	The Port will experience severe weather from a storm of great intensity that is expected to cross to the south of the port.
IX			Great danger	The Port will experience severe weather from a storm of great intensity that is expected to cross the coast to the north of the port.
X			Great danger	The Port will experience severe weather from a storm of great intensity that is expected to cross over or near to the port.
XI			Failure of communication	Failure of Communication with Meteorological head quarters has broken down and the local officer considers that there is danger of bad weather.



19.17 Vadinar Oil Terminal Limited (VOTL) of Essar

19.17.1 Facility Description

Vadinar Oil Terminal Limited (VOTL) is a wholly owned subsidiary of Essar Shipping & Logistics (ESLL) with a focus on investment in crude and product terminals. VOTL has set up a 32 Million tone terminal with crude reception and crude and product storage facility at Vadinar, Gujarat, India.

The VOTL facilities serve the following functions:

- Receiving crude oil from tankers at an SPM located in the Gulf of Kutch, with transfer of crude oil via pipeline to the VOTL crude storage facility, located within the fence – line of the EOL refinery;

- Receiving product from the refinery into a product tank farm, also located inside the Refinery fence-line for loading into tankers at the marine terminal jetty;
- Receiving seawater from the intake well that is pumped via pipeline to the EOL refinery, and then discharging seawater via the seawater outfall located near the location of the SPM.

The crude oil tank and product tank farms, which are located inside the fence - line of the EOL refinery, while owned by VOTL, are actually operated and maintained by the Refinery, and were not covered by this HAZID or the ERA. (These tanks farms have been risk assessed separately).

The areas where the Marine Terminal and the SPM are located in the Gulf of Kutch are part of a designated and controlled marine park and represent a sensitive marine environment. The on-land pipelines pass through low lying areas which consist of some farming land and are adjacent to several villages.

The VOTL marine terminal facility consists of the following systems for supporting the aforementioned functions:

- A Single Point Mooring (SPM) and Subsea Line for loading crude:

The SPM buoy is the gateway for crude oil input to the EOL refinery. The SPM is anchored to the seabed in the Gulf of Kutch, in around 35 m of water. Tankers are secured to the buoy via mooring hawsers. The tanker is held off the SPM by a pull-back tug. The offloaded crude oil is pumped by the crude tanker pumps through the floating hose(s), through the SPM, and then via flexible catenary hoses into the 48" rigid subsea pipeline, through a PLEM and then flows directly to the crude oil tank farm located within the EOL refinery. The SPM is located roughly 4Km from the Marine Terminal and 8Km from the crude oil pipeline landfall.

- Seawater Intake Unit and Outfall system:

Seawater is pumped from the seawater intake facility (located at pathfinder Creek, adjacent to the jetty) and delivered to meet the water needs of the refinery. Seawater flows through two filter packages in the seawater intake well and is then pumped to a seawater storage reservoir located in the Refinery via a 48" GRP pipeline. Chlorine is added to the seawater downstream of the pumps at the intake facility for prevention of marine growth in the pipeline and the Refinery seawater reservoir.

The seawater outfall dispose of waste brine (high salinity water) generated from different Refinery units through a diffuser located on the seabed close to the location of SPM. The seawater outfall flow is pumped from a seawater return reservoir at the Refinery through an on-land 48" GRP pipeline and then via an 8Km subsea pipeline.

- A jetty including three (3) Loading Arms:

The jetty is located at the inlet to pathfinder Creek, and is situated between two coral reefs which are part of a declared "Marine National Park". The jetty is used for shipping of refined white and black products to vessels. The jetty is connected with the refinery through 3 x 32" diameter pipelines which bifurcate into 7 x 24" lines on the trestle and finally culminate into three (3) loading arms. Each of the 7 x 24" lines are allocated to each of the seven (7) products handled at the jetty, namely: ATF (aviation turbine fuel), kerosene, MS 87 (motor spirit), MS 95 (motor spirit), naphtha, diesel and VGO / FO (vacuum gas oil and fuel oil). Tanker at the jetty is located via pipelines connected through three sets of loading arms with Quick Connector Disconnect Coupling.

- A pig station with three (3) Pig Receivers / Launchers and Terminal Area Slop Tank:

Pigging is carried out for clearing any previous pipeline content, separation of cargoes, cleaning inside pipeline coating and assessing any leak- buckle or damage- deformation in the internal section of pipelines (intelligent pigging). Products for export are pumped from the refinery to the jetty through 3 x 32" diameter cross- country pipelines. There are two (2) pipelines for white products (naphtha, MS, ATF, Kerosene, and diesel), and other is for black products (VGO / FO). To enable the flexibility of these pipelines to carry different products, pigging is carried out between the Refinery and the Marine Terminal Pigging station, where each line has its own pig receiving and launching facilities (total of 3 pig receivers / Launchers).

A slop tank is also provided for the pig stations to contain / collect liquid product drained from the pig station, and it is also used for transfer of products drained into the jetty Slop Tank (which are transferred by pump). Products drained into the slop tank are removed as required by an educator truck and taken back to the EOL Refinery where they are reprocessed.

- Pipelines between Terminal and Refinery (including crude oil and seawater lines) include the following:
 - 3x 32" diameter cross- country pipelines (two (2) pipelines for white products, and one for black products) between refinery and marine terminal (around 18 km in length)
 - Crude oil pipeline (48") between refinery and landfall (13 Km), and then a further 8Km of 48" subsea pipeline to the PLEM on the seabed below the SPM
 - Seawater intake (48") between marine terminal and refinery (17Km), and seawater outfall (48") between refinery and landfall (13 Km) plus 8Km of subsea line to the outfall diffuser.

All pipelines are buried on land within an earthen berm. Steel lines are wrapped and cathodic protected (crude / product lines). The seawater lines are GRP. There are no flanges or connections on crude / product lines on –land (other than at marine terminal for product), and only air vents are provided along the seawater lines. The subsea crude oil pipeline is concrete encased, with the only flanges at the point of landfall and at the subsea PLEM.

- Buildings including the Main Terminal Control Building (MTCB) and two substations (main substation located near the seawater intake station, and jetty substation).

The response strategy for the VOTL plan has been developed taking into account the spill risks, and possible sources of spillage associated with Marine Terminal operations including those at the SPM and Jetty berths and facilities within the Port.

The geographical area of operations is bound by, but not limited to, one mile either side of the line joining following coordinates.

SPM	:	690 39' 35" E
		220 30 14"N
LFP	:	690 43' 26"E
		220 27' 59"N
Berth B (North End)	:	690 40' 10.26"E
		220 27' 15.25"N
Berth A (South End)	:	690 40' 11"E
		220 26' 54"N
Sea Water Intake	:	690 40' 32"E
		220 26' 11" N

19.17.2 Oil Spill Risks

19.17.2.1 Identification of activities and risks

Oil spills will be categorized in accordance with the internationally recognized three tier classification system

Tier One	100 - 700 T
Operational spillages which can be dealt with using the resources immediately available	
Tier Two	700 – 10000 T
Medium size spillages which exceed VOTL resources and which require District and/or Regional assistance	
Tier Three	10000 > T
Large spillages which exceed the full resources of the District/Region and which may require National assistance and/or the implementation of the NOS - DCP	

19.17.2.2 Types of Oil likely to be spilled

No.	Oil Type	Strategy Figure	Specific Gravity	Genre	Characteristics	Examples
1	Light Oil	5.1	< 0.84	White oils	Non-persistent, Volatile	Aviation fuel, Kerosene, Motor spirit, Naphtha, HSD
2	Crude Oil	5.2	> 0.84	Black oils	Persistent, Viscous, Emulsion. Fresh oil amenable to dispersants	Arabian Light, Arabian Heavy, etc.
3	Heavy Oil	5.3	> 0.95	Black oils	Persistent, Viscous, Emulsion. Generally not amenable to dispersants	Fuel Oils, LSWR

Probable fate of spilled Oil

19.17.3 Preliminary Assessment

The ICG Coordinator will make a preliminary assessment of the incident by contacting the person reporting the spill, governmental officials, and the responsible party.

- Evaluating the magnitude and impact of the discharge or threat of discharge on the public health, welfare, and the environment;
- Determining in which jurisdiction the incident occurred;
- Determining or confirming the responsible party;
- Determining or confirming the source of the spill;
- Determining whether the spill has been stopped or is ongoing, and if ongoing, how quickly it can be controlled;
- Assessing the need for state assistance; and
- Assessing the feasibility of removal and determining the equipment needed to remove the oil.

19.17.4 Containment & Control

Clean-up actions must begin as soon as possible to minimize the effect on natural and economic resources. These actions may include locating the source of the discharge and preventing any further spillage, placement of containment boom to control the spread of oil and to protect sensitive areas, measuring and sampling, physical removal of the oil from water and land, the use of chemicals to herd or disperse the oil, and in situ burning.

19.17.5 Development of Oil Spill scenarios

VOTL is operating 02 Nos. Berths (A & B) for product evacuation & 01 No SPM for crude intake.

The VOTL is capable of accepting vessels ranging from 25000 to 100,000 DWT each at berth A & B and Vessels ranging from 87,000 to 325,000 DWT at SPM.

The Marine Terminal is located within an area which has been declared as a Marine National Park / Marine Sanctuary.

The mean tidal range is approximate 6 meters and current speed in excess of 2 knots may be experienced alongside jetty.

19.17.6 Port Operations

19.17.6.1 Pilotage

Pilotage is compulsory for all vessels. Pilotage and auxiliary support craft services are provided by Kandla Pot Trust (KTP).

19.17.6.2 Main Approach Channel

The least depth in the main approach channel to the tanker jetty is 13 meters; the maximum acceptable draft alongside jetty berths is 15 meters. A minimum under keel clearance of 6% of vessel's maximum sea going draft plus 0.60 meters is applied to all vessels under way.

While the risk of grounding is low, it cannot be wholly eliminated. The most likely cause is steering or propulsion system failure which could result in grounding on the channel margins with consequent damage to the bottom and/of the mid body plating. The potential spill quantities depend upon the size / type of tanker and the area of impact damage.

The vessels calling the product terminal, in bound and out bound will be escorted by minimum two tugs in fair weather condition. This considerably reduces the risk of the vessel running aground in the channel.

19.17.6.3 Approach to SPM Berth

Tankers bound for SPM will follow the deep water route. Berthing and un-berthing of the Tankers on the SPM will be done by KPT Pilots. Charted depth at SPM location is 34.5 meters. Grounding of Tankers in the SPM area is considered as very remote.

19.17.7 Oil Spill scenarios

19.17.7.1 Collision between Vessels Underway

The control which will be imposed on ship movements within terminal are designed to ensure that any risk or collision is minimized. For example, inward / outward bound ships will have sole occupancy of the approach channel to the jetty berth; additionally all departing vessels will remain under Pilotage up to the western limit of the terminal area. It is thus considered that the likelihood of collision between vessels underway within the terminal is remote. There is perhaps a greater risk of collision between vessels maneuvering to the SPM and the jetty anchorage position without Pilotage assistance.

19.17.7.2 Berthing incident (Jetty)

Oil spills can occur as a result of hull contact with the corners of breasting dolphins during ship berthing or un-berthing maneuvers. Such incidents are generally due to failure of a vessel's main propulsion or steering systems, loss of control onboard an attendant tug or pilot error or misjudgment. The potential spill quantities involved depend on the vessel type and the location and extent of the impact damage.

19.17.7.3 Tug impact

There are well documented incidents where cargo or bunker oil has been released as a result of hull impact damage by tugs. This can occur when tugs are approaching a vessel underway prior to berthing, or when coming alongside a moored vessel prior to un-berthing. The potential spill quantities again depend on the location and the extent of the impact.

Adequate fenders shall reduce the level of risk.

19.17.7.4 Cargo Transfer Operations (SPM Berth)

This section considers the potential sources of oil spills during the discharge of crude oil cargoes and is based on oil industry data and ITOPF statistics. It should be noted that the ITOPF statistics demonstrate that most oil spill incidents occur during routine cargo handling operations and that some 91% of these incidents resulted in spillages of less than 7 tones.

19.17.7.5 Connection of Floating Hose String

After the floating hoses have been lifted on board, blank flanges are unbolted from the ends of the hoses prior to connecting them to the ship's presentation flanges. Small spillages frequently occur during the removal of the blank flanges; these are caused by surging of the line contents as the floating hose sections

follow the wave pattern. While in most cases such spillages are contained within the ship's manifold drip tray, there are recorded incidents where oil has escaped overboard via scuppers, which have not been effectively plugged. Spillages of this nature should not exceed 1 m3.

19.17.7.6 Snapping of 24'' diameter Floating Hose

Spillage of crude oil due to snapping of a floating hose, during crude oil unloading operations @ 10000 m3/hr. estimated time taken for response is two minutes. Snapping of hose may occur due to accidental drifting of tanker, collision with SPM, the hose getting entangled due to movement of a tug boat very near to the SPM / Tanker, due to rough weather condition. Theoretically the quantity spilled would be 142 tons. Chances of a full bore snapping of the hose are classified as a rare phenomenon.

19.17.7.7 Sea and Overboard Discharge Valves

Oil can escape to the sea via sea or overboard discharge valves which are directly connected to the cargo pipeline system due to either incorrect line setting or defective valves. The likelihood of this occurring is considerably less on SBT vessels.

19.17.7.8 Slop Tank Overflow

Crude Oil Washing (COW) of cargo tanks will be undertaken during bulk cargo discharge; this operation entails the transfer of tank bottoms and washing oil back to back to the vessel's slop tank(s). The overflow of slop tanks as a result of instrumentation failure or operator error during this process is not uncommon. Checks on the system and operation, pre, during and post COW will considerably lower the associated risk.

19.17.7.9 Vessel Breakout

Other than a sudden and catastrophic failure of the mooring hawser leading to rupture of the floating hose string, it can be reasonably assumed that cargo discharge will have been suspended in weather conditions which approach the established environmental limits. It would also be normal practice to station a crewmember on the forecastle head to maintain a mooring watch. Under most circumstances, therefore, early warning of a potential breakout situation can be anticipated.

In any event, an emergency stop button for the main cargo pumps will be located at the ship's manifold and the deck watch keeper would initiate an ESD immediately the hose string parts.

A vessel breakout and loss of integrity of the floating hose string could result in a spill quantity of some 142 m³. This quantity is based on the following assumptions:

- Bulk flow rate
- Reaction time
- ESD activation time
- Hose contents

In case of undue stresses experienced by the floating hose string, the breakaway couplings will get activated. These are designed to seal both ends on activation.

19.17.7.10 Hull Failure

The incidence of oil pollution due to hull failure is low and some 84% of the incidents attributed to this cause by ITOPF involved spill quantities of less than 7 tones; these spills were caused mainly by minor hull fractures and weld failures. The potential for more serious incidents with spill quantities in excess of 700 tones must, however, be acknowledged.

19.17.7.11 Fire and Explosion

Fires and explosions onboard ship represent a safety hazard with the risk of oil pollution as a secondary impact. All tankers engaged for trading to the SPM facility will be equipped with inert gas systems; gives the control which will be imposed and enforced by VOTL in respect of the oxygen content of cargo tanks, the risk of fire and / or explosion in the cargo spaces must be regarded as minimal.

Strict monitoring and control of the main cargo pump room atmosphere will minimize the fire and explosion risks associated with this space.

Fires resulting from uncontrolled smoking in the accommodation, organization hot work such as welding and engine room fires can spread rapidly if not dealt with swiftly and give rise to incidents of a very serious nature.

While the likelihood of fire or explosion occurring onboard vessels berthed at the SPMs is low, the risk is nevertheless acknowledged. Such an incident could give rise to a spillage of 700 tons or more.

19.17.7.12 Spillages of Fuel Oil

Fuel oil bunkers will not be supplied to tankers moored to the SPM. It may, therefore, be necessary for vessels to undertake the internal transfer of fuel oil for trim or other operational reasons. A bunker tank overflow during such operations could result in spillages of < 1 ton.

Cargo Transfer Operation (Jetty Berth)

19.17.7.13 Ballast Discharge

Only fully SBT (Segregated Ballast Tank) vessels shall be chartered for trading to the Marine terminal; those ships which load refined products will also discharge their segregated ballast water concurrent with the loading operation.

Under fair weather and operational conditions, tankers at SPM will not engage in de-ballasting activity.

On some older designs of SBT tankers, the ballast pipelines pass through the cargo tanks and vice versa, any loss of ballast line integrity can result in the entrainment of cargo oil in the ballast water discharge. Industry records indicate that the spill quantity from this cause on board product carriers should not exceed 25 tones.

19.17.7.14 Loading Arms

The operation of loading arms can lead to minor releases of oil. Common sources are vent valves, swivel joints and hydraulic lines. Loading lines are equipped with PERC (Powered Emergency Release Coupling) and with DDV (Double Disk Valve)

19.17.7.15 Cargo Tank Overflow

Cargo tank overflows can occur on board loading vessels; spills of this nature can be due to instrumentation failure or human error. The spill quantity is a function of the flow rate and also the number of tanks being loaded at the time of the incident. Some of the oil will be retained on deck but in a worst case scenario, some oil could go overboard.

19.17.7.16 Hull Failure - Fire and Explosion

The risks of hull failure - fire and explosion are also similar to those for SPM vessels with the attendant spill quantities being proportional to the tanker size.

19.17.7.17 Effluent Discharges

Treated effluent from the refinery is discharged into the sea area. The discharge consent levels are set and monitored by the State Pollution Control Board and VOTL regularly tests for effluent quality.

Instrumentation malfunction, failure of in-line samplers or operator error can result in the entrainment of oil in the final discharge to harbor waters. Most spillages of this nature are not substantial, and based on industry experience elsewhere, are unlikely to exceed 5m³ in volume.

19.17.7.18 Special Equipment which may be used

- Workboats
- Trucks / cars (four wheel drive)
- Radio transmitter / receivers
- Workshop / repair facilities
- Bulldozers, mechanical scrapers and similar earthmoving equipment
- Vacuum trucks
- Tank trailers
- Life vests
- Explosive meters

19.18 Fire Fighting Facilities at Vadinar Oil Terminal Limited (VOTL) of Essar

19.18.1 Fire water supply pumps at Sea Water Intake

Fire pumps are vertical turbine type as per IS 1710

Dedicated fire pumps are provided for:

1. Fire Tower monitor system
2. Fire Hydrant System (There is no interconnection between two header)

19.18.2 Fire water Pump for Tower Monitor – 4 Nos

- a. Main Motor Driven Pump – 1 No (Discharge capacity 792m³/hr at 15 kg/cm²).
- b. Engine driven – 1 No (Discharge capacity 822m³/hr (standby)).
- c. Jockey Pump (Discharge capacity 33m³/hr at 10.5 kg/cm²).

19.18.3 Fire water Pump for Hydrant System – 4 Nos

- a. Main Motor Driven Pump – 1 No (Discharge capacity 792m³/hr at 15 kg/cm²).
- b. Engine driven – 1 No (Discharge capacity 822m³/hr (standby)).
- c. Jockey Pump (Discharge capacity 33m³/hr at 10.5 kg/cm²).

19.18.4 Fire Hydrant & Jumbo Curtain

Fire Hydrants is located at different section of premises to be protected depending upon nature of fire hazard, fire hydrants are double outlet type.

Each outlet capacity is 900 lpm at 7.5 kg/cm²

The flow rate of hydrant is 1800 lpm at 7.5 kg/cm²

19.18.5 Fire Hydrant Point – 31 Nos

- a. Berth A - 4 Nos
- b. Berth B – 4 Nos
- c. Pig area / cross country / MTCB – 16 Nos
- d. SWI – 03 Nos
- e. Between Berth A & B – 4 Nos

19.18.6 Jumbo Curtain at Berth A

The Jumbo curtains nozzle shall have discharge capacity of 3000 lpm of sea water at 7.5 kg/cm².

Total – 6 Nos of Jumbo Water Curtain

The nozzle shall be able to produce 14 meters. Vertical plane & 20 meters horizontal radius dense water curtain through 160 degree angle – 04Nos at jetty to protect loading arms and – 2 Nos one each at the breasting dolphin to protect tower monitors from the radiant heat in case of fire on tankers.

19.18.7 Jumbo Curtain at Berth B

The Jumbo curtains nozzle shall have discharge capacity of 3000 lpm of sea water at 7.5 kg/cm².

Total – 02 Nos of Jumbo Water Curtain

The nozzle shall be able to produce 13.5 meters. Vertical plane & 22 meters horizontal radius dense water curtain through 180 degree angle – 02Nos at jetty to protect loading arms.

19.18.8 Water / Foam Tower Monitor at Berth A

The monitor shall be suitable for both sea water and foam, each monitor shall be capable of discharging 6000 lpm of sea water and 36000 lpm of expanded foam at 10 Kg.cm² over a range of 100 meters in horizontal direction and 40 meters range in vertical direction. The monitor shall be capable of producing good quality of finished foam.

Horizontal range with water – 100 meters Horizontal
range with foam - 90 meters

The monitor shall be capable of 360 degree rotation in either direction in horizontal plane and 60 degree elevation 70 degree depressions in vertical plane. The monitors shall be achieved by remote control from control room.

Two nos of positive displacement pump have been provided. At a time one pump will be running and other will be acting as stand by. The Capacity of each pump 21.6 m³/hr at 16kg/cm²

19.18.9 Foam Compound Induction

Foam compound induction system is in line with balanced pressure proportioning type to ensure proper mixing of foam concentrate and right proportion and supply the same to the monitor line depending upon the water flow rate necessary automatic valve, spool valve and duplex pressure gauge have been provided to ensure 0 to 6% of foam compound induction.

Induction rate is set at 3% foam compound induction.

19.18.10 Water / Foam Tower Monitor at Berth B

The monitor shall be suitable for both sea water and foam, each monitor shall be capable of discharging 6000 lpm of sea water and 36000 lpm of expanded foam at 7 Kg.cm² over a range of 75 meters in horizontal direction and 35 meters range in vertical direction. The monitor shall be capable of producing good quality of finished foam.

Horizontal range of monitor – 75 meters

The monitor shall be capable of 360 degree rotation in either direction in horizontal plane Elevation – (+) 85 and (-) 45. The monitors shall be achieved by remote control panel near pantry in open area.

19.18.11 Foam supply system at Berth B

Foam supply system shall be operated by manually, located near Foam Tank, Foam supply system located at approximately 50 meters away from Berth B central platform. Since the pipeline will always be under pressure for throwing water / foam through the monitor:

One No foam solution storage tank is provided at south side of berth B with capacity of 16KL.

Foam pumps – 2 Nos (01 No stand by)
Each pump discharge capacity is – 37m³/hr

Two nos of positive displacement pump have been provided. At a time one pump will be running and other will be acting as stand by. The Capacity of each pump 37 m³/hr at 16kg/cm²

19.18.12 Foam Compound Induction

Foam compound induction system is in line with balanced pressure proportioning type to ensure proper mixing of foam concentrate and right proportion and supply the same to the monitor line depending upon the water flow rate necessary automatic valve, spool valve and duplex pressure gauge have been provided to ensure 0 to 6% of foam compound induction.

Induction rate is set at 3% foam compound induction.

19.18.13 Foam Trolley

Foam trolley is firefighting equipment ready to use initial level in case of fire, oil spillage in dyke.

Foam trolley capacity – 200 liters Discharge capacity – 225 lpm

Total – 8Nos of foam trolley available in field.

- Berth A – 2 Nos
- Berth B – 2 Nos
- Pig Area – 3 Nos
- SWI - 1 No

19.18.14 Ground Fixed Water cum Foam Monitors

Fixed foam monitors are ready for instant use in case of emergency and are able to discharge dense foam from orifice type foam nozzle. The discharge capacity of monitor is 2850 lpm

Monitor having facility to discharge water for cooling purpose, all fixed foam monitors are having 200 liters foam drum ready to use by monitor pick up tube.

Total – 4 Nos

- Pig Area – 2 Nos
- Berth B – 2 Nos

19.18.15 Fire Extinguisher

Portable Fire Extinguishers are the first aid of fire fighting equipments. All fire extinguishers installed in the jetty premises are clearly visible and accessible.

At Berth A

- DCP 75 Kg –4 Nos • DCP 50 Kg –2 Nos • DCP 10 Kg –6 Nos

At Berth B

- DCP 75 Kg –4 Nos
- DCP 10 Kg –6 Nos
- CO2 6.5 Kg –2 Nos

Other jetty area locations are also equipped with fire extinguishers

19.18.16 Innergen Total Flooding System

Innergen Total Flooding System has been designed for protection of MTCB floor underneath cabling and DCS instrument panels. It is automatic fire extinguishing flooding system. The contents of gas are (52% nitrogen gas, 40% argon gas, 8% CO₂ gas)

The system is kept in both auto / manual mode operation. There are 12 Innergen gas cylinders which are pressurized to 200 bar at 20 Degree Centigrade for fire protection system.

Innergen Total Flooding system is divided in five different Zones.

Zone 01 & 02: is instrumentation room, Ground Floor MTCB (There are 6 Nos discharge nozzle of Innergen System)

Zone 3: is panel room right side (There is 1 No discharge nozzle of Innergen System)

Zone 4: is panel room left side (There is 1 No discharge nozzle of Innergen System)

Zone 5: is Battery Room Ground Floor MTCB (There is 1 No discharge nozzle of Innergen System)

The system has been put in manual mode.

19.18.17 Manual Call Point (MCP)

MCPs have been installed in premises in different accessible & visible locations like:

- Berth A
- Pig Station
- Around MTCB Building
- SIW & Berth
- All MCP are indentified with Zebra cross red and yellow

In case of Emergency Alarm to be raised MCP glass should be used.

Total 69 Nos of MCPs are in premises connected to DCS panel. On activation of any one MCP alarm will be blow on DCS

- Berth A – 13 Nos
- Berth B – 6 Nos
- Pig Area – 7 Nos
- MTCB – 6 Nos
- SWI / SS – 12 Nos
- Road / Tresle / KPT – 25 Nos

19.18.18 Smoke Detectors

Smoke detectors have been provided inside building (MTCB) cable cellar room, electrical panel room, instrument panel room.

Due to availability smoke particles detector will get activated. Fed Red Becon & hooter will start and on DCS alarm will be sounded repeatedly.

Total No of Smoke Detectors – 68 Nos

19.18.19 Fixed Gas Detectors

Fixed gas detectors have been installed in the jetty premises where most critical hazardous zone is identified.

Fixed hydrocarbon detector detects the hydrocarbon vapours available in the atmosphere and it gives pre explosion alarm. The alarm is set at 10% of LEL.

Total No of Gas detectors – 25 Nos

- Berth A – 6 Nos
- Berth B – 6 Nos
- Pig Area – 5 Nos
- SWI / (H₂) / MTCB – 8 Nos

19.18.20 Life Saving Appliances

1. Life Buoy Ring – Life buoy ring with 30 meters 8 Inch Nylon rope have been installed in entire jetty premises. Total No of Life Buoy – 29 Nos
2. Life Work Vest – Life work vest have been installed in emergency almirah at berth A and Berth B and also installed at central platform of berth and SWI. Total No of Life Work Vest – 18 Nos
3. Life Jacket – Life jacket is available with the terminal whenever persons go to the SPM / Sea shore side life jacket has to be worn. Total No of Life jacket – 12 Nos

19.18.21 Emergency Escape Breathing Device (EEBD)

Emergency Escape Breathing Device is used to escape from place where emergency arises and it is difficult to reach a muster point / safe place, same shall be used in such emergency.

EEBD is ready to use for 15 minutes to see the person can be reached to safest place with normal breath.

Total Nos of EEBD – 5 Nos

- Berth A – 1 No
- Berth B – 1 No
- Pig Area – 1 No
- SWI – 1 No
- Store – 1 No

19.18.22 Breathing Apparatus Set (BA Set)

B A set is to be used in such emergency where it is difficult to breath during rescue operation. Fire Fighting, Toxic gas release, and Flammable gas in atmosphere.

B A set has been installed in jetty premises where it is most hazardous so it can be used immediately whenever necessary.

Total No of B A set – 6 Nos & 2 Nos Spare Air Cylinder

Emergency Almirah Berth A – 2 Nos

- SWI – 2 Nos
- MTCB – 1 No
- Store – 1 No

19.18.23 First Aid Box

First Aid Box is distinctively marked with a red cross on a white background. First aid box is kept in prominent place. Custodians of the first aid boxes are qualified first abiders only.

The names of the first aiders are displayed at the notice board of the control room.

The first aiders are available in each shift.

First aid box available at site – 8 Nos

First box location available in jetty premises and their locations are:

- MTCB – 1 No
- Berth A – 1 No
- Berth B – 2 Nos
- SWI – 1 No
- Security Gate – 1 No
- 70 – 1 – 1 No • 76 – 2 – 1 No

19.18.24 Portable Safety Instrument

1. Area Monitor – Area monitor is available in control room. It is used for continuous monitoring of hydrocarbon vapors in atmosphere. The area monitor lowest alarm is set at 5% of LEL on reaching this range area monitor will be sounding with high volume.

Area monitor is used in hot work area where the most critical hazardous area are identified such as Berth A / Berth B

2. Portable Multi Gas Detector – Multi gas detector is always available in control room and in the field with the fire men. Whenever any hot work permit is issued by SIC, Safety team checks the area and residual hazardous of concerned location and ensures that no hydrocarbon vapor is in the atmosphere. Stand by fire man continuously monitors and makes sure that the LEL always is 0%.
3. Chlorine Meter – The device is widely used for check the work environment before entering the chlorination room / area.
4. H₂S Meter – Very useful device for working crew for confined space work. I.e. Vessel, Tank & nearby hazardous area for continuous monitoring work environment.
5. Oxygen Resuscitator – It is a medical equipment and to give oxygen to casualty by trained person.

19.18.25 Chlorination System at SWI

Chlorine gas is most toxic and corrosive gas. In case of leak and in coming in contact with the skin irritation starts, inhalation is most dangerous if more than 15ppm it will be IDLH (Immediate Danger Life & Health)

Chlorine tonners have been laid down at chlorination system for chlorine injection in sea water line which is going to refinery.

3 Nos of fixed chlorine detectors have been provided at three different locations.

1 No Caustic Soda Tank capacity 8000 Liters with blower and hood

Hood provided on running cylinder, the detector laid would sense 0.5ppm in case of a leak. The blower starts automatically.

Chlorine containment kit & 2 Nos BA set is available in the SWI store.

19.18.26 Chlorine Kit

It is used for containment of chlorine gas in case chlorine leakage from the tonner valve assembly, plug or from body.

Work Permit System

Any routine work, testing of equipment, inspection, schedule maintenance, concern has to take work permit for particular job. SIC will make sure that before issuing work permit receiver must have completed TBRA & TBEA and also tool box talk.

- Hot work permit
- Cold work permit
- Electrical Isolation & restoration
- Confined space entry permit
- Vehicle entry check sheet
- Photography permit check sheet
- Isolation of fire fighting network
- Radiography check sheet.

19.19 Off Shore DMP of Indian Oil Corporation (Vadinar)

19.19.1 Introduction of Facility

Indian Oil Corporation (IOC) Ltd (Pipelines Division) owns and operates two offshore oil terminals in the Gulf of Kutch at Vadinar. The terminals are intended to handle the combined throughput requirement of its three refineries at Koyali, Mathura and Panipat. The oil terminal facilities comprise of two nos. Single Point Mooring (SPM) systems for moorings of tankers, off-shore /on-shore pipelines, the shore terminal comprising of 13 nos. of floating roof tanks with the total storage capacity of about one million tone and originating pumping station through which crude is pumped to the refineries at Koyali, Mathura and Panipat through the Salaya -Viramgam, Viramgam - Koyali, Viramgam-Chaksu, Chaksu-Mathura and Chaksu-Panipat pipeline system.

The offshore oil facilities are connected to the shore tanks by means of 1067 mm (42") dia. submarine pipeline of about 5.3 KM for SPM-I and 6.3 Km for SPM-II followed by twin 1067 mm (42") dia. onshore pipelines of 5.7 KM length each. Another 2.1 Km loop line of 1067 mm (42") dia. is also laid to interconnect the Pipe Line End Manifolds (PLEM) of both SPMs to facilitate shore based pigging operation of both offshore and onshore pipeline. A sketch showing the above is enclosed as Annexure-I. For operational flexibility, sub-sea isolation valves are provided at suitable locations. The tankers berthed at SPMs discharge the crude oil through two strings of floating hoses connected between the tanker manifold and SPMs, and two strings of submarine hoses connected between SPMs and the PLEM located at the end of the submarine pipeline at the seabed.

This off shore oil terminal in Gulf of Kutch near Vadinar together with its cross-country pipeline system to the refineries can be termed as a vital energy artery of the Western Region catering to the energy requirement of the entire Northwest region of the country.

19.19.2 Location of the SPM Terminal

The SPM facilities are situated within the territorial water of DEENDAYAL PORT TRUST(KPT). SPM-I is situated at Latitude 20° 30' 34" N and Longitude 69° 42' 04" E and SPM-II is situated at Latitude 22° 30' 14.36" N and longitude 69° 40' 53.60" E.

The drafts available at SPMs are 34.9 meters and 32.5 meters for SPM-I & SPM-II respectively. The KPT provides the infra structure as well as Pilotage facility for operating this terminal. The entry channel of approximately 126 km (70 Nautical miles) in the Gulf of Kutch is identified for the navigation of vessels by KPT.

A zone of 3.6 Km (2 nautical miles) around each SPM has been declared as the "No Anchorage Zone" and no vessel is allowed to anchor in this area to prevent fouling of their anchors with our SPM anchor chains or sub-sea hoses and the pipeline.

Hardware Details of SPM System at Vadinar

Sr No	Parameters	SPM – 1	SPM – 1
1	Capacity of Tankers to be handled	3,00,000 DWT	3,15,000 DWT
2	Mean Sea Level	34.9 MTR	32.5 MTR
3	Geographical Co – ordinates	LAT: 20° 30' 34 " N LONG: 69° 42' 04 " E	LAT: 22° 30' 14.36 " N LONG: 69° 40' 53.6 " E
4	Year of Commissioning	August - 1978	March - 1997
5	Off - Shore Line	5.3 KM	6.3 KM
	Loop Line Between SPM-I & SPM-II Is 2.1 Kms		
Hose Configuration			
(A) Floating Hose			
1	24" X 40' Half Float Hose	01 No in each String	01 No in each String
2	24" X 40' Decreasing Stiffness Hose	01 No in each String	01 No in each String
3	24" X 40' Standard Full Float Hose	21 Nos in STBD String & 22 Nos in Port String	20 Nos in STBD String & 21 Nos in Port String
4	Metallic Reducer	01 No in each String	01 No in each String
5	20" X 40' Full Float Hose	01 No in each String	01 No in each String
6	20"-16" X 40' Tapered Hose	01 No in each String	01 No in each String
7	16" X 35' Full Float Hose	02 Nos in each String	02 Nos in each String
8	16" X 30' Tanker Rail Hose	01 No in each String	01 No in each String

	Total Length in Meters in each string	Port STR: 331.83 STBD STR: 324.11	Port STR: 336.32 STBD STR: 324.13
(B) Submarine Hoses			
1	20" X 40' Carcass Double Submarine Hose	-----	04 Nos in each String
2	20" X 37.5' Carcass Double Submarine Hose	04 Nos in each String	-----
3	20" X 35' Carcass Double Submarine Hose	04 Nos in each String	04 Nos in each String
	Total Length in Meters in each String	OFF.SH : 44.20 ON. SH : 44.20	OFF.SH : 45.72 ON. SH : 45.72
	Type of Plem Valve Actuator	Rotary Vane	Spring Loaded

19.19.3 Tanker Operation

Tankers can be unloaded simultaneously from both the SPMs and any one SPM. The details of tanker operation are described below:

Pilots of KPT bring the tanker near SPM. There are two strings of floating hoses of 610 mm (24") dia for each SPM which are lifted by the crane of the tanker for connecting to tanker manifold. When the tankers are not there, these floating hoses are floating on sea and at the ends of the strings, butterfly valves are used to close/ blind the line and additionally blinds are fitted to avoid spillage of oil. Once the floating hose strings are connected to the tanker, the system is ready for discharge of cargo through SPM system.

Before commencement of discharge of the tankers, ullaging of the tanker is done and in the meanwhile shore tanks are also aligned and tank valves are operated for receipt of cargo into shore tanks. The inlet and outlet valves of the shore tanks are motor operated and can be closed within five minutes in case of any emergency or after the discharge of the tanker is over. KPT provides the tug for pull back operation to avoid tankers overriding the SPM buoy, under buoy hoses etc. to prevent damage to the buoy and oil pollution.

Further during the operation of the tanker, there is a constant watch on the SPM system and the hoses for any leakage or burst and the operating parameters are kept well within the designed limits besides observing all safety aspects for the safety of the tanker, buoy and its accessories. The work of connecting and disconnecting hoses and repair of lines has been given on contract. During discharge operations technical personnel from following agencies are always available:

- DEENDAYAL PORT TRUST
- IOC Salaya Mathura Pipeline (SMPL), Vadinar.

- M/S Underwater Services, Mumbai
- Crude Oil Tanker

There are isolating valves provided for isolation of the floating strings and under buoy hose strings for use in any emergency arising out of failure of hose or burst of hose during operation to prevent oil loss, pollution and to sustain operation through the other string. Thus by meticulously following the international marine standards of operations and maintenance the entire tanker discharge operation is kept totally spill proof.

Further the entire off-shore facilities are subjected to stringent inspection checks as per Oil Companies International Marine Forum (OCIMF) guidelines and rigorous preventive and schedule maintenance for the upkeep of the facilities/ equipment is done in order to avoid any unforeseen instances of hose burst, leaks or any other eventualities which may result in either small or large scale oil spills in the ocean.

19.19.4 Definition of Oil Spill Management

Accidental and unwanted discharge of crude oil in the sea during the operation of SPM system including accidental spillage, if any, from the oil tankers may be termed as an oil spill resulting into pollution of marine environment.

The oil spill may be minor, intermediate or major in nature depending upon the source and duration of the oil spill.

19.19.5 Oil Spill Classification

Oil spill can be broadly categorized into three categories depending upon the volume and area of oil spill, which has taken place. These three categories of oil spill are generally classified as Tier one, two and three and each Tier will require response strategies to suit its magnitude and manifestations as mentioned below:

TIER ONE

This would be a spill of a magnitude the local resources could respond to, successfully without assistance from other agencies.

TIER TWO

This would be a spill of a magnitude that would outstrip the local resources and would require assistance on a regional basis. This would either come from local/central Government or Local Industries Mutual Aid arrangement.

TIER THREE

This would be a spill of a magnitude that would surpass the capabilities of Tier one and Tier two. Additional resources would be required on a national and international level.

Clearly Tier one and Tier two levels of response equipment and manpower resources are governed by a number of criteria. These criteria are such as location, logistics for national and international assistance, nearby sensitivities and many others.

The following classification has been made as per OISD norms:

Tier Level	Volume
Tier –1	Up to 100 MT
Tier – 2	100 MT – 1000 MT
Tier – 3	More than 1000 MT

19.19.6 Risk Analysis & Causes of Spill

Accidental spill from tankers contribute an estimated 0.4 million tons annually globally. Analysis of tanker spills occurring throughout world shows that the majority occurs in port during routine ship operations such as loading, discharge and bunkering. The most of these spills are, however, relatively small. Over 92% are less than 7 tones and probably in total, contribute less than 20000 ton annually. In comparison, accidents, such as collisions and grounding give rise to less than 10% of oil spills from tankers, but a quarter of these are larger than 700 tons.

19.19.7 Spills Due to Collision

The statistical data shows that as a percentage of the total no. of incident, collision account for 5% of oil spill regardless of the quantity of oil released. The classification based on size of the spill shows more alarming statistics with 29% of all large spills (> 700 tons) being due to a collision. Almost 21% of the sizable spills involving the release of between 7 and 700 tons are due to collisions. Small spills of less than 50 barrel (7 tons) from a collision account for less than 2% of total.

19.19.8 Spills Due to Grounding

A similar analysis of statistical data shows that although as a percentage of the total incidence spills due to grounding are rather small, accounting for only 5.2 %. A different picture emerges when the quantities involved are scrutinized. Large spills of more than 700 tones caused by grounding account for 33% of all releases of that magnitude. Off the sizable spill between 7 - 700 tones about 18 % are a direct result of grounding. The small spills of up to 7 tones are fairly insignificant and are 2.7 % of the total spills in that category.

It is prudent to assume that in any collision or grounding, spill quantity may be more than 700 tones.

19.19.9 Most Likely Spills

The most likely maximum spill can result from a central compartment of a tanker being ruptured at the bottom of the hull releasing most of its contents. Quantities in the order of 7000 tones are therefore more probable due to the release of an assumed 90 % of the contents of a center tank of a typical 175,000 DWT single skin fully laden tanker ruptured due to grounding.

19.19.10 Collision with another Vessel

A collision with another vessel causing a tank to rupture will release only the contents of the tank above the water line. The ensuing spill caused by a gash in the tank resulting from a surface collision will release near about 1750 tones. Therefore the spill quantities in both the above scenarios pertaining to rupture due to collision and a bottom gash resulting from grounding are to be 1750 - 7000 tones when a single tank has been damaged.

19.19.11 Oil Spilled into Sea

Oil spilled into the sea undergoes a number of physical and chemical changes, some of which lead to its disappearances from the sea surface whilst others cause it to persist. The time taken depends primarily upon the physical and chemical characteristics of the oil, as well as the quantity involved, the prevailing climate and sea conditions and whether the oil remains at sea or is washed ashore.

In considering the fate of spilled oil at sea, a distinction is frequently made between nonpersistent oil, which tend to disappear rapidly from the sea surface, and persistent oil, which in contrast, dissipates more slowly and usually requires a clean-up response. Most crude oils and refined residual oils have varying degree of persistent depending upon their physical properties and size of the spill. The main physical properties, which affect the behavior of oil spilled at sea, are specific gravity, distillation characteristics, viscosity and pour point.

19.19.12 Most Small Oil Spills

Most spills will in fact be small, involving less than two tones and will occur mostly when the hose system failed at the terminal. This can usually be dealt with swiftly and efficiently by the terminal operator. Major spills are fortunately considered rare with estimated probabilities between one in 100 years to One in 220 years. In the event of such a large spill at the Gulf of Kutch efforts can be made either to contain and collect the oil using booms and skimmers, or to disperse it using chemical dispersant which are spread either from marine craft using side booms or aircraft (similar to crop spraying).

If oil is washed ashore on a hard sand beach, for instance, it can be quickly and effectively cleared by manual labour with the aid of trucks and bulldozers.

In some cases, bio-degradation method may be applied using bacteria to digest the oil which can halve the time that natural forces would take to achieve the same result. However, natural forces usually degrade any oil, which cannot be cleaned up, and such forces are exceptionally strong at the Gulf of Kutch and the effects of a pollution incident are rarely long term.

19.19.13 Impact of Second SPM at Vadinar

The second SPM was commissioned during March '97 at Vadinar location. Obviously this has an impact on the requirement for pollution preparedness.

It is felt that there will be an increase in the likelihood of a spill rather than the possible volume of oil spill. This position comes from the facts mentioned below:

Increase in vessel traffic.

Doubling of hoses, joints and other possible points of failure and Increases in connections and disconnection of hoses etc.

19.20 Responsibility during Emergency

The basic responsibility of combating oil spill disaster and marine pollution lies with the local port authority within its port jurisdiction and the defaulter companies/ organizations.

19.21 Chief Coordinator (Location Head, WRPL Vadinar)

- a. On getting information of oil spill, he will report to KPT authority and other resource agencies.
- b. He will co-ordinate all activities through Chief Operation Manager and Maintenance Manager (Marine).
- c. He will ensure that appropriate response and techniques are in action to clean up pollutants.
- d. He will ensure that all the resource agencies have been duly reported about incident.
- e. He will apprise Head of WRPL about the incident and actions undertaken.

- f. He will make arrangements for disposal of oil as per the directive of Regional Commander (West).
- g. He will be responsible for the resumption of Operations at SPM terminal.
- h. He will contact IOC (Shipping) and seek assistance required to meet the emergency.

19.22 Roles of IOC in Controlling Oil Spill Disaster

19.22.1 IOC Vadinar

- a. To assist KPT off shore oil terminal, and Coast Guard Vadinar action group, in implementation of local action plan.
- b. To assist KPT, Vadinar and Coast Guard Vadinar in obtaining additional available equipment and chemicals from identified resources if and when required.
- c. To assist in chartering/hiring of tankers to undertake transportation/ transshipment operation if so required by KPT.
- d. To arrange for storage of oil transshipped as above.
- e. To make assessment of the value of the oil transshipped.

19.22.2 IOC Shipping New Delhi

- a. To arrange for chartering tankers for Vadinar as required.

19.22.3 Indian Coast Guard – Central Coordinating Authority

- a. To receive the report of significant spillage of oil at sea.
- b. To keep the Ministry of Defense apprised of the development on receipt of information about oil spill.
- c. To decide upon the nature and extent of actions required and to advise the Regional Headquarters/Local Action Groups/authorities concerned regarding the action to be taken by the latter in consultation with Apex Committee on Control of Marine Pollution/Task Force on oil spills.

- d. To arrange for chartering of any tankers for oil transshipment operations, if required.
- e. If the resources available with the Regional Headquarters / Port authorities/other agencies, Local Action Group/authorities are inadequate, to mobilize all available and necessary resources and direct the same towards the concerned Regional Headquarters/Local Action Groups/authorities.

Regional Coast Guard Commanders (RCC)

- a. Receiving reports of oil pollution at sea.
- b. Coordinating the activities of RCC when activated.
- c. Keeping the Director General, Coast Guard apprised of developments.
- d. Processing and coordinating claims of the affected parties and participating agencies with a view to compilation for processing by Director General Shipping.
- e. Mobilizing Coast Guard resources to support On Scene Commander (OSC) action at spill area.
- f. Maintaining the Regional Contingency Plan (RCP) and forward revised plans to members as may be required by RCC.
- g. Receiving periodic reports from resource agencies on account of Pollution Equipment and material with a view to have an upto date inventory list in the Coast Guard western Region, Eastern Region and Andaman and Nicobar Region.
- h. Providing the administrative infrastructure to the RCC for conduct of routine and operational tasks.
- i. Providing additional sampling effort during spills when requested by OSC.
- j. Maintaining a list of national and international agencies that may be called upon to assist for pollution response at the discretion of RCC.
- k. Arranging for periodical exercise in pollution response.
- l. Providing sensor data to RCC/OSC as required.
- m. Pre-designating a Coast Guard OSC.

19.22.4 Responsibility of Port Authority

The port authorities will be responsible for response to accident / oil spill within Port Limits keeping the coast guard regional commander informed and request for any additional assistance through the Regional Communication/Operations Centers. The detailed responsibilities are as follows:

- a. To arrange for the preparation of a local contingency plan in consultation with Regional Head Quarter/Central Coordinating Authority.
- b. To identify a suitable sea going tug when required for operations
- c. To identify surface crafts
 - On which dispersant spraying equipment can be mounted and
 - Which can be used for rigging the booms
- d. To ensure that the purpose of part-XIII of Merchant Shipping Act, 1958, actions are taken by the various authorities under the overall legal receiver of the wrecks and dock concerned.
- e. To ensure that at least following minimum equipment is kept available locally at all time:

Inflatable booms

Dispersant spraying equipments capable of being mounted on surface craft.

Suitable dispersant chemicals of the nature and quantity estimated as requirement of Local Action Group as part of the local contingency plan.

Oil skimmer equipment

- a. Surface crafts on which above dispersant equipment can be mounted and which can be used for rigging booms etc.
- b. To arrange for training of personnel expected to be engaged in above operation.
- c. To arrange for periodic exercise under the guidance of the RCC to keep equipment and personnel on continuous readiness for oil spill response operation.
- d. To consult the Coast Guard or Director General Shipping or any other authority, when further advice/assistance is required.

- e. To keep the Coast Guard apprised of actions being taken.

19.22.5 Responsibility of Boarding Officer

- a. Inform Chief Crisis Coordinator / Alternate Chief Crisis Coordinator, Maintenance Manager (Marine), IOC Control room, Marine Department about the oil spill incident.
- b. Stop the cargo or slow down the cargo as may be the case and accordingly isolate the affected portion causing the oil spill.
- c. Instruct the O&M contractor to fight the oil spill & locate the source of oil spill and coordinate with various agencies for oil spill containment.
- d. To carry out the water flushing of the SPM system as per the requirement in coordination with IOC control room.

19.22.6 Reporting & Alerting Procedure

After knowing major oil spill, Chief Coordinator, IOCL is to report the same immediately to KPT authority who in turn will inform Commander Coast Guard Region (West). Besides informing KPT, Chief Coordinator, IOCL should inform DC, Jamnagar, Forest Department Jamnagar and Gujarat Pollution Control Board Jamnagar, Gandhinagar regarding the incident.

19.22.7 Handling SPM Emergency

In case of any burst or leakage in floating / under buoy hoses or in any system of SPM, is noticed by the master or Deputy Officer or Our Boarding officer or any other person, the above incident should be immediately brought to the notice of Master/ Deputy Officer of the Ship. On getting the information, the discharging operation should be immediately stopped and the IOC control room at Vadinar should be informed through VHF channel 12 and 07 (US) about the stoppage of oil discharge. The master of the ship/ IOC Boarding officer with the help of crew members of ship and supporting contract vessel of IOC should try to assess where the spill is coming from and try to contain the spill by means of deploying booms available with the ship/contract vessels of IOC. Procedure to be adopted in case of leakage from following is as detailed below:

19.22.8 Floating Hose

- Stop discharge.
- Close the butterfly valve near tanker manifold and isolation valve near SPM.
- Contain the leak
- Further operation can be done only after replacement of burst/leaked hose or hoses

19.22.9 Under Bouy Hose

- Stop discharge.
- Close the PLEM valve of the leaking line.
- Contain the leak
- Further operation can be done only after replacement of burst/leaked hose or hoses.

19.22.10 Central Swivel Leak

If the leak is not controllable then

- Cast-off the vessel.
- Contain the leak.
- Arrest the leak.
- Re-berth the vessel.
- Restart operation.

19.22.11 Central Swivel Leak

The officer on board of the vessel can decide in consultation with pilot/master of the vessel whether the ship can continue at berth. If necessary, arrangement should be made to replace the damaged mooring rope.

19.22.12 Damage to Buoy

It is due to overriding of tanker. The officer on board of the vessel can decide in consultation with the pilot/master of the vessel whether the ship can continue at berth.

19.22.13 Pollution Control near SPM

- a. The master of the vessel will be informed about the oil spillage by boarding officer. The master in turn will contact the port signal station, which is provided with VHF channels 16, 12, 10 and 07 (US) and give a detailed report of the incidence to KPT.
- b. The signal station in turn will inform the Chief Operation Manager (COM) Offshore Oil Terminal (OOT) KPT.
- c. Boarding officer will also inform IOC shore control room/ marine department through VHF and IOC control room in turn will inform the incident to CMNM / Chief Coordinator, IOCL, Vadinar.

- d. Upon receipt of information from port signal station, COM, KPT will direct all the crafts presently posted at Vadinar to combat the oil spill within port limit.
- e. The tug / launches of KPT should carry sufficient quantity of dispersant before leaving Vadinar jetty.
- f. Since the flow of underwater current around Vadinar coast is very high, usage of oil skimmer to recover oil from any leakage from SPM and other floating hoses is not much effective, hence the pollution control near SPM done presently is limited to spray of dispersant.

19.22.14 Typical Case of Oil Spill Combating at Vadinar

In case of any accidental oil spill in and around SPM following action plan is to be brought to effect immediately in line with the disaster plan in association with KPT.

1. Reporting:

- a. On getting any information about oil spill noticed by the Master or the Duty Officer of the vessel, or Boarding Officer of IOC on board, working SPM Maintenance Contractor, Coast Guard patrol party, KPT pilot or any other person, the above incident should be brought to the notice of the Master / Duty Officer of the ship. On getting any such information, the discharging operation should immediately be suspended and the IOC tank farm which is also available on VHF channel 12 and 07 (US) should be immediately informed about the stoppage of discharge.
- b. On getting such information from Boarding Officers, the shift in charge in IOC shore control room shall inform the incident to Chief Coordinator, IOCL, Vadinar and the necessary line isolation from ship to shore tank farm should be ensured by closing necessary valves.
- c. The master or the Boarding Officer of the vessel should contact the Port Signal Station which is provided with VHF channel 16,12,10 and 07 (US) and give a detailed first hand information report of the incident.
- d. The Signal Station, in turn, should inform the COM, KPT. COM, KPT may in turn pass on the information to their authorities and Coast Guard etc.
- e. IOC officer on board should also pass on the information to location head Vadinar through IOC control room on VHF channel and check back with COM, KPT for confirmation of the message receipt through Port Signal Station.
- f. Chief Coordinator, IOCL, Vadinar will immediately establish contact with ED WRPL Gauridad and pass on the first hand information report besides informing the incident to statutory bodies like Gujarat Pollution Control Board (GPCB) and Forest Department / National Marine Park authorities.

2. Alerting: |

- a. COM, KPT will direct the crafts posted at Vadinar to proceed to SPM and during the passage rig-up the dispersant spraying booms.
- b. IOC, Vadinar should ask its maintenance contract vessel to be ready for deployment of spill combating facilities on board at short notice on demand from COM, KPT.
- c. Small tug available with SPM maintenance contractor should also be put on alert for deployment, if so demanded by KPT for replenishment of oil dispersant and other support services.

3. Operational Requirements:

- a. In view of the strong current experienced at Vadinar only dispersant may be sprayed by 3 tugs of KPT while the fourth craft would be busy in replenishing her stock of dispersant chemicals from the storage provided at Vadinar jetty.
- b. The Master of harbour tugs / launches should ensure that sufficient quantity of dispersant chemical is carried out on board prior to leaving the jetty.
- c. In view of the strong currents experienced at Vadinar and the location of the SPM, Commander TMS Hayes, Advisor on Marine Pollution, International Maritime Organization in his Mission Report has indicated that it will not be possible to contain the oil spill and use a skimmer to collect oil. He therefore has recommended that the KPT should equip at least three crafts with dispersant spraying units. Accordingly, the Port had provided only the dispersant spraying equipments for use at Vadinar.

4. Execution:

The craft should move downstream of the oil spill and then start streaming up against the current while carrying out spray of dispersant chemicals with a systematic run over the oil spill, till the total spill gets dispersed.

5. Support Services:

IOC shall assist KPT and Coast Guard in

- a. Implementing the local action plan.
- b. In obtaining additional equipments and chemicals from HQs of KPT and Coast Guard, if and when required.
- c. Chartering of tankers to undertake transportation / transshipment operation if so required by KPT.
- d. Arranging for the storage of oil transported at shore and
- e. Making assessment of the value of the oil transshipped.

6. Claims:

In case the oil spill in and around SPM terminal is due to any problem of tanker or any negligence from tanker operation crew, following steps should be taken for claim, which will be done by DC / COM, KPT.

COM, KPT should inform the Master of the Vessel holding him responsible for the spillage/pollution and also steps taken by the Port to combat the oil spill and for cleaning operations and the charges thereof as per rules.

Record of all expenditures towards the use of port craft / tugs / dispersant chemicals / port vehicles and any other material should be maintained by the DC / COM, KPT for subsequent recovery from the Master/Agent of the ship, prior to her departure.

7. Final Report :

The detailed report of the oil spill in chronological order supported with available data/records will be prepared by KPT and sent to respective Organizations including IOC. However necessary reports for informing IOC official should be prepared by Chief Coordinator, IOCL, and Vadinar. He will also submit necessary reports to statutory bodies like Gujarat Pollution Control Board, Forest Department/National Marine Park authorities.

19.22.15 Relationship with Coast Guard & Port Trust

The Indian Coast Guard and Port Trust along with IOC would be among the main organization involved in the more practical aspects of oil spill response at Vadinar terminal.

It has been therefore, the endeavor of KPT / IOCL / ESSAR / Indian coast Guard to ensure that good working relationship, understanding of individuals, operating procedure are developed and understood before the high pressure environment of spill response prevents the building of such ties.

All relationship with the Indian Coast Guard has been undertaken with the knowledge that in the National Disaster Plan it states that ICG is the controlling body for all oil spill response activities.

19.23 Oil Spill Equipment Available with IOCL Vadinar

Sr.No	Item Description	Qty
01	Inter Tidal Boom	600 mm
02	Coastal Boom	600 mm
03	Disc Skimmer	1No
04	Mop Skimmer	1No

05	Dispersant Spray Sets	2 Sets
06	On Shore Cleaning System	1 No
07	Floating Tank 25m ³	2 Nos
08	Floating Tank 12.5m ³	4 Nos
09	Off Loading Pump	1 No

19.24 Oil Spill Consumables Available with IOCL Vadinar

Sr.No	Item Description	Qty
01	Oil Spill Dispersant	9800 Liter
02	Oil absorbent pillow (1.5'x1'x5")	72 Nos
03	Oil absorbent boom (length-10'x dia-7")	120 Nos
04	Oil absorbent sheet (1.5'x1.5')	760 Nos

19.25 Imp Telephone Nos of Govt Officials related to Oil Spill Combating

Sr No	Description	Telephone No		Fax Number
		Office	Residence	
1	District Collector Jamnagar (0288)	2555869	2554059 09427306210	
2	Collector Office Jamnagar (0288)	2557601 – 5	-----	2555899
3	Superintendent of Police Jamnagar (0288)	2554203	2555868 09427305071	2556382
4	Municipal Fire Station Jamnagar (0288)	2550101	-----	-----
5	Regional Officer Gujarat Pollution Control Board Jamnagar (0288)	2752366	2540741	2753540
6	Conservator of Forest Jamnagar (0288)	2552077	2553327 09425049064	2679371

7	Police outpost Vadinar (02833)	256541	-----	-----
8	KPT Control Tower Vadinar (02833)		-----	-----
9	Deputy Superintendent of Police, Khambalia (02833)	234262	234726	234262
10	Deputy Collector, Khambalia (02833)	234577	234714	234577
11	Commander Coast Guard, Porbandar (0286)	2241794 /2240958	2244234	2244056
12	Gujarat Pollution Control Board, Gandhinagar, (079)	23222756 /23222095	-----	23232156
13	Chief Conservator of Forest Gandhinagar, (079)	23254123	-----	23229917
14	Director Environment, Govt. of Gujarat. Gandhinagar, (079)	23251062	-----	23252156
15	CG, Station Vadinar	256560 /256579	256534	256560
16	COM, KPT, Vadinar	256749	256522	256540
17	Head (Environment), RIL, (Mr. Kannan)	95288- 3012152		952833- 3012199
18	RPL, Port Operation Center			
19	Mundra (Port operation Center)	0283828820 1 to 288207, 0283822003 3		95288- 288270

19.26 Important Telephone Nos of VOTL Marine Operations

Sr No	NAME	DESIG	TEL (OFF)	MOBILE NO.
1.	Capt Deepak Sachdeva	Chief Operations Officer	02833-241777	9925153618
2.	Capt. Alok Kumar	Port Captain		9909908611
3.	Commandt. Raghuvanam	Head- Port Facility Security	02833-241780	9909021183
4.	V. Gopalakrishnan	Admin Officer	02833-241779	9979891335
5.	Control room	Shift -in charge	02833-241775	9979868460
6.	Control room fax		02833-241779	

19.27 Emergency Telephone Nos of outside agencies including District Authorities

19.27.1 Fire Station

SL No	Dept. Name / Officer's Name	Office	Resident
1	Inspector CISF (02833)	256542	-

2	Municipal Jamnagar (0288)	2550340 2550101 2675091 101	2550340
---	---------------------------	--------------------------------------	---------

19.27.2 SHO (Police)

SL No	Dept. Name / Officer's Name	Office	Resident
1	District Superintendant of Police	2554203	2555868
2	Deputy Superintendant of Police	2552940	2542970
3	Police Control Room	100 2550200	-
4	Police Inspector, City 'A' Division	2550243	2676667
5	Police Inspector, City 'B' Division	2550244	2550315
6	Police Inspector, Panchkoshi 'A' Division	2550359	-
7	Police Inspector, Panchkoshi 'B' Division	2676556	-
8	Dhrol	02897- 222033	-
7	Dy. SP Khambhaliya Police Inspector Circle	234726	
8	Office, Khambhaliya	234744	

19.27.3 Collectorate

SL No	Dept. Name / Officer's Name	Office	Resident
1	Collector Shree & District Magistrate Shree	2555869	2554059
2	Additional Collector Shree	2550284	2672131
3	Resident Deputy Collector Shree	2553183	2556102

4	Sub divisional Magistrate Shree	2552130	2552807
5	Mamlatdar Shree (City)	2674575	2660950
6	Collector Control Room	2553404	-
7	Circuit House, Lal Bungalow	2550237-38	-
8	Deputy Collector, Khambhaliya	234577	

19.27.4 District Authority

SL No	Dept. Name / Officer's Name	Office	Resident
1	District Development Officer	2553901	2552402
2	Deputy District Development Officer	2550221	2755070
3	District Health Officer	2671097	2756252

19.27.5 Forest Department

SL No	Dept. Name / Officer's Name	Office	Resident
1	Conservator of Forest Marine National Park	2552077	2552327
2	Deputy Conservator of Forest Marine National Park	2552077	2679374
3	Deputy Conservator of Forest (Distribution)	2553664	2559787
4	Deputy Conservator of Forest (Common)	2553026	2554387

19.27.6 Port Department

SL No	Dept. Name / Officer's Name	Office	Resident
1	Port Officer - Bedi Port	2670207	2556106
2	Port Office - Okha	262001	262010

19.27.7 Railway Station

SL No	Dept. Name / Officer's Name	Office	Resident
1	Railway Inquiry - Jamnagar	2755222	-
2	Railway Inquiry - Hapa	2570410	-
3	Officer, Railway Station - Jamnagar	2755169	-
4	Officer, Railway Station - Hapa	2570410	-

19.27.8 Airport Office

SL No	Dept. Name / Officer's Name	Office	Resident
1	Airport Officer	2712187	2560252
		2712413	2560262
2	Indian Airlines - Jamnagar	2550211	2554768

19.27.9 Station Transport

SL No	Dept. Name / Officer's Name	Office	Resident
1	S.T.Inquiry	2550270	-
2	Manager, S.T.Depo	2676904	-
3	Divisional Director - Jamnagar	2570608	2570486

19.27.10 Hospitals, Ambulance Sevas, Blood Banks & NGO's

Sr No	Dept. Name / Officer's Name	Telephone No
-------	-----------------------------	--------------

		Office	Residence
Hospital			
1	Guru Govindsinh Hospital (Emergency)	2661087 2550204-06	-----
2	Samarpan Hospital	25566423 2712728	-----
3	Mental Hospital	2712728	-----
4	Dental Hospital	2750218	-----
5	Ayurvedic Hospital	2550368	-----
6	City Dispensary – Ranjit Road	2676456	-----
7	Oswal Hospital	2562705 2566833 2676521	-----
8	Adarsh Hospital	2665566	-----
9	Jivandep Healthcare Pvt Ltd	2558176 2558275	-----
10	KPT Primary Health Centre, Vadinar	256539	-----
Ambulance Seva			
1	Fire Branch, Jamnagar Mahan agar Palikir	102	-----
2	Aaryasamaj	2550220	-----
3	Guru Govindsinh Hospital	2541081	-----
4	Jilla Panchayat, Jamnagar	2550221	-----
5	Taxi Association, Jamnagar	2560547	-----
6	Mahavir Samaj Sevak Dal	2550225	-----
Blood Bank			
1	Guru Govindsinh Hospital	2550227	-----
2	J.H.M. Blood Bank	2550208	-----

3	Deepchand Gardy Memorial Blood Bank	2672529	-----
4	Omkar Charitable Trust Blood Bank	2673339	-----
NGO			
1	Aandabawa Seva Sanstha	2540155	-----
2	Kabir Ashram	2558049	-----
3	Shree Pranami Seva Sanstha	2551353	-----
4	Nawanagar Chamber of Commerce	2550250	-----
5	Youth Hostel Association of India	2558040	-----
6	Jamnagar Factory Owners Association	2560002	-----
7	Jamnagar Brass Foundry Association	2730271	-----
8	M.P.Shah Udyognagar Association	2550960	-----
9	Kasturba Stree Vikasgruh	2751730	-----
10	Indian Road Cross Society	2553583	-----
11	Rotary Club	2550348	-----
12	Lions Club	2673193	-----
13	Jamnagar Vepari Mahamandal	2533185	-----

19.28 Mutual Aid Members

Sr.No	Name of Mutal-Aid-Scheme Member	Telephone No. Office	Residence/ Mobile Nos.
1	Chairman - Collector	2555869 9978406210	2554059
2	Addl. Collector	2550284 99784 05182	2672131
3	Jt.Chairman Commissioner,JMC	2552321	2552372

4	MR Prajapati - Secretary, MAS, GSFC	2432216	2712768/ 9979853306
5	RN Shah - Treasurer-MAS, GSFC	2432242	9979862520

6	MAS OFFICE	2542764	
7	Office of Supdt. of Police	2554203	2555868
8	Police Control Room - Jamnagar	2550200	2344249(Sikka) 2846125(Padana)
9	District Disaster Control Room	2553404 / 2541485/ 1077 (Toll Free)	9426950783 (DDMO) Mr.Yaswant Sinh Parmar
10	PB Shah ,Asst. DISH - Jamnagar	2678206	9824583767
11	Mr. Desai -Home Guard Jamnagar	2553862	
12	Dr. Gosai RMO - GG Hospital	2550240 /2541081	2551689 / 9824258885
13	Control Room GMB - Jamnagar	2711805 / 2756909	
14	KK Bisnoi - JMC CFO	2550340/101 (2662691)	9879531101
15	Indian Coast Guard - Vadinar	02833 - 256579	1090 (Terror Helpline Toll free)
16	Sanjay Goyal -IOCL Vadinar	02833 - 256330	9909909016
17	P Palanivelu- Jt. Secretary MAS,EOL	02833 - 241892	9825210517
18	PK Prasad - IOCL Theba	2570712	9426911475
19	HS Modha - Fire Officer	2344116	9925214054
20	Chetansinh Jadeja - Fire	2344272 -75/	9099038083

	Officer, SDCC	2439322 (Fire)	
21	V.Koti, VP(Fire) RIL	6611193	9998972008
22	D K Thakur Jt. Secretary- MAS-TCL	02892 - 665247	9227676113
23	Mr. Dipak Roy, Mgr.(O&M) - K Kumar AM - GSPL	9925013159 9879599464	
24	MJ Sunaria - Digjam Ltd.	2712972/73/74	
25	PB Sakharkar -GAIL	6611437	9624089696
26	Indian Navy- Valsura	2550263-357	
27	Indian Air Force, Jamnagar	2720007, Extn.4222(fire)	2550245
28	PR Thatte, VP Bharat Oman Refinery	02833 -256450	9427206501
29	MU Khan - Cairn India		966253945
30	For any Emergency Ambulance / Fire		108

19.29 Details of Fire Fighting Equipment at Vadinar

Sr.No	Description of system	Quantity
1	Water Cum Foam Monitors	
	Fixed Monitors	05 Nos.
	(1200/1500/1800/2580/3840) LPM	2138 lpm (475 gpm)
	Portable Monitors	02 Nos. (Fire Station)
	(1200/1500/2580/3840) LPM	1000 gpm (4500 lpm)
	Foam trolley tank capacity and Qty of AFFF in it.	3 No. of trolleys with 200 liters each.
2	Hoses /Nozzles /Accessories	
	Hose	152 No.

	Type	Type B
	Nozzles	
	Universal (Triple purpose) nozzle	33 No. Diffuser branches
	Jet nozzle (Standard branch)	60 Nos. of Aluminium and 6 no. of Gunmetal
	Fog nozzle	11 Nos.
	Foam branch (FB-5X)	07 Nos.
	Water curtain nozzle	01, Good
	Hose Boxes	64 Nos.
	Foam Concentrate (AFFF)	28000Ltrs(Min)
FIRE SIREN		
	Hand operated	02 Nos
	Electrical	03 Nos.
	Sand buckets with cover	30 Nos.
	Manual fire call points	13 Nos.
3	Safety Equipment	
	Explosimeter (make)	02 Nos (ENDEE GP200L)
	Fire proximity suit	11 Nos.
	Water gel blanket (expiry date)	01 No. (Expiry date Feb. 2010)
	Safety torch	10 Nos.
	Safety goggles	30 Nos.
	Red and Green Flags for drill	01 No each
	Breathing Apparatus Set (Indicate make)	07 Nos make DRAGER
	Spare Breathing Apparatus cylinder	06 Nos
4	Fire Extinguishers	
	CO ₂ Type	66 Nos.
	2.0 Kg	28 Nos

	3.2Kg	10 Nos.
	4.5 Kg.	23 Nos.
	6.8 Kg.	05 Nos.
	DCP Type	148 Nos.
	5.0 Kg	28 Nos.
	10.0 Kg	116 Nos.
	75 Kg	04 Nos.
5	Fixed Fire Fighting Facilities	
	Fire water pond/tank (no. and capacity)	3 no. ponds 6000 KL each.
	Foam tender with accessories	3 Nos
6	Fire Fighting Engines	
	Engine driven FF pump a) 385KL/Hr @ 88m b) 350 KL/Hr @ 88m	4 Nos 2 Nos
	Motor Driven FF pump a) 385 KL/Hr @ 91mb) 350 KL/Hr @ 91m	1 No 2 Nos
	Jockey Pump 60 KL/Hr @ 120m	2 Nos

19.30 Details of Fire Fighting Equipment at Jamnagar

Sr.No	Description of system	Quantity
1	Water Cum Foam Monitors	
	Fixed Water Monitors	03 Nos.
	(1200/1500/1800/2580/3840) LPM	3500 lpm
	Fixed Water Cum Foam Monitors	03 Nos.
	(1200/1500/2580/3840) LPM	1200 lpm
2	Hoses /Nozzles /Accessories	

	Hose	15 Nos.
	Type	Type B
	NOZZLES	
	Universal (Triple purpose) nozzle	04 Nos. Diffuser branches
	Jet nozzle (Standard branch)	03 Nos.
	Fog nozzle	03 Nos.
	Foam branch (FB-5X)	03 Nos.
	Water curtain nozzle	02 Nos
	Hose Boxes	10 Nos.
	Foam Concentrate (AFFF)	5100 Liters
	Fire Siren	
	Hand operated	01 No.
	Electrical	01 No.
	Sand buckets with cover	24 No.
	Manual fire call points	06 Nos.
3	Safety Equipment	
	Explosimeter (make)	01 No. (ENDEE GP200L)
	Fire proximity suit	1 No.
	Water gel blanket (Expiry date)	01 No. (Expiry date Feb. 2010)
	Safety torch	02 Nos.
	Safety goggles	1 No.
	Red and Green Flags for drill	01 no. each
	Sand scoops	04 Nos.
	Stretcher	01 No.
	Breathing Apparatus Set (Indicate make)	01 No., make DRAGER
	Spare Breathing Apparatus cylinder	01 No.
4	Fire Extinguishers	


	CO ₂ Type	33 Nos.
	2.0 Kg	13 Nos.
	3.2Kg	Nil
	4.5 Kg.	15 Nos.
	6.8 Kg.	05 Nos.
	DCP Type	27 Nos.
	5 Kg	01 No
	10 Kg	20 Nos.
	75 Kg	06 Nos.
5	Fixed Fire Fighting Facilities	
	Fire Water Mains (size) and date of Pressure Testing	8" Dia tested on July'10
	Fire water pond/tank (no. and capacity)	2 nos above ground tanks of 700 KL each.
	Mainline pump shed fixed foam flooding system (Manual/auto)	Auto with UV/IR detectors
6	Fire Fighting Engines	
	Engine driven FF pumps (150 kl/hr @ 100M)	2 Nos
	Motor Driven FF pump (150 kl/hr @ 100M)	1 No
	Jockey Pump(10 kl/hr @ 100M)	1 No

20 ANNEXURES - GRAPHS


20.1 Graphs & Contours of various MCLS worked out at Jetty (Refer Chapter 4.7)

20.1.1 Jetty One – LPG

20.1.1.1 Instantaneous Release – Toxic Threat Zone (Graph)



20.1.1.2 Instantaneous Release – Toxic Threat Zone (Contour)




August 25, 2010
2:21 PM
Kandla Jetty Map

OIL JETTY


266

Upgraded Emergency Plan / DMP for Kandla Port Gandhidham (Kutch)

20.1.1.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.1.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




August 25, 2010
2:20 PM
Kandla Jetty Map

OIL JETTY

20.1.1.5 Instantaneous Release – Overpressure (Graph)




20.1.1.6 Instantaneous Release – Overpressure (Contour)




August 25, 2010
2:23 PM
Kandla Jetty Map

OIL JETTY

20.1.1.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.1.8 Evaporating Puddle – Toxic Threat Zone (Contour)



August 25, 2010
2:25 PM
Kandla Jetty Map


OIL JETTY

20.1.1.9 Evaporating Puddle – Flammable Area of Vapor Cloud (Graph)



- $\geq 12,000$ ppm = 60% LEL = Flame Pockets (not drawn)
- $\geq 2,000$ ppm = 10% LEL
- Confidence Lines


20.1.1.10 Evaporating Puddle – Flammable Area of Vapor Cloud (Contour)



August 25, 2010
2:27 PM
Kandla Jetty Map

OIL JETTY

20.1.1.11 Evaporating Puddle – Overpressure (Graph)




20.1.1.12 Evaporating Puddle – Overpressure (Contour)



August 25, 2010
2:28 PM
Kandla Jetty Map

OIL JETTY

20.1.1.13 Burning Puddle – Thermal Radiation (Graph)



20.1.1.14 Burning Puddle – Thermal Radiation (Contour)




August 25, 2010
2:30 PM
Kandla Jetty Map


OIL JETTY

20.1.2 Jetty One – Toluene


20.1.2.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.2.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.2.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.2.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.2.5 Instantaneous Release – Overpressure (Graph)




20.1.2.6 Instantaneous Release – Overpressure (Contour)




20.1.2.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.2.8 Evaporating Puddle – Toxic Threat Zone (Contour)



20.1.2.9 Burning Puddle – Thermal Radiation (Graph)




20.1.2.10 Burning Puddle – Thermal Radiation (Contour)




20.1.3 Jetty Two – Acrylonitrile


20.1.3.1 Instantaneous Release – Toxic Threat Zone (Graph)



20.1.3.2 Instantaneous Release – Toxic Threat Zone (Contour)



20.1.3.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.3.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




OIL JETTIES

August 25, 2010
 2:42 PM
 Kandla Jetty Map

20.1.3.5 Instantaneous Release – Overpressure (Graph)




20.1.3.6 Instantaneous Release – Overpressure (Contour)




OIL JETTIES

August 25, 2010
2:43 PM
Kandla Jetty Map

20.1.3.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.3.8 Evaporating Puddle – Toxic Threat Zone (Contour)



August 25, 2010
2:47 PM
Kandla Jetty Map

OIL JETTIES

20.1.3.9 Burning Puddle – Thermal Radiation (Graph)




20.1.3.10 Burning Puddle – Thermal Radiation (Contour)




August 25, 2010
2:51 PM
Kandla Jetty Map

OIL JETTIES


20.1.4.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.4.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.4.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.4.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.4.5 Instantaneous Release – Overpressure (Graph)




20.1.4.6 Instantaneous Release – Overpressure (Contour)



20.1.4.7 Burning Puddle – Thermal Radiation (Graph)




20.1.4.8 Burning Puddle – Thermal Radiation (Contour)




20.1.5 Jetty Two – Benzene


20.1.5.1 Instantaneous Release – Toxic Threat Zone (Graph)



20.1.5.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.5.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




- $\geq 7,200$ ppm = 60% LEL = Flame Pockets
- $\geq 1,200$ ppm = 10% LEL
- Confidence Lines


20.1.5.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.5.5 Instantaneous Release – Overpressure (Graph)




20.1.5.6 Instantaneous Release – Overpressure (Contour)




20.1.5.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.5.8 Evaporating Puddle – Toxic Threat Zone (Contour)



20.1.5.9 Burning Puddle – Thermal Radiation (Graph)




20.1.5.10 Burning Puddle – Thermal Radiation (Contour)




20.1.6 Jetty Three – 1:3, Butadiene


20.1.6.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.6.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.6.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.6.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.6.5 Instantaneous Release – Overpressure (Graph)




20.1.6.6 Instantaneous Release – Overpressure (Contour)




20.1.6.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.6.8 Evaporating Puddle – Toxic Threat Zone (Contour)




20.1.6.9 Evaporating Puddle – Flammable Area of Vapor Cloud (Graph)




20.1.6.10 Evaporating Puddle – Flammable Area of Vapor Cloud (Contour)




20.1.6.11 Evaporating Puddle – Overpressure (Graph)




20.1.6.12 Evaporating Puddle – Overpressure (Contour)



20.1.6.13 Burning Puddle – Thermal Radiation (Graph)




20.1.6.14 Burning Puddle – Thermal Radiation (Contour)




20.1.7 Jetty Three – Acetone


20.1.7.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.7.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.7.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.7.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.7.5 Instantaneous Release – Overpressure (Graph)




20.1.7.8 Evaporating Puddle – Toxic Threat Zone (Contour)



20.1.7.9 Burning Puddle – Thermal Radiation (Graph)




20.1.7.10 Burning Puddle – Thermal Radiation (Contour)




20.1.8 Jetty Three – Methanol


20.1.8.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.8.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.8.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.8.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.8.5 Instantaneous Release – Overpressure (Graph)




20.1.8.6 Instantaneous Release – Overpressure (Contour)




20.1.8.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.8.8 Evaporating Puddle – Toxic Threat Zone (Contour)



20.1.8.9 Burning Puddle – Thermal Radiation (Graph)




20.1.8.10 Burning Puddle – Thermal Radiation (Contour)




20.1.9 Jetty Four – Propylene


20.1.9.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.9.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.9.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.9.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.9.5 Instantaneous Release – Overpressure (Graph)




20.1.9.6 Instantaneous Release – Overpressure (Contour)




20.1.9.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.9.8 Evaporating Puddle – Toxic Threat Zone (Contour)




20.1.9.9 Evaporating Puddle – Flammable Area of Vapor Cloud (Graph)




20.1.9.12 Evaporating Puddle – Overpressure (Contour)



20.1.9.13 Burning Puddle – Thermal Radiation (Graph)




20.1.9.14 Burning Puddle – Thermal Radiation (Contour)




20.1.10 Jetty Four – Vinyl Chloride


20.1.10.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.10.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.10.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.10.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.10.5 Instantaneous Release – Overpressure (Graph)




20.1.10.6 Instantaneous Release – Overpressure (Contour)



20.1.10.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.10.8 Evaporating Puddle – Toxic Threat Zone (Contour)




20.1.11 Jetty Five – Ammonia


20.1.11.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.11.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.11.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.11.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.11.5 Instantaneous Release – Overpressure (Graph)




20.1.11.6 Instantaneous Release – Overpressure (Contour)




20.1.11.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.11.8 Evaporating Puddle – Toxic Threat Zone (Contour)



20.1.11.9 Burning Puddle – Thermal Radiation (Graph)




20.1.11.10 Burning Puddle – Thermal Radiation (Contour)




20.1.12 Jetty Five – HSD


20.1.12.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.12.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.12.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)



20.1.12.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.12.5 Instantaneous Release – Overpressure (Graph)




- ≥ 8.0 psi = destruction of buildings
- ≥ 3.5 psi = serious injury likely
- ≥ 1.0 psi = shatters glass
- Confidence Lines


20.1.12.6 Instantaneous Release – Overpressure (Contour)




20.1.12.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.12.8 Evaporating Puddle – Toxic Threat Zone (Contour)




20.1.12.9 Evaporating Puddle – Overpressure (Graph)




20.1.12.10 Evaporating Puddle – Overpressure (Contour)



20.1.12.11 Burning Puddle – Thermal Radiation (Graph)




20.1.12.12 Burning Puddle – Thermal Radiation (Contour)




20.1.13 Jetty Six – Motor Spirit


20.1.13.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.13.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.13.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)




20.1.13.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.13.5 Instantaneous Release – Overpressure (Graph)




20.1.13.6 Instantaneous Release – Overpressure (Contour)




20.1.13.7 Evaporating Puddle – Toxic Threat Zone (Graph)




20.1.13.8 Evaporating Puddle – Toxic Threat Zone (Contour)




20.1.13.9 Evaporating Puddle – Flammable Area of Vapor Cloud (Graph)




20.1.13.10 Evaporating Puddle – Flammable Area of Vapor Cloud (Contour)



20.1.13.11 Evaporating Puddle – Overpressure (Graph)




20.1.13.12 Evaporating Puddle – Overpressure (Contour)




20.1.13.13 Burning Puddle – Thermal Radiation (Graph)


20.1.14.1 Instantaneous Release – Toxic Threat Zone (Graph)




20.1.14.2 Instantaneous Release – Toxic Threat Zone (Contour)




20.1.14.3 Instantaneous Release – Flammable Area of Vapor Cloud (Graph)



20.1.14.4 Instantaneous Release – Flammable Area of Vapor Cloud (Contour)




20.1.14.5 Instantaneous Release – Overpressure (Graph)




- ≥ 8.0 psi = destruction of buildings
- ≥ 3.5 psi = serious injury likely
- ≥ 1.0 psi = shatters glass
- Confidence Lines


20.1.14.6 Instantaneous Release – Overpressure (Contour)



20.1.14.7 Burning Puddle – Thermal Radiation (Graph)



20.1.14.8 Burning Puddle – Thermal Radiation (Contour)



CBRN: Chemical Biological Radio Activity Nuclear related contingencies Dos & Donts

20 ANNEXURE Very useful telephone numbers

NDMA CONTACT DETAILS

NDMA Bhawan,
A-1, Safdarjung Enclave,
New Delhi - 110029
Telephones:
+91-11-26701700
Control Room: +91-11-26701728
Fax: +91-11-26701729
E-mail: controlroom@ndma.gov.in

NDMA CONTROL ROOM

Name	Office	Fax	Mob.	E.mail id
Control Room	011-26701728 011-1078	011-26701729	9868891801 9868101885	controlroom@ndma.gov.in , ndmacontrolroom@gmail.com ,

GSDMA

- Block No.11 , 5thFloor, Udyog Bhavan , Sector-11 , Gandhinagar, Gujarat.
- *Email*

info@gsdma.org
- *PHONE* +91-79-23259283

21.1 Telephone Nos of Gujarat State District Collectors

No.	District	Collector Name	Phone	Fax
1	Ahmedabad (079)	Dr. Vikrant Pandey	(O)079-27551681	7927552144
2	Amreli (02792)	Shri Oak Aayush Sanjeev	(O)02792-222307	2792222710
3	Anand (02692)	Shri Dilip Kumar Rana	(O)02692-261575	2692261575
4	Arvalli (02774)	Shri Nagarajan M.	(O)02774-250200	2774250202
5	Banaskantha (02742)	Shri Sagale Sandip J.	(O)02742-257171	2742252740
6	Bharuch (02642)	Shri Ravi Kumar Arora	(O)02642-240600	2642240602
7	Bhavnagar (0278)	Shri Harshadkumar Ratilal Patel	(O)02782428822	2782427941
8	Botad (02849)	Shri Sujeet Kumar	(O)02849271301	2849271304
9	Chhotaudepur (02669)	Shri Sujal Jayantibhai Mayatra	(O)02669-233003	2669233002
10	Dahod (02673)	Shri Vijaykumar Lalubhai Kharadi	(O)02673-239001	2673239005
11	Dangs-Ahwa (02631)	Shri N.K. Damor	(O)02631220201	2631220294

12	Devbhumi Dwarka-Khambhaliya	Dr. Narander Kumar Meena	(O)02833232804	2833232102
13	Gandhinagar (079)	Shri S. K. Langa	(O)079-23220630	7923259040
14	Gir-Somnath-Veraval (02876)	Shri Ajay Prakash	(O)02876240001	2876243300
15	Jamnagar (0288)	Shri Ravi Shanakar	(O)02882555869	2882555899
16	Junagadh (0285)	Dr. Pardhi Sourabh Zamsingh	(O)0285-2630100	2852635599
17	Kachchh (02832)	Ms. Remya Mohan Moothadath	(O)02832250020	2832250430
18	Kheda (0268)	Shri S.B. Patel	(O)0268-2553334	2682553358
19	Mahisagar-Lunavada (02674)	Shri R.B. Barad	(O)02674-250664	2674250655
20	Mehsana (02762)	Shri H K Patel	(O)02762222211	2762222202
21	Morbi (02822)	Shri R. J. Makadia	(O)02822-240701	2822240701

22	Narmada-Rajpipla (02640)	Shri I.K. Patel	(O)02640222161	2640222171
23	Navsari (02637)	Dr. M. D. Modia	(O)02637-244999	2637281540
24	Panchmahal (02672)	Shri Udit Agrwal	(O)02672-242800	2672242899
25	Patan (02766)	Shri Anand Babulal Patel	(O)02766233301	2766233055
26	Porabandar (0286)	Shri M. A. Pandya	(O)0286-2221800	2862222527
27	Rajkot (0281)	Dr. Rahul Babubhai Gupta	(O)0281-2473900	2812453621
28	Sabarkantha (02772)	Ms Praveena D.K.	(O)02772-241001	2772241611
29	Surat (0261)	Dr. Dhaval Kumar Patel	(O)0261-2652525	2612655757
30	Surendranagar (02752)	Shri Kankipati Rajesh	(O)02752-282200	2752283862
31	Tapi-Vyara (02626)	Shri R.S. Ninama	(O)02626224460	2626221281
32	Vadodara (0265)	Ms. Shalini Agarwal	(O)0265-2433000	2652431093
33	Valsad (02632)	Shri C.R. Kharsan	(O)02632253613	2632243417

21.2 District Level Authorities

District Collector Office

Near Circuit House, Mandvi Road,
Nr. Mota Bandh,
Bhuj,
Gujarat - 370001

- +91 2832 250650
- +91 2832 250430
- collector-kut@gujarat.gov.in

Emergencies

District Helpline

Call : +91 2832 1077

District EOCs Helpline No.

Call : +91 2832 250650

Commissioner of Rescue & Relief

Call : 1070

Shri R. M. Thakkar

Dy. Mamlatdar Disaster

+91 2832 250923

342

Upgraded Emergency Plan/ DMP for Kandla Port Gandhidham (Kutch)

MP Bhuj		252595	251177
Dy. Collector, Anjar Mob. 9825228049		243345	243363
Shri N. C. Rajgor Mamlatdar, Anjar +91 2836 242588 mam-anjar@gujarat.gov.in		242588	243362
Shri J. S. Sindhi (I/C) Mamlatdar, Gandhidham +91 2836 250270 mam-gandhidham@gujarat.gov.in		250475 250270	222875 250475

Collector, Jamnagar		2555869	2554059
Collector's Control Room, Bhuj. Mehul Padharia Kutch District Project Officer Officer 02832- 252347 09557920767 02832- 224150 mehul.nitb04@gmail.com District Project Officer Disaster Risk Management Program, District Emergency Operation Center(DEOC) , Emergency Operation Branch, Collector Office, Kutch		2252347 2231733 02832- 252347 09557920767 02832- 224150	-
Doordarshan, Bhuj		2251107	
Dy. Mamlatdar, Gandhidham		250475 250270	
Civil Defense, Gandhidham		220221	
PGVCL, Gandhidham		221728 222809	
GW&SB, Gandhidham		220975	
GSRTC, Gandhidham		220198	
Duty Officer, All India Radio, Bhuj		222503	
State Information Dept. (Shri Antani)		224859 250954	253034 252855
Air Force Duty Officer, Bhuj		252501 252502	
Air Force, Bhuj		223450	
Air Port, Bhuj		254550	
Aerodrome Officer, Kandla		238370	223247
Indian Navy, Jamnagar		550263 to 5	550825
Air force, Jamnagar		550245 to 7	550247

21.3 List of Telephone Numbers of Gujarat Maritime Board

Sr. No.	Name, Designation and place of Office	Tele. No. (Office)	Tele. No. (Residence)	Fax No.
1	Chairman, G'nagar	23250508 23250506		079-23250589
2	VC&CEO,Gandhinagar	23238363	23262280	23234703
3	Chief Nautical Officer, Gandhinagar	23238346-47		-do-
4	Chief Engineer(C), Gandhinagar	23238346		-do-
5	Officer on Special Duty, Gandhinagar	23238346	079- 2323232	-do-
6	Exe. Asst. to VC&CEO,	3238363	7451465	-
	Gandhinagar			
7	Head Office, G'nagar	3238346 to 8	-	34703/04
8	Port Officer, Magdalla	0261- 2470533	-	2475645
9	Port Officer, Bharuch	02642- 241772	229082	220377
10	Port Officer, Bhavnagar	0278- 2519221	2568580	2211026
11	Port Officer, Jafrabad	02794- 245165		245152
12	Port Officer, Porbandar	0286- 2242408	2242412	2244013
13	Port Officer, Veraval	02876- 220001	242956	243138
14	Port Officer, Okha	02892-	262010	262002

		262001		
15	Port Officer, Jamnagar	0288- 2755106	2557163	2756909
16	Port Officer, Navlakhi Main Gate	02822- 220435		232470
17	Port Officer, Mandvi	02834- 220033	220040	230033
18	Traffic Inspector, Mundra	02838- 222136	222136	-
19	Executive Engineer(C), Jakhau	02831- 287261	222996	-
20	Gujarat Pipavav Port Ltd., Chief Operating Officer, Duty Office	02794286314 86001/92	286070	-
21	Gujarat Adani Port Ltd., Mundra.	02838- 288201 to 8	287241	-

21.4 For supply of Food Packets etc. following agencies to be contacted.

Sr. No.	Name of Agency	Contact Person	Telephone No.
1	Arya Samaj Mandal	Mr.Vachanidhi	231223 Mob. 9824221332
2	Agrawal Samaj	Mr.Dinanath	231638
3	RSS	Mr. Sunil Kothari	222560 / 232909
4	Lions Club, Gandhidham	Mr. Naresh Bulchandani	220212 Mb: 982428470

5	Rotary Club, Gandhidham	Mr. Rajabhai / P.K. Mukherjee	228213 / 232035
6	Red Cross Society	Dr. Bhavesh Acharya	234854, 232736
7	Lohana Mahajan, Gandhidham	Mr. Premji Bhai Thakker	220925
8	Rajasthan Yuva Mandal	Mr. Sunil Bajaj (President) Mr. Dilip Jain	221459 / 230902 234525 / 9825168170
9	Swaminarain Mandir	Mr.Lavjibhai Thackker	231555, 233666
10	Sindhi Youth Circle	Mr.Vijay Khubchandani & Mr.Kundabhai	220490
11	Satwara Samaj	Mr.Agavjibhai	235659
12	Sitaram Parivar	Mr.Mohanbhai Dharsi	222373, 234603
13	Gurudwara, Gandhidham		220643
14	Swaminarayan Gurukul	Swamimukta Prasadji	228098, 226555

21.5 Apart from the above, if required, the following hotels may be contacted for the supply of food packets:-

Sr. No.	Name of Hotel	Contact Person	Telephone No.
1	Shiv	Mr. Nagendra Singh / Mr. Bharat Singh	237712-13-14-15, 221297
2	Sharma Resorts	Mr. Madan Mohta / Mr. J. Gonasaives	31824/231823/231825/ 224885-86-87-88-89

3	Satkar	Mr. Babu Bhai Agrawal	234100/222597 234101 (R)
4	Natraj	Mr. Maulinbhai Acharya	221749/221956/221955 221954/238002
5	President	Mr. Rameshbhai	220053/229364/238002
6	K.K.Caterers	Kaniyalal Rajwani	(O) 227419, (R) 224995, (Mob) 9825226998
7	Bhawani Caterers	Mr. Hukamsinh Purohit	230366(PP)
8	Hotel Mid-Town, Adipur	Mr. Nagendra Singh	9825226568 260237/260080
9	Hotel Sea-Rock, New Kandla	Mr. Vithal Shetty	270490

21.6 List of Labour contractors operating at Kandla Port

Sr. No.	Name of the Company	Contact person	Address	Contact Nos
1	Neelkant Handling A/c Shree Radhey Shipping	Haresh Bupendra	Tenament B Plot 290, Ward 10/A, G'dham	237040 9825001743
2	Ratnakar Handling A/c Aditya Marine	Radhakishan Parida	83-84, GIDC G'dham	9879123371
3	Tirupati Handling Co.	Dayalal B. Rabari	6-8, Goyal Chamber, GIM	235504 9825056599

4	Al Pirani Al Sailani	Akbar Yakub	CS-10, Port Colony, Kandla	22053,232174 9979331100 9825787808
5	Shree Ravechi Handling A/c Trinity Shipping	Mahadeva Agaria	11,2nd Floor, Plot.343, Ward 12- B, GIM	250286 9825361347
6	Shree Ramdev Handling	Nimbaram Gulabji	377, Sector-7 GIM	9825348935 9979898564
7	AVB & Co	Mukesh Gujjar	15, GF, Gokul Park, GIM	232967
8	Ashapura Labour Supply	Khimji Jallabhai Rathod	48, GIDC, Near Ambika Weigh Bridge, GIM	9979053378 9898128069
9	Shree Krishna Handling	Harinder Yadav	E – 108, GHB ,Sec- 5,GIM	9879549803
10	Naasmin & Co	Umar Osman Chamadia	Plot – 14, Sector- 7, GIM	9898333397
11	M.S. Logistics	Asgar Haji Mungrani	Shop No. 5, Opp.CISF Gate,Kandla	9825241065 9913620407
12	Shree Majeesa Handling	Jugal Kishor Joshi	Block 24, MIG, Kidana, GIM	9879373992 9979898564
13	Shree Kailash Handling Co.	Mohanbhai Heera	Plot No. 7, Sector- 8, GIM	9825228555 9879288875
14	Javed Abu Saicha	Javed Abu Saicha Gani Patel	Shop – 13, Port Colony,	9825092748 9825563094
			Kandla	

15	Shree Ganesh Handling	Dayabhai Rabari	6-8, Goyal Chamber, GIM	9825056599
16	Bhupendra & Co	Mayur M Ahir	Plot 253, Ward 12/C, GIM	9727762191 9825225239

21.7 List of Doctors in Gandhidham Complex

Sr No	Name of Doctor	Telephone	Telephone	Mobile No
Consulting Physician (MD Medicine)				
1	Dr. Babita	261802	322111	
2	Dr. Gandhi C. K.	234561	230111	
3	Dr. Gonsair R. M.	230333	239944	
4	Dr. Johnson Samuel	222344	232244	
5	Dr. Morkahia V. L.	222008	232161	
6	Dr. Raiyani V. R.	230022	234214	9824241220
7	Dr. Sakaria S. B.	230114	230947	
8	Dr. Siju	230160	223852	
Dentist				
1	Dr. Asha Y. Parekh	234295	234451	
2	Dr. Ajay Bhimjiani	233347	260256	982544118
3	Dr. Chadotra M.	220142	237909	
4	Dr. Hitesh Sheth	226763	220965	
5	Dr. Kela B.V.	222094	231181	
6	Dr. Sanghvi V.K.	234979	223343	
7	Dr. Sharma R.	229211	227627	
8	Dr. Singh N.	230769	261343	

9	Dr. Soneta S.	236319	229172	
Dermatologist				
1	Dr. Jhala J.J.	223568	235567	
2	Dr. Deepak Sorathia	242882		9426909822
E.N.T. Surgeon				
1	Dr. Dave A.B.	221931 260394	260461	
2	Dr. Harani D.D.	222096	239121	9825227322
3	Dr. Khatri R.S.	222701	235959	9879195798
4	Dr. Maheswari S.K.	231874	250940	
M.B.B.S				
1	Dr. Acharya B.F.	220715	232736	9825210157
2	Dr. Acharya C.M.	220263		
3	Dr. (Mrs.) Acharya S.C	232606		
4	Dr. Agarwal B.B.	227767	570212	9825225599
5	Dr. Asher G.K.	239139	233765	
6	Dr. Bhadra D.M.		230259	
7	Dr. (Mrs.) Bhatia K.	260255		
8	Dr. C. Jonwal	220263	263987	
9	Dr. (Mrs.) Chellani	220099	270441	
10	Dr. Chudasama V.K.		240952	
11	Dr. Dasani M.G.	260001	261495	
12	Dr. Goswami S.K.	261399		
13	Dr. Guptabhaya D.N.	221305	231777	
14	Dr. Gurdasani V.S.	260674		
15	Dr. Harani H.C.	235369	239327	

16	Dr. (Mrs.) HitemathU.S.	261844	260097	
17	Dr.Joshi N.L.	260666	261661	
18	Dr. Kela H.V.	232069	232071	
19	Dr. Khushlani A.	260562	260738	
20	Dr. Leon A.	261802	262188	
21	Dr. Makwana	220263	263406	
22	Dr. Minocha Ravi	236306	232127	
23	Dr.Mehta H.K.	231590	235021	
24	Dr. Mehta J.R.	220164	220834	
25	Dr. Morbia V.M.	230011		
26	Dr. Parekh S.K.	260608	261123	
27	Dr. Puri R.P.	223355		
28	Dr.Rawal S.	235119		
29	Dr. Singh D.P.	221990		9825359928
30	Dr. Thakkar A. D.	220582	222829	
31	Dr. Thakkar H. M.	223506	222350	
32	Dr. Thakkar M. C.	260577		
33	Dr. Thakkar S. B.	221046 228267 221177	238467	
34	Dr. Vaccharajani N. D.	220088		
35	Dr. Vasudev Jethani	260577	261650	
36	Dr. Vora C. B.	223084		
37	Dr. Vadhvani Vjay	262076	262843	
38	Dr. Zola Mithubhai	260608		
39	Dr. (Mrs.) Raiyani P.V.	230022	234214	

40	Dr. (Mrs.) Singh R. D.	221990		
General Surgeon				
1	Dr. Ahir J. K.	237744		
2	Dr. Dasani D. G.	229231 227505	223346	
3	Dr. Gandhi R. G.	236700	229156	

4	Dr. Girdhani R. C.	233300	231219	
5	Dr. Jiladiya A.	220263	244844	
6	Dr. Joshi Y. V.	221557 230013	233324	
7	Dr. Naik S. K.	234333	231332	
8	Dr. Patel J. K.	230007		
9	Dr. Vora Chetan	224787	229369	9825225942

Obstetrician & Gynecologist				
1	Dr. (Mrs.) Acharya N.B.	220715	232736	9825226700
2	Dr. Alpa D. Mehta	262599	265266	
3	Dr. Chandrakant Thacker	224488	225588	
4	Dr. Darshak Mehta	220263	265266	9824211534
5	Dr. (Mrs.) Gor A. A.	235135	239635	
6	Dr. Khanchandani	260833	260839	
7	Dr. (Mrs.) Kaur J. P.	229655	220673	
8	Dr. (Mrs.) Naik P. S.	234333	231332	
9	Dr. (Mrs.) Patel M. H.	230202	230353	

Ophthalmic Surgeon				
1	Dr. Gor A.	235135	239635	
2	Dr. Masand S. N.	220139	234187	9825196989

3	Dr. Parikh Y. B.	234295	234451	
Orthopedic Surgeon				
1	Dr. Hotchandani	220039	261530	
2	Dr. Patel H. A.	230202	230353	
3	Dr. Sailesh Ramawat	230160		
4	Dr. Vachhani P. S.	230400	222400	
Pediatrician				
1	Dr. Dubal J. A.	232591	233777	
2	Dr. Jeswani R. M.	255689		9825229249
3	Dr. Majithiya M. S.	222413 222406	227134	
4	Dr. Rupesh Seth	260836	222397	
5	Dr. Naveen Thacker	230195	230894	
6	Dr. Nitin Thacker	221046	220615	
Pathologist				
1	Dr. Sukla K. L.	221611	234062	
2	Dr. (Mrs.) Pawde S. V.	230370	231352	
3	Dr. (Mrs.) Verma G. H.	229168	238386	
		Psychiatrist		
1	Dr. Barot S.	221041	234885	
		Radiologist		
1	Dr. Shah R. M.	222878 234215	222868 235868	
2	Dr. Bhupendra Shah	572824	227724	

21.8 List of Essential Services

HOSPITALS	OFFICE	RESIDENT
-----------	--------	----------

1	General Hospital, Bhuj Civil Surgeon, Bhuj	222850	250554
2	Referral Hospital, Anjar	232455	
3	Rambaugh Hospital Gandhidham	220263	
4	Divine Life, Adipur	261802	
5	Railway Hospital Gandhidham	231874	
6	Government Dispensary dipur	260608	
TELECOMMUNICATION			
1	General Manager, BSNL, Bhuj	253000	252322
2	Dy. Manager, Bhuj	252505	251505
3	Area Manager, Gandhidham	238000	235000
4	SDO, Gandhidham	236250	236251
ELECTRICITY			
1	S.E., PGVCL, Bhuj	222550	250189
2	Jr. S.E., Anjar	243008	242656
3	XEN, Anjar	242845	242446
4	Dy. Engineer, Gandhidham	222809	--
5	Line Office, Gandhidham	221728	
WATER SUPPLY			
1	S.E., GWS&SB, Bhuj	221806	250601
2	XEN, Bhuj	250685	253016
3	SE, Anjar	242416	242421
4	XEN, Gandhidham	220717	223273
5	Control Room, Gandhidham	221252	

6	Water Tank, Sunderpuri	231313	
7	Water Tank, NU-4	654564	
8	Gandhidham Municipality	231610	
9	Chief Officer, Gandhidham Municipality	234967	

21.9 List of Vehicle Suppliers

Sl. No	Name of Institution	Contact Person	Parking Place	Name and Phone No.	Availability
			Phone No.	of Driver	Vehicle.
(A) Vehicle Hire Contractors					
2	M/s Rohit Enterprise /RISHABH ENTERPRISE	Mr. Rohit Shah 228550/237538 237547 (O) 234140 (R) Mob.9825225121			
3	M/s Jai Somnath Travels (GIM)	Mr. Mishra Mob.9825386739			
(B) Ambulance Pool					
01	St. Joseph Hospital, Gandhidham	Administrator 230160/229336	Hospital Premises	Driver available round the clock	First come first serve

02	IFFCO-Kandla on contract, Dispensary No. 20164 Dr. Mehta (R) 220832 Plant. Dispt. 270832	Mr. Mukesh Agrawal Hotel Gokul 221311			First come first serve
03	Kandla Salt Mfg. Ass. Neelkanth Bldg.	Mr. Shamji Ahir 231485 (R) 222765/220421 (O)	Zanda Chowk	Driver available round the clock	First come first serve
04	Zhulelal Mandir Trust	Mr. Kundan Guwalani 221760 (R) 229800 (O) Kundan Stores 221533/227800 229580	Mandir Premises	255580	
05	Red Cross Society	Dr. B F Acharya 225636/230345	Red Cross	Driver available round the clock	
06	Western Railway, Gandhidham	Medical Supdt. 231874 (R)	Hospital		
07	Rambaugh Government Hospital	220263	Hospital Premises	Driver available round the	
				clock	

08	Gautam Frei Pvt Ltd.	Mr. Ramesh Proprietor 232605/220163, 230345 (O)	GIDC Work shop Sector 10C, Plot No. 24.		First Come First Serve
09	Sindhu Sewa Trust, Samiti Adipur	Mr. Jotwar (R) 260836, 260698 TBX-45, Adipur	Hospital Premises	Driver round the clock residence in hospital (Break duty at present)	
10	Tolani Eye Hospital	1. Supd (O) 260497 (R) 260773 2. Vic Chairman (C 260373 Mr. N Chandnani (R) 260456, Prabhu Chaya, Behind Prabhu Darshan	Hospital Premises	One driver in absence of compounder residing in hospital	First Come first Serve
11	Divine Life Society, Adip	261802	Hospital Premises	Round the clock	
12	Atmaram Severam Charitable Trust	237759 Mok 9825225294	Gandhid ham	Round the clock	
13	Dev Smru Trust	222096/231073			

14	Mobile Morgue	229430/239965	Lions Club		
15	Shav Vahini/Mobile Mrogue	239965			

21.10 List of Clearing & Forwarding Agents at Kandla

A V Joshi & Co Tel. 232605, 232227, 230345	C. Jivram Joshi & Sons (Gujarat) Tel. 220621 Fax. 231141
Fax. 233924 Mr. Harshandu Mr. Vaidya (Mob.) 9825226013	Mr. Sunil Chowdhari (Mob) 9825225400
ACT Shipping Ltd Tel. 270111/12/13, 270530, 220407 Fax. 270579, 232175	Cargo Movers Tel. 220453, 230883, 270563 Fax.231687
A. Jaswantrai & Co. Tel. 222630, 222717, 222145, 221943 Fax. 232308, 270385	Cargo Clearing Agency (Gujarat) Tel. 221721, 221674, 220655, 270542 Fax. 233034
Asia Shipping Services Tel. 230954. Fax. 231285	Chinubhai Kalidas & Brothers Tel. 232284 Fax. 231881
Airol Shipping Services Tel. 230080, 220180. Fax. 236131	CAP Shipping Pvt Ltd Tel. 221460, 232081 Fax. 233734
Aarpee Clearing Agency Tel. 222614. Fax. 255252	Centrans Shipping Agency (I) Pvt Ltd Tel. 256854 Fax. 234074
Ashirwad Clearing Agencies Tel. 232426, 233245 Fax. 234107	Cargo Shipping Tel. 270802, 270803 Fax. 270802
Ambalika Enterprises Tel. 255382. Fax. 255577	C. Joshi & Sons Tel. 221094

Ashmka Shipping (Tel. 222481)	Dilip A Goplani Tel. 224082, 255423 Fax. 224082
Ashis Enterprise (Tel. 234722)	D.B.C. & sons Gujarat Pvt Ltd Tel. 270263, 270348, 270503 Fax. 270631
Anchor Shipping Tel. 235781 Fax. 235781	Damjidhiroo & Sons Tel. 222329, 221328 Fax. 230139
B N Thakkar & Co., Tel. 222293, 222285, 270239 Fax. 230556	Dvji Premji Punara & Sons Tel. 222057, 221338 Fax. 230139
B. Devchand & Sons Pvt Ltd Tel. 232220 Fax. 234014	Express Transport Pvt Ltd Tel. 220193, 220179, 270591, 222565 Fax: 220193
Benits Forwarders Pvt Ltd Tel. 221707, 222086 Fax. 223151	Friends & Friends Shipping Pvt Ltd Tel. 232227, 231588 Fax. 233924
Blue Sea Shipping Agencies Tel. 235317 Fax. 255221	Fast & Fair Company Tel. 255254, 238175 Fax. 255254
Bhanu Clearing Agency Tel. 256861 Fax. 256861	Flamingo Shipping & Forwarding Pvt Ltd Tel. 256755, 257756 Fax. 256755
Global Marine Agencies Tel. 222928, 223196, 223252 Fax. 255418	Liladhar Passoo Forwarders Pvt Ltd Tel. 252288, 252297, 252402, 252617 Fax. 252383
Gayatri Shippers Tel. 230692, 223292 Fax. 230818	Lalbahi Trading Company Tel. 222139
Hiral Enterprise Te. 255644	Leap Forwarders Pvt Ltd Tel. 255530, 255509 Fax. 252383
Hindustan Shipping services Tel. 255644, 222821 Fax. 256618	Link International Tel. 255206/07 Fax. 255530

Hardip Shipping Logistics Pvt Ltd Tel. 232909, 222560 Fax. 232909	Lexicon Shipping Agencies Pvt Ltd Tel. 229951- 53 Fax. 229949/50
Hansraj Pragji & Sons Tel. 221650, 255228 Fax. 255228	Logistics Enterprise Pvt Ltd Tel. 255157, 255458 Fax. 255520
H K Dave Pvt Ltd Tel. 221504, 2333632 Fax. 230411	Mathuradas Narndas & Sons Forwards Pvt Ltd, Tel. 252224, 252350, 252115 Fax.252221
Intralink Clearing & Forwarding Tel. 255188 Fax. 23148	Magal Singh & Company Tel. 224030, 255253, 234688
J M Baxi & Co. Tel. 270630/35, 270148/50, 270525 Fax. 270616	Meridian Shipping Services Tel. 233981, 255362 Fax. 230701
Jesia Mistry Agencies Pvt Ltd Tel. 222317, 223317	Megha Shipping Agency Tel. 222671, 255304 Fax. 230937
Jaisu Shipping Company Pvt Ltd Tel. 270428, 270128/538 Fax.270556	Mayur Forwarders Pvt Ltd Tel. 222671, 255304 Fax. 230937
Jivanlal Laloobhai Tel. 220308, 230530 Fax. 231640, 233803	Maritime service Pvt Ltd Tel. 222671, 255304 Fax. 255304
Krishna Clearing Agency Tel. 223813, 230501 Fax. 233135	Marathon Shipping Combine Tel. 222202, 230106 Fax. 255220
Kiran Roadlines Tel. 232297, 231984, 234108 Fax.231422	Shiv Shipping Service Tel. 255568 Fax. 22256
Kandla Clearing Agency Pvt L td Tel. 232337, 223211, 223210 Fax.230402	Narendra Forwarders Pvt Ltd Tel. 232504, 231795 Fax. 256678
Kamat & Co. Tel. 223471, 232730, 232729 Fax. 255243, 270779	Natwar Parikh Industries Ltd Tel. 232628 Fax. 232628

K S Chaya & Co Tel. 256604 Fax. 230693	New Dholera Shipping & Trading Company Limited. Tel. 222637 Fax. 255329
Kashyap Shipping Ltd Tel. 220816 Fax. 230030	National Shipping Tel. 232319 Fax. 232319
Kanak Shipping & Transport Tel. 231314, 230543, 222059 Fax.221702	Navjeevan Enterprise Tel. 252611, 252360 Fax. 252515
IEE & Muirhead Pvt Ltd Tel. 231535/36 Fax. 231018.	N. G. Bhanushali & Company Tel. 233648, 256791 Fax. 256879
OTA Kandla Pvt Limited	Shivji Kanji & Company

Tel. 220145, 223241, 270450 Fax.223241	Tel. 230127, 223728, 223729 Fax.220308
Pravin Bhatt & Sons Tel. 224032, 230079 Fax. 230079	South India Corp. (Agencies) Limited Tel. 234646, 231494, 221276, 255209 Fax.234416
Prime Forwarders Tel. 234047, 232505 Fax. 231345	S J Thacker & Company Tel.255678,221745 Fax.230659
Purshotam Ramjee & Company Tel. 220354, 222287 Fax. 231754	Star Shipping Services Tel.255424,255425,235326(F)255426
Patel Handling Agency Tel. 221718, 224024, 231004, 270017 Fax. 231143	Shivani Shipping, Tel. & Fax.256836
P S Bedi & Company Tel. 223201, 222841 Fax. 255494	Sea Trans Shipping Agency Tel. 255564 Fax. 233228, 233517
Purshotam Chtrabhuj Thacker Tel. 222720	Seaster Shipping Services Tel. 255349 Fax. 232719
Prashant Shipping Tel. 255306, 223927 Fax. 223927	Seaway Shipping Services Tel. 234272 Fax. 232719

Pramukh Forwarders Tel. 255400 Fax. 232602	Star Clearing Agencies Tel. 230273, 255529, 222983 Fax.232719
P M Agency Pvt Ltd Tel. 232553, 233973, 236414 Fax.255413	S S Shipping Agencies Tel. 236605, 238283 Fax. 236605
Raj Shipping Service Tel. 233948, 232402 Fax. 231395	SPN Shipping Services Tel. 222453, 270733 Fax. 236605
Rajesh Shipping Service Tel. 255444, 255450/52, Fax.255151	Sierra Shipping Pvt Limited Tel. 255395 Fax. 232771
Rudra Shipping Service Tel. 220429, 255317 Fax.255317	Sonal Enterprises Tel. 252666, 252053
Rishi Shipping Tel. 220813, 229830, 2555661/2/3 Fax. 238943, 255522 Mr. B K Mansukhani (M)9825225170	S R Clearing Agency Tel. 232974, 255494 Fax. 255494
Rudraksh Shipping Service Tel. 235937 Fax. 255582	St. John Freight System Limited Tel. 235414, 236444 Fax.235414
Sanghvi Freight Forwarders Pvt Ltd Tel. 234993, 234995, 222401 Fax.230508	Siddi Shipping Services Tel. 232356, 230268 Fax.256712
Sri R K Shipping Pvt Ltd Tel. 232028, 231940, 231936 Fax. 232740	Spalsh Shipping Pvt Limited Tel. 255562, Fax. 220710
Shakti Enterprises Tel. 223531, 221591 Fax. 233898	Thakarshi Madhavji & Sons Tel. 255457, 255458 Fax. 221770
Shree Ambica Commercial Company Tel. 220213, 221253	Trinity Shipping & Allied Services Pvt Ltd Tel. 223703, 230911 Fax. 232060

Shri Maruti Shipping Services. Tel. 270760, 256853, 233245 Fax.220308	Tokto Shipping Services Tel. 234040
Unity Shipping Tel. 255271	Vinson Tel. 220466 Fax. 231948
Umiya Shipping Agency Tel. 255640 Fax. 233625	Vaz Forwarders Ltd Tel. 235317 Fax. 255221
Unique Forwarders Tel. 230080, 255417 Fax. 236131	Varsh Shipping & Travels Tel. 222386, 255300 Fax. 255300
V. Arjoon Tel. 221049, 221335, 222058, 223307 Fax. 234167	Venus Clearing Agency Tel. 233960 Fax. 233362
Velji Dosabhai & Sons Tel. 270220, 270025, 221818, 231423 Fax. 270164, 232363	Vishal Shipping & Handling Tel. 223960 Fax. 233362
Vishvajyoti Enterprises Tel. 252381, 252318 Fax. 253091	Worldwide Cargo Care Pvt Ltd Tel. 221290, 221479, 220307, 230217 Fax. 231913
Velji P & Sons Tel. 255327, 231545, 231546, 270976 Fax. 255328	Zenith Trade Link Tel. 223193 Fax. 255522
Vailash Transport Co. Tel. 233579, 223580	

21.11 Surveyors at Kandla

Adnuralty Marine Services Tel. 235412, 256813 Fax. 256813	Marine Consultants & Surveyors Pvt Ltd Tel. 255293 Fax. 234416
Capt. S. Kochar & co. Tel. 222247, 221084 Fax. 231357	Murray Fenton (India) Surveyors Limited Tel. 235960, 236238 Fax. 233335

Dr. Amin Superintendents & Surveyors Pvt Limited, Tel. 221520, 235636 Fax. 226527	M. M. Cargo Gear & Marine Surveyors Tel. 231385 Fax. 235255
Det Norske Veritas (DNV) Tel. 232712	M.B.S. Surveyors Tel. 256782
Geo-Chem Laboratories Pvt Limited Tel. 221841, 222179 Fax. 233743	Navark & Mareng Surveyors & Consultants Tel. 232123, 233270
G. P. Dave & Sons Tel. 234288 Fax. 234382	S.G.S. India Limited Tel. 221857, 238047, 231869 Fax.232883
Gupta & Associates Tel. 222542 Fax. 222542	S. K. S. Surveyors Assessors Tel. 220555
Inspectorate (India) Consulting	Seascan Surveyors Pvt Limited
Engineering Pvt Limited Tel. 221520, 235636 Fax. 255217	Tel. 221833, 233639, 221627 Fax. 233639
Indian Register of Shipping & Indian Register Quality System Tel. 238623, 233695 Fax. 233695	Sterling Surveyors Tel. 230216 Fax. 230216
Iteng Engineering Tel. 221520, 255429 Fax. 255247	Technomar Surveyors Pvt Limited Tel. 221966
J B Boda Surveyors Pvt Limited Tel. 231801, 231946 Fax. 231693	TCRC Surveyors Tel. 220862, 230050 Fax. 230050
Lloyds Register of Shipping Tel. 234068	Uni Lab (India) Surveyors and Superintendents Tel. 255503
Mitra S K Pvt Limited Tel. 222648	Universal Cargo Inspection Agencies Tel. 222542

Metcalfe Hodgkinsons Pvt Limited Tel. 220940, 221740, 233707, 221845 Fax. 231629	U Marine (India) surveyors Tel. 220070 Fax. 233228
--	---

ANNEXURE-I**PARTICULARS OF THE ACTION PLAN COMMITTEE MEMBERS**

Sr. No	Name	Desgn.	Telephone Nos.			
			Office	Resi.	Fax	Mobile
1	Mr SANJAY MEHTA, IFS	Chairman	233001 234601	233002	235982	
2	Mr.	Deputy Chairman	234121	234218	236323	
3	Capt. T. Srivnivas	Dy. Conservator	233585	232806	233585	98252 32982
4	Mr. A. Krishnan	Dy. FA & CAO	220214	223854	-	98252 27036
5	Mr. R. V. Rajwani	Dy. FA & CAO	221648	226112	-	98793 70975
6	Mr. AJAY GUPTA	Sr. DD (EDP)	239623	234116	-	98252 27095
7	Mr. Bimal Kumar Jha	Secretary	220167	231939	233172	81410 84794
8	Mr.	Sr. Dy. Secy	220033	234730	-	98252 27480
9	Mr. Suresh Balan	Dy. Secretary	221375	236086	-	98252 27044
10	Mr.	Sr. Astt. Secy	221679	-	-	82380 37207
11	Mr.	SE(H) and OSD(Estate)	270429	235683		98252 25963
12	Mr. Y. K Singh	Personnel Officer	223828	228584		98252 27079
13	Mr.	Traffic Manager				
14	Mr. S. Krupanand Swamy	Sr. Dy.TM	270270	235100		98252 27049
15	Mr. Shankar Jivaji	Deputy TM	270324	234918		94264 51554
16	Mr. D. N. Sondhi	FA & CAO	233174	-	233174	98252 14726
17	Capt. S. K. Pathak	Harbour Master	270201	231310		98258 03499
18						
19	Mr. Sunil Kumar	Flotilla Supdt.	270280	226121		78746 27756
20	Mr. K. Varughese	FCSO	270176/ 78	227512	270176	98252 27041

21	Mr. SSP PATIL	Chief Engineer	233192	228777	220050	98252 27243
22	Mr	C.M.E.	270632	231043		
23	Mr.	Dy. CME	270426	226067	270184	98252 35196
24	Mr. N M Parmar	DY CHIEF ENGINEER	270787	252624		98252 27046
25	Dr. Kalindi Gandhi	Chief Medical Officer	225767 220072	225555	232288	98256 11208
26	Dr. Mahesh Bapat	Sr. MO	234598	228167		96876 07528
27	Shri CHAUDHRI	Sr. Commandant CISF	271037	229140	271037	98252 27282

THE TELEPHONE NUMBERS OF SOME OF THE VIPS

Sr. No.	Name and Designation	Fax / Mobile	Telephone (Office)	Telephone (Resi)
1	District Collector, Bhuj	02832-250430	250020	250350
2	Resident Add. Collector, Bhuj	250430 9978405099	250650	
3	Superintends of Police, Bhuj,	99784 05073	250444 250250	250850
4	Asstt. Supdt. Of Police, Bhuj		253405	250850
5	Dy. Collector, Anjar	99784 05079	243345	243345
6	Mamlatdar, Anjar		242588	243362
7	Mamlatdar, Gandhidham.	75670 03975	250475 250270	222875 250475
8	Traffic Manager, IOC	234396	231871	236442
9	Air Force Commander, Jamnagar		2550245	-
10	Collector, Jamnagar		2555869	2554059
11	Commandant, BSF, Gandhidham		223845	
12	Mrs. Vinod Chawda, MP, Kachchh	02832 - 225466 9825905467		
13	Mr. Vasan Ahir, MLA, Anjar	9825025148		
14	Dr. Nimaben Acharya, MLA, Bhuj	9825226700	220715	
15	Mr. Rameshbhai Maheshwari, Gandhidham	9909910619		
16	Mr. Tarachand Chedda, MLA, Mandvi	9825225394		
17	Mr. Pankaj Mehta, MLA, Rapar	9825227883		
18	Mr. <u>Shaktisinh Gohil</u> ,	95865 58120		

	MLA, Abdasa,			
19	Kum. Tulsi P. Anandani, SRC	260401	260404 260811	260631
20	Civil Surgeon, GK Gen. Hospital, Bhuj		222850	

ANNEXURE –III**IMPORTANT TELEPHONE NUMBERS OF
INDIAN METEOROLOGICAL DEPARTMENT**

Designation	Address	Office	Resi.	Fax
Director General	Mausam Bhavan, Lodi Road, New Delhi.	011- 24611842	011- 24633692	011- 24611792
		011-		011- 24619167

D.D.G.M. (C.W)	-do -	24611068		
D.D.G.M. (WF)	Met Office, Simla Office, Pune	020- 25535886	020- 25884104	020- 24623210 25893330 25535201
D.D.G.M.	RC Colaba, Mumbai	022- 22150517	22150417	
Director (ACWC)	-do-	022- 22150405	022- 22150452	
Director (I/c)	Met Center Ahmedabad	079- 22865012 22867206		079- 22865449
Met I/C	MET Centre, Ahmedabad	22861413		
Dr. Jayanta Sarkar,	Director I/C.	22865165, 22867657		

Websites

www.imd.emet.in

www.imdmumbai.gov.in

DISASTER MANAGEMENT CELL

Chief Executive Officer,
 9978407002(M), 079-3259276(O)
 079-23254900(R)
 079-3259248(FAX)

ANNEXURE-IV**TELEPHONE NOS. OF STATE MINISTERS**

Sr. No.	Name and Designation	<u>Telephone Numbers</u>		
		Office	Residence	Mobile / Fax
1	Mrs. Anandiben Patel, Hon'ble Chief Minister, Block No.1, 5th Floor, Sachivalaya, Gandhinagar	O) 079 – 23232611- 19	(R) 079 - 23222020	(F) 079 - 23222101
2	Mr Babubhai B. Bokhiriya, Minister for Agri., Animal husbandary. Fisheries	079 - 23238109		079 - 23250133
3	Shri Sankarbhai Chaudhry Min. for Health & Family Welfare and Transport	079 – 23250193		079 – 23250145
4	Shri Ramanlal Vora Min. for Social Justice and Empower	079 - 23238078		079 - 23257973

	Department			
5	Shri Mangubhai C. Patel Forest and Environment, Tribal Development.	079 - 23250113		079 - 23250306
6	Shri Bhupendrasinh Manubha Chudasma, Education, Food and Civil Supplied.	079 - 23243389		079 - 23250120
7	Mr Saurabhai Patel, (Finance, Energy and Petrochemicals, Salt Industries, Tourism)	079 - 23238152	23250625	079- 23250215

OFFICIALS

Sr. No.	Designation	office		Fax
01	Chief Secretary, GAD	23220372		23250305
02	Principal Secretary, GAD	23250016		23222101
03	Addl. Chief Secretary, Port & Road Transport	23250506		23252132
04	Principal Secretary (Industries & Mines)	23250701		23250844
05	Principal Secretary (Labour & Employment)	23250871		
06	Addl. Chief Secretary (Home)	23250701		23250844
07	Principal Secretary (Energy & Petro-chemicals)	23250771		23250797
08	Principal Secretary (Finance)	23220286		
09	Principal Secretary (Revenue)	23251603		23251325

10	Principal Secretary (Education)	23251301		23251325
11	Chairman, GMB	23238346	23249356	

ANNEXURE – V**TELEPHONE NOS. OF GUJARAT STATE DISTRICT COLLECTORS**

Sr. No.	District	Office	Residence
1	Ahmedabad	27551681	22863595
2	Amreli	222307	222301
3	Anand	242871	261000
4	Banaskantha	257171	257007
5	Bharuch	240600	223701
6	Bhavnagar	2428822	2568866
7	Dahod	221999	221888
8	Dang	220201	220202
9	Gandhinagar	23220330	23254884
10	Jamnagar	2555869	2554059
11	Junagadh	2651202	2650203
12	Kachchh	250020	250350
13	Kheda	2550856	2556700
14	Mehsana	222200	253565
15	Narmada	222162	222161
16	Navsari	244999	246000
17	Panchmahal	242800	242900
18	Patan	233301	233300

19	Porbandhar	2243800	2243801
20	Rajkot	2463900	2172900
21	Sabarkantha	241001	223001
22	Surat	2471121	2471416
23	Surendranagar	282200	282201
24	Vadodara	2433000	2313131
25	Valsad	253613	253060
26	Vapi	224400	220221

Control Room (Earthquake, Gandhinagar):

3251914 / 3251910 / 3240339 / 3240303 (Fax)

ANNEXURE – VI

GUJARAT STATE DISASTER MANAGEMENT AUTHORITY
TEL. NOS OF SENIOR OFFICIALS

Sr. No.	Name and Designation	Office	Residence	Mobile
1	Dr.Ranjit Banerjee, IAS, Chief Executive Officer, GSDMA	079-3259276 Fax.0793259248		9978407002
2	Mr V.Thirupuzzah,IAS, Addl. CEO, GSDMA	079-3259502 Fax.0793259275	079- 6309273	9825095148
3.	Mr. H.N. Gamit,IAS, Director(Admn.)	079-3259278		9978407005

ANNEXURE –VII

DISTRICT LEVEL AUTHORITIES (EAST)

Name and Designation of Officer	Fax	Telephone Nos. (Office)	Telephone Nos. (Residence)
District Collector, Bhuj. 9978406212	250430	(02832) 250020	02832- 250350
Resident Add. Collector, Bhuj Mob.9978405099	250430	250650	
Mr. Deepakkumar Menghani (IPS) S. P.-(Purab),9978405690		280233	
Mr. C.R. Kotad, GPS Dy. SP (Anjar)9825304239	243254		
Mr. D.R. Agrawat(GPS) Dy. SP(HQ)9825225071			
Mr. Chirag Patel,(GPS) Dy. SP.9824543004	0837- 224040		
Control Room(DC-5)Purab	280287		
Mr. Vinod Chawda, M.P.,Kachchh		(m)	
Dy.Collector, Anjar Mob. 9825228049		243345	243363
Mamlatdar, Anjar Mob. 9879278174		242588	243362
Mamlatdar, Gandhidham 7567003975		250475 250270	222875 250475
Collector, Jamnagar		2555869	2554059
Collector's Control Room, Bhuj.		2252347 2231733	-
Dy. Mamlatdar, Gandhidham		250475 250270	9427719800
Civil Defence, Gandhidham		220221	

PGVCL, Gandhidham		221728 222809	
GW&SB, Gandhidham		220975	
GSRTC, Gandhidham		220198	
Duty Officer, All India Radio, Bhuj		221412	
State Information Dept. (Shri Sony) (m) 9879012714		224859 250954	253034 252855
Air Force,Duty Officer, Bhuj		252501 252502	
Air Force, Bhuj		223450	
Air Port, Bhuj		254550	
Aerodrome Officer, Kandla		238370	223247
Indian Navy, Jamnagar		550263 to 5	550825
Airforce, Jamnagar		550245 to 7	550247

ANNEXURE – VIII**List of Telephone Numbers of Gujarat Maritime Board**

Sr. No.	Name, Designation and place of Office	Tele. No. (Office)	Tele. No. (Residence)	Fax No.
1	Mr. Rajgopal, Chairman, Gandhinagar.	23250508 23250506		079-23250589

2	Mr. A. K. Rakesh VC & CEO,Gandhinagar	23238363	23262280	23234703
3	Chief Nautical Officer, Gandhinagar	23238346-47		-do-
4	Chief EngineerI, Gandhinagar	23238347		-do-
5	Officer on Special Duty, Gandhinagar	23238346	079- 2323232	-do-
6	Exe. Asst. to VC&CEO, Gandhinagar	3238363	7451465	-
7	Head Office, Gandhinagar	3238346 to 48	-	34703/04
8	Port Officer, Magdalla	0261-2470533	-	2475645
9	Port Officer, Bharuch	02642-241772	229082	220377
10	Port Officer, Bhavnagar	0278-2519221	2568580	2211026
11	Port Officer, Jafrabad	02794-245165		245152
12	Port Officer, Porbandar	0286-2242408	2242412	2244013
13	Port Officer, Veraval	02876-220001	242956	243138
14	Port Officer, Okha	02892-262001	262010	262002
15	Port Officer, Jamnagar	0288-2755106	2557163	2756909
16	Port Officer, Navlakhi Main Gate	02822-220435		232470
17	Port Officer, Mandvi	02834-220033	220040	230033
18	Traffic Inspector, Mundra	02838-222136	222136	-
19	Executive EngineerI, Jakhau	02831-287261	222996	-
20	Gujarat Pipavav Port Ltd., Chief Operating Officer, Duty Office	02794-286314 86001/92	286070	-
21	Gujarat Adani Port Ltd.,	02838-	287241	-

	Mundra.	288201 to 208		
--	---------	---------------	--	--

ANNEXURE – IX**POLICE AUTHORITIES**

Name and Designation of Officer	Telephone Nos. (Office)	Telephone Nos. (Residence)
PARIXITA RATHORE S. P. (Purab), 99784 05690	280233	
Dy. SP (Anjar)9825304239	243254	
Dy. SP(HQ)9825225071	243254	
Dy. SP.9824543004	224040	
Police Control Room,DC-5,Poorab, Gandhidham	280287	
Police Control Room, Bhuj	253593 / 250960	Fax – 250427

Dy. Supdt. Of Police, Anjar	02836-243254	242596
Dy. Supdt. Of Police – Bhachau	02837-224040	224020
Bhachau Police Station	02837-224036	
Anjar Police Station	02836 – 242517	242517
Gandhidham Police Station	A. 100/232500/ 229513 B. 233752	
Kandla Police Station	270527	
Adipur Police Station	260615	
Air Commander, Jamnagar	0288-2720003 -009	
Commandant, BSF, GIM	223845	
Air Force Commander, Bhuj	(02832)244005-10	
Army, Bhuj, C.O 128 AD Regmt	229239,229942	

ANNEXURE – X**For the supply of food packets etc., the following Agencies will be contacted:**

Sr. No.	Name of Agency	Contact Person	Telephone No.
1	Arya Samaj Mandal	Mr.Vachanidhi	231223 / 9824221332
2	Agrawal Samaj	Mr. Sunil Sharma	234977
3	RSS	Mr. Sunil Kothari	222560
4	Rotary Club, Gandhidham	Mr. Samir shah	9825093732
5	Red Cross Society	Dr. Bhavesh Acharya	234854 / 232736
6	Lohana Mahajan, Gandhidham	Mr. J.P. Thakkar	9879109826
7	Marvaari Yuva Manch	Mr.Sunil Bajaj (President) Mr. Prashant Agarwal	9879015408
8	Swaminarain Mandir	Mr.Lavjibhai Thackker	231555, 233666
9	Gandhidham Sindhi Youth Circle	Mr.Vijay Khubchandani & Mr.Kundabhai	220490
10	Satwara Samaj	Mr.agavjibhai	235659
11	Sitaram Parivar	Mr.Mohanbhai Dharsi	222373, 234603
12	Gurudwara, Gandhidham		220643
13	Swaminarayan Gurukul	Swamimukta Prasadji	228098, 226555

Apart from the above, if required, the following hotels may be contacted for the supply of food packets:-

Sr. No.	Name of Hotel	Contact Person	Telephone No.
1	Grand Shiv	Mr Nagendra Singh	221297, 9825226568
2	Sharma Resorts	Mr Madan Mohta	31824/231823/231825/ 224885-86-87-88-89
3	Satkar	Mr Babu Bhai Agrawal	234100/222597
4	Natraj	Mr. Acharya	221749/221956/221955 221954/238002
5	President	Mr. Romesh	220053
6	K.K.Caterers	Mr. Kaniyalal Rajwani	(M) 98252 26998 (M) 98983 74896
7	Hotel Mid-Town, Adipur	Mr. Nagendra Singh	98252 26568 260237/260080
8	Hotel Sea-Rock, New Kandla	Mr. Devidas Shetty	270490

LIST OF LABOUR CONTRACTORS OPERATING AT KANDLA PORT

Sr. No.	Name of the Company	Contact person	Address	Contact Nos
1	Neelkant Handling A/c Shree Radhey Shipping	Haresh Bupendra	Tenament B Plot 290, Ward 10/A, G'dham	237040 98250 01743
2	Ratnakar Handling A/c Aditya Marine	Radhakishan Parida	83-84, GIDC G'dham	98791 23371
3	Ganesh Handling Co.	Dayalal B. Rabari	6-8, Goyal Chamber, GIM	235504
4	Al Pirani Al Sailani	Akbar Yakub	CS-10, Port Colony, Kandla	22053 / 232174 99793 31100 98257 87808
5	Shree Ravechi Handling A/c Trinity Shipping	Mahadeva Agaria	11, Second Floor, Plot.343, Ward 12- B, GIM	250286 9825361347
6	Shree Ramdev Handling	Nimbaram Gulabji	377, Sector-7 GIM	9825348935 9979898564
7	AVB & Co	Mukesh Gujjar	15, GF, Gokul Park, GIM	232967
8	Ashapura Labour Supply	Khimji Jallabhai Rathod	48, GIDC, Near Ambika Weigh Bridge, GIM	9979053378 9898128069
9	Shree Krishna Handling	Harinder Yadav	Plot E – 108, Guj Housing Soccity, Sec-5, GIM	9879549803
10	Naasmin & Co	Umar Osman Chamadia	Plot – 14, Sector- 7, GIM	9898333397
11	M.S. Logistics	Asgar Haji Mungrani	Shop No. 5, Opp. CISF Gate,	9825241065 9913620407

			Kandla	
12	Shree Majeesa Handling	Jugal Kishor Joshi	Block 24, MIG, Kidana, GIM	9879373992 9979898564
13	Shree Kailash Handling Co.	Mohanbhai Heera	Plot No. 7, Sector- 8, GIM	9825228555 9879288875
14	Javed Abu Saicha	Javed Abu Saicha Gani Patel	Shop – 13, Port Colony, Kandla	9825092748 9825563094
15	Shree Ganesh Handling	Dayabhai Rabari	6-8, Goyal Chamber, GIM	9825056599
16	Bhupendra & Co	Mayur M Ahir	Plot 253, Ward 12/C, GIM	9727762191 9825225239

ANNEXURE –
XII

LIST OF CIVIL ELECTRICAL AND MECHANICAL CONTRACTORS

Sr. No.	Name & Address of Contractor	Office	Resi	Mobile
1	Mr. Dilip Bhandbe, M/s Mukund Ltd.	223412		
2	M/s. Maheshwari Const. Co., SDX-N-5, Gandhidham-Kutch Mr Rameshbhai	232134		
3	M/s. Apex Engineers, Bajaj Chambers, 12/B, Gandhidham – Kutch (Mr. Vishal)	222002 222223		9898226666
4	M/s. Gadhvi Constructions, Plot No.524, Sector – 5, Gandhidham – Kutch	235772		9426215258
5	M/s. Advance Builders & Contractors, B-23, Apnanagar, Gandhidham – Kutch.		232864 234242	9825255934
6	M/s. Mohan Construction Co., 415, 2/B, Adipur (Mr.Mohan)		264140	9825174351
7	M/s. Star Decorators, 17, Plot No.5, 12/A, National Highway, Gandhidham – Kutch (Mr. Vinod Bajaj)	221450		
8	M/s. Kamal P. Chellani, DBZ-S-81-A, Gandhidham-Kutch (Mr.Kamal)			9825221542
9	M/s. K.K.Construction, E-71, Gujarat Housing Society,			230064

	Devi Krupa, Sector -5, Gandhidham (Mr Milanbhai)			
10	M/s. Mepabhai Madan, Plot No. 21/22, Sector-9, Opp. KPT Office, Gandhidham Mr Rajubhai	222209 222210		233627
11	M/s. S. B. Singh, B-110, Sapna Nagar, Gandhidham – Kutch	239351		
12	M/s. Dipesh Construction Co., 11, Apurva Chambers, Ganga Gate, Anjar – Kutch. (Mr. Parth) (Mr. Sukhdevbhai)	242997	243319	9824294260 9825179040
13	M/s. Raj Construction Co., Deepak Complex, Plot No.315, Ward 12/B, Gandhidham-Kutch Mr Rajesh Makhijani	220911		
14	M/s. M. V. Rajani,444, 2/B, Matruchhaya,Rambaugh Road, Adipur – Kutch (Mr. Narayan)	260800 262920		9825225690
15	M/s. Bhimji Velji Sorathia, 21, Nilesh Park, Plot No.80, Sector – 8, Near New Court Building, Gandhidham – Kutch (Mr. Bhimji Velji)	231383		9825225948
16	M/s. Sollone & Parco Engg. Co., CCX-165, Adipur – Kutch (Mr Ravi Solanki)	261298 263248		9825222919
17	M/s. Mahesh Construction,			

	Plot No. 415, 2/B, Adipur- Kutch (Mr. Mahesh)		264140	9825091599
18	M/s. Patel Construction Co. Zanda Chowk, Gandhidham (Mr. Tejabhai Kangad)	220421		9825227199
19	M/s. M. G. Bhavnani, Plot No.102, Sector 1/A, Gandhidham – Kutch			9825191636
20	M/s. Patel Engineering Works, Gandhidham	231832		
21	M/s. H.M.G. Gandhidham	235710 234609		
22	M/s. Mukund Limited Mumbai	022- 25347373		
23	M/s. Bajaj Electric Mumbai	022- 23724192		
24	M/s. Mishra Brothers Gandhidham	221172		
25	M/s. Sonu Electricals 18, K.P.Shopping Centre, Near Jivan Bharati School, Karelibaug, Vadodara-390018 Shri Jayendrasingh.B. Thakker	0265- 2464108	2647886	
26	M/s. Ravi Electronics, "Prashant", 20, New Jagnath Rajkot – 360 001 Mr. G.K.Patel	465256 460 253		
27	M/s Megha Technicals, CCX – 165, Adipur – Kutch (Mr. Ravi Solanki)	261298 263248		9375320232

28	M/s Maruti Construction, Gandhidham – Kutch			9824893851
29	M/s Ramesh Meghji Sorathia, Anjar – Kutch			9825225948
30	M/s Mohit Construction, B-168, Shaktinagar, Gandhidham – Kutch			9825227072

ANNEXURE – XIII**LIST OF SALT LAND LESSEES**

Sr. No .	Name of Salt Works	Contact Person	Tel. No. Office	Tel. No. Residence
1	Asstt. Salt Commissioner, Gandhidham	Mr. Jagdish Tripathi	233670	263690
2	M/s. Kanoria Chemicals and Ind. Ltd., Plot No.220,	Mr. B. N. Singh, Mr. J. Singh	229470 0237-74433	283325 9825225841

	Sector -4, Gandhidham	Factory -		
3	Shree Krishna Salt Industries, Central Bank Compound, Gandhidham	Mr. Kantibhai Thakkar Mr. Vikash Patel Mb: 9825206214	234727 233990	235315 234089
4	M/s. Chirai Salt Works, DBZ-S-46, Jawahar Chock, Gandhidham.	Mr.Sureshbhai Mr.Parasbhai Mb: 9825225181 Mr.Mayajar	221109 221267 9826214709	234386 233081
5	M/s. Bhuvneshwari Salt Works, TCX-S-62, Gandhidham	Mr.Sreechandji Jain Mob: 9825222269	237114 235203	233605 236860
6	M/s. Dangershee Salt Works, Shop No. D-93, P.B.No.9, Gandhidham	Mr.Hiralal Parekh Mb: 9825019661 Mr. R.B.Agrawal Mb: 9825019662 Mr. Bhikhabhai (Salt Area)	222765 223440 9825225667	232767
7	M/s. Shree Laxmi Salt Allied Ind., "Shree Sadan", 207 / 12-B, Gandhidham	Mr. Rajubhai Rathi Mr. Rameshbhai Rathi Mob.: 9824214901	232167	232167 235482
8	M/s. Jyoti Salt Industries, "Sukh Sadan", Opp. Hotel President, Gandhidham	Mr.Acharya Sukhdevbhai Mr. Sukhdevbhai Acharya Mb: 9825226075	223776 221082 221089 223094	221876
9	M/s. New Kandla Salt and Chemical Co., "Maitri Bhavan", Plot No.18, Sector 8,	Mr. Ashokbhai Sanghvi Mr. Babulalji Sanghvi	232227 231588 234087	234325 231814 232122

	Gandhidham	Mb: 9825226091 Mr. Sukhrajbhai Mb: 98252 26011		
10	M/s. Kutch Salt Works, New Kandla	Mr. Mitenbhai Mb: 9825225990 Mr. S.P.Giria, Works Manager, Mb: 9825228085	234659 022- 22040561 22041598 270371	238633

11	M/s. Vijay Salt Works and Allied Industries, "Friends House", P.No. 50, Sector -1A, P.B.No.106, Gandhidham	Mr. Harishbhai Chaturani Mb: 9825064241 Mr. Babulal Nahata Mr. Lalchandji Nahata	231119 252247 223743	234856 9825228398
12	M/s. Rajesh Salt Works, "Chandan Chambers" National Highway, Plot No.18, 12/A, Gandhidham.	Mr. Kishorbhai Thakkar Mob: 9825177081 Mr. Rameshbhai Mb: 9825226026	220586 221048 222301	234387
13	M/s. Western Chemical, DBZ-S-151, Gandhidham	Mr. Naranbhai Mb: 9825226092	233185 230913	230141
14	M/s. Urvakunj Nicotine Ltd., Central Bank Compound, Plot No.31, Sector No.9, Gandhidham	Mr. Mahendrabhai Patel – 9825206214 Mr. Vikash Patel Mb: 9825226214	234727	234480
15	M/. Friends Salt Works, "Maitri Bhavan", Plot No.18, Sector No.8, Gandhidham	Mr. Babulalji Mb: 9825226015 Mr. Ashokbhai Mb: 9825226091 Mr. Sukhrajbhai Mb: 9825226011	232227 231588 234087	231646 231814
16	Smt. Savitri H.Pandya, DBZ-N-21/A, Gandhidham	Mr. Jagdihbhai	220212 238112	255612

17	Smt. Vimlaben.H. Pandya, DBZ-N-21/A, Gandhidham	Mr. Jadishbhai Mr.Amritlal Pandya Mb: 9825225212	220212/ 238112/ 238212/ 255612 Fax: 222930	
18	M/s. Rajendra Salt Works, D-125, Jawahar Chowk, Gandhidham	Mr. Tarachand	-	-
19	Mr Natwarlal Agrawal, TCX-S-75, Gandhidham	Mr. Natwarlal Mb: 9825393555	222672	231564
20	Mr Indrumal Khubchand, C/o Gulab Salt Works, D-125, Jawahar Chowk, Gandhidham	Mr. Tarachand	233041 234388	234937
21	Mr Virji Khimji C/o Ajit Salt works, D-75, Gandhidham	Mr. Kirtibhai	220310	-
22	Mr Girdharilal.S. Agrawal, Plot No.126, Ward – 12/B, Gandhidham	Mr. Girdharilal	232862	234755
23	Mr Vijay Kumar.D. Palan & Mri Jagdish Kumar.D.	Mr. Navrotambhai Palan	220310	-
24	M/s. Satya Salt Works, DBZ-S-183, Gandhidham	Mr. Candubhai Mb: 9825225911	224055 221445	234739 234469
25	Shri Premji Gangji Soni,	Mr. Mahesh Soni	221263	-

	DBZ-S-183, Gandhidham			
26	Smt. Geetadevi P. Chaturani Plot No.13, Sector 1, Gandhidham	Mr. Romesh / Ashwin Mr. Dayalbhai Chaturani, Mb:9825064245	221048 256713 220586 256706 Fax: 222930	-
27	Shri Rashmin A.Pandya DBZ-N-21/A, Gandhidham	Mr. Jagdish Pandya	220212 238112 238212 Fax: 222930	-
28	M/s. Neelkanth Enterprise, DBZ-S-60, Gandhidham	Mr. Shamjibhai Mb: 9825 25711	220421 220103 Fax: 223560	231485
29	Dayalal G.Chaturani Shop No.1 to 4, "Chandan Chamber" Plot No.18, Ward No.12, Gandhidham	Mr.Dayal	221048 220588	-
30	Shri Chaganlal Punamchand, DBZ-N-197, Gandhidham	Mr. Chaganlal	220545	-

Annexure –**XIV****LIST OF STEVEDORES AT THE PORT**

Sr. No.	Name	Address	Fax No.	Telephone Nos.	
				Office	Resi.
1	M/s. Cargo Movers	"Cargo House" BBZS-32A, Gandhidham	231687	220453 231365	261280
2	M/s. DBC & Sons (P) Ltd.	Seva Sadan-II, Room No. 303 / 304, New Kandla	270631	270503 270263 270348	-
3	M/s. A.V.Joshi & Co.	Plot No. 18, Sector-8, Maitry Bhavan, Nr. Post Office, Gandhidham –Kutch	233924	231070 232227 231588	234909

4	M/s. Agarwal Handling Agencies	DBZ-N-47, Gandhidham – Kutch	232749	220282 233187	232749
5	M/s. ACT Shipping P. Ltd	Seva Sadan-II, Room No. 206/207, New Kandla	232175	270111 270112 270015 229967 231734	261308 231416
6	M/s. Cargo Carriers	214/215, Rishab Corner, Plot 93, Sector- 8, GIM	230030	220816 231649 230030	231694
7	M/s. Cargo Clearing Agency (Gujarat)	Plot No. 271, Ward 12-B, Gandhidham	233034	221721 220655	231452
8	M/s. Chotalal Premji Stevedores Pvt. Ltd	C-8, Shaktinagar, GIM	231509	270009	-
9	M/s. Hiralal Maganlal & Co.	C-11, GIDC Area, Gandhidham – Kutch	223914	223914 231832	223878 232430
10	M/s. New Dholera Shipping Company	Goyal Commerce Centre Building – 1, Plot No.259, Ward 12B, Gandhidham – Kutch	-	222637 232267	237284
11	M/s. J.M. Baxi & Co.	Seva Sadan – II, Room No. 301 / 306, New Kandla	270646	270630 270550 270448	260427
12	M/s. Pestonjee	Seva Sadan-II, Room	270650	270257	262914

	Bhicajee (Kutch)	No.203, New Kandla	270556	270367 270221	
13	M/s. OTA Kandla Pvt. Ltd.	BBZ-N-324, Gandhidham	223241	220145 270560	223241
14	M/s. Purshotamdas Jeramdas & Co.	5, Vaswani Chamber, Plot 16, Sector-8, GIM	222850	238242 222598	220598
15	M/s. R. Tulsidas & Co.	Ahit Building , Plot No.323, Gandhidham – Kutch	232308	222717 221943	-
16	M/s. Robinsons	101 / 102, Maritime House, Plot No.45, Sector – 9A, Gandhidham – Kutch	234394	221578 223836	231767
17	Rishi Shipping	Plot 50, Sector 1/A GIM	238943	229830 229831	
18	M/s. Vinsons	BBZ-S-25, Gandhidham – Kutch	231948	220466	222395 239460
19.	Sical Logistics Ltd	403, 4 th Floor, Madhuban Compex, OSLO, GIM	234416	234646 234194	
20	Parekh Marine Agency	C-8, Shaktinagar GIM	231509	229297 221158 230587	
21	Krishna Shipping and	Transport Nagar, NH	233135	230501	

	Allied Services	GIM		223814 229085	
22	Kevar Carrier Handling & Transport	Shop 24, Tolani Chamber, Sector -8 GIM	228298	228298	
23	Trinity Shipping & Allied Industries	Trinity House, Plot 46 Sec 1/A, GIM	232060	230911 230910	
24	Velji P & Sons(P) Ltd	2 nd Floor, Deepak Compex, 315, 12/B GIM	236168	231545 231546 225466	
25	Asean Marine Services	Ashit Bldg, Plot 33 Sector 1/A, GIM	232308	222717 221943 222145	
26	Rishikiran Roadlines	Kiran House, Plot 8 Sector 8, GIM	231422	231894 234108	
27	Universal Shipping Services	Hotel Sea Bird, Plot 173, Sector 1/A GIM	235251	230663 226050 226037	
28	R.T.Bhojwani & Sons	DBZ -S- 146, GIM	232423	222211 221831	
29	Logistic Enterprises(P) Ltd	C-8, Shaktinagar, GIM	231509	235341 230587	

30	Seaways Shipping (P) Ltd	2 nd Floor, Plot 351 Ward 12/B, GIM		226183 237147	
31	Seacrest Shipping Services Pvt. Ltd	216, 2 nd Floor Om Corner, Plot 336 Ward 12/B, GIM	227028	233325	
32	Shree Maruti Shipping Services	18/21, Swaminarayan Bldg, Sector 9, GIM	234107 250690	233245 237247 250690	
33	Liladhar Pasoo Forwarders P.Ltd	Plot 4, Sector -1 KASEZ, GIM	252383 253506	252286 252297 252612	
34	Shree Radhey Shipping Company	14-16/C, GF Green Park, GIM	232967	222919 228919 238883	
35	Pearl Shipping	220, Rishab Corner, Plot 93, Sector 8 GIM	235570	225283 225284	
36	Patel Shipping Agency	Patel Avenue, Floor 2, Plot 170, Sector 1/A GIM	231143	224024	
37	Ashirvad Shipping	18-21, Swaminarayan Bldg, Sector- 9, GIM	250690	233245 237247 222822	
38.	M/s. Swaminarayan	1 st Floor, H-6, Op. Tejas Society,	079-	231981,	

	Vijay Trade Carriar	Ghatlodia, Ahmedabad	231983	231982	
--	---------------------	-------------------------	--------	--------	--

LIST OF TANK FARM OWNERS

Sr. No.	Tank Farm Owners	Persons to be contacted in case of emergency		
		Name and Position	Telephone No.	Mobile No.
1	Kesar Enterprises Ltd., Near Oil Jetty, Old Kandla (Kutch)-370210	Mr. R.K. Gupta Gen. Manager	270435 (O) 295676 I	9375349181
2	Kessar Enterprises Ltd, Terminal II, Plot No. 5 &6 Old Kandla	Mr. R.K. Gupta G.M	270435 (O) 270177 (O)	9375349181
2	Chemical & Resins Pvt.Ltd Terminal –I, Near Oil Jetty, Old Kandla, Kutch Terminal – II, Near West Gate, New Kandla – Kutch	Mr. Manoj Kumar Gupta, Terminal Manager	270505(O) 270916 (O)	99240 44424
3	Indo-Nippon Co. Ltd., Plot No.2, K.K.Road, Old Kandla,	Mr. R.N. Pathak Asst. Terminal Manager	270795(O) 235818I 270295 (O)	9879571295
4	J. R. Enterprise, Plot No.3, Old Kandla,	Mr. Devendra Dadhich, Terminal In-charge	653528 (O) 257152 ®	9898238380
5	Friends Oil & Chemical Terminals Pvt. Ltd., Near Booster Pump Station, Old Kandla, Kutch	Mr.S.Ramakrishnan Terminal Manager	270987 (O) 257249 ®	9879572107
6	Indian Oil Corporation Ltd., Main Terminal, GIM	Mr. AK. Khanna Sr. Term. Manager	233274 (O) 229002 I	9427216637

	Foreshore Terminal, Kandla KBPL LPG Import Plant	Mr. KS Rao, Sr.TM Mr. PS Negi Plant Manager	270394 (O) 270628 (O) 270477 (O) 233359 ® 270978 (O) 236944 ®	9426416108 9426725342
7	United Storage & Tank Ltd Near IOC Foreshore Terminals, New Kandla Gas Terminal, Plot No. 4 Old Kandla	Mr. Manoj Gor Terminal Manager Mr. G. Chudasama	270609 (O) 653525 (O) 651238 ® 653529 (O)	989850029 9904366855
8	IFFCO Kandla Unit, Kandla, Kutch	Mr. M.R. Patel. Execut. Director, Mr. N.C. Patel, Sr. Manager	270711 270352(O) 270381 (O)	9687666888 9979026415
9	BPCL, KK Road, GIM	Mr.Vineet Bhudhai Sr. Manager Operations	234313 (O) 257808 ®	9409305433
10	HPCL KK Road, GIM	Mr. Murthy Manager (Installation)	230936 (O) 220084 (O) 233078 Ext 109(R)	
11	INEOS ABS (I) Ltd Plot No. 8 Old Kandla	Mr. Vineeth Nair Dy. Manager	270087 (O) 234409 I	9825237029
12	Liberty Investments Pvt. Ltd., Plot No. 1 & 2, Block 'H', New Kandla	Mr. Jitendra Vaidya Terminal Manager	270151 (O) 270464 (O) 270468 I	9825025645

13	Avean International Pvt. Ltd., Liquid Storage Tank Terminal, Plot No. B-1, New Kandla	Mr. Bharat Rathod Terminal Manager	270537 (O)	9375310260
14	Rishi Kiran Logistics Pvt Limited, Plot No. 7, Link Road Old Kandla	Mr. RH. Pandya GM (Terminal)	270223 (O) 270443 (O)	9879104556
15	N.P.P. Pvt. Ltd., Old Kandla	Mr. Jud Sequeira, GM(Terminal)	270347 (O) 257807 (R)	9099944900
16	Friends Salt Works and Allied Industries, KK Road, Old Kandla	Mr. NJ.Zinduwadia Sr. Manager Mr. HA. Mehta Sr. Manager	270814 (O) 262698 I 271260 (O) 235072 I	9825506361 9825506360
17	IMC Ltd, Cargo Jetty New Kandla	Mr. Anil Brahmbhat	270369(O) 653524 (O) 657963	9898126243
18	Agencies & Cargo Care Ltd., Plot No.3,New Kandla	Mr.Shivkumar Menon, Term. Mgr.	270714 (O)	9825226765
19	Dipak Estate Agency Plot No. 5-6, Block –A Behind Petrol Pump New Kandla	Mr. Narendra Thacker	270375 (O)	9879611243
20	Parker Agrochem Exports Ltd, Plot No. 3 –4,Block- H New Kandla	Mr. Bharat Thacker	270486 (O) 270528 (O) 231876 I	9825238260
21	Tejmalbhai & Co Plot 10, Block- A New Kandla	Mr. Ankitbhai Chandan	271330 (O) 230090 I	9825225101 9825222101
22	Parker Agrochem	Mr. P.Raja Babu	270528 (O)	9979158543

	Product P Ltd, Plot 7-9, Block-A, New Kandla	Dy Manager	231876 I	
23	Mother Dairy Fruit & Vegetable Pvt. Ltd, Near Oil Jetty, Old Kandla	Mr. Saju Therattu	270654 (O) 270655 (O) 230979(R)	9974022681
24	Mother Dairy Fruit & Vegetable Pvt. Ltd., Nr. Oil Jetty, Old Kandla	Mr. Saju Therattu	270654(O) 270655(O) 230979(R)	9974022681

ANNEXURE – XVI**LIST OF SCHOOLS IN GANDHIDHAM – KANDLA COMPLEX**

Sr. No.	Name of School	Contact Person	Telephone No.
1	Dr. C. G. High School	Principal	220271
2	SVP Gujarat Vidhyalaya	Principal	220242
3	M.P. Patel Kanya Vidhyalaya	Principal	220705
4	Adarsh Maha Vidhyalaya	Principal	234172
5	Adarsh Kanya Vidhyalaya	Principal	220175
6	Bhartiya Vidhya Mandir, Kandla Bhartiya Vidhya Mandir, Gopalpuri	Head Master Head Master	271049 233684
7	Central School, (IFFCO)	Principal	221288
8	Central School (Railway)	Principal	220657

9	Modern School	Principal	220284
10	Mount Carmel School	Principal	234262
11	Aum Vidhyalaya, IFFCO	Principal	221104
12	Saint Xavier's School, Adipur	Principal	260265
13	Maitri Maha Vidhyala, Adipur	Principal	260445
14	Maitri Kanya Vidhyalaya, Adipur	Principal	260612
15	Model Excelsior High School, Adipur	Principal	260707
16	Gujarat Vidhyalaya, Adipur	Principal	261312
17	Nagarpalika High School, Anjar	Principal	242510
18	Adarsh Nivasi School, Gandhidham	Principal	223246
19	P.N.Amersey School	Principal	223646
20	Shree Gurunanak English School	Principal	238421
21	Swaminarayan Gurukul	Principal	228098
22	Kairali English School	Principal	221050
23	Sarvodaya Pradhamic Shala Near Oslo Cinema, Gandhidham		227958
24	Ganeshnagar Pr.Shala, G'nagar		
25	Jagjivan Pra. Shala, Sapnanagar, Gandhidham		
26	Cargo Pra. Shala, Sapnanagar, Gandhidham		
27	Old & New Sunderpuri Schools	Head Master	224867
28	G'dham Pr. Shala, Near Shivaji Park, Gandhidham	Head Master	229255
29	Adipur Prathmic Shala, Adipur	Head Master	264525 264181
30	Kandla Pr. Shala, Shirva Camp & Thermal Colony & United Salt Works	Head Master	253198

ANNEXURE – XVII**LIST OF DOCTORS IN GANDHIDHAM COMPLEX**

Sl. No.	Name of Doctor	Telephone Numbers	
		Office	Residential
ANAESTHETIST			
1	Dr. (Mrs.) Dubal	232591	233555
2	Dr. (Mrs.) S.R.Gandhi	236700	229156
3	Dr. P. P. Kour	229655	220673

PHYSICIAN			
1	Dr. (Mrs) Gandhi	234561	230111
2	Dr. Johnson	222344	232244
3	Dr. Morakhiya	222008	232161
4	Dr. Sakaria	230114	230947
5	Dr. Siju Jacob (St. Joseph Hospital)	230160	223852
6	Dr. Acharya	220715	232736
7	Dr. D. P. Singh	221990	221990

SURGEONS			
1	Dr. D.G.Dasani	229231	223346
2	Dr. Girdhani	233300	231219
3	Dr. Y.V.Joshi	221557	233324

4	Dr. Hotchandani	230039	261530
5	Dr. Hemang Patel	230202	230353
6	Dr. Vachani	230400	222400
7	Dr. J.K.Ahir	237744	--
8	Dr. Harani	222096	222096

GYNAECOLOGISTS			
1	Dr. (Mrs.) N.B.Acharya	220715	232736
2	Dr. Chandrakant Thakker	224488	225588
3	Dr. (Mrs.) Rekha Singh	221990	221990
4	Dr. (Mrs.) Naik P.S.	234333	231332

PAEDIATRICIANS			
1	Dr. J. A. Dubal	232591	233777
2	Dr. Navin Thakker	230195	230894
3	Dr. Nitin Thakker	221046	220615

PATHOLOGISTS			
1	Dr. K. L. Shukla	221611	234062
2	Dr. (Mrs.) Seema Pavde	230370	231352
3	Dr. (Mrs.) Verma G.H.	229168	238386

ANNEXURE – XVIII***LIST OF ESSENTIAL SERVICES***

HOSPITALS	OFFICE	RESIDENT
------------------	---------------	-----------------

1	General Hospital, Bhuj Civil Surgeon, Bhuj	222850	250554
2	Referral Hospital, Anjar	232455	
3	Rambaugh Hospital, Gandhidham	220263	
4	Divine Life, Adipur	261802	
5	Railway Hospital, Gandhidham	231874	
6	Government Dispensary, Adipur	260608	

TELECOMMUNICATION			
1	General Manager, BSNL, Bhuj	253000	252322
2	Dy. Manager, Bhuj	252505	251505
3	Area Manager, Gandhidham	238000	235000
4	SDO, Gandhidham	236250	236251

ELECTRICITY			
1	S.E., PGVCL, Bhuj	222550	250189
2	Jr. S.E., Anjar	243008	242656
3	XEN, Anjar	242845	242446
4	Dy. Engineer, Gandhidham	222809	--
5	Line Office, Gandhidham	221728	

WATER SUPPLY			
1	S.E., GWS&SB, Bhuj	221806	250601
2	XEN, Bhuj	250685	253016

3	SE, Anjar	242416	242421
4	XEN, Gandhidham	220717	223273
5	Control Room, Gandhidham	221252	
6	Water Tank, Sunderpuri	231313	
7	Water Tank, NU-4	654564	
8	Gandhidham Municipality	231610	
9	Chief Officer, Gandhidham Municipality	234967	

ANNEXURE – XIX***LIST OF VEHICLES SUPPLIER***

Sl. No	Name of Institution	Contact Person	Parking Place Phone No.	Name and Phone No. of Driver	Availability of Vehicle.
(A) Vehicle Hire Contractors					
1	M/s Rohit Enterprise	Mr Rohit Shah 228550/237538 237547 (O) 234140 I Mob.9825225121			
(B) Ambulance Pool					
01	St. Joseph Hospital, Gandhidham	Administrator 230160/229336	Hospital Premises	Driver available round the clock	First come first serve
02	Red Cross Society, Gandhidham.	230269	Red Cross	Driver available round the	

				clock	
03	Western Railway, Gandhidham	238891, 231874	Hospital		
04	Rambaugh Government Hospital, Adipur	261625	Hospital Premises	Driver available round the clock	
05	Gautam Freight Pvt Ltd.	Mr Ramesh, Proprietor 232605/220163, 230345 (O)	GIDC Work shop Sector- 10C, Plot No. 24.		First Come First Serve
06	Tolani Eye Hospital	Supdt.(O)260497 - 260773	Hospital Premises	One driver in absence of compounde r residing in hospital	First Come first Serve
07	Sterling Divine Life Hospital, Adipur	260577, 7698166555	Hospital Premises	Round the clock	
08	Dev Smruti Trust Dr. Harani	222096, 9825227322			
09	Mobile Morgue	229430/239965	Lions Club		
10	Shav Vahini/Mobile Mroque	239965			
11	Varsha Cheritable Trust C/o Hareshkumar Tulsidas	9909829555			
12	Hari Om Trust Mr. K. Parmar	260833			

PLACEMENT OF PORT CRAFTS ON CYCLONE WARNING.

(A)	SHIPPING TUGS	Heera Mehul	Bunder
		Kalinga	Maintenance Jetty (West side)
(B)	PILOT LAUNCHES AND SURVEY LAUNCHES	M. L. BHARINI, M.L. NIHARIKA M. T. SWATI	Floating Crafts Jetty
		ML Karishma	Bunder Basin
		ML Nirishak	Inside Bunder Area North Side.
I	G.S. LAUNCHES AND MOORING LAUNCHES	M. L. Mrinal	Inside Bunder Area North Side on Pilot Launches
		M. L. Unnati M.L. Vaishali	Inner Side of Floating Craft Jetty
		M. L. Vijay M. L. Priyadashani PL Rakshak	Inside Bunder Area North on G. S. and Pilot Launches.

ANNEXURE –XXI**LIST OF LICENSE HOLDERS TO KEEP THEIR CRAFTS INSIDE THE PORT AREA.**

Sl. No.	Name of Party	Name of Nodal Officer	Tele. (Office)	Tele. (Resi)
01	M/s Jaisu Shipping Co. P Ltd., Kewalramani House, Dinshaw, Bldg. Road, New Kandla	Mr.Preetam, Director, Mob. 9825226114	270538 270128 270428	260235 260224
02	M/s Gautam Freight Pvt Ltd., Plot No. 24, Sector, 10/C, GIDC Area, Gandhidham	Mr. Ramesh Singhvi, CMD	231386 232605 230345 220163	234176 230328
03	M/s Bapu's Shipping, Plot No. 32, Sec – 9 GIM	Mr. Vishalsinh Jadeja	222002	
04	M/s Blue Ocean Sea Transport, Manali Chamber, Plot No.306, Sec 1/A GIM	Mr. Hukumat T. Bhojwani & Mr. Dushyant Patel	239143 222518 230488 239058	
05	M/s Rishi Shipping, Rishi House, Sec 1/A, Plot No. 50 Gandhidham	Mr. Manoj Mansukhani Proprietor	220843 229830 229831 223913 229517 Fax. No. 238943	
06	M/s Velji P & Sons, Deepak Complex, 2 nd Floor, Plot No. 315,	Mr. Sureshchandra	231545 231546	232247

	Ward 12/B, GIM			
07	M/s A.S. Moloobhoy & Sons, Anchor House Shivkripa Bldg, Plot No. 135, Sec 1/A, GIM	Mr. Adil Sheth M- 9375312077	326543 225060 225061 225060	
08	M/s Gudani International Pvt. Ltd, C/o Chemoil Adani Mithakali Circle, Ahmedabad.		079- 25555765 25555266	

Annexure-XXII**LIST OF TRAVEL AGENCIES**

Sr. No.	Name of Agency	Phone No.	Mobile
01	M/s. Rathod Tours and Travels, Gandhidham	222444	222959
02	M/s. Rishabh Enterprises, M/s. Rishabh Tours and Travels, 30-31, Tolani Chamber, Plot no. 2, Sector No. 8, Nr. B.M. Petrol Pump, Gandhidham	228550 237538 237547	234140 9825225121
03	M/s. Jai Somnath Travels, Mr. Mishra		9727304414
04	M/s. Agrawal Tourists, Gandhidham	221311 220068	
05	M/s. Krishna Travels, Gandhidham	220683 234838	
06	M/s. Shiv Tourists, Gandhidham	221454	
07	M/s. Thakker Travels, Gandhidham	225097	9825271072

LIST OF MAJOR HEAVY LIFT OPERATORS AT K P T

NAME OF PARTY	NAME OF CONTACT PERSON	Phone Number
Swastik Heavy Lifters	Mr. Jigneshbhai Mr. Aslambhai	9825758151 9825228421
Kutch Carrier Transport Co	Mr. C. R. Thackar	9825225591
Agarwal Handling Agency	Mr. Rakesh Thackar	9426928728
Active Cargo Movers	Mr. Narendra	9825220411
Raghuvirsingh & Sons	Mr. Harcharan	9879104853
Thacker Brothers	Mr. Kamleshbhai	9825296107
Kiran Roadlines	Mr. Pankaj Gadvi	9879104552
Regal Shipping	Mr. Ashok Dudi	9825326328
Rathore Freight Carriers		220759/ 220380

ADDITIONAL LIST OF FIRMS FOR PAY-LOADERS/CRANES

M/s Mahalaxmi Transport Co., Plot No. 35, Sector No. 8, Behind Hotel Fun & Food, Gandhidham	Mr H K Rathod	(O)222387 I233500
M/s Kandla Earth Mover, DBZ-S-151, Gandhidham	Mr Sanjay Goyal	(O)221759 I222338 (M) 9825020550
Mr Lalji Bhavanji Sathwara, Laljibhai Sathwara, Plot No. 27, Shop No.5, Sector-9/A, Gandhidham		(O)234118 I232566 (M) 9825225957

LINER AND STEAMER AGENTS AT KANDLA

Sl. No.	Name	Fax No.	Tele. No.	Mobile
01	M/s ACT Shipping Ltd Mr. Harshad Gandhi	232175/ 270597	270111 270115-6 229967 231734	9825226141
02	M/s Admiral Shipping Ltd	233596	230552 232823	
03	M/s Areadia Shipping Ltd	232542	234254 223486	
04	M/s Ambica Maritime Ltd Mr. Amit Vyas	252447	252479 252349	9825225210
05	M/s APL (India) Pvt Ltd., Mr. Murli Krishnan	236361	224601/2 236357 236355	9825225753
06	M/s Arebee Star Maritime Agencies Pvt Ltd. Mr. anil Talwar	235831	220465 235832	9824229109
07	M/s Ashit Shipping Ser. Pvt Ltd. Mr. Sanjay Thakkar	232308	221943 222717 222145	9825225698
08	M/s Atlantic Shipping Pvt Ltd	223372	230552	
09	M/a Asia Shipping Services. Mr. Mohan Karia239326	231285	234526 230954	
10	M/s Bayland Freight Systems Pvt Ltd., Mr. Danendran Gopalan	239326	225522/23	9825230880
11	M/s B D Vithlani Shipping Services Pvt Ltd.	234104	232220 221081	
12	M/s Cargo Conveyors Mr. Shekhar Ayachi Mob. 9825226102	233034	221460 220655	
13	M/s CCA Shipping Services Mr. K C Varghese	233034	221721 220655	9825225217
14	M/s Chowgule Brothers	229227	278521	9825361782

	Mr. C R Soman		225051 232365	
15	M/s Coastline Services (India) Pvt Ltd.	221137	232095 222853	
16	M/s Container Marine Agency Pvt Ltd	234541	230026 220416	
17	M/s Conftreight Shipping Agency (India) Pvt Ltd. Mr. K T R Nair	-	233615 236157	
18	M/s Cresent Shipping Agency (India) Pvt Ltd Mr. Sanjay Salve.	224506	221290 221957	9825227311
19	M/s DBC Freight International	230832	230832 230639	
20	M/s DBC Sons (Gujarat) Pvt Ltd. Mr. R C Vazirani	270631	270263 270503	
21	M/s Depe Global Shipping Agency Pvt Ltd. Mr. Jaydeep Roy	232079	231528 233608 234582	9825228121
22	M/s Evershine Shipping Services. Mr. Kishan Motwani	234083	221588 237408	
23	M/s Forbes Gokak Ltd	231464	222634 235004	
24	M/s Freight Connection (India) Pvt Ltd	231357 270726	222247 222545 270727	
25	M/s GAC Shipping (India) Pvt Ltd. Mr. V C Rao	231429	231427 237244	9825225136
26	M/s Ganges Liners Pvt Ltd	233437	231608 233436	
27	M/s German Exp. Shipping Agency Pvt Ltd	236040	223269 236040	
28	M/s Goodrich Maritime Pvt Ltd	222875	222882 222883	
29	M/s G P Dave & Sons (Shipping)	234382	234288 234382	
30	M/s Greenways Shipping Agencies Pvt Ltd	232079	233608 234585	
31	M/s K. Shipping Services Pvt Ltd	233632	231933	

32	M/s Halar Ship & Freight Forwarders. Mr. Tejas Shrma	270224	270192 270568	9825212646
33	M/s Hind Shipping Agencies. Mr. Mahesh Vyas	234795	232710 235375	
34	M/s Hindustan Shipping Services. Mr. M D Sorathiya	239110	239110 222821	9824214994
35	M/s InterOcean Shipping India Pvt Ltd. Mr. Suresh Tripathy	232579	235201 230589	9825225583
36	M/s Intra Trade Pvt Ltd. Mr. B P Vasavda	233295	233313 231255	9825226129
37	M/s Trades Shipping Pvt Ltd	231463	235572 233606	
38	M/s James Mackintosh Marine (A) Pvt Ltd. Mr. Satish Nair	270793	270792 270846	9825226077
39	M/s. J.M. Baxi & Co.	270646	270630 270635 270525	9825225107
40	M/s Kutch Shipping Agency Pvt Ltd.	233339	221148 250226/ 7/8	
41	M/s Liladhar Passop Forwarders Pvt Ltd. Mr. S. Chakraborty	252383	252297 252402 252288	9825020523
42	M/s Maersk (India) Ltd. Mr. Dinesh Joshi	231388	231387 236192 233963	9825270419
43	M/s Maheshwari Handling Agency Pvt Ltd. MR. Chaggan Maheshwary	230575 234633	223228 230393	9825227111

44	M/s Maltrans Shipping Agencies India Pv Ltd.	230606	220147 230336 235022	
45	M/s Mathurdas N. & Sons	252221	252224	

	Forwarders Ltd.		252350	
46	M/s Meridian Shipping Agency Pvt Ltd	230212	220305 230220	
47	M/s Mitsutor Shipping Agency Pvt Ltd	230411	220110	
48	M/s M M Shipping Services	235255	231385 238385	
49	M/s Modest Shipping Agency Pvt Ltd	-	230576	
50	M/s NLS Agency India Pvt Ltd. Mr. Sanjay Salve	232413	231318 220305	9825237311
51	M/s Orient Express Lines Ltd	230359	232186 232805	
52	M/s Orient Ship Agency Pvt Ltd. Mr. H G Digrani	233518	223430 223487	9824214801
53	M/s Oscar Shipping Agencies.	231812	226959/60 232123	
54	M/s Parekh Marine Agencies Pvt Ltd. Mr. Mitesh Dharamshi	231509	221409 235341	9825226557
55	M/s Patel Handling Agency (Capt. Kalra)- 9825062912	231143	224024 231004 221718	
56	M/s Patvolk (Mr. Shreekumar Nair)	231464	222624 235004	
57	M/s Pearl Shipping Agency. Capt. Kalra	231143	224024 221718	9825062912
58	M/s Penguin Shipping Agencies Pvt Ltd.	230606	230336 220147	
59	M/s Pestonjee Bhieajee (Kutch)	270650 270556	270221 270257 270367	9825226962
60	M/s Prudential Shipping Agencies Pvt Ltd. Mr. Siddharth Mishra	232911	230479 233982	9825226477
61	M/s P&R Nedlloyed India Pvt Ltd	232207	224906/7 232128	

62	M/s R T Bhojwani & Sons Mr. Gopichand Bhijwani	232423	223831 220839	9825225639
63	M/s Sahasu Shipping Services Pvt Ltd	236358	225224 237854	
64	M/s Sai Shipping Co. (P) Ltd Mr. S T Hingorani	231972	221369 231739	9825228681
65	M/s Samrat Shipping Co Pvt Ltd	232890	231983 222939	
66	M/s Samsara Shipping Pvt Ltd. Mr. Pranesh Rathod	233165	228602	9825225755
67	M/s Scorpio Shipping Agency	-	223085	
68	M/s SDS Shipping Pvt Ltd	231542	221326 221087	
69	M/s Seanay Shipping Pvt Ltd	270026	270788	
70	M/s Seabridge Maritime Agencies Pvt Ltd	231509	221409 221158	
71	M/s Seafreight Pvt Ltd	222850	233530 222393	
72	M/s Sealand Agencies India Pvt Ltd	230584	231179 230584	
73	M/s Scamar Shipping India	255563	-	
74	M/s Scatrade Shipping	234171	233810	
75	M/s Sentrans Maritime Pvt Ltd	236129	230002 220702	
76	M/s South India Corporation (Agencies) Ltd Mr. Antony	234416	221276 234646 231494	9825226256
77	M/s Spoonbill Maritime Agencies Pvt Ltd	234167	221049 222058 234454	
78	M/s Star International	231395	233948 232402	

79	M/s Taipan Shipping Pvt Ltd	236040	223269 227010	
80	M/s Taurus Shipping Services. Mr. Sukhveersingh	231266	221334 223074	9825227325
81	M/s Oceanic Shipping Agency Pvt Ltd	270631	270263 270503	
82	M/s TICC Container Line (Kandla) Pvt Ltd	237854	237854	
83	M/s Total Transport Systems Pvt Ltd	231463	222634	
84	M/s Transocean Shipping Agency Pvt Ltd	-	230832	
85	M/s Transworld Shipping Services India Pvt Ltd Mr. Sandeep Rajvanshi	231913	229824 221290	9825225733
86	M/s Trinity Shipping & All. Services Pvt Ltd Mr. Soly	222060	230911 223703	9825225245
87	M/s Unimarine Agencies (Gujarat). Mr. Jaikumar Ramdasani	224633	224631/ 32 223113	9825225216
88	M/s Unique Shipping Services Pvt Ltd	-	232729 232730	
89	M/s United Liner Agencies of India Pvt Ltd, Capt Rakesh Kumar	236040	227779 223269	9825225741
90	M/s Universal Freight Systems	252383	252288 252297	
91	M/s Universal Shipping Services Mr. Anil Pillai	235251	230663 231708	9824215168
92	M/s Velhi P. Sons (Agencies) Pvt Ltd	255328	255327 231545	
93	M/s Vibhuti Shipping Pvt Ltd Mr. Vinod	236219	236719 230035 232424	9825226536

ANNEXURE-XXV**LIST OF CLEARING & FORWARDING AGENTS AT KANDLA**

A V Joshi & Co Tel. 232605, 232227, 230345 Fax. 233924 Mr. Harshandu Mr. Vaidya (Mob.) 9825226013	C. Jivram Joshi & Sons (Gujarat) Tel. 220621 Fax. 231141 Mr. Sunil Chowdhari (Mob) 9825225400
ACT Shipping Ltd Tel. 270111/12/13, 270530, 220407 Fax. 270579, 232175	Cargo Movers Tel. 220453, 230883, 270563 Fax.231687
Jaswantraï & Co. Tel. 222630, 222717, 222145, 221943 Fax. 232308, 270385	Cargo Clearing Agency (Gujarat) Tel. 221721, 221674, 220655, 270542 Fax. 233034
Asia Shipping Services Tel. 230954. Fax. 231285	Chinubhai Kalidas & Brothers Tel. 232284 Fax. 231881
Airol Shipping Services Tel. 230080, 220180. Fax. 236131	CAP Shipping Pvt Ltd Tel. 221460, 232081 Fax. 233734
Aarpee Clearing Agency Tel. 222614. Fax. 255252	Centrans Shipping Agency (I) Pvt Ltd Tel. 256854 Fax. 234074
Ashirwad Clearing Agencies Tel. 232426, 233245 Fax. 234107	Cargo Shipping Tel. 270802, 270803 Fax. 270802
Ambalika Enterprises Tel. 255382. Fax. 255577	C. Joshi & Sons Tel. 221094
Ashmka Shipping (Tel. 222481)	Dilip A Goplani Tel. 224082, 255423 Fax. 224082
Ashis Enterprise (Tel. 234722)	D.B.C. & sons Gujarat Pvt Ltd Tel. 270263, 270348, 270503 Fax. 270631
Anchor Shipping Tel. 235781 Fax. 235781	Damjidhiroo & Sons Tel. 222329, 221328 Fax. 230139
B N Thakkar & Co., Tel. 222293, 222285, 270239	Dvji Premji Punara & Sons Tel. 222057, 221338 Fax. 230139

Fax. 230556	
B. Devchand & Sons Pvt Ltd Tel. 232220 Fax. 234014	Express Transport Pvt Ltd Tel. 220193, 220179, 270591, 222565, Fax. 220193
Benits Forwarders Pvt Ltd Tel. 221707, 222086 Fax. 223151	Friends & Friends Shipping Pvt Ltd Tel. 232227, 231588 Fax. 233924
Blue Sea Shipping Agencies Tel. 235317 Fax. 255221	Fast & Fair Company Tel. 255254, 238175 Fax. 255254
Bhanu Clearing Agency Tel. 256861 Fax. 256861	Flamingo Shipping & Forwarding Pvt Ltd Tel. 256755, 257756 Fax. 256755
Global Marine Agencies Tel. 222928, 223196, 223252 Fax.255418	Liladhar Passoo Forwarders Pvt Ltd Tel. 252288, 252297, 252402, 252617 Fax. 252383
Gayatri Shippers Tel. 230692, 223292 Fax. 230818	Lalbahi Trading Company Tel. 222139
Hiral Enterprise Te. 255644	Leap Forwarders Pvt Ltd Tel. 255530, 255509 Fax. 252383
Hindustan Shipping services Tel. 255644, 222821 Fax. 256618	Link International Tel. 255206/07 Fax. 255530
Hardip Shipping Logistics Pvt Ltd Tel. 232909, 222560 Fax. 232909	Lexicon Shipping Agencies Pvt Ltd Tel. 229951-53 Fax. 229949/50
Hansraj Pragji & Sons Tel. 221650, 255228 Fax. 255228	Logistics Enterprise Pvt Ltd Tel. 255157, 255458 Fax. 255520
H K Dave Pvt Ltd Tel. 221504, 2333632 Fax. 230411	Mathuradas Narndas & Sons Forwards Pvt Ltd, Tel. 252224, 252350, 252115 Fax.252221
Intralink Clearing & Forwarding Tel. 255188 Fax. 23148	Magal Singh & Company Tel. 224030, 255253, 234688
J M Baxi & Co. Tel. 270630/35, 270148/50, 270525 Fax. 270616	Meridian Shipping Services Tel. 233981, 255362 Fax. 230701

Jesia Mistry Agencies Pvt Ltd Tel. 222317, 223317	Megha Shipping Agency Tel. 222671, 255304 Fax. 230937
Jaisu Shipping Company Pvt Ltd Tel. 270428, 270128/538 Fax.270556	Mayur Forwarders Pvt Ltd Tel. 222671, 255304 Fax. 230937
Jivanlal Laloobhai Tel. 220308, 230530 Fax. 231640, 233803	Maritime service Pvt Ltd Tel. 222671, 255304 Fax. 255304
Krishna Clearing Agency Tel. 223813, 230501 Fax. 233135	Marathon Shipping Combine Tel. 222202, 230106 Fax. 255220
Kiran Roadlines Tel. 232297, 231984, 234108 Fax.231422	Shiv Shipping Service Tel. 255568 Fax. 22256
Kandla Clearing Agency Pvt Ltd Tel. 232337, 223211, 223210 Fax.230402	Narendra Forwarders Pvt Ltd Tel. 232504, 231795 Fax. 256678
Kamat & Co. Tel. 223471, 232730, 232729 Fax. 255243, 270779	Natwar Parikh Industries Ltd Tel. 232628 Fax. 232628
K S Chaya & Co Tel. 256604 Fax. 230693	New Dholera Shipping & Trading Company Limited. Tel. 222637 Fax. 255329
Kashyap Shipping Ltd Tel. 220816 Fax. 230030	National Shipping Tel. 232319 Fax. 232319
Kanak Shipping & Transport Tel. 231314, 230543, 222059 Fax.221702	Navjeevan Enterprise Tel. 252611, 252360 Fax. 252515
IEE & Muirhead Pvt Ltd Tel. 231535/36 Fax. 231018.	N. G. Bhanushali & Company Tel. 233648, 256791 Fax. 256879
OTA Kandla Pvt Limited Tel. 220145, 223241, 270450 Fax.223241	Shivji Kanji & Company Tel. 230127, 223728, 223729 Fax.220308
Pravin Bhatt & Sons Tel. 224032, 230079 Fax. 230079	South India Corp. (Agencies) Limited Tel. 234646, 231494, 221276, 255209 Fax.234416
Prime Forwarders	S J Thacker & Company

Tel. 234047, 232505 Fax. 231345	Tel.255678,221745 Fax.230659
Purshotam Ramjee & Compnay Tel. 220354, 222287 Fax. 231754	Star Shipping Services Tel.255424,255425,235326(F)255426
Patel Handling Agency Tel. 221718, 224024, 231004, 270017 Fax. 231143	Shivani Shipping, Tel. & Fax.256836
P S Bedi & Company Tel. 223201, 222841 Fax. 255494	Sea Trans Shipping Agency Tel. 255564 Fax. 233228, 233517
Purshotam Chtrabhuj Thacker Tel. 222720	Seaster Shipping Services Tel. 255349 Fax. 232719
Prashant Shipping Tel. 255306, 223927 Fax. 223927	Seaway Shipping Services Tel. 234272 Fax. 232719
Pramukh Forwarders Tel. 255400 Fax. 232602	Star Clearing Agencies Tel. 230273, 255529, 222983 Fax.232719
P M Agency Pvt Ltd Tel. 232553, 233973, 236414 Fax.255413	S S Shipping Agencies Tel. 236605, 238283 Fax. 236605
Raj Shipping Servie Tel. 233948, 232402 Fax. 231395	SPN Shipping Services Tel. 222453, 270733 Fax. 236605
Rajesh Shipping Service Tel. 255444, 255450/52, Fax.255151	Sierra Shipping Pvt Limited Tel. 255395 Fax. 232771
Rudra Shipping Service Tel. 220429, 255317 Fax.255317	Sonal Enterprises Tel. 252666, 252053
Rishi Shipping Tel. 220813, 229830, 2555661/2/3 Fax. 238943, 255522 Mr. B K Mansukhani (M)9825225170	S R Clearing Agency Tel. 232974, 255494 Fax. 255494
Rudraksh Shipping Servie Tel. 235937 Fax. 255582	St. John Freight System Limited Tel. 235414, 236444 Fax.235414
Sanghvi Freight Forwarders Pvt Ltd	Siddi Shipping Services

Tel. 234993, 234995, 222401 Fax.230508	Tel. 232356, 230268 Fax.256712
Sri R K Shipping Pvt Ltd Tel. 232028, 231940, 231936 Fax. 232740	Spalsh Shipping Pvt Limited Tel. 255562, Fax. 220710
Shakti Enterprises Tel. 223531, 221591 Fax. 233898	Thakarshi Madhavji & Sons Tel. 255457, 255458 Fax. 221770
Shree Ambica Commercial Company Tel. 220213, 221253	Trinity Shipping & Allied Services Pvt Ltd Tel. 223703, 230911 Fax. 232060
Shri Maruti Shipping Services. Tel. 270760, 256853, 233245 Fax.220308	Tokto Shipping Services Tel. 234040
Unity Shipping Tel. 255271	Vinson Tel. 220466 Fax. 231948
Umiya Shipping Agency Tel. 255640 Fax. 233625	Vaz Forwarders Ltd Tel. 235317 Fax. 255221
Unique Forwarders Tel. 230080, 255417 Fax. 236131	Varsh Shipping & Travels Tel. 222386, 255300 Fax. 255300
V. Arjoon Tel. 221049, 221335, 222058, 223307 Fax. 234167	Venus Clearing Agency Tel. 233960 Fax. 233362
Velji Dosabhai & Sons Tel. 270220, 270025, 221818, 231423 Fax. 270164, 232363	Vishal Shipping & Handling Tel. 223960 Fax. 233362
Vishvajyoti Enterprises Tel. 252381, 252318 Fax. 253091	Worldwide Cargo Care Pvt Ltd Tel. 221290, 221479, 220307, 230217 Fax. 231913
Velji P & Sons Tel. 255327, 231545, 231546, 270976 Fax. 255328	Zenith Trade Link Tel. 223193 Fax. 255522
Vailash Transport Co. Tel. 233579, 223580	

ANNEXURE-XXVI**SURVEYORS AT KANDLA**

Adnuralty Marine Services Tel. 235412, 256813 Fax. 256813	Marine Consultants & Surveyors Pvt Ltd Tel. 255293 Fax. 234416
Capt. S. Kochar & co. Tel. 222247, 221084 Fax. 231357	Murray Fenton (India) Surveyors Limited Tel. 235960, 236238 Fax. 233335
Dr. Amin Superintendents & Surveyors Pvt Limited, Tel. 221520, 235636 Fax. 226527	M. M. Cargo Gear & Marine Surveyors Tel. 231385 Fax. 235255
Det Norske Veritas (DNV) Tel. 232712	M.BS. Surveyors Tel. 256782
Geo-Chem Laboratories Pvt Limited Tel. 221841, 222179 Fax. 233743	Navark & Mareng Surveyors & Consultants Tel. 232123, 233270
G. P. Dave & Sons Tel. 234288 Fax. 234382	S.G.S. India Limited Tel. 221857, 238047, 231869 Fax.232883
Gupta & Associates Tel. 222542 Fax. 222542	S. K. S. Surveyors Assessors Tel. 220555
Inspectorate (India) Consulting Engineering Pvt Limited Tel. 221520, 235636 Fax. 255217	Seascan Surveyors Pvt Limited Tel. 221833, 233639, 221627 Fax. 233639
Indian Register of Shipping & Indian Register Quality System Tel. 238623, 233695 Fax. 233695	Sterling Surveyors Tel. 230216 Fax. 230216
Iteng Engineering Tel. 221520, 255429 Fax. 255247	Technomar Surveyors Pvt Limited Tel. 221966
J B Boda Surveyors Pvt Limited Tel. 231801, 231946 Fax. 231693	TCRC Surveyors Tel. 220862, 230050 Fax. 230050
Metealfe Hodgkinsons Pvt Limited Tel. 220940, 221740, 233707, 221845 Fax. 231629	U. . Marine (India) surveyors

	Tel. 220070 Fax. 233228
--	-------------------------

ANNEXURE – XXVII**LIST OF JOURNALISTS****PRINT MEDIA**

Sr. No.	Name of Newspaper	Correspondent & Address	Tel. No.	Fax
1	Kutchmitra Neewspaper	Mr. Adwait Anjaria Bureau Chief Gandhidham	222930	222930
2.	Kutch Uday,	Mr. Gangaram Bhanushali Editor, Plot.No.287, Sector-1/A, Nr.Gayatri Mandir, Gandhidham	235851 231213 9825226987	231267 239887
3	Pandya News Agency	Mr. Jagdish Pandya, Main Bazaar, Gandhidham	220212 238112 238212	221412
4.	AAjkal	Mr. Nidhiresh Raval Bureau Chief Gandhidham	9825517030	229834
5.	Chanchal	Mr. Satish Upadhyay Bureau Chief, Shardha Appartment, Hinglaj Vadi,Bhuj	02832-252942	02832-252945
6.	Sandesh	Ms. Kulsumben Yusuf,	02832-229200	255601

	Bhuj	Editor, Bhuj		228797
7.	Sandesh - Gandhidham	Mr. Jaydeep Purohit Bureau Chief Office No.: 108, Golden Point, Plot No. 31, Sector – 8, Gandhidham	222411	233211
	Sandesh Ahmedabad	Sandesh Sandesh Bhavan, Lad Society Road, Behind Vastrapur Gam, Ahmedabad-380015	079- 6762952, 6765480, 6765481, 6765482,	
8.	Gujarat Samachar Gandhidham	Mr. Awesh Malviya, B-ureau Chief, Gandhidham	9825425978	228222
	Gujarat Samachar Ahmedabad	Lok Prakashan Ltd. Gujarat Samachar Bhavan, Khanpur, AHMEDABAD	30410000	
9.	Jansatta – Loksatta	Ms Jayshreeben Mehta, Bureau Chief,Gim	9825225453 228797	---
10.	Indian Express Rajkot	216, Dhan Rajni Complex, Dr. Yagnik Road,Rakot	0281- 22481156	0281- 2481158
11.	The Times of India	Sterling Apartments,	9879324200	---

	Rajkot	1st floor, Jawahar Road, Rajkot – 360001	0281- 2226995 2227490	
	The Times of India Ahmedabad	SAKAR-1, 2nd Floor, Opp. Gandhigram Rly. Station, AHMEDABAD-380 009	079- 26554430, 26554431	079- 26587741 26554458
9.	DNA	Mr. D. V. Maheshwari Bureau Chief, Bhuj	02832- 251689	
10.	Mumbai Samachar, Chaupal	Mr. Tridev Vaidya Bureau Chief , Bhuj	02832- 231200	
11.	UNI	Mr. Mahesh Gadhvi Bureau Chief , Bhuj	9428294194	
12.	Exim Newsletter	Mr. P. G.,Nair, Bureau Chief Gandhidham	234194 9898573833	
13.	Daily Shipping Times	Mr. Haresh Manji Bureau Chief Gandhidham	222665 9925744679	
14.	Divya Bhaskar	Mr. Jayesh Shah Bureau Chief Gandhidham	9909944054	
15.	ETV	Mr. Rakesh Kotwal Bureau Chief Gandhidham	9909944080	
16.	Bhandarkar Shipping	Mr. Mehul Raval Bureau Chief Gandhidham	231455 / 9724307499	
17.	Hindustan Times, Ahmedabad	50, 5th Floor, Srikrishna Centre,	079- 6560049	079- 6560037

		Mithakali, Ahmedabad	6560061	
--	--	-------------------------	---------	--

PRINT MEDIA

18.	Mr. Kishore Ahir	Dy. Director	9427974892
19.	Shri Soni	Assistant Director	9879012714
20.	Mr. Shailesh Vyas	Chief News, All India Radio	9426802510

ANNEXURE-XXVIII**LIST OF FLEET OWNERS**

Sl. No.	Name of Company	Contact Person	Tel. Office	Tel. Resi.	Mobile
01	M/s A V Joshi & Company	Mr. Ramesh Singhvi Mr. Thacker MR. Harshandhu	231386 232605 233147	234176 221451 234325	98251 91325 98252 26105 98252 26013
02	M/s Rishi Shipping	Mr. B. K. Manshukhani Mr. Manoj Manshukhani	220843 229830 238943	234889 235587	98252 25170
03	M/s Maheshwari Handling Agency	Mr. C. P. Maheshwari Mr. Chandan Maheshwari	223228 230393	222339	98252 27111
04	M/s ABC	Mr. Latif Mr. Mithu Mr. Kasam	220483 221390 270190	234163 231477 251684	98252 26707
05	M/s Ganesh Transport	Mr. Hira Rabari Mr. Visa Rabari	223638 223915	260425	
06	M/s Kewar Carrier		220483 227553	234163	
07	M/s Krishna Transport Service	Mr. K. M. Thakker Mr. Pankaj Thacker	223814 224938	220998 234988	98250 19699 98252 25228
08	M/s Gautam Freight Ltd	Mr. Ramesh Singhvi	220163 230345	230328 234176	98251 91325

VTS GOK OFFICERS OF MASTER CONTROL CENTER (MCC) KANDLA

Sr. No.	Name	Designation	Mobile number
01	Shir B. Mishra	Deputy Director	7383576832
02	Shri Hansraj	Deputy Director	9428863924
03	Shri Mukesh Parmar	Asstt. Executive Engineer	9016106566
04	Shri M. Nimare	Asstt. Executive Engineer	9408553192

RADIO ACTIVE DISASTERS DoS AND DONTs

NUCLEAR EMERGENCIES - HOW TO RESPOND:

Nuclear facilities in India adopt internationally accepted guidelines for ensuring their safe operations and safety to the public and the environment. An independent regulatory authority oversees their safe operations. While the limits for radiation release/exposure have been set at a fraction of what can cause any significant harm, emergency procedures get implemented even when these very low limits are exceeded. As a result, it is extremely unlikely that the public near a nuclear facility will be exposed to any radiation beyond the permissible limits. However, to reassure the public, contingency plans are put in place even to handle such unlikely scenarios.

Keeping these facts in mind, if you still feel concerned on hearing any news or rumour about an incident at a nearby nuclear facility, follow these simple guidelines. These guidelines could also be followed in the event of any other nuclear emergency in your area, which does not even involve any nuclear facility.

- **DO THE FOLLOWING:**

1. Go indoors. Stay inside.

2. Switch on Radio/TV and look out for public announcements from your local authority.
3. Close doors/windows.
4. Cover all food, water and consume only such covered items.
5. If in the open, cover your face and body with a wet handkerchief, towel, dhoti or saree. Return home, change/remove clothes. Have a complete wash and use fresh clothing.
6. Extend full co-operation to local authorities and obey their instructions completely - be it for taking medication, evacuation, etc.

• **DO NOT DO THE FOLLOWING:**

1. Do not panic.
2. Do not believe in rumours passed on by word of mouth from one person to another.
3. Do not stay outside or go outside.
4. As far as possible, AVOID - water from open wells/ponds, exposed crops and vegetables, food, water or milk from outside.
5. Do not disobey any instruction of the District or Civil Defence Authorities who would be doing their best to ensure the safety of yourself, your family and your property.

AN OVERVIEW OF THE EMERGENCY RESPONSE PLANS IN THE DEPARTMENT OF ATOMIC ENERGY:

1. The Department of Atomic Energy (DAE) has been identified as the nodal agency in the country in respect of man made radiological emergencies in the public domain.
2. For this purpose, a Crisis Management Group (CMG) has been functioning since 1987 in DAE. In the event of any radiological or nuclear emergency in the public domain, the CMG is immediately activated and will co-ordinate between the local authority in the affected area and the National Crisis Management Committee (NCMC). The CMG comprises of senior officials drawn from various units of DAE like the Nuclear Power Corporation of India Ltd (NPCIL), Bhabha Atomic Research Centre (BARC), Heavy Water Board (HWP) and the Directorate of Purchase and Stores (DP&S). It also includes a senior official from the regulatory authority, the Atomic Energy Regulatory Board (AERB). Each member is backed by an alternate member, so that the CMG can be activated at a very short notice. Several Resource Agencies from BARC also backup the CMG. They can provide advice and assistance in the areas of radiation measurement and protection and medical assistance to radiation affected personnel.
3. As regards major nuclear facilities of DAE like the nuclear power stations, they have an Exclusion Zone of 1.6 km surrounding the power station in which no habitation is permitted. The entire area is fenced or walled off and defines the boundary of the site. Beyond this is the public domain and an area of 16 km radius around the plant site is called the Off Site Emergency Planning Zone (EPZ).
4. As a general practice, elaborate and comprehensive safety systems are in place for the operation of any nuclear facility. These are in turn overseen by the AERB who have powers to license and even shutdown any facility which violates their guidelines. However, as a matter of abundant caution, even some "beyond design basis" accidents are postulated for the nuclear power stations. It is only under such highly unlikely scenarios, that there is a possibility of a radiological emergency in the public domain. Therefore, in addition to the other types of emergency response plans in place within the facility to handle local emergencies, response plans have also been drawn up for handling such emergencies in the public domain, which are called as "Off Site Emergencies". These plans - drawn up separately in detail for each site - which are under the jurisdiction of the local District Administration, cover an area of about 16 km radius around the plant or the Off Site Emergency Planning Zone.
5. The first three types of Emergencies which are foreseen and for which detailed plant specific emergency response plans have been drawn up are Emergency Standby, Personnel Emergency and Plant Emergency. In all these, the consequences of the accident are expected to be limited to the plant facility only. The next type of Emergency which is foreseen is the Site Emergency, wherein the consequences of an accident are not expected to cross the site boundary, that is, the Exclusion Zone - which means that even under this condition, there is no radiological emergency in the public domain. The last type of Emergency which assumes the highly unlikely possibility of radiological releases in the public domain is the "Off Site Emergency" and detailed response plans have been drawn up even for this hypothetical scenario at each site. **The local District Administration, the Crisis Management**

Group, DAE and the National Crisis Management Committee (NCMC) get involved in this last type of Emergency.

6. It is mandatory for NPCIL to have comprehensive and well laid out plans to deal with all the above types of Emergencies. Barring the last one, all the others fall within the domain of responsibility of NPCIL, and the AERB as the Regulatory Authority approves these plans. It is also mandatory for the NPCIL to periodically test out these plans by way of Exercises and Drills and take corrective measures as stipulated by the Safety Committees and AERB. As the first stage of the trigger mechanism, the Crisis Management Group, DAE and its resource agencies are automatically alerted even when a Plant or Site Emergency/Exercise takes place.
7. In accordance with statutory requirements, it is the local District Administration which is responsible for drawing up and testing the Off Site Emergency Plans. NPCIL has co-ordinated with all concerned District Administration to enable them to draw up comprehensive Off Site Emergency Plans for each power station. It may be mentioned that the AERB does not permit any nuclear power station to be commissioned unless and until, such plans for all types of Emergencies are in place well before the commissioning date.
8. The Off Site Emergency Plans are also periodically tested and all power stations have ensured that this is being done atleast once in about two years. During these exercises, all the Members and Alternate Members of the Crisis Management Group, DAE, the Resource Agencies and Key Officials in Mumbai and Delhi are alerted. In these Exercises, the district administration is fully involved and the reports of the independent observers (from AERB, NPCIL and CMG) are used as a feedback to further improve the Emergency Response System.
9. Recognising the importance of communications in the handling of any Emergency, **Emergency Control Rooms (ECRs) are maintained at Mumbai at two different locations. These manned and operated on a round-the-clock and on all days of the year and maintain continuous contact with all the critical facilities of DAE.** The ECRs are equipped with Wireless, Telephone, Facsimile, VSAT and Electronic Mail facilities. These are tested practically on a daily basis to ensure their continuous availability. Further, each major site also carries out fortnightly or monthly communication exercises to test all the links in the entire communication chain.
10. In addition to about 165 communication exercises, about 110 emergency exercises are carried out every year. During the period from 1987 to 2000, 34 Off Site Emergency exercises have been conducted by the respective district administrations at various locations in the country. These involve direct participation by local district officials like police, health, transport, etc. At the end of each of these exercises, the District Collector/Magistrate chairs a "critique or feedback" session at which the deficiencies are recorded for taking corrective actions.
11. As regards transport of nuclear material, mandatory design specifications for the packaging, systems and procedures for handling and transport are in place to ensure that there is no release of radioactivity in the public domain in the unlikely event of such an accident. However, even if such an event were to occur, the procedures are such that the Emergency Control Room at the DAE Secretariat gets an alert which in turn would immediately activate the Crisis Management Group, DAE.
12. In the event of any other type of nuclear emergency in the public domain arising from the unauthorized presence or suspected presence of nuclear materials, a booklet giving the essential guidelines to be followed has been circulated to State Governments and Union Territories. Among other steps, the guidelines require that the nearest listed DAE facility as well as the DAE Emergency Control Room be also contacted immediately, who would then advise on the further necessary steps to be taken to attend to the emergency.

This short write up is primarily meant to educate the public and instill confidence about the Emergency Response System of DAE to handle radiation emergencies. As regards nuclear facilities of DAE, the regulatory and safety systems ensure that equipment are designed to operate safely and even in the unlikely event of any failure or accident, mechanisms like plant and site emergency response plans are in place to ensure that the public is not affected in any manner. In addition, detailed plans which involve the local public authorities, are also in place to respond if the consequences were to spill into the public domain. The System is also in a position to respond to any other radiation emergency in the public domain that may occur at locations which do not even have any DAE facility.

