

## **SCHEDULE - A**

Name of work:

**Special Repairs to the road network by Resurfacing with Polymer Modified Bitumen inside cargo jetty area.**

<b>Sr. No.</b>	<b>Kind of Materials</b>	<b>Qty.</b>	<b>Rate</b>	<b>Unit</b>	<b>Place of Delivery</b>
<b>1</b>	Cement	143.00	--	M. T.	Brought By Contractor
<b>2</b>	Reinforcement Bars	30.00	--	M. T.	Brought By Contractor
<b>3</b>	Emulsion	47.00	--	M. T.	Brought By Contractor
<b>4</b>	Bitumen VG-40	149.00	--	M. T.	Brought By Contractor
<b>5</b>	Bitumen PMB-76E-10	1026.00	--	M. T.	Brought By Contractor

Note; Quantities shown above are tentative

**Contractor**

**Executive Engineer (H),  
Deendayal Port Authority**